

FEET

This survey was made with a Wilde T-2 theodolite, Serial No. 92997, with automatic vertical indexing and microscopic angle-reading capabilities enabling the instrument man to read angles, either horizontal or vertical, to 1 sec. of arc. Distances greater than 500 feet were measured with electronic distance measuring equipment, a Hewlett-Packard Model 3800 Distance Meter, having a range of 10,000 feet and an absolute accuracy of 0.01 feet plus the distance measured divided by 100,000 in the normal operating temperature range. Both of these instruments were in good condition at the time of the survey and all adjustments were in good order.

Due to the inter-relationship of this survey with Survey Nos. 4768 and 4770, a control traverse embracing all of the above surveys was made. Angular error was $0^{\circ}00'02''$. Closure was in the proportion of 1:189,000. Two secondary traverses were made to tie in some points on this survey. Their accuracy was in the proportion of 1:7500 and 1:8000. Due to the steepness of the terrain, and heavy cover of brush and trees throughout most of the area, most corners were surveyed in by radiation from the control points. Some short traverses were used, and tied back into control by closing angles. Angular values, horizontal and vertical, are the mean of direct and inverse observation from the distant signal. Final corners, wherever possible, were checked by measurement of angles between control points from the final point as set. The concurrency of this survey and Survey Nos. 4768 and 4770, and the fact that all these surveys are based on the beforementioned control traverse, the bearing of the line common to secs. 17 and 18 was determined as follows:

June 4, 1974, at the Witness Corner of Sections 17, 18, 19 and 20, T. 11 S., R. 16 E., Gila and Salt River Meridian, located 2 chains northerly from the true point, according to the official record thereof, in latitude $32^{\circ}28'15''$ N., longitude $110^{\circ}44'46''$ W., (as determined by scaling from U.S.G.S. quadrangle, BELLOTA RANCH, dated 1957) I made two observations of Polaris, with the following results:

Observation No. 1

Average 105th Meridian time	= 8:38:48 p.m.
G.C.T. (June 5)	= 3:38:48
L.H.A.	= $165^{\circ}34'42''$
Horizontal angle, clockwise, from the $\frac{1}{2}$ sec. cor. of secs. 17 and 18, to traverse point "C"	= $29^{\circ}43'00''$
Horizontal angle, clockwise, Polaris to point "C"	= $30^{\circ}14'13''$

FEET

Bearing of Polaris
(West of Meridian) = -0°15'00"
 Bearing, W.C. to
 point "C" = N. 29°59'13" E.
 Bearing of sec. line,
 W.C. to $\frac{1}{2}$ sec. cor.
 of secs. 17 and 18 = N. 0°16'13" W.

Observation No. 2

Average 105th Meridian
 time = 8:45:34 p.m.
 G.C.T. (June 5) = 3:45:34
 L.H.A. = 164°16'24"
 Horizontal angle,
 clockwise, from the
 $\frac{1}{2}$ sec. cor. of secs.
 17 and 18 to traver-
 se point "C" = 29°43'00"
 Horizontal angle,
 clockwise, Polaris
 to point "C" = 30°13'34"
 Bearing of Polaris
 (West of Meridian) = -0°13'28"
 Bearing, W.C. to
 point "C" = N. 30°00'06" E.
 Bearing of sec. line,
 W.C. to $\frac{1}{2}$ sec. cor.
 of secs. 17 and 18 = N. 0°17'06" W.

Used the average of the above data; sec. line,
 Witness Cor. to $\frac{1}{2}$ sec. cor., N. 0°16'40" W., as
 a basis of bearing for this survey.

The geographic position of Cor. No. 1 of the
 H T FRACTION lode was computed (from its tie to
 the Witness Cor. of secs. 17, 18, 19 and 20), to
 be Latitude 32°28'33" N., Longitude 110°44'39" W.

The lines were measured with either a Lufkin
 steel tape or with the aforementioned electronic
 distance meter. The tape was 200 feet in length,
 graduated every foot for 200 ft., with an added
 foot on the zero end graduated in tenths and
 hundredths; the tape was compared with a 100.00
 foot standard tape at the time of beginning the
 survey, and found to be correct. Distances were
 read twice with E.D.M. equipment. Chained dis-
 tances were also measured twice.

The average magnetic declination was determined
 to be 13°30' E.

 Mineral Survey No. 4769

FEET	
	<p>H T FRACTION LODE</p> <p>At Cor. No. 1 of the H T FRACTION lode of this survey, identical with Cor. No. 2, M.S. No. 2871 HIDDEN TREASURE lode, Cor. No. 3, M.S. No. 2871 IMPERIAL lode and Cor. No. 1 Daily Extension No. 2 lode, uns.</p> <p>Found a 5/8 in. diam. steel pin, with aluminum cap, projecting 18 ins. in a mound of stones, mkd. M.S. 2871-I-3-HT-2-4768-DE-2-1. Added M.S. 4769-HTF-1 to aluminum cap; from which</p> <p>The Witness Cor. of secs. 17, 18, 19 and 20, T. 11 S., R. 16 E., bears S. 18°44'53" W., 1950.21 ft. dist., monumented with an iron post, 2 ins. diam., 12 ins. above ground, firmly set, with a brass cap properly mkd.</p> <p>The 1/4 sec. cor. of secs. 17 and 18, bears N. 43°14'58" W., 932.7 ft. dist., monumented with an iron post, 1 in. diam., 10 ins. above ground, firmly set, with a brass cap properly mkd.</p> <p>Cor. No. 4, M.S. No. 3499 DAILY EXTENSION lode, bears N. 44°21'24" W., 13.1 ft. dist.</p> <p>Cor. No. 3, M.S. No. 2871 HIDDEN TREASURE lode, bears N. 77°39'04" E., 751.69 ft. dist.</p> <p style="text-align: center;">Thence N. 24°02'29" E.</p>
13.19	Intersect line 3-4, M.S. No. 3499 DAILY EXTENSION lode, at a point from which Cor. No. 3 bears N. 79°32'38" E., 710.24 ft. dist.
296.64	Lode line; discovery point bears S. 77°25'59" E., 587.28 ft. dist.
315.	Center of road, 16 ft. wide, bears N. 42° E. and S. 42° W.
600.00	<p>Cor. No. 2.</p> <p>Set a 5/8 in. diam. steel pin, 30 ins. long, with aluminum cap, projecting 20 ins. in a mound of stones, mkd. M.S. 4769-HTF-2; from which</p> <p>Cor. No. 3, M.S. No. 3499 DAILY EXTENSION lode, bears S. 48°27'35" E., 613.75 ft. dist.</p> <p>A cor. of the location, identical with Cor. Nos. 1, 2, 3 and 4, M.S. No. 2871 HIDDEN TREASURE, ROOSEVELT, WAY-UP and IMPERIAL lodes, respectively, bears N. 24°02'29" E., 16.08 ft. dist.</p>

(This form bound on left side)

FEET	
	Thence S. 75°25'19" E.
415.	Center of road, 15 ft. wide, bears N. 10° E. and S. 10° W.
470.	Center of road, 15 ft. wide, bears N. 1° W. and S. 1° E.
585.	Center of road, 12 ft. wide, bears N. 4° E. and S. 4° W.
599.53	Intersect line 3-4, TURKEY lode, uns., at a point from which Cor. No. 3 bears S. 8°56'23" W., 262.97 ft. dist.
650.	Center of road, 20 ft. wide, bears N. 29° E. and S. 20° W.
660.	Wash, 20 ft. wide, course N. 31° E.
930.	Center of road, 18 ft. wide, bears N. 46° E. and S. 46° W.
1035.	Center of road, 20 ft. wide, bears N. 81° E. and S. 81° W.
1170.	Center of road, 15 ft. wide, bears N. 63° E. and S. 63° W.
1305.	Center of road, 20 ft. wide, bears N. 17° E. and S. 17° W.
1322.16	Intersect the common lines, 4-5 M.S. No. 2871 HIDDEN TREASURE lode, and 3-4 M.S. No. 3499 DAILY NO 3 lode, at a point from which Cor. No. 4, HIDDEN TREASURE lode, identical with Cor. No. 3, DAILY NO 3 lode, and Cor. No. 2, M.S. No. 3499 DAILY EXTENSION lode, bears S. 20°37'20" W., 256.71 ft. dist.
1349.52	Cor. No. 3. Set a 5/8 in. diam. steel pin, 30 ins. long, with aluminum cap, projecting 18 ins. in a mound of stone, mkd. M.S. 4769-HTF-3; from which Point for Cor. No. 3, M.S. No. 3017 EAGLE NO. 2 lode, bears N. 41°14'40" W., 72.96 ft. dist. Cor. No. 3, M.S. No. 3504 Oversight lode, bears N. 46°06'55" W., 96.41 ft. dist. A cor. of the location bears S. 75°22'42" E., 10.67 ft. dist. Thence S. 24°02'29" W.
113.98	Intersect line 2-3; TURKEY lode, uns., at a point from which Cor. No. 3 bears N. 87°22'07" W., 721.04 ft. dist.
255.04	Lode line; discovery point bears N. 77°25'59" W., 771.02 ft. dist.

FEET	
301.15	Intersect the common lines, 2-3 M.S. No. 3499 DAILY NO 3 lode, and 1-2 M.S. No. 3499 DAILY EXTENSION lode, at a point from which Cor. No. 3, DAILY NO 3 lode, identical with Cor. No. 2, DAILY EXTENSION lode, and Cor. No. 4, M.S. No. 2871 HIDDEN TREASURE lode, bears N. 7°13' E., 42.05 ft. dist.
340.	Center of road, 15 ft. wide, bears N. 6° E. and S. 6° W.
503.50	Cor. No. 4. Set a 5/8 in. diam. steel pin, 30 ins. long, with aluminum cap, projecting 18 ins. in a mound of stones, mkd. M.S. 4769-HTF-4; from which Cor. No. 2, M.S. No. 3499 DAILY EXTENSION lode, identical with Cor. No. 3, M.S. No. 3499 DAILY NO 3 lode and Cor. No. 4, M.S. No. 2871 HIDDEN TREASURE lode, bears N. 21°17'12" E., 243.03 ft. dist. Cor. No. 3, TURKEY lode, uns., bears N. 55°18'11" W., 683.05 ft. dist. A cor. of the location bears S. 79° 23'11" E., 28.59 ft. dist. Thence N. 79°24'35" W.
415.	Wash, 10 ft. wide, course N. 15° W.
440.	Center of road, 20 ft. wide, in curve, bears N. 58° E. and N. 53° W.
925.	Center of road, 15 ft. wide, bears N. 28° W. and S. 28° E.
985.	Center of road, 20 ft. wide, bears N. 5° W. and S. 13° E.
1050.	Center of road, 20 ft. wide, bears N. 48° E. and S. 28° W.
1180.	Center of road, 20 ft. wide, bears N. 10° E. and S. 10° W.
1368.70	Cor. No. 1, and place of beginning.
Mineral Survey No. 4769	
AREAS	
	Acres
Total area, H T FRACTION lode ----	16.861
Area in conflict with --	
M.S. No. 2871 HIDDEN TREASURE lode ----	10.105

(This form bound on left side)

FEET

M.S. No. 3499 DAILY NO 3 lode -----	0.121
M.S. No. 3499 DAILY EXTENSION lode -----	6.389
M.S. No. 3499 DAILY EXTENSION lode, exclusive of its conflict with M.S. No. 2871 HIDDEN TREASURE lode -----	6.349
Turkey lode, uns. -----	3.131
Turkey lode, uns., exclusive of its conflict with: (1) M.S. No. 2871 HIDDEN TREASURE lode -----	0.068
(2) M.S. No. 3499 DAILY NO 3 lode -----	3.068
(3) M.S. No. 3499 DAILY NO 3 lode and M.S. No. 2871 HIDDEN TREASURE lode -----	0.005

LOCATION

This survey is located in sec. 17, of T. 11 S., R. 16 E., Gila and Salt River Meridian. The survey of the H T FRACTION lode is wholly within the location as marked on the ground; Cor. No. 1 is identical with a cor. of the location; Cor. Nos. 2, 3 and 4 differ to the extent previously shown. Loc. mons. are mounds of stone with posts therein.

EXPENDITURES

The improvements and the value of the labor and improvements made upon or for the benefit of the lode location embraced in this survey by the claimant or its grantors are as follows:

No. 1 The discovery point of the H T FRACTION lode, is on the lode line 587.28 ft. from a point on line 1-2, 296.64 ft. from Cor. No. 1.
Value, none.

No. 2 A diamond drill hole collar, designated #84 by claimant, the center of which bears N. 84°32'13" E., 1164.05 ft. dist. from Cor. No. 1 H T FRACTION lode. The drilling collar is on M.S. No. 2871 HIDDEN TREASURE lode. This hole, according to results of a drift survey furnished by claimant; was drilled on a slant, so that it crosses an apparent fraction of Public Land between line 3-4, M.S. No. 2871, HIDDEN TREASURE lode, and line 2-3, M.S. No. 3499, DAILY EXTENSION lode.

From the above information, I computed the length of the drill hole within said apparent fraction to be 92.14 lineal ft.

FEET

Total depth of hole 4 in. diam., 1126.0 lineal ft.

Total cost of hole, \$7852.40

Value of 1 lineal ft., \$6.974

Value of 92.14 lineal ft., \$642.58

OTHER IMPROVEMENTS

Primitive drilling access roads as indicated on the map of this survey.

Claimant herein.

OTHER CORNER DESCRIPTIONS AND SUPPLEMENTAL DATA

M.S. No. 2871 HIDDEN TREASURE lode: Cor. No. 1, identical with Cor. Nos. 2, 3 and 4, M.S. No. 2871 ROOSEVELT, WAY-UP and IMPERIAL lodes, respectively, is monumented with a 5/8 in. diam. steel pin in a mound of stone, no markings or bearing objects; Cor. No. 2, identical with Cor. No. 3, M.S. No. 2871 IMPERIAL lode, Cor. No. 1, Daily Extension No. 2 lode, uns. and Cor. No. 1, H T FRACTION lode of this survey, heretofore described; Cor. No. 3 is monumented with a stone, firmly set and properly mkd.; Cor. No. 4, identical with Cor. Nos. 2 and 3, M.S. No. 3499 DAILY EXTENSION and DAILY NO 3 lodes, respectively, was destroyed by road construction. I reestablished the cor. by "broken boundary" adjustment of a traverse from Cor. No. 3, M.S. No. 3504 Oversight lode to Cor. No. 3. Set a 5/8 in. diam. steel pin, with aluminum cap, mkd. HT-4-2871-DE-2-D3-3-3499; Cor. No. 5, identical with Cor. No. 4, M.S. No. 2871 ROOSEVELT lode and Cor. No. 2, M.S. No. 3054 Grand Central lode. Set a 5/8 in. diam. steel pin in the center of a stone mound for cor. point. A stone outcrop bears N. 10° E., 10 ft. dist., mkd. RX2-3054 and a loose stone bears S. 70° E., 26 ft. dist., mkd. BOX3054; Cor. No. 6, identical with Cor. No. 3, M.S. No. 2871 ROOSEVELT lode could not be found. Its position (not monumented), was calculated by "broken boundary" adjustment of a traverse from Cor. No. 5 to Cor. No. 1. Line 1-2 was found to be S. 24°02'29" W., 616.08 ft., instead of S. 20°00' W., 600.0 ft. as approved; line 2-3 was found to be N. 77°39'04" E., 751.69 ft., instead of N. 76°53'40" E., 755.17 ft., as approved in M.S. No. 3499; line 3-4 was found to be S. 75°06'58" E., 723.6 ft., instead of S. 75°44' E., 725.73 ft., as approved in M.S. No. 3499; line 4-5 was found to be N. 20°37'20" E., 614.39 ft., instead of N. 20°00' E., 612.16 ft., as approved in M.S. No. 3504; line 5-6 was calculated to be N. 77°58'46" W., 713.86 ft., instead of N. 78°00' W., 750.0 ft., as approved; line 6-1 was calculated to be S. 79°01'14" W., 713.86 ft., instead of S. 79°00' W., 750.0 ft., as approved.

FEET

M.S. No. 2871 ROOSEVELT lode: Cor. No. 1, identical with Cor. No. 4, M.S. No. 2871 WAY-UP lode could not be found; Cor. Nos. 2, 3 and 4, described above. Line 1-2 is shown as approved; lines 2-3 and 3-4 described above.

M.S. No. 2871 WAY-UP lode: Cor. No. 2, identical with Cor. No. 1, M.S. No. 2871 IMPERIAL lode and on line 1-2, M.S. No. 2871 HOMESTAKE lode could not be found; Cor. Nos. 3 and 4 described above. Lines 2-3 and 3-4 are shown as approved.

M.S. No. 2871 IMPERIAL lode: Cor. Nos. 1, 3 and 4 described above; Cor. No. 2, on line 1-2, M.S. No. 2871 LONE PINE lode is monumented with a stone, firmly set, top broken, visible scribing I-871. Line 2-3 was found to be S. 81°27'39" E., 1451.93 ft., instead of S. 81°00' E., 1500.0 ft., as approved; lines 3-4 and 4-1 described above.

M.S. No. 3017 EAGLE No. 2 lode: Cor. No. 2, identical with Cor. No. 2, M.S. No. 3017 GOLDEN PEAK No. 2 lode; Cor. No. 2, M.S. No. 3504 Oversight lode and on line 3-4, M.S. No. 3499 SPHINX lode, is monumented with an oak post in a mound of stone mkd. 2E2-3017-2-3504OS; Cor. No. 3, on line 2-3, M.S. No. 3504 Oversight lode was destroyed by road construction. Its position (not monumented) was established at record distance from Cor. No. 3 and on line 2-3, M.S. No. 3504 Oversight lode; Cor. No. 4 is monumented with a pine post in a mound of stone, mkd. 3017 E-4. Line 2-3 was found to be N. 60°45'49" W., 1474.87 ft., instead of N. 61°31' W., 1473.0 ft., as approved in M.S. No. 3504; line 3-4 was found to be N. 59°49'12" E., 591.84 ft., instead of N. 59°16' E., 591.01 ft., as approved in M.S. No. 3504.

M.S. No. 3499 DAILY EXTENSION lode: Cor. No. 1, identical with Cor. No. 2, M.S. No. 3499 CAVE lode and on line 2-3, M.S. No. 3499 DAILY NO 3 lode, was destroyed by road construction; Cor. No. 2 described above; Cor. No. 3 is a loose stone in a stone mound, top broken, visible markings X4 3499. Set a 40d nail. Cor. No. 4 is monumented with a stone, firmly set and properly mkd.; Cor. No. 5, identical with Cor. No. 3, M.S. No. 3499 CAVE lode, is monumented with an old mound of stone, no markings. Set a 40d nail. Line 1-2 is shown as approved; line 2-3 was found to be N. 77°10'55" W., 748.45 ft., instead of N. 78°00' W., 750.0 ft., as approved; line 3-4 was found to be S. 79°32'38" W., 725.0 ft., instead of S. 79°00' W., 728.0 ft., as approved; line 4-5 was found to be S. 7°29'42" W., 346.82 ft., instead of S. 7°13' W., 347.87 ft., as approved. From Cor. No. 3 to Cor. No. 3, M.S. No. 2871 HIDDEN TREASURE lode bears N. 56°58'12" E., 36.4 ft., instead of N. 52°52' E., 37.95 ft., as approved.

FEET

M.S. No. 3499 DAILY NO 3 lode: Cor. No. 2, identical with Cor. Nos. 1, 2 and 2, M.S. No. 3499 CAVE, WEDGE NO 3 and CALUMET lodes, respectively, could not be found; Cor. No. 3 described above; Cor. No. 4 has been destroyed and was reestablished at record distance of 5.6 ft., on line 4-5, M.S. No. 2871 HIDDEN TREASURE lode, from the intersection of line 3-4 DAILY NO 3 lode with line 3-4, M.S. No. 3504 Oversight lode. Set a 5/8 in. diam. steel pin with aluminum cap, mkd. 3499 D3-4. Cor. No. 5, identical with Cor. No. 3, M.S. No. 3499 DAILY NO. 5 lode was apparently destroyed by road construction. The point for the cor. was determined by single proportionate measurement between reestablished Cor. No. 4 and Cor. No. 2, M.S. No. 3017 EAGLE NO. 2 lode, identical with Cor. No. 2, M.S. No. 3504 Oversight lode. Line 2-3 is shown as approved; line 3-4 was found to be N. 20°37'20" E., 378.49 ft., instead of N. 20°00' E., 378.75 ft., as approved; line 4-5 was found to be S. 57°14'58" E., 504.36 ft., instead of S. 58°01' E., 503.65 ft., as approved.

M.S. No. 3504 Oversight lode: Cor. No. 2 described above; Cor. No. 3 is monumented with a stone, firmly set, and properly mkd. and with a stone mound 2 ft. West; Cor. No. 4 has been destroyed and was reestablished on line 1-2, M.S. No. 3054 Grand Central lode at a point N. 68°29'05" W., at record distance of 26.85 ft., from the intersection of line 1-2, Grand Central lode with line 3-4, M.S. No. 3017 EAGLE No. 2 lode. Set a 5/8 in. diam. steel pin with aluminum cap, mkd. 3504 OS-4. Line 2-3 was found to be N. 60°45'49" W., 1499.37 ft., instead of N. 61°31' W., 1497.5 ft., as approved; line 3-4 was found to be N. 59°49'24" E., 404.8 ft., instead of N. 59°16' E., 404.29 ft., as approved.

Note concerning the following unsurveyed lode locations: Daily Extension No. 2 and TURKEY. Although these unsurveyed claims are junior in location to this survey, it has been discussed and shown on the plat with their corners referred to by corner number. The reason for this is that the Daily Extension No. 2 and TURKEY lodes are presently being surveyed by me under orders for Mineral Survey Nos. 4768 and 4770, respectively. Since corner numbers have already been assigned, I have elected to refer to such corners by corner numbers rather than by general location. Due to the fact that these surveys have not been approved, I have herein referred to said lodes as unsurveyed. At the time of the survey, conditions were as follows:

Daily Extension No. 2 lode, uns.: All corners are in place. Line 1-2 bears S. 7°59'48" W., 535.6 ft., line 4-1 bears S. 81°01'56" E., 1495.88 ft.

FEET

TURKEY lode, uns.: All corners are in place. Line 2-3 bears N. 87°22'07" W., 1278.78 ft., line 3-4 bears N. 8°56'23" E., 567.25 ft.

The line bet. secs. 17 and 18, T. 11 S., R. 16 E., from the W.C. of secs. 17, 18, 19 and 20, to the ¼ sec. cor. of secs. 17 and 18, was found to be N. 0°16'40" W., 2526.12 ft., instead of N. 0°03' W., 2508.0 ft., as described in the official record.

FIELD ASSISTANTS

Name	Capacity
<u>Joseph Domler</u>	<u>Instrumentman</u>
<u>Lee Jones</u>	<u>Chainman</u>

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

11

CERTIFICATE OF SURVEYOR

Name of Mineral Surveyor ROBERT L. FRAZER	Date July 31, 1974
---	------------------------------

I HEREBY CERTIFY That in pursuance of an order received from the Bureau of Land Management, at Phoenix, Arizona, dated November 14, 1973, I have carefully executed the survey of the claim of Continental Copper, Inc. known as the (lode, placer, or mill site) H T Fraction lode situated in Section 17 Township 11 S., Range 16 E., Gila & Salt River Meridian, in the State of Arizona

This survey, designated as number 4769, has been executed by me and under my direction and has been made in strict conformity with said order, the Manual of Instructions for the Survey of Public Lands of the United States, and in the specific manner described in the foregoing field notes.

I FURTHER CERTIFY That the labor expended and improvements made upon and for the benefit of the (lode or placer) lode location(s) embraced in the said mining claim by claimant(s) or its grantors are fully stated in my report. The character, extent, location, and itemized value are specified in full detail. No portion of, or interest in, said labor and improvements so credited to this claim has been included in the estimate of expenditures upon any other claim.

P.O. Box 1711, Tucson, Az. *Robert L. Frazer*
(Location) 857 02 (Signature of Mineral Surveyor)

CERTIFICATE OF APPROVAL

Office Arizona State Office
Location Phoenix, Arizona
Date July 21, 1975

The foregoing field notes of mineral survey number 4769, in Section 17 Township 11 S., Range 16 E., Gila and Salt River Meridian, in the State of Arizona, executed by Robert L. Frazer Mineral Surveyor, under order dated November 14, 1973, having been critically examined and the necessary corrections made prior to their certification by the surveyor, the field notes and the survey therein described are hereby approved.

E. F. Spang Acting State Director
(Authorized Signature) (Title)
Edward F. Spang

CERTIFICATE OF TRANSCRIPT

I CERTIFY That the foregoing transcript of field notes of the above described mineral survey number is a true copy of the original field notes.

(Authorized Signature) (Title)

18, U. S. C. section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious, or fraudulent statements or representations as to any matter within its jurisdiction.

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Form 1000
October 1958

11

CERTIFICATE OF SURVEY

Name of land owner: ROBERT J. FARRER
Date of survey: July 11, 1954
Section: 14
Twp: 36 N. R: 10 W.
County: YAVAPAI
State: ARIZONA
The survey was made in accordance with the provisions of the Act of October 3, 1917, and the Act of March 3, 1909, and the rules and regulations thereunder. The land is situated in the SW 1/4 of Section 14, Township 36 North, Range 10 West, Yavapai County, Arizona. The area surveyed is 40 acres, more or less. The survey was made by the undersigned, a duly qualified and licensed surveyor, and the same is true and correct to the best of his knowledge and belief.

[Handwritten signature: Robert J. Farrer]
Robert J. Farrer, Surveyor

CERTIFICATE OF APPROVAL

Name: _____
Title: _____
Signature: _____
Date: _____
The survey was approved by the undersigned, a duly qualified and licensed surveyor, and the same is true and correct to the best of his knowledge and belief.

[Handwritten signature]

CERTIFICATE OF CORRECTION

Name: _____
Title: _____
Signature: _____
Date: _____
The survey was corrected by the undersigned, a duly qualified and licensed surveyor, and the same is true and correct to the best of his knowledge and belief.