

4-688

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED
LAND OFFICE
BUREAU OF LAND MANAGEMENT

FEB -8 1963

10 A.M.
PHOENIX, ARIZONA

MINERAL SURVEY NO. 4587

Arizona

Land District.

FIELD NOTES

Of The Survey Of The Mining Claim Of

William H. Passey

Known As The

Christmas and Good Luck lodes

Tonto Basin Mining District,

Gila County, Arizona

Section 25, Township 4 N., Range 11 E.

Surveyed under order dated October 25, 1961

by Oscar T. Smith
Mineral Surveyor.

Claim located January 1, 1896, 19

Survey commenced April 2, 1962

Survey completed April 15, 1962

Address of claimant Mesa, Arizona Atty. for claimant:
Morris & Malott
Globe, Arizona

DATES OF AMENDED LOCATIONS

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
WASHINGTON, D. C. 20250

LAND ACQUISITION STATEMENT

Section 106

STATEMENT OF WORK

1. Name of the project: [Illegible]

2. Description of the project: [Illegible]

3. Objectives of the project: [Illegible]

4. Scope of the project: [Illegible]

5. Schedule of the project: [Illegible]

6. Budget of the project: [Illegible]

7. Personnel assigned to the project: [Illegible]

8. Other information: [Illegible]

STATEMENT OF WORK

=Chains=

This survey was made with a Keuffel & Esser Co. Transit No. 131481 with horizontal limb 5 ins. diam., having two double opposite verniers, and full vertical circle 5 ins. diam., having one double vernier; the verniers read to one minute of arc; the eyepiece is equipped with a colored shade set in the dust shutter for making direct observations upon the sun. The instrument was in good condition at the time of the survey and all adjustments were in good order.

All azimuths in this record were determined by the method of deflection angles referred to the meridian determined by the following observation: April 2, 1962, at cor. No. 1 of the Good Luck lode, in latitude $33^{\circ}39'40''$ N. and longitude $111^{\circ}11'$ W., I make a series of six altitude observations upon the sun for azimuth at approximately equal time intervals, three each with the telescope in direct and reversed positions observing opposite limbs of the sun, and reading the horizontal angle from a reference point 600 ft. northwestward counterclockwise to the sun.

Mean time of observation,
105th meridian standard time = $3^{\text{h}}39^{\text{m}}30^{\text{s}}$ p.m.

Declination of sun at mean
time of observation = $5^{\circ}01'09''$ N.

Mean observed vertical angle
to sun's center = $36^{\circ}58'20''$

Mean horizontal angle from
reference point to sun's
center = $60^{\circ}57'$ N-W

True bearing to reference
point = N. $50^{\circ}43'47''$ W.

The lines were measured with a Keuffel & Esser steel tape 500 ft. in length, graduated every foot for 500.00 feet with the first and last foot graduated in tenths and hundredths; the tape was compared with a standard 100.00 ft. invar tape at the time of beginning the survey and found correct.

All lines and connections of this survey were run by direct methods. The magnetic declination observed at each corner of the survey gave a uniform value of $13^{\circ}40'$ E.

Feet

GOOD LUCK LODE

At cor. No. 1 of the Good Luck lode, identical with cor. No. 1 Christmas lode of this survey.

Set an iron pipe, 3 ft. long, 2 ins. diam., 18 ins. in the ground, with iron cap mkd. GL-1-C-L-4587; from which

The Mineral Monument No. 1-4587 bears S. $21^{\circ}14'30''$ W., 545.60 ft. dist.

No local bearing objects or bearing trees available.

Thence S. $39^{\circ}16'$ W.

Chains Feet	
140.00	Canyon, course bears S. 21° E.
800.00	Top of ridge, bears N. 69° E. and S. 69° W.
965.00	Top of ridge, bears N. 15° W. and S. 15° E.
1500.00	Cor. No. 2. Set an iron pipe, 3 ft. long, 2 ins. diam., 18 ins. in the ground with iron cap mkd. GL-2-4587; from which A corner of the location bears S. 50°44' E., 34.00 ft. dist. No local bearing objects or bearing trees available. Thence N. 50°44' W.
300.00	Lode line; discovery point bears N. 39°16' E., 1400.00 ft. dist.
500.00	Canyon, course bears S. 46° W.
600.00	Cor. No. 3. Set iron pipe, 3 ft. long, 2 ins. diam., 18 ins. in the ground, with iron cap mkd. GL-3-4587. No local bearing objects or bearing trees available. Thence N. 39°16' E.
417.00	Canyon, course bears S. 5° W.
790.00	Top of ridge, bears N. 29° W. and S. 29° E.
1500.00	Cor. No. 4, identical with cor. No. 2 Christmas lode of this survey. Set an iron pipe, 3 ft. long, 2 ins. diam., 18 ins. in the ground with iron cap mkd. GL-4-C-2-4587; from which A cor. of location bears N. 45°35' W. 53.00 ft. dist. No local bearing objects or bearing trees available. Thence S. 50°44' E.
300.00	Lode line; discovery point bears S. 39°16' W., 100.00 ft. dist.
350.00	Canyon, course bears S. 30° E.
600.00	Cor. No. 1, and place of beginning.

SURVEY NO. 4587

Chains Feet	CHRISTMAS LODGE
	Beginning at cor. No. 1, identical with cor. No. 1 of the Good Luck lode of this survey. Thence N. 50°44' W.
250.00	Canyon, course bears S. 30° E.
300.00	Lode line; discovery point bears N. 39°16' E., 750.00 ft. dist.
600.00	Cor. No. 2, identical with cor. No. 4 of the Good Luck lode of this survey. Thence N. 39°16' E.
70.00	Canyon, course bears S. 35° E.
905.00	Top of ridge, bears N. 41° W. and S. 41° E.
1500.00	Cor. No. 3. Set an iron pipe, 3 ft. long, 2 ins. diam., 18 ins. in the ground with iron cap mkd. C-3-4587. No local bearing objects or bearing trees available. Thence S. 50° 44' E:
110.00	Canyon, course S: 19° E.
300.00	Lode line; discovery point bears S. 39°16' W., 750.00 ft. dist.
600.00	Cor. No. 4. Set an iron pipe, 3 ft. long, 2 ins. diam., 18 ins. in the ground, with iron cap mkd. C-4-4587. No local bearing objects or bearing trees available. Thence S. 39°16' W.
300.00	Canyon, course bears S. 14° E.
805.00	Top of ridge, bears N. 44° W. and S. 44° E.
1335.00	Canyon, course bears S. 50° E.
1500.00	Cor. No. 1, and the place of beginning.

AREAS

	Acres
Total area, Good Luck lode	20.661
Total area, Christmas lode	20.661

LOCATION

This survey is located in Sec. 25, T. 4 N., R. 11 E., G. & S. R. M., Arizona, (unsurveyed).

Claim

The survey of the Good Luck and Christmas lodes is wholly within the location as marked on the ground; all corners are identical except the ones previously shown.

EXPENDITURES

The improvements and the value of the labor and improvements made upon or for the benefit of each of the lode locations embraced in said mining claim by the claimant or its grantors is not less than \$500.00, and said improvements are as follows:

- No. 1 The discovery point of the Good Luck lode being on the lode line 100 ft. from a point on line 4-1, 300.00 ft. from cor. No. 1.
No value
- No. 2 A cut, 10 ft. wide; the face of which bears N. 55°35' W., 267 ft. dist. from cor. No. 1, Good Luck lode, runs S. 44° W., 20 ft. to a 15 ft. face and portal of tunnel 4 x 7 ft. in size, running S. 40° W., 120 ft. to breast.
Value of cut and tunnel, \$4950.00
- No. 3 A cut, 5 ft. wide, the face of which bears S. 8°40' E., 315 ft. dist. from cor. No. 4, Good Luck lode, runs S. 52° W., 16 ft., to an 8 ft. face.
Value, \$160.00
- No. 4 A cut, 5 ft. wide, the face of which bears S. 50°17' W., 664.0 ft. dist. from cor. No. 1, Good Luck lode, runs S. 38° W., 25 ft., to a 10 ft. face.
Value, \$325.00
- No. 1 The discovery point of the Christmas lode, being on the lode line, 750.00 ft. dist. from line 1-2, 300.00 ft. from cor. No. 1.
No value.
- No. 2 A tunnel, 4 x 6 ft. in size, the portal of which bears N. 38°30' W., 296 ft. from cor. No. 1, Christmas lode, runs N. 40° E., 252.00 ft., to breast.
Value, \$7560.00
- No. 3 A shaft, the center of which bears N. 0°42' W., 466 ft. dist. from cor. No. 1, Christmas lode, 12x12x21 ft. deep.
Value, \$1512.00
- No. 4 A tunnel, 4 x 6 ft. in size, the portal of which bears N. 1°28' E., 477.0 ft. dist., from cor. No. 1, Christmas lode, runs N. 39° E., 185 ft. to breast.
Value, \$5550.00
- No. 5 A trench, 5 ft. wide and 5 ft. deep, the southwest end of which bears N. 2°37' E., 498 ft. dist. from cor. No. 1, Christmas lode, runs N. 27°20' E., 47.0 ft. dist.
Value, \$585.00
- No. 6 A trench, 18 ft. wide, 7 ft. deep, the southwest end of which bears N. 4°42' E., 541 ft. dist. from cor. No. 1, Christmas lode, runs N. 27°30' E., 78 ft.
Value, \$4900.00

Claims

- No. 7 A tunnel, 4 x 6 ft. in size, the portal of which bears N. $10^{\circ}32'$ E., 654 ft. dist. from cor. No. 1, Christmas lode, runs N. 39° E., 150 ft. to breast.
Value, \$4500.00.
- No. 8 A cut, 4 ft. wide, the face of which bears N. $13^{\circ}44'$ E., 705 ft. dist. from cor. No. 1, Christmas lode, runs N. 39° E., 20 ft. to a 20 ft. face.
Value, \$400.00.

OTHER IMPROVEMENTS

None.

OTHER CORNER DESCRIPTIONS AND SUPPLEMENTAL DATA

None.

FIELD ASSISTANTS

Name	Capacity
Jerry Brewer	Chainman
Gerald Sanders	Chainman

SURVEY NO. 4587

Owner

Notes

No. 7
 A tunnel, 4 x 6 ft. in size, the portal of which bears
 10° 25' E., 634 ft. dist. from cor. No. 1, Christmas
 lode, runs N. 20° E., 150 ft. to cross.
 Value, \$2500.00.

No. 8
 A cut, 4 ft. wide, the face of which bears
 70° E., 100 ft. dist. from cor. No. 1, Christmas lode, runs
 N. 25° E., 20 ft. to a 10 ft. face.
 Value, \$400.00.

OTHER IMPROVEMENTS

None.

OTHER CORNER DESCRIPTIONS AND SUPPLEMENTAL DATA

None.

FIELD ASSISTANTS

Name

Capacity

Patric Sabers
 Jerry Brewer

Christian
 Christian

ESTABLISHMENT OF U. S. M. M. NO. 1-4587

The U. S. M. M. No. 1-4587 has a lat. of $33^{\circ}39'37''$ N. and long. of $111^{\circ}10'56''$ W. and is an iron pipe 3 ft. long, 2 ins. diam., 18 ins. in the ground, with iron cap mkd. U.S.M.M. 1-4587; from which

The U. S. Reclamation Service B. M. Elev. 2141+ at center of Roosevelt Dam bears N. $62^{\circ}33'20''$ E., 7930.15 ft. dist.

A tunnel, 4 x 6 ft. in size, runs N. 39° E., 150 ft. to breast, the portal of which bears N. $15^{\circ}24'20''$ E., 1194.20 ft. dist.

A tunnel, 4 x 6 ft. in size, runs N. 40° E., 252.00 ft. to breast, the portal of which bears N. $1^{\circ}03'$ E., 740.24 ft. dist.

ESTABLISHMENT OF U. S. N. W. NO. 1-1287

The U. S. N. W. No. 1-1287 has a list of "RESERVED" N. W. sections of 11' 10" N. and is an iron pipe 12' long, 12' dia. in the ground, with iron caps at U. S. N. W. 1-1287; from which

The U. S. Reclamation Service has a list of "RESERVED" N. W. sections of 11' 10" N. and is an iron pipe 12' long, 12' dia. in the ground, with iron caps at U. S. N. W. 1-1287; from which

A tunnel, 4 x 6 ft. in size, runs N. 25° E., 120 ft. to crest, the portal of which bears N. 12° 24' E., 120 ft. dist.

A tunnel, 4 x 6 ft. in size, runs N. 40° E., 225 ft. to crest, the portal of which bears N. 1° 02' E., 24 ft. dist.



UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

CERTIFICATE OF SURVEYOR

April 14, 1962

I, OSCAR T. SMITH,
 Mineral Surveyor, hereby certify upon honor that in pursuance of an order received from the Department
 Management
 of the Interior, Bureau of Land/ _____, at Phoenix, Arizona
 dated October 25, 1961, I have faithfully and correctly executed the survey of
 the mining claim of William H. Passey
 known as the Christmas and Good Luck lodes
 (Lode, placer, or mill site)
 situate in Tonto Basin Mining District, Gila County, Arizona,
Section 25 (unsurveyed).
 T. 4 N., R. 11 E. Gila & Salt River Meridian, Arizona, and
 (State)
 designated as Survey No. 4587, which is represented in the foregoing field notes as having been
 executed by me and under my direction, and that said survey has been made in strict conformity with said order,
 the Manual of Instructions for the Survey of the Public Lands of the United States, and in the specific manner
 described in the foregoing field notes, and I do further certify that the labor expended and improvements made
 upon or for the benefit of the above location(s) embraced in the said mining claim by
 (Lode or placer)
 claimant(s) or his grantors are fully stated in my report therein, and that the character,
 extent, location, and itemized value thereof are specified therein with particularity and full detail, and that no
 portion of, or interest in, said labor and improvements so credited to this claim has been included in the estimate
 of expenditures upon any other claim.


Globe, Arizona
(Place)


 (Mineral Surveyor)

CERTIFICATE OF APPROVAL

Bureau of Land Management, State Office
 (Office)
Phoenix, Arizona February 12, 1963
 (Place) (Date)

The foregoing field notes of mineral survey No. 4587, in Section 25 (Tonto Basin
Mining District), T. 4 N., R. 11 E. (unsurveyed) G. & S. R. Meridian,
Arizona, executed by Oscar T. Smith, Mineral Surveyor,
 (State)
 under order dated October 25, 1961, having been critically examined and the necessary
 corrections made prior to their certification by the surveyor, the field notes and the survey therein described
 are hereby approved.


 Fred J. Weiler
 State Director
 (Title)

CERTIFICATE OF TRANSCRIPT

I CERTIFY that the foregoing transcript of field notes of the above described mineral survey No. _____
 is a true copy of the original field notes.

 (Title)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

CERTIFICATE OF SURVEYOR

1922

(PAGE 1 OF 1)

Mineral Surveyor, hereby certify upon honor that in pursuance of an order received from the Director of the Interior, Bureau of Land Management, at Washington, D.C.,

dated October 22, 1922, I have faithfully and conscientiously executed the survey of

the mining claim of [Name],

known as the [Name] and [Name] lodes

situated in [Name] Mining District, [Name] County, [Name] State,

Section 15, Township 12 N., Range 11 E., [Name] Meridian, and

which is represented in the foregoing field notes as having been

surveyed by me and under my direction and that said survey, as being conducted in conformity with said order,

and in accordance with the instructions of the Director of the Interior, and in the specific manner

described in the foregoing field notes, and in full conformity with the laws and regulations of the United States

Department of the Interior, and that the same are correct and true, and that the same are

correct and true, and that the same are correct and true, and that the same are correct and true,

and that the same are correct and true, and that the same are correct and true, and that the same are correct and true,

[Signature]
Surveyor

CERTIFICATE OF APPROVAL

I, the Director of the Interior, Bureau of Land Management, do hereby approve the foregoing field notes of [Name] and

the same are correct and true, and that the same are correct and true, and that the same are correct and true,

and that the same are correct and true, and that the same are correct and true, and that the same are correct and true,

and that the same are correct and true, and that the same are correct and true, and that the same are correct and true,

and that the same are correct and true, and that the same are correct and true, and that the same are correct and true,

and that the same are correct and true, and that the same are correct and true, and that the same are correct and true,

and that the same are correct and true, and that the same are correct and true, and that the same are correct and true,

[Signature]
Director

CERTIFICATE OF TRANSCRIPT

I hereby certify that the foregoing transcript of field notes of the above described mineral survey No. [Number]

is a true and correct copy of the original field notes.

and that the same are correct and true, and that the same are correct and true, and that the same are correct and true,

and that the same are correct and true, and that the same are correct and true, and that the same are correct and true,

and that the same are correct and true, and that the same are correct and true, and that the same are correct and true,

UNITED STATES DEPARTMENT OF THE INTERIOR 9605 (952)
BUREAU OF LAND MANAGEMENT M.S. 4587
ARIZONA STATE OFFICE

NOTICE OF CANCELLATION OF MINERAL SURVEY

The Good Luck and Christmas lodes, Mineral Survey No. 4587, located in section 25, Township 4 North, Range 11 East, Gila and Salt River Meridian, Arizona, are hereby canceled.


These claims have not been filed with the Arizona State Office, Bureau of Land Management, in accordance with Section 314, 90 STAT. 2769, (43 U.S.C. 1744).

This cancellation was necessitated to clear the record.

The Mineral Survey Plat should be noted as follows:

"Good Luck and Christmas lodes, M.S. 4587 were canceled April 20, 1999, by memo 9605 (952) M.S. 4587, which is now a part of the original field notes."

April 20, 1999
Date


Chief Cadastral Surveyor of Arizona

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
ALABAMA STATE OFFICE

NOTICE OF CANCELLATION OF MINERAL SURVEY

The Good Luck and Old Adams Mines, Mineral Survey No. 4287, located in section 22, Township 4 North, Range 11 East, G11S and Salt River Landings, Alabama, are hereby canceled.

These plates have not been filed with the Alabama State Office, Bureau of Land Management, in accordance with section 314, 30 STAT., 3789, 143 U.S.C. 1789.

This cancellation was necessitated to clear the record.

The Mineral Survey list should be noted as follows:

Good Luck and Old Adams Mines, M.S. 4287 were canceled April 20, 1907, by order 9002 (2002) M.S. 4207, which is now a part of the original file.

Handwritten signature

Chief Central Surveyor of Alabama

April 20, 1907