

Form 3400-11
(September 1967)
(formerly 4-683)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Mineral Survey number
4770

State
Arizona

Land District
Arizona

FIELD NOTES

Of the Survey of the Mining Claim of *(name and address of Claimant)*

Continental Copper Inc.,
c/o Evans, Kitchel & Jenckes, P.C.
363 N. First Ave., Phoenix, Arizona 85003

Known as the *(name of group, if any)*

CONSISTING OF LOCATIONS NAMED AND LOCATED AS FOLLOWS

NAME OF LOCATION	DATE	
	LOCATED	AMENDED
Turkey	11-12-70	

Mining district Old Hat		County Pima	
Section 17	Township 11 South	Range 16 East	Meridian Gila & Salt River
Survey commenced May 5, 1974		Survey completed July 1, 1974	Survey under order dated Nov. 15, 1973
Name of Mineral Surveyor Robert L. Frazer			

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

40

41

42

43

44

45

46

47

48

49

50

51

52

53

54

55

56

57

58

59

60

61

62

63

64

65

66

67

68

69

70

71

72

73

74

75

76

77

78

79

80

81

82

83

84

85

86

87

88

89

90

91

92

93

94

95

96

97

98

99

100

FEET

This survey was made with a Wilde T-2 theodolite, Serial No. 92997, with automatic vertical indexing and microscopic angle-reading capabilities enabling the instrument man to read angles, either horizontal or vertical, to 1 sec. of arc. Distances greater than 500 feet were measured with electronic distance measuring equipment, a Hewlett - Packard Model 3800 Distance Meter, having a range of 10,000 feet and an absolute accuracy of 0.01 feet plus the distance measured divided by 100,000 in the normal operating temperature range. Both of these instruments were in good condition at the time of the survey and all adjustments were in good order.

Due to the inter-relationship of this survey with Survey Nos. 4768 and 4769, a control traverse embracing all of the above surveys was made. Angular error was 0°00'02". Closure was in the proportion of 1:189,000. Two secondary traverses were made to tie in some points on this survey. Their accuracy was in the proportion of 1:7500 and 1:8000. Due to the steepness of the terrain, and heavy cover of brush and trees throughout most of the area, most corners were surveyed in by radiation from the control points. Some short traverses were used, and tied back into control by closing angles. Angular values, horizontal and vertical, are the mean of direct and inverse observation from the distant signal. Final corners, wherever possible, were checked by measurement of angles between control points from the final point as set. The concurrency of this survey and Survey Nos. 4768 and 4769, and the fact that all these surveys are based on the beforementioned control traverse, the bearing of the line common to secs. 17 and 18 was determined as follows:

June 4, 1974, at the Witness Corner of Sections 17, 18, 19 and 20, T. 11 S., R. 16 E., Gila and Salt River Meridian, located 2 chains northerly from the true point, according to the official record thereof, in latitude 32°28'15" N., longitude 110°44'46" W., (as determined by scaling from U.S.G.S. quadrangle, BELLOTA RANCH, dated 1957) I made two observations of Polaris with the following results:

Observation No. 1

Average 105th Meridian	
time	= 8:38:48 p.m.
G.C.T. (June 5)	= 3:38:48
L.H.A.	= 165°34'42"
Horizontal angle,	
clockwise, from the	
½ sec. cor. of secs.	
17 and 18, to traverse	
point "C"	= 29°43'00"
Horizontal angle,	
clockwise, Polaris	
to point "C"	= 30°14'13"

FEET

Bearing of Polaris
(West of Meridian) = $-0^{\circ}15'00''$
 Bearing, W.C. to
 point "C" = $N. 29^{\circ}59'13'' E.$
 Bearing of sec. line,
 W.C. to $\frac{1}{2}$ sec. cor.
 of secs. 17 and 18 = $N. 0^{\circ}16'13'' W.$

Observation No. 2

Average 105th Meridian
 time = 8:45:34 p.m.
 G.C.T. (June 5) = 3:45:34
 L.H.A. = $164^{\circ}16'24''$
 Horizontal angle,
 clockwise, from the
 $\frac{1}{2}$ sec. cor. of secs.
 17 and 18 to traver-
 se point "C" = $29^{\circ}43'00''$
 Horizontal angle,
 clockwise, Polaris
 to point "C" = $30^{\circ}13'34''$
 Bearing of Polaris
 (West of Meridian) = $-0^{\circ}13'28''$
 Bearing, W.C. to
 point "C" = $N. 30^{\circ}00'06'' E.$
 Bearing of sec. line,
 W.C. to $\frac{1}{2}$ sec. cor.
 of secs. 17 and 18 = $N. 0^{\circ}17'06'' W.$

Used the average of the above data; sec. line,
 Witness Cor. to $\frac{1}{2}$ sec. cor., $N. 0^{\circ}16'40'' W.$, as
 a basis of bearing for this survey.

The geographic position of Cor. No. 1 of the
 Turkey lode was computed (from its tie to the
 Witness Cor. of secs. 17, 18, 19 and 20), to be
 Latitude $32^{\circ}28'40'' N.$, Longitude $110^{\circ}44'14'' W.$

The lines were measured with either a Lufkin
 steel tape or with the aforementioned electronic
 distance meter. The tape was 200 feet in length,
 graduated every foot for 200 ft., with an added
 foot on the zero end graduated in tenths and
 hundredths; the tape was compared with a 100.00
 foot standard tape at the time of beginning the
 survey, and found to be correct. Distances were
 read twice with E.D.M. equipment. Chained dis-
 tances were also measured twice.

The average magnetic declination was determined
 to be $13^{\circ}30' E.$

 Mineral Survey No. 4770

TURKEY LODGE

At Cor. No. 1 of the Turkey lode of this survey.

FEET		
	<p>Set a 5/8 in. diam. steel pin, 30 ins. long, with aluminum cap, projecting 20 ins., in a mound of stones, mkd. M.S. 4770-TURKEY-1; from which</p> <p>The Witness Cor. of secs. 17, 18, 19 and 20, T. 11 S., R. 16 E., Gila and Salt River Meridian, bears S. 48°09'38" W., 3726.36 ft. dist.; monumented with an iron post, 2 ins. diam., 12 ins. above ground, firmly set, with a brass cap properly mkd.</p> <p>The 1/4 sec. cor. of secs. 17 and 18, T. 11 S., R. 16 E., Gila and Salt River Meridian, bears N. 89°10'09" W., 2788.73 ft. dist.; monumented with an iron post, 1 in. diam., 10 ins. above ground, firmly set, with a brass cap properly mkd.</p> <p>Cor. No. 4, M.S. No. 3017 EAGLE No. 2 lode, bears S. 59°57'56" W., 156.35 ft. dist.</p> <p>Cor. No. 2, M.S. No. 3054 Grand Central lode, identical with Cor. Nos. 4 and 5, M.S. No. 2871, ROOSEVELT and HIDDEN TREASURE lodes, respectively, bears S. 79°53'42" W., 507.24 ft. dist.</p> <p>Cor. No. 4, M.S. No. 3504 Oversight lode, on line 1-2 Grand Central lode, bears S. 63°16'17" W., 356.5 ft. dist.</p> <p>A cor. of the location bears S. 87°21'05" E., 47.9 ft. dist.</p> <p style="text-align: center;">Thence S. 8°56'23" W.</p>	
144.51	Intersect line 4-1, M.S. No. 3017 EAGLE No. 2 lode, at a point from which Cor. No. 4 bears N. 60°15'41" W., 130.02 ft. dist.	
272.48	Intersect the common lines, 1-2 M.S. No. 3054 Grand Central lode, and 4-5 M.S. No. 3504 Oversight lode, at a point from which Cor. No. 4, Oversight lode, bears N. 68°29'05" W., 296.74 ft. dist. and Cor. No. 2, Grand Central lode, identical with Cor. Nos. 4 and 5, M.S. No. 2871 ROOSEVELT and HIDDEN TREASURE lodes, respectively, bears N. 68°29'05" W., 491.26 ft. dist.	
287.29	Lode line; discovery point bears N. 87°04'24" W., 450.0 ft. dist.	
	A cor. of the location bears S. 87°04'37" E., 30.0 ft. dist.	
535.	Center of road, 15 ft. wide, bears N. 53° E. and S. 53° W.	

(This form bound on left side)

FEET		
567.26	<p>Cor. No. 2.</p> <p>Set a 5/8 in. diam. steel pin, 30 ins. long, with aluminum cap, projecting 18 ins. in a mound of stones, mkd. M.S. 4770-TURKEY-2; from which</p> <p>Point for Cor. No. 3, M.S. No. 3017 EAGLE No. 2 lode, on line 2-3, M.S. No. 3504 Oversight lode, bears N. 71°43'19" W., 588.51 ft. dist.</p> <p>Cor. No. 4, M.S. No. 3499 DAILY NO 3 lode, on line 4-5, M.S. No. 2871 HIDDEN TREASURE lode, bears N. 63°07'13" W., 554.18 ft. dist.</p> <p>The calculated point for Cor. No. 5, M.S. No. 3499 DAILY NO 3 lode, identical with Cor. No. 3, M.S. No. 3499 DAILY NO. 5 lode, bears S. 72°21'37" W., 73.58 ft. dist.</p> <p>Cor. No. 3, M.S. No. 3504 Oversight lode, bears N. 71°17'11" W., 612.59 ft. dist.</p> <p>Cor. No. 3, H T FRACTION lode, uns., bears N. 75°44'57" W., 526.94 ft. dist.</p> <p>A cor. of the location bears S. 40° 21'51" E., 92.9 ft. dist.</p> <p>Thence N. 87°22'07" W.</p>	
35.	Center of road, 20 ft. wide, bears N. 51° E. and S. 51° W.	
112.96	Intersect line 4-5, M.S. No. 3499 DAILY NO 3 lode, at a point from which Cor. No. 4, on line 4-5 M.S. No. 2871 HIDDEN TREASURE lode, bears N. 57°14'58" W., 453.56 ft. dist.	
249.81	Intersect the common lines, 2-3 M.S. No. 3017 EAGLE No. 2 lode and 2-3 M.S. No. 3504 Oversight lode, at a point from which the point for Cor. No. 3, EAGLE No. 2 lode, bears N. 60°45'49" W., 354.42 ft. dist. and Cor. No. 3, Oversight lode, bears N. 60°45'49" W., 378.92 ft. dist.	
557.74	Intersect line 3-4, H T FRACTION lode, uns., at a point from which Cor. No. 3 bears N. 24°02'29" E., 113.98 ft. dist.	

FEET	
579.20	Intersect the common lines, 3-4 M.S. No. 3499 DAILY NO 3 lode and 4-5 M.S. No. 2871 HIDDEN TREASURE lode, at a point from which Cor. No. 4, DAILY NO 3 lode, bears N. 20°37'20" E., 239.3 ft. dist. and Cor. No. 5, HIDDEN TREASURE lode, identical with Cor. No. 4, M.S. No. 2871 ROOSEVELT lode and Cor. No. 2, M.S. No. 3054 Grand Central lode, bears N. 20°37'20" E., 475.2 ft. dist.
613.	Center of road, 15 ft. wide, bears N. 13° E. and S. 13° W.
895.	Center of road, 15 ft. wide, bears N. 40° E. and S. 40° W.
1185.	Center of road, 40 ft. wide, bears N. 40° E. and S. 33° W.
1231.73	Intersect line 3-4, M.S. No. 2871 HIDDEN TREASURE lode, at a point from which Cor. No. 3, bears N. 75°06'58" W., 99.86 ft. dist.
1235.	Center of wash, 20 ft. wide, course N. 18° W., center of road, 20 ft. wide, bears N. 25° W. and S. 25° E.
1278.78	<p>Cor. No. 3.</p> <p>Set a 5/8 in. diam. steel pin, 30 ins. long, with aluminum cap, projecting 20 ins. in a mound of stone, mkd. M.S. 4770-TURKEY-3; from which</p> <p>Cor. No. 3, M.S. No. 2871 HIDDEN TREASURE lode, bears N. 64°37' W., 54.79 ft. dist.</p> <p>Cor. No. 3, M.S. No. 3499 DAILY EXTENSION lode, bears N. 87°22'21" W., 80.07 ft. dist.</p> <p>Thence N. 8°56'23" E.</p>
10.04	Intersect line 3-4, M.S. No. 2871 HIDDEN TREASURE lode, at a point from which Cor. No. 3 bears N. 75°06'58" W., 52.84 ft. dist.
120.	Center of road, 15 ft. wide, bears N. 17° W. and S. 13° E.
262.97	Intersect line 2-3, H T FRACTION lode, uns., at a point from which Cor. No. 3, bears S. 75°25'19" E., 749.99 ft. dist.
286.59	<p>Lode line; discovery point bears S. 87°04'24" E., 828.07 ft. dist.</p> <p>A cor. of the location bears N. 87° 04'26" W., 80.01 ft. dist.</p>

(This form bound on left side)

FEET	
552.07	Intersect the common lines, 6-1 and 2-3 M.S. No. 2871 HIDDEN TREASURE and ROOSEVELT lodes, respectively, at a point from which the point for Cor. No. 6, HIDDEN TREASURE lode, identical with Cor. No. 3, ROOSEVELT lode, bears N. 79°01'14" E., 83.75 ft. dist.
567.25	Cor. No. 4. Set a 5/8 in. diam. steel pin, 30 ins. long, with aluminum cap, projecting 20 ins. in a mound of stones, mkd. M.S. 4770-TURKEY-4; from which Point for Cor. No. 6, M.S. No. 2871 HIDDEN TREASURE lode, identical with Cor. No. 3, M.S. No. 2871 ROOSEVELT lode, bears N. 89°18'43" E., 79.86 ft. dist. Thence S. 87°22'07" E.
60.63	Intersect the common lines, 6-1 and 2-3 M.S. No. 2871 HIDDEN TREASURE and ROOSEVELT lodes, respectively, at a point from which the point for Cor. No. 6, HIDDEN TREASURE lode, identical with Cor. No. 3, ROOSEVELT lode, bears N. 79°01'14" E., 19.65 ft. dist.
107.70	Intersect the common lines, 5-6 and 3-4 M.S. No. 2871 HIDDEN TREASURE and ROOSEVELT lodes, respectively, at a point from which Cor. No. 5, M.S. No. 2871 HIDDEN TREASURE lode, identical with Cor. No. 4, M.S. No. 2871 ROOSEVELT lode, and Cor. No. 2, M.S. No. 3054 Grand Central lode, bears S. 77°58'46" E., 685.51 ft. dist.
175.	Center of wash, 20 ft. wide, course N. 20° E.
185.	Center of road, 15 ft. wide, bears N. 20° E. and S. 20° W.
816.20	Intersect line 2-3, M.S. No. 3054 Grand Central lode, at a point from which Cor. No. 2, identical with Cor. No. 5, M.S. No. 2871 HIDDEN TREASURE lode, and Cor. No. 4, M.S. No. 2871 ROOSEVELT lode, bears S. 18°41'03" W., 116.37 ft. dist.
818.44	Intersect line 4-5, M.S. No. 2871 ROOSEVELT lode, at a point from which Cor. No. 4, identical with Cor. No. 5, M.S. No. 2871 HIDDEN TREASURE lode, and Cor. No. 2, M.S. No. 3054 Grand Central lode, bears S. 19°44'18" W., 117.01 ft. dist.
918.	Center of road, 15 ft. wide, bears N. 45° W. and S. 45° E.
1045.	Center of road, 15 ft. wide, bears N. 37° E. and S. 37° W.
1278.78	Cor. No. 1, and place of beginning.
Mineral Survey No. 4770	

FEET	AREAS	Acres
	Total area, Turkey lode -----	16.552
	Area in conflict with --	
	M.S. No. 2871 HIDDEN TREASURE lode --	8.906
	M.S. No. 2871 ROOSEVELT lode -----	0.923
	M.S. No. 3017 EAGLE No. 2 lode -----	4.037
	M.S. No. 3017 EAGLE No. 2 lode, exclusive of its conflict with:	
	(1) M.S. No. 2871 HIDDEN TREASURE lode -----	4.015
	(2) M.S. No. 3054 Grand Central lode -----	3.414
	(3) M.S. Nos. 2871 and 3054 HIDDEN TREASURE and Grand Central lodes -----	3.392
	M.S. No. 3054 Grand Central lode ----	2.093
	M.S. No. 3054 Grand Central lode, exclusive of its conflict with M.S. No. 2871 ROOSEVELT lode -----	2.090
	M.S. No. 3499 DAILY NO 3 lode -----	1.218
	M.S. No. 3504 Oversight lode -----	3.611
	M.S. No. 3504 Oversight lode, exclusive of its conflict with:	
	(1) M.S. No. 2871 HIDDEN TREASURE lode -----	3.551
	(2) M.S. No. 3017 EAGLE No. 2 lode -----	0.149
	(3) M.S. No. 3499 DAILY NO 3 lode -----	2.929
	(4) M.S. Nos. 2871 and 3499 HIDDEN TREASURE and DAILY NO 3 lodes -----	2.869
	(5) M.S. Nos. 2871, 3017, 3499, HIDDEN TREASURE, EAGLE No. 2 and DAILY NO 3 lodes, respectively -----	0.147
	H T FRACTION lode, uns. -----	3.131
	H T FRACTION lode, uns., exclusive of its conflict with:	
	(1) M.S. No. 2871 HIDDEN TREASURE lode -----	0.068
	(2) M.S. No. 3499 DAILY NO 3 lode -----	3.068
	(3) M.S. No. 2871 and 3499 HIDDEN TREASURE and DAILY NO 3 lodes -----	0.005
	LOCATION	
	<p>This survey is located in sec. 17, T. 11 S., R. 16 E., Gila and Salt River Meridian. The sur- vey of the TURKEY lode is wholly within the loca- tion as marked on the ground; Cor. Nos. 3 and 4 are identical with corners of the location; Cor. Nos. 1 and 2 differ to the extent previously shown. Loc. mons. are mounds of stone with posts therein.</p>	

FEET	
	EXPENDITURES
	The improvements and the value of the labor and improvements made upon or for the benefit of the lode location embraced in said mining claim by the claimant or its grantor are as follows:
No. 1	The discovery point of the Turkey lode is on the lode line 450 ft. from a point on line 1-2, 287.29 ft. from Cor. No. 1. Value, none.
No. 2	A diamond drill hole, designated No. 30 by claimant, center of which bears S. 71°57'39" W., 467.83 ft. dist. from Cor. No. 1; 4 in. diam., 947 ft. deep; value of 947 ft. at \$6.63 per ft. Value, \$6,278.61.
	OTHER IMPROVEMENTS
	Primitive drilling access roads as indicated on the map of this survey. Claimant herein.
	OTHER CORNER DESCRIPTIONS AND SUPPLEMENTAL DATA
	M.S. No. 2871 HIDDEN TREASURE lode: Cor. No. 1, identical with Cor. Nos. 2, 3 and 4, M.S. No. 2871 ROOSEVELT, WAY-UP and IMPERIAL lodes, respectively, is monumented with a 5/8 in. diam. steel pin in a mound of stone, no markings or bearing objects; Cor. No. 2, identical with Cor. No. 3, M.S. No. 2871 IMPERIAL lode, Cor. No. 1, Daily Extension No. 2 lode, uns. and Cor. No. 1, H T FRACTION lode, uns., is monumented with a 5/8 in. diam. steel pin in a mound of stone, firmly set, and properly mkd.; Cor. No. 3 is monumented with a stone, firmly set and properly mkd.; Cor. No. 4, identical with Cor. Nos. 2 and 3, M.S. No. 3499 DAILY EXTENSION and DAILY NO 3 lodes, respectively, was destroyed by road construction. I reestablished the cor. by "broken boundary" adjustment of a traverse from Cor. No. 3, M.S. No. 3504 Oversight lode to Cor. No. 3. Set a 5/8 in. diam. steel pin, with aluminum cap, mkd. HT-4-2871-DE-2-D3-3-3499; Cor. No. 5, identical with Cor. No. 4, M.S. No. 2871 ROOSEVELT lode and Cor. No. 2, M.S. No. 3054 Grand Central lode. Set a 5/8 in. diam. steel pin in the center of a stone mound for cor. point. A stone outcrop bears N. 10° E., 10 ft. dist., mkd. RX2-3054 and a loose stone bears S. 70° E., 26 ft. dist., mkd. BOX3054; Cor. No. 6, identical with Cor. No. 3, M.S. No. 2871 ROOSEVELT lode could not be found. Its position (not monumented), was calculated by "broken boundary" adjustment of a traverse from Cor. No. 5 to Cor. No. 1. Line 2-3 was found to be N. 77°39'04" E., 751.69 ft., instead of N. 76°53'40" E., 755.17 ft., as approved in M.S. No. 3499; line 3-4 was found to be S. 75°06'58" E., 723.6 ft., instead of S. 75°44' E., 725.73 ft., as approved in M.S. No. 3499; line 4-5 was found to be N. 20°37'20" E.,

FEET	
	<p>614.39 ft., instead of N. 20°00' E., 612.16 ft., as approved in M.S. No. 3504; line 5-6 was calculated to be N. 77°58'46" W., 713.86 ft., instead of N. 78°00' W., 750.0 ft., as approved; line 6-1 was calculated to be S. 79°01'14" W., 713.86 ft., instead of S. 79°00' W., 750.0 ft., as approved.</p> <p>M.S. No. 2871 ROOSEVELT lode: Cor. Nos. 2, 3 and 4 described above; Cor. No. 5 is monumented with a 3/4 in. diam. iron pipe, in a mound of stones, no markings or bearing objects. Lines 2-3 and 3-4 described above; line 4-5 was found to be N. 19°44'18" E., 590.17 ft., instead of N. 19°38' E., 576.5 ft., as approved in M.S. No. 3054.</p> <p>M.S. No. 3017 EAGLE No. 2 lode: Cor. No. 1, identical with Cor. Nos. 1, 2 and 3, M.S. No. 3017 EAGLE, COPPER PEAK and GOLDEN PEAK No. 2 lodes, respectively, and Cor. No. 1, M.S. No. 3504 Oversight lode, was destroyed in mining operations; Cor. No. 2, identical with Cor. No. 2, M.S. No. 3017 GOLDEN PEAK No. 2 lode and Cor. No. 2, M.S. No. 3504 Oversight lode, on line 3-4, M.S. No. 3499 SPHINX lode, is monumented with an oak post, in a mound of stone, mkd. 2E2-3017-2 3504OS; Cor. No. 3, on line 2-3, M.S. No. 3504 Oversight lode was destroyed by road construction. Its position (not monumented) was established at record distance from Cor. No. 3 and on line 2-3, M.S. No. 3504 Oversight lode; Cor. No. 4 is monumented with a pine post, in a mound of stone, mkd. 3017 E-4. Line 2-3 was found to be N. 60°45'49" W., 1474.87 ft., instead of N. 61°31' W., 1473.0 ft., as approved in M.S. No. 3504; line 3-4 was found to be N. 59°49'12" E., 591.84 ft., instead of N. 59°16' E., 591.01 ft., as approved in M.S. No. 3504. That portion of line 4-1 from Cor. No. 4 to Cor. No. 6, M.S. No. 3504 Oversight lode, (established on lines 1-2 and 4-1, M.S. No. 3017 EAGLE and EAGLE No. 2 lodes, respectively, and on line 4-1, M.S. No. 3054 Grand Central lode, monumented with an old pine post lying in a mound of stone) was found to be S. 60°15'41" E., 904.18 ft., instead of S. 61°06' E., 907.3 ft., as approved in M.S. No. 3504.</p> <p>M.S. No. 3054 Grand Central lode: Cor. No. 1, identical with Cor. No. 5, M.S. No. 3504 Oversight lode, is monumented with an old pine post, lying in a mound of stone. Scribing on rock outcrop bears N. 19°10' E., mkd. BO 13054 OS 3504; Cor. No. 2 described above; Cor. No. 3 is a mound of stone, no markings or bearing objects. Line 1-2 was found to be N. 68°29'05" W., 1230.1 ft., instead of N. 69°08' W., 1227.4 ft., as approved. The intersection of line 1-2 with line 3-4, M.S. No. 3017 EAGLE No. 2 lode, is at a point S. 68°29'05" E., 221.37 ft., from Cor. No. 2, instead of S. 69°08' E., 221.5 ft.,</p>

(This form bound on left side)

FEET

as approved in M.S. No. 3504 and at a point from which Cor. No. 4, M.S. No. 3017 EAGLE No. 2 lode, bears N. $59^{\circ}49'12''$ E., 182.86 ft., instead of N. $59^{\circ}16'$ E., 182.57 ft., as approved in M.S. No. 3504; line 2-3 was found to be N. $18^{\circ}41'03''$ E., 566.09 ft., instead of N. $19^{\circ}10'$ E., 573.9 ft., as approved.

M.S. No. 3499 DAILY EXTENSION lode: Cor. No. 1, identical with Cor. No. 2, M.S. No. 3499 CAVE lode and on line 2-3, M.S. No. 3499 DAILY NO 3 lode, was destroyed by road construction; Cor. No. 2 described above; Cor. No. 3 is a loose stone in a stone mound, top broken, visible markings X4.3499. Set a 40d nail. Cor. No. 4 is monumented with a stone, firmly set and properly mkd. Line 1-2 is shown as approved; line 2-3 was found to be N. $77^{\circ}10'55''$ W., 748.45 ft., instead of N. $78^{\circ}00'$ W., 750.0 ft., as approved; line 3-4 was found to be S. $79^{\circ}32'38''$ W., 725.0 ft., instead of S. $79^{\circ}00'$ W., 728.0 ft., as approved. From Cor. No. 3 to Cor. No. 3, M.S. No. 2871 HIDDEN TREASURE lode bears N. $56^{\circ}58'12''$ E., 36.4 ft., instead of N. $52^{\circ}52'$ E., 37.95 ft., as approved.

M.S. No. 3499 DAILY NO 3 lode: Cor. No. 1, identical with Cor. No. 2, M.S. No. 3499, DAILY NO. 5 lode and on line 1-2, M.S. No. 3499 CALUMET lode could not be found; Cor. No. 2, identical with Cor. Nos. 1, 2 and 2, M.S. No. 3499 CAVE, WEDGE NO 3 and CALUMET lodes, respectively, could not be found; Cor. No. 3 described above; Cor. No. 4 has been destroyed and was established at record distance on line 4-5, M.S. No. 2871 HIDDEN TREASURE lode, from the intersection of line 3-4 DAILY NO 3 lode with line 3-4, M.S. No. 3504 Oversight lode. Set a 5/8 in. diam. steel pin with aluminum cap, mkd. 3499 D3-4; Cor. No. 5, identical with Cor. No. 3, M.S. No. 3499 DAILY NO. 5 lode was apparently destroyed by road construction. The point for the cor. was determined by single proportionate measurement between reestablished Cor. No. 4 and Cor. No. 2, M.S. No. 3017 EAGLE NO. 2 lode, identical with Cor. No. 2, M.S. No. 3504 Oversight lode. Lines 2-3 and 5-1 are shown as approved; line 3-4 was found to be N. $20^{\circ}37'20''$ E., 378.49 ft., instead of N. $20^{\circ}00'$ E., 378.75 ft., as approved; line 4-5 was found to be S. $57^{\circ}14'58''$ E., 504.36 ft., instead of S. $58^{\circ}01'$ E., 503.65 ft., as approved.

M.S. No. 3499 DAILY NO. 5 lode: Cor. Nos. 2 and 3 described above; Cor. No. 4, identical with Cor. No. 3, M.S. No. 3499 SPHINX lode could not be found. Line 2-3 is shown as approved; line 3-4 was determined by single proportionate measurement and found to be S. $57^{\circ}14'58''$ E., 640.90 ft., instead of S. $58^{\circ}01'$ E., 640.0 ft., as approved.

FEET

M.S. No. 3504 Oversight lode: Cor. Nos. 1, 2, 5 and 6 described above; Cor. No. 3 is monumented with a stone, firmly set, and properly mkd., and with a stone mound 2 ft. West; Cor. No. 4 has been destroyed and was established at record distance on line 1-2, M.S. No. 3054 Grand Central lode, from the intersection of line 1-2, M.S. No. 3054 Grand Central lode with line 3-4, M.S. No. 3017 EAGLE No. 2 lode. Set a 5/8 in. diam. steel pin, with aluminum cap, mkd. 3504 OS-4. Line 2-3 was found to be N. 60°45'49" W., 1499.37 ft., instead of N. 61°31' W., 1497.5 ft., as approved; line 3-4 was found to be N. 59°49' 24" E., 404.8 ft., instead of N. 59°16' E., 404.29 ft., as approved; line 4-5 was found to be S. 68°29'05" E., 1035.57 ft., instead of S. 69°08' E., 1032.75 ft., as approved; line 5-6 is correct as approved.

Note concerning the following unsurveyed lode location: H T FRACTION. Although this unsurveyed claim is senior in location to this survey, it has been discussed and shown on the plat with their corners referred to by corner number. The reason for this is that the H T FRACTION is presently being surveyed by me under order for Mineral Survey No. 4769. Since corner numbers have already been assigned, I have elected to refer to such corners by corner numbers rather than by general location. Due to the fact that this survey has not been approved, I have herein referred to said lode as unsurveyed. At the time of this survey, conditions were as follows:

H T FRACTION lode, uns.: All corners are in place. Line 2-3 bears S. 75°25'19" E., 1349.52 ft., line 3-4 bears S. 24°02'29" W., 503.50 ft.

The line bet. secs. 17 and 18, T. 11 S., R. 16 E., from the W.C. of secs. 17, 18, 19 and 20, to the 1/4 sec. cor. of secs. 17 and 18, was found to be N. 0°16'40" W., 2526.12 ft., instead of N. 0°03' W., 2508.0 ft., as described in the official record.

FIELD ASSISTANTS

Name	Capacity
<u>Joseph Domler</u>	<u>Instrumentman</u>
<u>Lee Jones</u>	<u>Chainman</u>

FEET		

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

CERTIFICATE OF SURVEYOR

Name of Mineral Surveyor Robert L. Frazer	Date July 31, 1974
---	------------------------------

I HEREBY CERTIFY That in pursuance of an order received from the Bureau of Land Management, at Phoenix, Arizona, dated November 15, 1973, I have carefully executed the survey of the claim of Continental Copper, Inc. known as the (lode, placer, or mill-site) Turkey situated in Section 17 Township 11S., Range 16 E., Gila and Salt River Meridian, in the State of Arizona

This survey, designated as number 4770, has been executed by me and under my direction and has been made in strict conformity with said order, the Manual of Instructions for the Survey of Public Lands of the United States, and in the specific manner described in the foregoing field notes.

I FURTHER CERTIFY That the labor expended and improvements made upon and for the benefit of the (lode or placer) location(s) embraced in the said mining claim by claimant(s) or grantors are fully stated in my report. The character, extent, location, and itemized value are specified in full detail. No portion of, or interest in, said labor and improvements so credited to this claim has been included in the estimate of expenditures upon any other claim.

P.O. Box 1711, Tucson, AZ 85702

(Location)

(Signature of Mineral Surveyor)

CERTIFICATE OF APPROVAL

Office Arizona State Office
Location Phoenix, Arizona
Date September 8, 1975

The foregoing field notes of mineral survey number 4770, in Section 17 Township 11 S., Range 16 E., Gila and Salt River Meridian, surveyed unsurveyed Meridian, in the State of Arizona, executed by Robert L. Frazer, Mineral Surveyor, under order dated November 15, 1973, having been critically examined and the necessary corrections made prior to their certification by the surveyor, the field notes and the survey therein described are hereby approved.

ACTING STATE DIRECTOR State Director
(Title)

CERTIFICATE OF TRANSCRIPT

I CERTIFY That the foregoing transcript of field notes of the above described mineral survey number is a true copy of the original field notes.

(Authorized Signature)

(Title)

Title 18, U. S. C. section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious, or fraudulent statements or representations as to any matter within its jurisdiction.

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
CERTIFICATE OF SURVEY

Section 16
T. 12 N., R. 10 E., S. 10 E.

Name of landowner: Robert H. Praxer
Date: July 31, 1974

Surveyed by: [Name] of [Firm]
Location: [Address]
Reference to the [Map]

The survey described in this certificate was made in accordance with the provisions of the laws of the State of Arizona, and the rules and regulations of the Bureau of Land Management, and the survey is hereby certified to be correct and true.

Robert H. Praxer
[Signature]

P.O. Box 1111, Tucson, AZ 85702

CERTIFICATE OF APPROVAL

Date: [Date]
By: [Signature]
Title: [Title]

The survey described in this certificate was made in accordance with the provisions of the laws of the State of Arizona, and the rules and regulations of the Bureau of Land Management, and the survey is hereby certified to be correct and true.

[Signature]
[Signature]

CERTIFICATE OF SURVEY

The survey described in this certificate was made in accordance with the provisions of the laws of the State of Arizona, and the rules and regulations of the Bureau of Land Management, and the survey is hereby certified to be correct and true.

[Faint text at the bottom of the page, possibly a footer or additional notes.]