## B. M. Barreller 1951 Bible Norbs ge trekoukyst of the 1951 Soldierson Lines of 14 Sally, Range S W. Level **Crass** B**ase and M**orridian, ARTEONA, 1951 Wateria. U. S. Deputy Surveyer. Lil 29-1869, 14

## **BOOK 1951**

SURVEYS IN NAVAJO INDIAN RESERVATION.
FIELDNOTES
of the
Subdivision Lines of Townships 13 and 14 North,
RANGE 5 WEST,
Of the Navajo Special Meridian, in the Territory of New Mexico, surveyed under the direction of Hon. Jos. S. Wilson, Commissioner of the General Land Office,,
By Ehud N. Darling, U. S. Surveyor, under his Contract, bearing date, Washington D. C., April 29th, 1869, and subsequent Special Instructions.  ***********************************
Commenced Jan.14th, and Completed January 25th,

500K 1951.

## NAMES OF ASSISTANTS.

William Clark,
William Burgess.

Pablo Torres,
Phillippe Delgado

Chainmen.
Chainmen.
Cornermen.

Measuring Chain compared with Standard as per Manual instructions.

## I N D E X.

Subdivision of Twp. 14 N., Subdivision of Township 13 N. Range 5 W. of the Navajo Range 5 W. of the Navajo Special Special Meridian. 6 33 5 3 2 61 15-1 2 10 8 . 12 32 8 26 9 23 10 19 11 15-12 16 13 18 31 17 26 16 22 15 18 14 14 21 22 24 19 30 20 25 21 22 22 17 23 13 24 3 ·30 — 26j25 30 29 29 24 28 21 27 17 26 12 25 33 35 36 31 24 32 24 33 20 34 16 35 12 36

rownsnip is morth kange o west of the Mavajo Special Meridian Commenced Jan 24th, and completed January 25th, 1870. BOUK 1951

Chains. FIELD NOTES OF THE

SUBDIVISION LINES OF FRACTIONAL TOWNSHIP 13 NORTH, RANGE 5 WEST OF THE NAVAJO SPECIAL MERIDIAN.

The southern portion of the Township being in a mountainous country and almost entirely worthless, I commenced at the corner to secs. 25. 30. 31 and 36 and

Ran West on true line between secs. 25 and 36.

Var. 14° 10' E.

Set granite 14x10x8 for 2 sec. corner as per 40.00 instructions.

Set sandstone 24x12x3 marked as per instructions 80.00 for the corner to sees. 25, 26, 35 and 36. Surface rolling. Prairie. Soil 2nd rate.

> North between secs. 25 and 26. Var. 14° 10' E.

Set sandstone 15x12x3 for  $\frac{1}{2}$  sec. cor. as per instructions.

Set sandstone 20x7x5 marked as per instructions 80.00 for the corner to secs. 23, 24, 25 and 26. Surface rolling. Prairie. Soil 2ndrate.

> East on random between secs. 24 and 25. Ver. 14° 10' E.

40.00 Set temporary & sec. corner.

47.10 Dry creek, course S. E.

40.00

Intersect Range line 12 1ks. North of corner 79.85 to secs. 19, 24, 25 and 30.

Then N. 89° 55' W. on true line.

53	1951	Field Motes of the Subdivision Lines of Township	
BOOK	~	13 North, Renge 5 West of the Navajo Special Meri	dian.
	Chains		4
	40.00	Set temporary is sec. corner.	
	80.20	Intersect Range line 18 lks. south of corner	<b>~</b> ~
		to secs. 1, 6, 7 and 12.	
		Then S. 89° 52' W. on true line.	
		Var. 14° 10' E.	
	40.10	Set charred post, built mound and dug pits for	
		½ sec. corner as per instructions.	
	80.20		
		Surface rolling. Prairie.	
		Soil 2nd rate.	
		North on random between seas. 1 and 2.	
		Var. 14° 10' E.	
	40.00	Set temporary 2 sec. corner.	
	80.24	Intersect north boundary of Township 27 lks.	
		west of corner to sees. 1, 2, 35 and 36.	
		Then S. 12' W. on true line.	
		Var. 14° 10' E.	
	40.24	Set charred post, built mound and dug pits for	
		½ soc.corner as per instructions,	
	80.24	Gorner to sees. 1, 2, 11 and 12.	
		Surface rolling. Prairie.	
		Soil 2nd rate.	
		boll sile level	
	·		
		From corner to secs. 23, 24, 25 and 26,	
		West on true line between secs. 23 and 26	
		Var. 14° E.	
	37.20	Dry creek, 20 lks. wide, course N. E.	-
	40.00	Set sandstone 15x14x3 for 2 sec. corner as per	

40.00 Set sandstone 15x14x3 for 2 sec. corner as per instructions.

80.00 Set sandstone 16x12x3 marked as per instructions for the cor. to sees. 22, 23, 26 and 27.

Surface rolling. Prairie. Soil 2nd rate.

Field Notes of the Subdivision Lines of Township 59

	13 North, Range b west of the Mavajo beeter merical
Chains	North between secs. 22 and 23. BOOK
	Var. 14° Mast.
40.00	Set sandstone 14x12x3 for ½ sec. corner as per
±0.00	instructions.
61.30	Dry bed of creek 20 lks wide, course E.
80.00	Deposited marked stone set charred post, mark-
00.00	ed, built mound and dug pits as per instructions,
	for the corner to sees. 14, 15, 22 and 23.
	Surface broken. Prairie.
	Soil 2nd rate.
	DOTE BALL TOO
	East on mandom between secs. 14 and 23.
	Var. 14° East.
40.00	Set temporary 2 sec. corner.
43.00	Dry bed of creek, 20 lks. wide, course N.E.
80.20	
	secs. 13, 14, 23 and 24.
	Then N. 89° 55' West on true line.
	Var. 14° Hast.
40.10	Set sandstone 15x14x4 for \$\frac{1}{2}\$ sec. corner as per
	instructions.
80.20	
	Surface rolling. Prairie.
	Soil and rate.
	North between secs. 14 and 15.
	Var. 14° East.
40.00	Set sandstone 14x12x3 for \$\frac{1}{2}\$ sec. corner as per
	instructions.
20.00	Set granite 14x9x6 marked as per instructions
	for the corner to sees. 10 , 11, 14 and 15.
	Surface rolling. Prairie.
	Soil 2nd rate.

<i>(</i>	55 1951	Field Notes of the Subdivision Lines of Frac!l North, Range 5 West of the Navajo Special Meridi	
<del>,</del> 0	Chains.		lan.
		East on random between secs. 11 and 14.	
	40.00	Var. 14° Fast.	
	ļ	Set temporary & sec. corner.	
	80.25		
		secs. 11, 12, 13 and 14.	
		Then N. 89° 51' W. on true line.	
		Ver. 14° East.	
	40.1.2½	Set sandstone 26x12x7 for \$\frac{1}{2}\$ sec. corner as per instructions.	
	80.25	Corner to secs. 10 , 11, 14 and 15.	
		Surface rolling. Prairie.	
		Soil 2nd ra te.	
			<u>.</u>
		North between secs.10 and 11.	•
		Var. 14° East.	
	33.70	Ravine, 75 lks. wide, course Bast.	<del></del>
	40.00	Set charred post, built mound and dug pits for	•
		½ sec. corner as per instructions.	
	80.00	Set slate 20x18x2 marked as per instructions	
		for the Corner to secs. 2, 3, 10 and 11.	
		Surface rolling. Prairie.	
		Soil 2nd rate.	
			•
		East on random between secs. 2 and 11.  Var. 14° East.	
	40.00	Set temperary & sec. corner.	
	79.90	Intersect sec. line 7 lks. south of corner to	
		secs. 1, 2, 11 and 12.	
		Then S. 89° 57' W. on true line.	-
		Var. 14° East.	• 3
	39.95	Set sandstone 14x12x4 for & sec. corner as per	
		instructions.	
	79.90	Corner to secs. 2, 3, 10 and 11.	
	1	· ·	

Field Notes of the Subdivision Lines of Fracl Township 13 North. Range 5 West of the Navaho Special Meridian.

	Unains.	13 NOTTH, Range 5 West of the Wavano booths and		
	l l	Surface rolling. Prairie.	BOOK	1951
*		Soil 2nd rate.	l	
·				
	1.	North on random between secs. 2 and 3.		
		Var. 14° East.		
	40.00	Set temporary ½ sec. corner.		
	1	Intersect Township line 17 lks. west of the		
		corner to secs.2, 3, 34 and 35.		
		Then S. 7' W.on true line.		•
	·	Var.14° E.		
	39.85	Set granite 14x10x5 for ½ sec.corner as per		
		instructions.		
	79.85	Corner to secs. 2, 3, 10 and 11.		
•		Surface rolling. Prairie.		
•		Soil 2nd rate.		
		From corner to secs. 14, 15, 22 and 23,		
		West on true line between secs. 15		
		and 22. Va. 14° E.		
	40.00	Set sandstone 16x12x3 for $\frac{1}{2}$ sec. cor as per in-		
	40.00	structions.		
· •	80400	To Ma 1 1 - man instruction	8	
•		for the corner to secs. 15, 16, 21 and 22.		
		Surface rolling. Prairie.		•
	·	Soil 2nd rate.		
		N. 43. 1.4		
		North between secs. 15 and 16.  Var. 14° East.		
	1000	Set granite 12x9x8 for \(\frac{1}{4}\) sec. cor. as per in-		
•	40.00			
š	<b>74</b> 50	Ravine, 65 lks. wide, course N.E.		
•	74.50	Set sandstone 18x13x4 marked as per instruc-		
	80.00	tions for the corner to secs. 9, 10, 15 and 1	.6.	
	\$\frac{1}{2}	CIOUR TOT BUG COLUCT OF BOOK S, TO, TO COLUCT		

10 BOOK 1951

Field Notes of the Subdivision Lines of Fracl Township
13 North, Range 5 West of the Navajo Special Meridian.

	13 North, Range o west of the Mavelo special merities
Chains	Surface rolling. Prairie.
	Soil 2nd mim. rate.
	East on random between secs. 10 and 15.
	Var. 14° East.
7.60	Ravine, 70 lks. wide, course N. E.
40.00	Set temporary \( \frac{1}{4} \) sec. corner.
8 0.25	Intersect sec. line 12 lks. south of corner to
	secs. 10, 11, 14 and 15.
	Then S. 89° 55' West on true line.
	Var. 14° East.
$40.12\frac{1}{2}$	Set sandstone 13x10x6 for \( \frac{1}{4} \) sec. cor. as per
	instructions.
80.25	Corner to secs. 9, 10, 15 and 16.
	Surface broken. Prairie.
	Soil 3rd rate.
	North between near O and 70
	North between secs. 9 and 10.
40.00	Var. 14° East.
40.00	Set sandstone 16x15x3 for \( \frac{1}{4} \) sec. cor. as per
47.00	instructions.
41.20	Ravine 75 lks. wide, course N.E.
80.00	Set sandstone 18x14x5 marked as per instructions,
	for the corner to secs. 3, 4, 9 and 10.
	Surface rolling. Prairie.
	Soil 2nd rate.
	East on random between secs. 3 and 10.
	Var. 14° East.
31.20	Ravine 80 lks. wide, course N. E.
40.00	Set temporary ½ sec. corner.
80.30	Intersect sec. line 24 links south of corner
	to secs. 2, 3, 10 and 11.

5811

1951

Field Notes of the Subdivision of Fracl Township
13 North. Range 5 West of the Navajo Special Meric

		13 North, Range 5 West of the Navajo Special Me	eridian
• (	hains.	Then S. 89° 49' W. on true line.	BOOK
The same		Var. 14° East.	
	10.75	Set sandstone 16x14x5 for \frac{1}{4} sec.corner as per	
	40.15		
		instructions.	
	80.30	Corner to secs. 3, 4, 9 and 10.	
•		Surface rolling. Prairie.	
		Soil 2nd rate.	
,		North on random between secs. 3 and 4.	
	·	Var. 14° East.	
	40.00	Set temporary ½ sec. corner.	
	80,35	Intersect Township line 20 lks.west of the cor	+
•		ner to secs. 3, 4, 33 and 34.	
•		Then S. 9' West on true line.	
E 1997		Var. 14° E.	
	40.35	Set sandstone $14x12x3$ for $\frac{1}{4}$ sec. corner as per	
		instructions.	-
	80.35	Corner to secs. 3, 4, 9 and 10.	
		Surface rolling. Prairie.	
		Soil 2nd rate.	
		COMPAN DECORTONION	
		GENERAL DESCRIPTION	
		of  North Pence 5 west of	·
		Fractional Township 13 North Range 5 west of	
		the Navajo Special Meridian.	a
		The land in this Township is generally 2nd	
	1	rete all prairie.	Į.

The land in this Township is generally 2nd rate, all prairie.

Surface mostly rolling. It is well adapted to either farming or grazing purposes, and gives

evidence of having been well cultivated not many years ago. In sec. 3 there is a Spring

of very fine water.

59		
12	% Fiel	d Notes of the Subdivision Lines of Township
BOOK	]	4 North, Range 5 West of the N. S. Meridian.
<b>V</b>	Chain	8
		Commenced January 14th,, Completed January 19th
		1870.
		North between secs. 35 and 36.
		Var. 15° East.
	40.00	Set granite 18x9x5 for ½ sec. corner as per
		instructions.
	77.00	Dry bed of creek, 20 lks. wide, course N.E.
	80.00	Set sandstone 14x12x3 marked as per instructions
	·	for the corner to secs.25, 26, 35 and 36.
		Surface broken. Prairie.
		Soil 2nd rate.
		East on random between secs. 25 and 36.
		Var. 15° East.
	8.50	Dry bed of creek 20 lks. wide, course N.E.
	40400	
		Intersect Range line 25 links south of corner
,		to secs. 25, 30, 31 and 36.
		Then S. 89° 49' W. on true line.
		Var. 15° East.
	39.93	
		½ sec. cor. as per instructions.
	79.86	
		Surface broken. Prairie.
		Soil 2nd rate.
		North between secs. 25 and 26.
	1	Var. 15° East.

Var. 15° East.

40.00 Set sandstone 16x14x3 for \( \frac{1}{4} \) sec. corner as per instructions.

57.60 Dry bed of creek, course east, 15 links wide.

80.00 Set sandstone 28x20x2 marked as per instructions for cor. to secs. 23, 24, 25 and 26

•

	s. s.	14 Horon, Range o Head or the ha valo brooter merrarent
	Chains.	Surface broken . Prairie. BOOK 1951
		Soil 2nd rate.
		East on random between secs.24 and 25.
		Var.15° Rast.
	40.00	Set temporary ½ sec. corner.
	59.00	Ravine, 75 1ks. wide, course North East.
	79.76	
	13.10	to secs. 19, 24, 25 and 30.
		Then S. 89° 47' W. on true line.
		Var. 15° East.
	39.88	Set sandstone 14x12x3 for \( \frac{1}{2} \) sec. cor, ner, as
	39.00	per instructions.
	79.76	Corner to sections 23, 24, 25 and 26.
	19.10	Surface rolling. Prairie.
	. 1	Soil 2nd rate.
		0
	·	North between secs. 23 and 24.
		Var. 15° East.
	40.00	Set sandstone 15x13x3 for \( \frac{1}{2} \) sec. corner as
		per instructions.
	80400	Set sandstone 18x14x5 marked as per instruc-
		tions for the corner to secs. 13, 14, 23 and 24
		Surface broken. Prairie.
		Soil 2nd rate.
		East on random between secs. 13 and 24.
		Var. 15° East.
•	4.00	Enter bottom, bears N. W. and S. E.
	6.50	Enter cottonwood timber, bears N. W. and S. E.
	17.50	Rio San Juan, course N. W.
	21.50	Leave same. Low banks. Sandy bottom and rapid
		current.
	1	

14 1961 61 04 Chai

Field Notes of the Subdivision Lines of Township 14 North Range 5 West of th Navajo Special Mer.

Chains 40.00	Set temporary ½ sec. corner
80.10	Intersect Range line 20 links North of corner
	to secs. 13, 18, 19 and 24.
	Then N. 89° 51' W. on true line.
	Var. 15° East.
40.05	Set charred post, built mound and dug pits for
	\$\frac{1}{4}\$ sec. corner as per instructions.
80.10	Corner to secs. 13, 14, 23 and 24.
	Surface rolling. Prairie.
	Soil 1st and 2nd rate.
	North between secs. 13 and 14.
	Var. 15° East.
3.20	Enter river bottom, bears east and west.
9.50	Enter cottonwood timber, bears N. W. and S. E.
18.30	"Rio San Juan", course N. W.
29.00	Leave same; low banks; sandy bottom; and rapid
	current.
40.00	Set sandstone 14x12x4 for $\frac{1}{4}$ sec. corner as per
	instructions.
80.00	Set sandstone 18x12x6 marked as per instruc-
	tions for the corner to secs. 11, 12, 13 and 14.
	Surface rolling. Prairie.
	Soil 1st rate.
	East on random between secs. 12 and 13.
	Var. 15° East.
40.00	Set temporary ½ sec. corner.
80.20	Intersect Range line 14 lks. south of corner to
	secs. 7, 12, 13 and 18.
	Then S. 89° 54' W. on true line.
	Var. 15° East.
40.10	Set charred post, built mound and dug pits for

		Field Notes of the Subdivision Lines of Township	1.5
-	ى	14 North Range 5 West of the N. S. M.	e e
•	Chains.	$\frac{1}{4}$ sec. corner as per instructions.	1951
•	80.20	Corner to secs. 11, 12, 13 and 14.	
	00.20	Surface rolling. Prairie.	
		Soil 2nd rate.	
·		BOIT DAIG TUO	
v.		North between secs. 11 and 12.	
		Var. 14° 10' E.	
	40.00	Set sandstone 16x12x4 for \frac{1}{4} sec. corner as per	
	. *	instructions.	
	45.00	"Rio San Juan" course N.N.E.	
	55.00	Leave same; scattering cottonwoodstimber along	
		banks; clear water; rapid current and gravelly	
		bottom.	
	80.00	Set sandstone 17x9x4 marked as per instructions	
		for the corner to secs. 1, 2, 11 and 12.	
		Surface gently rolling. Prairie.	
		Soil 1st rate.	
		East on random between secs. 1 and 12.	
		Var. 15° E.	
	21.00	Rio San Juan, course north.	
	25.00	Leave same; rapid current; about 4 feet deep;	
	2000	clear water and gravelly bottom.	
	40.00	Set temporary ½ sec. corner.	
	l .	Intersect Range line 21 lks. south of corner to	
		secs. 1, 6, 7 and 12.	
		Then S. 89° 51' W. on true line	
	·	Var. 15° East.	
	40.04	Set sandstone 16x10x6 for \frac{1}{4} sec. corner as per	
•		instructions.	
<b>,</b> :	80.08		
		Surface rolling. Prairie.	
		Soil 1st and 2nd rate.	
5			

16 196!

Field Notes of the Subdivision Lines of Township
No. 14 North, Range 5 West of the Navajo Special M.

		o. 14 North, Range 5 West of the Navajo Special M
,	inains.	Nouth as mandam between good 1 and 2
		North on random between secs. 1 and 2.
		Var. 15° East.
	40.00	Set temporry ½ sec. corner.
	80.20	Intersect Township line 20 lks. west of corner
		to secs. 1, 2, 35 and 36.
		Then S. 9' W. on true line.
		Var. 15° E.
	40.20	Set sandstone 14x12x3 for $\frac{1}{4}$ sec. corner as per
		instructions.
	80.20	Corner to secs. 1, 6, 7 and 12.
		Surface rolling. Prairie.
	·	Soil 2nd rate.
	•	North between secs. 34 and 35.
		Var. 15° 05' E.
	40.00	Set sandstone 14x12x4 for \frac{1}{4} sec. corner as per
		instructions.
	80.00	Set granite 12x12x6 marked as per instructions
		for the corner to secs. 26, 27, 34 and 35.
		Surface rolling. Prairie.
		Soil 2nd rate.
		East on random between secs. 26 and 35.
		Var. 15° 05' East.
	40.00	
	40.00	Set temporary & sec. corner.  Intersect sec. line 20 links south of corner to
	79.70	
		secs. 25, 26, 35 and 36.  Then S. 89° 51' W. on true line.
		Var. 15° 05' East.
	39.85	
*	33.00	½ sec. corner as per instructions.
	79.70	
	13.10	Surface rolling. Prairie. Soil 2nd rate.
		Dulland lolling   Ilalilo boll Sha land
	1	•

Field Notes of the Subdivision Lines of Township No.

14 North. Range 5 West of the N.S.M.

BOOK 1951

Chains	North between secs. 26 and 27.
	Var. 15° 05' East.
05.70	Dry bed of creek, 15 lks. wide, course east.
25.10	Set sandstone 15x14x3 for $\frac{1}{4}$ sec. corner as per
40.00	
*	instructions.
80.00	Set sandstone 16x13x3 marked as per instructions
	for the corner to secs. 22, 23, 26 and 27.
	Surface rolling. Prairie.
	Soil 2nd rate.
	East on random between secs. 23 and 26.
	Var. 15° 05' East.
40.00	Set temporary 4 sec. corner.
79.86	Intersect sec. line 16 links south of corner to
	secs. 23, 24, 25 and 26.
	Chen S. 89° 53' E. on true line.
	Var. 15° 05' East.
39.93	Set sandstone 14x13x3 for \frac{1}{4} sec. corner as per
00.00	instructions.
79.86	Corner to secs. 22, 23, 26 and 27.
,0.00	Surface broken. Prairie.
	Soil 2nd rate,
	North between secs. 22 and 23.
	Var. 15° 05' East.
40.00	Set sandstone: $16x14x3$ for $\frac{1}{4}$ sec. corner as per
	instructions.
80.00	Set sandstone 24x16x3 marked as per instruc-
	tions for the corner to sections 14, 15, 22 and
	23.
	Surface broken. Prairie.
	Soil 2nd rate.

Field Notes of the Subdivision Lines of Ewnship No. 14 North, Range 5 West of the N. S. M.

*		14 North, Range o West of the N. S. M.
	Chains.	East on random between secs. 14 and 23.
		Var. 15° 05' East.
	40.00	
	80.16	Intersect section line 10 lks. north of corner
		to secs. 13, 14, 23 and 24.
		Then N. 89° 56' W. on true line.
	40.00	Var. 15° 05' East.
	40.08	Set sandstone 20x18x2 for \( \frac{1}{4} \) sec. corner as per
		instructions.
	80.16	Corner to sections 14, 15, 22 and 23.
	· · · · · · · · · · · · · · · · · · ·	Surface broken. Prairie.
		Soil 2nd rate.
		North between secs. 14 and 15.
	*	Var. 15° 05' East.
	14.50	Dry bed of creek, 20 links wide, course N. E.
	40.00	
		½ sec. corner as per instructions.
	80.00	Set sandstone 18x12x5 marked as per instruc-
		tions for the corner to secs. 10, 11, 14 and 15.
		Surface broken. Prairie.
		Soil 2nd rate.
		boll and lave.
		East on random between secs. 11 and 14.
		Var. 15° 05' East.
	40.00	Set temporary ½ sec. corner.
	54.50	Enter river bottom, bears N. and South.
	59.00	Enter cottonwood timber, bears north and south.
	61.15	Rio San Juan, course North.
	65.50	Leave same; low banks; gravelly bottom, and
		rapid current.
	66.50	Leave cottonwood timber.
	80.10	Intersect sec. line 20 lkg. north of corner to

	·	14 North, Range 5 West of the N.S.M.	66
	Chains	. 11 10 10 and 14	
	·	secs. 11, 12, 13 and 14.  Then N. 89° 51' W. on true line.	1951
		Var. 15° 05' East.	
	40.05		
	40.05	Set sandstone 16x12x5 for \frac{1}{4} sec.corner as per	
	00.70	instructions.	
	80.10	Corner to secs. 10, 11, 14 and 15.	
	,	Surface rolling. Prairie.	
		Soil 2nd rate.	
		<b>\</b>	
		East on random between secs. 11 and 14.	
		Var. 15° 05' East.	
	40.00	Set temporary ½ sec. corner.	
	54.50	Enter Niver bottom, bears N. and south.	•
	59.00	Enter cottonwood timber, bears north and south.	
	61.15	Rio San Juan, course north.	
	65.50	Laave same; law banks; gravelly bottom; and	
		rapid current.	
	66.50	Leave cottonwood timber.	
	80.10	Intersect sec. line 2 links north of corner to	
		secs. 11, 12, 13 and 14	
		Then N. 89° 51' W. on true line.	•
		Var. 15° 65' East.	
•	40.05	Set sandstone 16x12x5 for 2 sed corner as per	
		instructions.	
	80.10	Corner to secs. 10, 11, 14 and 15.	
		Surface rolling. Prairie.	,
		Soil 2nd rate.	
		North between secs. 10 and 11.	
		Var. 15° 05' East.	
	40.00	Set sandstone 14x8x8 for \frac{1}{4} sec.cor. as per in-	
		structions.	
	80.00	Set sandstone 12x10x8 marked as per instruc-	
		tions for the corner to secs. 2, 3, 10 and 11.	
	1	I.	

East on random between secs. 27 and 34.

Var. 15° 05' East.

40.00 Set temporary \(\frac{1}{4}\) sec. corner.

80.24 Intersect sec. line 18 links north of corner to secs. 26, 27, 34 and 35.

Then N. 89° 52' W. on true line.

Var. 15° 05' East.

-21Field Notes of the Subdivision Lines of Township

		read motos or one papartition mines of lownship		
_		14 North. Range 5 West of the N. S. Meridian.		68
	Chains.	B	$o_{OK}$	105.
	40.18	Set sandstone 18x14x3 for \frac{1}{4} sec. corner as per	/	1951
		instructions.		
	80.24	Corner to secs. 27, 28, 33 and 34.	·	
		Surface broken. Prairie.		
		Soil 2nd rate.		
	·			
		North between secs. 27 and 28.		
	•	Var. 15° 15' East.		
	40.00	Set sandstone 12x9x9 for \( \frac{1}{4} \) sec. corner as per		
		instructions.		
	51.60	Dry bed of creek 20 lks. wide, course N.E.		•
	80.00	Set sandstone 14x10x5 marked as per instruc-		
		tions for the corner to secs. 21, 22, 27 and		•
		28.		
		Surface broken. Prairie.		
		Soil 2nd rate.		
		,		
		East on random between secs. 22 and 27.		
		Var. 15° 05' East.		
	30.00	Dry creek, 20 lks. wide, course N.		
	40.00	Set temporary \(\frac{1}{4}\) sec. corner.		
	80.30	Intersect sec. line 25 links north of corner to		
		secs. 22, 23, 26 and 27.		
		Then N. 89° 49' W. on true line.		
		Var. 15° 05' East.		
	40.15	Set sandstone 12x12x7 for \( \frac{1}{4} \) sec. corner as per		
		instructions.	•.	
	80.30	Corner to secs. 21, 22, 27 and 28.		
		Surface broken. Prairie.		
		Soil 2nd rate.		

Surface broken. Prairie.

Soil 2nd rate.

East on random between secs. 10 and 15.

Field	Notes	of the	e Subdiv	ision L:	ines	of	Township
14 No.	eth Ro	ance 5	West of	the N	C M	ami	diam

		<b>-23-</b> *****
		Field Notes of the Subdivision Lines of Township
	I dl I	14 North, Range 5 West of the N. S. Meridian. 70
	Chains	
	40.00	195 <sub>1</sub>
	79,480	
	10,100,	to secs. 10, 11, 14 and 15.
		Then S. 89°53' W. on true line.
		Var. 15° 05' East.
	39.90	
	85.50	instructions.
	79.80	
	10.00	Surface broken. Prairie.
		Soil 2nd rate.
	-	
		North between secs. 9 and 10.
		Var. 15° 05' E.
	40.00	Set sandstone 14x14x4 for \$\frac{1}{4}\$ sec. corner as
		per instructions.
	80.00	•
		tions for the corner to secs. 3, 4, 9 and 10.
		Surface broken. Prairie.
		Soil 2nd rate.
		East on random between secs. 3 and 10.
		Var. 15° 05' East.
	40.00	Set temporary ½ sec. corner.
	79.65	Intersect sec. line 30 lks.south of corner to
		secs. 2, 3, 10 and 11.
	•	Then S. 89° 47' W. on true line.
		Var. 15° 05' East.
	39.82	Set sandstone 16x13x3 for ½ sec. cor. as per
		instructions.
	79.65	Corner to secs. 3, 4, 9 and 10.
		Surface broken. Prairie.
		Soil 3rd rate. Balance of line North not run.
		Rough and mountainous.
i al	Sap 5.7 Sa	

24 100

Field Notes of the Subdivision Lines of Township 14 North, Range 5 West of the Navajo Special Meridian.

	the continue of the control of the c
Chains.	North between secs. 32 and 33.
	Var. 15° 10' E.
40.00	Set sandstone 16x14x5 for \frac{1}{4} sec. corner as per
10.00	instructions.
80.00	Deposited marked stone, set charred post, mark-
00.00	ed, built mound and dug pits as per instruc-
	tions for the corner to secs. 28, 29, 32 and
	33.
	Surface rolling. Prairie.
	Soil 2nd rate.
	boll and lates
	East on random between secs. 28 and 33.
	Var. 15° 10' East.
40.00	Set temporary ½ sec. corner.
79.80	Intersect sec. line 25 lks. south of corner to
	sections 27, 28, 33 and 34.
	Then S. 89° 49' W. on true line.
•	Var. 15° 10' East.
39.90	Set sandstone 16x12x3 for 4 sec. corner as per
	instructions.
79.80	Corner to secs. 28, 29, 32 and 33.
	Surface broken. Prairie.
	Soil 3rd rate.
	North between secs. 28 and 29.
	Var. 15° 10' East.
40.00	
10.00	instructions.
80.00	
	tions for the corner to secs. 20, 21, 28 and 29
	Surface broken. Prairie. Soil 3rd rate.

Field Notes of the Subdivision Lines of Township

Chains	No. 14 North Range 5 West of the Navajo Special Meridian
onains	East on random between secs. 21 and 28. BOOK 1951
	Var. 15° 10' East.
40.00	Set temporary ½ sec.corner.
79.86	Intersect sec. line 18 links south of corner
	to secs. 21, 22, 27, and 28.
	Ten S. 89° 52' W. on true line.
	Var. 15° 10' East.
39.93	Set sandstone 12x10x8 for ½ sec. corner as per
	instructions.
79.86	Corner to secs.20, 21, 28 and 29.
	Surface broken. Prairie.
	Soil 3rd rate.
-	North between secs. 20 and 21.
·	Var. 15° 10' E.
40.00	Set sandstone 16x12x4 for ½ sec. corner as per
	instructions.
69.10	Dry bed of creek, 28 lks. wide, course N.E.
80.00	Set sandstone 14x12x5 marked as per instruc-
	tions for the corner to secs. 16, 17, 20 and
	21.
	Surface broken. Prairie.
	Soil 3rd rate.
	East on random between secs. 16 and 21.
	Var. 15° 10' Rast.
18.50	Dry bed of creek, 30 lks. wide, course north.
40.00	Set temporary ½ sec. corner.
52.00	Dry bed of creek, 25 lks. wide, course north.
80.15	Intersect sec. line 20 lks.North of corner to
	secs. 15, 16, 21 and 22.
	Then N. 89° 51' W. on true line.

Field Notes of the Subdivision Lines of Township 14 North. Range 5 West of the N. S. M.

	4 North, Range o west of the N. D. M.
Chains.	Var. 15° 10' East.
40.07	Set sandstone 18x16x4 for \frac{1}{4} sec. corner as per
	instructions.
80.15	Corner to secs. 16, 17, 20 and 21.
	Surface broken. Prairie.
	Soil 3rd rate.
·	
	North between secs. 16 ad 17.
	Var. 15° 10' East.
16.80	Dry bed of creek, 25 lks. wide, course east.
40.00	Set sandstone 14x12x4 for $\frac{1}{4}$ sec. corner as per
	instructions.
80.00	Set sandstone 14x12x4 marked as per instruc-
	tions for the corner to secs. 8, 9, 16 and 17.
	Surface broken. Prairie.
	Soil 2nd rate.
	East on random between secs. 9 and 16.
	Var. 15° 10' East.
40.00	Set temporary 1 sec.corner.
80.30	
	secs. 9, 10, 15 and 16.
	Then N. 89° 49' W. on true line.
	Var.15° 10' East.
40.15	Set sandstone 15x13x3 for ½ sec. corner as per
	instructions.
80.30	Corner to secs. 8, 9, 16 and 17.
	Surface, broken. Prairie.
	Soil 3rd rate.
	North between secs. 8 and 9.
	Var. 15° East.
	Aut • To Time • •

	•	North Range 5 West of the N. S. M.	
•	Chains.	Bo	
	40.00	por a	1951
	00.00	instructions.  Set sandstone 14x11x4 marked corner to secs.	he
	80.00		
	·	4, 5, 8 and 9.	
		Surface broken. Prairie.	
		Soil 2nd rate.	
		East on random between secs. 4 and 9.	
		Var. 15° 10' E.	
	40.00	Set temporary ½ sec. corner.	
	80.12	Intersect sec. line 30 lks. north of corner	
		to secs. 3, 4, 9 and 10.	
		Then N. 89° 47' W. on true line.	
		Var. 15° 10' East.	
	40.06	Set charred post, built mound and dug pits for	
		½ sec. cor. as per instructions.	
	80.12	Corner to secs. 4, 5, 8 and 9.	
		Surface level. Prairie.	
		Soil 3rd rate.	
		North on random between secs. 4 and 5.	
	e e e e	Var. 15° 10' East.	
	40.00	Set temporary ½ sec. cor.	
	79.30	Intersect Dwnship line 45 links East of corner	
		to secs. 4, 5, 32 and 33.	
		Then S. 21' E. on true line.	
		Var. 15° 10' East.	
	39.30	Set sandstone 16x14x5 for \( \frac{1}{4} \) sec. corner as per	
		instructions.	
	79.30	Corner to secs. 4, 5, 8 and 9	
		Surface broken. Prairie.	
	N.	Soil 2nd rate.	

,		<b>-28-</b>
28	F	ield Notes of the Subdivision of Township
75		4 North Range 5 West of the N. S. M.
<b>40</b>	nains.	North between sections 31 and 32.
	¥	Var. 15° 10' East.
1	0.00	Set sandstone 18x14x3 for \frac{1}{4} sec. corner as per
4	- 1	instructions.
		Set sandstone 16x14x3 marked as per instruc-
0		tions, for the corner to secs. 29, 30, 31 and
	1	32.
	l	Surface broken. Frairie.
	1	Soil 2nd rate.
		Soft Sur rate.
		East on random between secs. 29 and 32.
		Var. 15° 10' East.
4	10.00	Set temporary ½ sec. corner.
8	30.16	Intersect sec. line 25 lks. north of corner to
	·	secs. 28, 29, 32 and 33.
	·	Then N.89° 49' W. on true line.
		Var. 15° 10' East.
	40.08	Set sandstone 13x8x8 for 4 sec. corner as per
		instructions.
	80.16	Corner to secs. 29, 30, 31 and 32.
		Surface broken. Prairie.
		Soil 2nd rate.
		West on random between secs. 30 and 31.
		Var. 15° East.
	40.00	Set temporary ½ sec.corner.
4.	78.10	Intersect Range line 20 links north of corner
	10.10	to secs. 25, 30, 31 and 36.
		Then N. 89° 51' E. on true line.
		Var. 15° East.
	38.10	Set sandstone 16x12x3 for 1 sec. corner as per
	90.10	instructions.
	78.10	Intersect range line 20 links north of corner
Marie Control of the	1. ~ ~ ~ ~	1 · · · · · · · · · · · · · · · · ·

Field Notes of the Subdivision of Township

14 North Range 5 West of the N. S. M. 76 Chains. sections 25, 30, 31, and 36, BOOK 1951 Then N. 89° 51' E. on true line. Var. 15° East. Set sandstone 16x12x3 for  $\frac{1}{4}$  sec. corner as per 38.10 instructions... 78.10 Corner to secs. 29, 30, 31 and 32. Surface rolling. Prairie. Soil 2nd rate. North between secs. 29 and 30. Var. 15° E. Set sandstone 14x12x4 for \$\frac{1}{4}\$ sec.corner as per 40.00 instructions. Set sandstone 14x10x8 marked as per instruc-80.00 tions for the corner to secs. 19, 20, 29 and 30. Surface broken. Prairie. Soil 2nd rate. East on random between secs. 20 and 29. Var. 15° East. Dry bed of creek, 15 lks. wide, course N.E. 25.20 40.00 Set temporary \( \frac{1}{4} \) sec. corner. Intersect sec. line 15 lks. North of corner to 80.24 secs. 20, 21, 28 and 29. Then N. 89° 53' W. on true line. Var. 15 East. Set sandstone 13x10x4 for \$\frac{1}{4}\$ sec. corner as per 40.12 instructions. 80.24 Corner to secs. 19, 20, 29 and 30. Surface broken. Prairie. Soil 2nd rate.

Set sandstone 16x12x5 for 4 sec. corner as per

39.88

instructions.

**30** 

Field Notes of the Subdivision Lines of Township
No. 14 North, Range No. 5 West of the N. S. M.

No. 14 North. Range No. 5 West of the N. S. M. Chains. 79.76 Corner to secs. 17, 18, 19 and 20. BOOK 1951 Surface broken. Prairie. Soil 2nd rate. West on random between secs. 18 and 19. Var. 15° East. 40.00 | Set temporary & sec. corner. 77380 Intersect range line 16 lks. south of corner to secs. 13, 18, 19 and 24. Then S. 89° 53' E. on true line. Var. 15° East. Conglomerate 16x12x5 for 4 sec. corner as per 37.80 instructions. 77.80 Corner to secs. 17, 18, 19 and 20. Surface rolling. Prairie. Soil 2nd rate. North between secs. 17 and 18. Var. 15° East. 40.00 Set charred post built mound and dug pits for ‡ sec. cor. as per instructions. 80.00 Set sandstone 16x12x5 marked as per instructions for the corner to secs. 7, 8, 17 and 18. Surface rolling. Prairie. Soil 2nd rate. East on random between secs. 8 and 17. Var. 15° E.

40.00 | Set temporary ½ sec. corner.

79.76 Intersectusec. line 25 lks. south of corner to secs. 8, 9, 16 and 17.

Then S. 89° 49' W. on true line.

Var. 15° East.

Field Notes of the Subdivision Lines of Township 14 North, Range 5 West of the N. S. M.

12	14 Morth, Range o mest of the M. D. M.
Chains	Set granite 18x12x6 for \( \frac{1}{4} \) sec. corner as per
	instructions.
79.76	Corner to secs. 7, 8, 17 and 18.
	Surface broken. Prairie.
	Soil 2nd rate.
-	
	West on random between secs. 7 and 18.
	Var. 15° East.
40.00	Set temporary 1 sec. corner.
77.70	
174.00	secs. 7. 12. 13 and 18.
·	Then S. 89° 49' E. on true line.
	Var. 15° East.
37.70	
37.70	instructions.
77.70	
77.70	Surface broken. Prairie.
	Soil 2nd rate.
	Soll Situlate.
	North between secs. 7 and 8.
	Var. 15° East.
40.00	
40.00	per instructions.for the section corner.
00.00	Set sandstone 15x12x3 marked as per instructions
80.00	for the corner to sees. 5, 6, 7 and 8.
	Surface broken . Prairie. Soil 2nd rate.
	Duriage broken. Iluirio
	East on random between secs. 5 and 8.
	Var. 15° East.
40.00	Set temporary & sec. corner.
79.85	Intersect sec. line 35 lks. south of corner to
	secs. 4, 5, 8 and 9.
	Then S. 89° 45' W. on true line.
1	

<u> </u>	14 North, Range o west of the N. D. M.
Unains	Var. 15° East. BOOK
39.92½	Set sandstone 16x10x4 for \( \frac{1}{4} \) sec. corner as per
	instructions.
79.85	Corner to secs. 5, 6, 7 and 8.
	Surface broken. Prairie.
	Soil 3rd rate.
·.	
	west as mandam between good 6 and 7
	West on random between secs. 6 and 7.  Var. 15° East.
40.00	Set temporary ½ sec.corner.  Intersect range line 35 lks. south of corner to
77.60	
	Then S. 89° 45' E. on true line.
	Var. 15° East.
27 60	,
37.60	instructions.
77.60	
17.80	Surface broken. Prairie.
	Soil 2nd rate.
	bell and laco.
	North on random between sections 5 and 6.
	Var. 15° East.
40.00	
79.80	
	to secs. 5, 6, 31 and 32.
	Then S. 13' E. on true line.  Var. 15° East.
00.00	
39.80	instructions.
79.80	- a N 10
19.00	COLUCT TO SCOS. O, O, I and O.
1	<b>1</b>

of

Township 14 North Range 5 West of the Navajo Special Meridian.

This Township is nearly all prairie, surface generally rolling and broken. It is well adapted to grazing purposes and large portions of it to farming.

The "San Juan" is particularly well adapted to agricultural purposes. The River averages about 3.50 chs.; low banks; gravelly bottom; clear water and rapid current about 4 feet deep.

> Ehud N. Darling, U. S. Surveyor.

Subscribed by said Ehud N. Darling, U. S. Surveyor, and sworn to before me, this 11th day of May, at Washington D.C.

Wm. Martin, J. P.