

recd April 10. 1892

21

*unreferred*

Plattets - x

BOOK 637

To You L. O. May 27, 1892.

Survey approved

August 31, 1892

4-671

No. 637

637

**FIELD NOTES**

*of the*

**GENERAL LAND OFFICE**

*Subdivision Fractional*

**T5S R7E.**

By Daniel Drummond U.S.D.S.

**UNDER CONTRACT N<sup>o</sup> 19.**

*Dated June 13, 1891.*

*SUR. Tp. Commenced. Dec. 2/91.*

*SUR. Tp. Completed. Dec. 7/91.*

2

Township 55 R. 7E

6	5	4	3	2	5	1
7	8	9	10	11	12	3
18	17	16	15	14	13	
19	20	21	22	23	24	
30	29	28	27	26	25	
31	32	33	34	35	36	

BOOK 637 61 No. 637 3 cont<sup>a</sup>

Subdivision Fractional T.S.R. 76.

18X18X12 ins in each Sec 5 1/2 ft  
dist. and raised a mound  
of earth 2 ft high 4 1/2 ft low  
around post.

Land level

Soil sandy loam 1<sup>st</sup> rate

Timber, dense mesquite  
brush for 38 chs.

S89°38'E. on a true line bet  
Secs 10, 12

Var 12°56'E.

Over level ground.

40.00 Set a post 4 ft long 4 ins square  
with marked stone 12 ins in  
the ground for 1/4 Sec low  
marked 1/4 S. on N. face dog  
pits 18X18X12 ins E & W of  
post 5 1/2 ft dist. and raised

4

BOOK 637 62.

Subdivision fractional T5 S. R7E.

Chains

117.

a mound of earth  $1\frac{1}{2}$  ft high  
 $3\frac{1}{2}$  ft base around post.  
 Intersect E bdy of Tp at a  
 point  $S 0^{\circ} 14' E. 33.31$  chs from  
 the cor to Secs 6 & 7 T5 S. R8E  
 which is a post recently re-established  
 and heretofore described  
 by me. I here set a post  
 4 ft long 4 ins square with  
 marked stone 12 ins in the  
 ground for closing cor to  
 Secs 1 & 12 marked

C. C. T. 5 S. R7E. on W.

S. 1 on N and

S 12 on S faces

with 1 notch on N and 5 notches  
 on S faces dry pits  $18 \times 18 \times 12$   
 ins N. S. & W. of post  $5\frac{1}{2}$  ft  
 dia and raised a mound

Subdivision Fractional T.S. R. 7 Co.

Chains

of earth 2 ft high 4' 1/2 ft base  
around post.

Land level

Soil sandy loam 1<sup>st</sup> rate

Timber, mesquite brush

N. 0° 3' E on a true line bet  
Secs 1 & 2.

Var. 12° 56' E.

Over level ground

7.10 Wood road corner E & W.

40.00 Set a post 4 ft long 4 in square  
with marked stone 12 in in the  
ground for 1/4 Sec cor marked  
1/4 S. on W. face dug pits 18 x 18  
x 12 in N & S. of post 5 1/2 ft dist  
and raised a mound of earth  
1 1/2 ft high 3 1/2 ft base around  
post.

6

Subdivision Fractional T. 5 S. R 7 E.  
chains

77.00 Wagon road to Gila river  
bears NE.

113.10 Intersect N. bdy of Tp. at a  
point S. 89° 49' W. 36.62 chs.  
from the cor. to Secs 35 & 36  
T. 4 S. R 7 E <sup>as recently established by me</sup> where I set  
a post 4 ft long & 4 in square  
with marked stone 12 in in  
the ground for Closing Cor  
to Secs 1 & 2 marked  
C.C. T. 5 S. R 7 E on S.

1 on E end

12 on W. face, with  
1 notch on E and 5 notches  
on W. faces. dug pits 18x18  
x 12 in S. E & W of post  
5 1/2 ft dist and raised a  
mound of earth 2 ft high  
& 1 1/2 ft base around post

Subdivision Fractional T.S. R7E.

Name

Land level

Soil sandy loam 1<sup>st</sup> rate

Timber, mesquite brush.

Dec. 7<sup>th</sup> 1891.

## General Description

This township contains nearly every variety of land from plains to mountains. and the soil ranges from rocky gravelly to rich sandy loam. There is also some rich black loam near the Santa Cruz overflow or wash. The land is mountainous in Secs. 17. 20. 29 and 32. the balance of the fractional surveyed portion is generally level. No. Springs or natural water flowing on the



Surface, the washes are dry, except during heavy rains. Agricultural crops cannot be grown without artificial irrigation. The soil is exceedingly rich, and with the aid of irrigation, abundant crops might be grown.

The mean declination for the plat, the average of six observations is  $12^{\circ} 56'$  East. There are two settlers one in sec. 13, and one in 24.

The timber is mesquite, and is very dense in many portions. Palo Verde in the western part.

Daniel Drummond  
U.S. Deputy Surveyor.

BOOK 637

10

U. S. Surveyor-General's Office,

TUCSON, A. T., *May 26* 1882

The foregoing Field Notes of the Surveys of  
*Fractional*

*T. S. D. R. 7 E*

Gila and Salt River Meridian

in *Arizona* executed by

*David Drummond*

U. S. Deputy Surveyor, under his contract dated

*June 13<sup>th</sup> 1881*

having been critically examined, the necessary corrections and explanations made, the said Field Notes and the surveys they describe are hereby approved.

*Repaer Johnson*  
U. S. Surveyor-General  
for the Territory of Arizona.