

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

ORIGINAL

FIELD NOTES

OF THE

SURVEY OF THE SOUTH AND NORTH BOUNDARIES

AND

SUBDIVISIONAL LINES

OF

TOWNSHIP 14 NORTH, RANGE 11 WEST

Of the GILA AND SALT RIVER *Meridian,*

In the State of ARIZONA

EXECUTED BY

DeWitt A. Crain, Cadastral Surveyor

Under special instructions dated November 29, 1957, *which provided*
for the surveys included under Group No. 318, *approved* November 29, 1957
and assignment instructions dated December 26, 1957

Survey commenced January 13, 1958

Survey completed March 25, 1958

14

BOOK 4550
INDEX DIAGRAM

Township 14 North, Range 11 West

9	8	7	7	6	5
6	49 5	37 4	30 3	23 2	16 1
48	47	36	29	23	16
7	47 8	35 9	28 10	22 11	15 12
46	45	35	28	21	14
18	44 17	34 16	27 15	21 14	14 13
43	43	34	26	20	13
19	42 20	33 21	26 22	19 23	13 24
41	40	32	25	19	12
30	40 29	32 28	25 27	18 26	11 25
39	38	31	24	18	11
31	37 32	31 33	24 34	17 35	10 36
5	4	3	3	2	1

Township 14 North, Range 11 West

Chains

The west boundary was surveyed by Otis Ross in 1915-16, as represented on the plat of T. 14 N., R. 12 W. The east boundary of the township was surveyed by W. H. Thorn and Ty White in 1923, as represented on the plat of T. 14 N., R. 10 W.

The following field notes are those of the survey of the south and north boundaries, and of the subdivision of T. 14 N., R. 11 W.

The survey was executed with a W. and L. E. Gurley solar transit, serial No. 541328, which conforms to the standard instrumental specifications of the Bureau of Land Management. The instrument was maintained in precise adjustment throughout the progress of the survey.

The measurements were made with a narrow steel tape, 8 chains in length, graduated to tenths of links for the first link, to links for the next 99 links and thereafter at intervals of 10 links. The tape was tested by comparison with a standard steel tape, 1 chain in length and found correct. The measurements were made on the slope and the vertical angle of each interval was ascertained by two clinometers in good adjustment. The slope distances were properly reduced to horizontal equivalents which are entered in the field note record.

The geographic position of the southeast corner of the township is latitude $34^{\circ} 30' 04''$ N. and longitude $113^{\circ} 21' 31''$ W., as determined from data furnished with the special instructions.

The mean magnetic declination was found to be $14^{\circ} 45'$ E.

South Boundary, T. 14 N., R. 11 W.

Beginning at the cor. of Ts. 13 and 14 N., Rs. 10 and 11 W., an iron post, 3 ins. diam., set, mkd. and witnessed as described in the official record.

West, bet. secs. 1 and 36.

Asc. 15 ft. over rolling S. slope.

3.60 Low round spur, slopes S. 80° W.; desc. 142 ft. to cor., over rolling W. slope.

33.80 Enter draw, drains W.

40.00 Point for the $\frac{1}{4}$ sec. cor. of secs. 1 and 36.

Set an iron post, 30 ins. long, 12 ins. in the ground, and in a mound of stone, 4 ft. base to top of post, with brass cap mkd.

T14N R11W

$\frac{1}{4}$ $\frac{S36}{S1}$

T13N

1958

Cor. falls on S. slope, on N. side of draw.

41.90 Leave draw, drains N. 70° W.; asc. over rolling N. slope.

51.00 Small spur, slopes N. 80° W.; desc. over W. slope.

52.00 Wash, 1 ch. wide, 4 ft. deep, drains NW.; thence over nearly level land to cor.

80.00 Point for the cor. of secs. 1, 2, 35 and 36.

South Boundary, T. 14 N., R. 11 W.

Chains

Set an iron post, 30 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

T14N R11W
S35 | S36
 S2 | S1
 T13N
 1958

Raise a mound of stone, 3 ft. base, 2 ft. high, W. of cor.

Land, rolling.
 Soil, sandy and rocky.
 Timber, yellow paloverde, catclaw and juniper.
 Undergrowth, creosote bush, ocotillo and buckhorn cholla.

West, bet. secs. 2 and 35.

Over nearly level land.

38.90 Wash, 40 lks. wide, 4 ft. deep, drains NNW.

40.00 Point for the ¼ sec. cor. of secs. 2 and 35.

Set an iron post, 30 ins. long, 2½ ins. diam., on bedrock, and in a mound of stone, 4 ft. base to top of post, with brass cap mkd.

T14N R11W
 ¼ S35
 S 2
 T13N
 1958

Asc. 65 ft. over rocky E. slope.

42.40 Top of ascent, bench, bears N. and S.; desc. 120 ft. over broken W. slope.

47.90 Old fence line, bears N. 10° W. and S. 10° E.

78.00 Point selected for the witness cor. of secs. 2, 3, 34 and 35.

Set an iron post, 30 ins. long, 2½ ins. diam., 14 ins. in the ground, and in a mound of stone, 4 ft. base to top of post, with brass cap mkd.

T14N R11W
S34 | S35
 S3 | S2
 T13N
 1958

78.70 Rim of canyon, bears N. 70° W. and S. 70° E.; desc. 30 ft. over rocky W. slope.

80.00 True point for the cor. of secs. 2, 3, 34 and 35 falls on unsafe slope of canyon.

Land, rough and broken.
 Soil, rocky.
 Timber, yellowpaloverde.
 Undergrowth, none.

South Boundary, T. 14 N., R. 11 W.

Chains

West, bet. secs. 3 and 34.

Desc. 70 ft. over rocky W. slope into wash in bottom of canyon.

.85 Wash, drains N. 60° W.; asc. 60 ft. over rocky N. slope.

3.10 S. rim of canyon, bears W. and S. 80° E.; thence along broken and rocky N. slope.

15.30 Desc. 55 ft. over rocky NW. slope.

17.30 Wash in canyon, drains S. 60° W.; asc. 30 ft. over rocky SE. slope.

21.20 Rocky spur, slopes SSW.; desc. 174 ft. over rocky and broken W. slope.

32.70 Same wash, drains NW.

38.10 Same wash, drains SW.; asc. 30 ft. over rocky SE. slope to cor.

40.00 Point for the $\frac{1}{4}$ sec. cor. of secs. 3 and 34.

Set an iron post, 30 ins. long, 2 $\frac{1}{2}$ ins. diam., 18 ins. in the ground, and in a collar of stone, with brass cap mkd.

T14N R11W

$\frac{1}{4}$ S34
S 3

T13N
1958

Asc. 20 ft. over rocky E. slope.

46.00 Desc. 146 ft. over rocky and broken W. to SW. slope to the cor.

78.70 Arizona Highway No. 93, bears N. 20° W. and S. 20° E.

80.00 Point for the cor. of secs. 3, 4, 33 and 34.

Set an iron post, 30 ins. long, 2 $\frac{1}{2}$ ins. diam., 20 ins. in the ground, and in a mound of stone to top of post, with brass cap mkd.

T14N R11W

S33 | S34

S4 | S3

T13N

1958

Land, rough and broken.

Soil, rocky.

Timber, yellow paloverde.

Undergrowth, none.

West, bet. secs. 4 and 33.

Desc. 113 ft. over rocky W. slope.

18.00 Small wash, drains N.; asc. over E. slope.

22.20 Road, bears NNW. and SSE.; desc. 40 ft. over W. slope.

28.20 Fence, bears N. and S.

37.00 Black Wash, 1 ch. wide, 2 ft. deep, drains N. 30° W.; asc. 55 ft. over E. slope.

40.00 Point for the $\frac{1}{4}$ sec. cor. of secs. 4 and 33.

South Boundary, T. 14 N., R. 11 W.

Chains

Set an iron post, 30 ins. long, 2½ ins. diam., 6 ins. in the ground, and in a mound of stone, 5 ft. base to top of post, with brass cap mkd.

T14N R11W

¼ S33
S 4

T13N
1958

Asc. 45 ft. over rolling E. to NE. slope.

47.60 Low spur, slopes NNW.; desc. over NW. slope.

61.30 Wash, drains N.; thence asc. over nearly level land.

80.00 Point for the cor. of secs. 4, 5, 32 and 33.

Set an iron post, 30 ins. long, 2½ ins. diam., 22 ins. in the ground, and in a mound of stone to top of post, with brass cap mkd.

T14N R11W

S32 | S33
S5 | S4

T13N
1958

Land, rolling.

Soil, sandy.

Timber, none.

Undergrowth, creosote bush and buckhorn cholla.

West, bet. secs. 5 and 32.

Asc. 30 ft. over rolling NE. slope to cor.

40.00 Point for the ¼ sec. cor. of secs. 5 and 32.

Set an iron post, 30 ins. long, 2½ ins. diam., 22 ins. in the ground, and in a collar of stone, with brass cap mkd.

T14N R11W

¼ S32
S 5

T13N
1958

Asc. 75 ft. over rolling NE. slope.

80.00 Point for the cor. of secs. 5, 6, 31 and 32.

Set an iron post, 30 ins. long, 2½ ins. diam., 24 ins. in the ground, and in a collar of stone, with brass cap mkd.

T14N R11W

S31 | S32
S6 | S5

T13N
1958

Land, rolling.

Soil, sandy and rocky.

Timber, yellow paloverde, smokethorn and catclaw.

Undergrowth, creosote bush, Saguaro cactus, buckhorn cholla and ocotillo.

South Boundary, T. 14 N., R. 11 W.

Chains	West, bet. secs. 6 and 31.
	Asc. 75 ft. over rolling NE. slope.
40.00	Point for the $\frac{1}{4}$ sec. cor. of secs. 6 and 31.
	Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 20 ins. in the ground, and in a mound of stone, with brass cap mkd.
	T14N R11W $\frac{1}{4}$ $\frac{S31}{S 6}$ T13N 1958
	Asc. over rolling N. to NW. slope.
74.77	Intersect the E. bdy. of sec. 36, T. 14 N., R. 12 W.. Point for the closing cor. of Ts. 13 and 14 N., R. 11 W.
	Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, and in a collar of stone, with brass cap mkd.
	T14N R12W R11W S36 $\frac{S31}{S 6}$ C T13N 1958
	From this closing cor. the cor. of Ts. 13 and 14 N., R. 12 W., bears S. 3.36 chs. dist. and is monumented by an iron post, 3 ins. diam., set, mkd. and witnessed as described in the official record.
	Land, rolling. Soil, sandy and rocky. Timber, yellow paloverde, smokethorn and catclaw. Undergrowth, creosote bush and ocotillo.

North Boundary, T. 14 N., R. 11 W.

	From the cor. of Ts. 14 and 15 N., Rs. 10 and 11 W., which is monumented with an iron post, 3 ins. diam., set, mkd. and witnessed as described in the official record.
	West, bet. secs. 1 and 36.
	Desc. over rolling S. to SW. slope.
16.70	Wash, 1.50 chs. wide, 3 ft. deep, drains SSE.; thence over rolling S. slope.
40.00	Point for the $\frac{1}{4}$ sec. cor. of secs. 1 and 36.
	Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 18 ins. in the ground, and in a collar of stone, with brass cap mkd.
	T15N R11W $\frac{1}{4}$ $\frac{S36}{S 1}$ T14N 1958
44.60	Wash, 2 chs. wide, drains SSE.; asc. 110 ft. over SE. slope.
58.60	Low ridge, spur, slopes S.; desc. 50 ft. over W. slope.

North Boundary, T. 14 N., R. 11 W.

Chains	
64.00	Wash, 20 lks. wide, 4 ft. deep, drains S.; asc. over E. slope.
80.00	Point for the cor. of secs. 1, 2, 35 and 36. Set an iron post, 30 ins. long, 2½ ins. diam., 20 ins. in the ground, and in a mound of stone, with brass cap mkd.
	T15N R11W <u>S35</u> <u>S36</u> S2 S1 T14N 1958
	Land, rolling. Soil, sandy and rocky. Timber, juniper. Undergrowth, creosote bush.
	West, bet. secs. 2 and 35. Over rolling slope.
14.20	Asc. 100 ft. over E. to NE. slope.
22.50	Spur, slopes N.; desc. 115 ft. over NW. slope.
30.20	Wash, 40 lks. wide, 4 ft. deep, drains S.; asc. 115 ft. over SE. slope.
39.60	Ridge, bears N. and S.
40.00	Point for the ¼ sec. cor. of secs. 2 and 35. Set an iron post, 30 ins. long, 2½ ins. diam., 18 ins. in the ground and in a collar of stone, with brass cap mkd.
	T15N R11W ¼ <u>S35</u> S 2 T14N 1958
	Desc. 165 ft. over W. slope.
54.10	Wash, 40 lks. wide, 4 ft. deep, drains S.; asc. 75 ft. over SE. slope.
58.90	Spur, slopes S.; desc. 85 ft. over SW. slope.
63.10	Wash, 50 lks. wide, 6 ft. deep, drains S.; asc. 130 ft. over SE. slope.
76.70	Ridge spur, slopes SW.; desc. 40 ft. over W. slope.
79.55	Road, bears N. and SW.
80.00	Point for the cor. of secs. 2, 3, 34 and 35. Set an iron post, 30 ins. long, 2½ ins. diam., 16 ins. in the ground, and in a mound of stone to top of post, with brass cap mkd.
	T15N R11W <u>S34</u> <u>S35</u> S3 S2 T14N 1958
	Land, rolling and broken. Soil, sandy and rocky.

North Boundary, T. 14 N., R. 11 W.

Chains

Timber, paloverde and juniper.
Undergrowth, creosote bush, buckhorn cholla and Saguaro cactus.

West, bet. secs. 3 and 34.

Desc. 55 ft. over W. slope.

2.30 Wash, drains SW.; asc. 60 ft. over SE. slope.

8.00 Spur, slopes SE.; desc. 125 ft. over rocky SW. slope.

16.50 Wash, 40 lks. wide, 4 ft. deep, drains S.; asc. 60 ft. over rocky SE. slope.

21.40 Rocky spur, slopes S.; desc. 170 ft. over rocky SW. slope.

27.20 Wash, 30 lks. wide, 4 ft. deep, drains S.; asc. 165 ft. over rocky and broken SSE. slope to the cor.

40.00 Point for the $\frac{1}{4}$ sec. cor. of secs. 3 and 34.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 14 ins. in the ground, and in a mound of stone to top of post, with brass cap mkd.

T15N R11W

$\frac{1}{4}$ S34

S 3

T14N

1958

Asc. 155 ft. over rocky and broken SSE. slope.

66.80 Top of ascent, in saddle, bears N. and SSW.; desc. 40 ft. over rocky SSW. slope.

75.90 Desc. 135 ft. over steep rocky W. slope to cor.

80.00 Point for the cor. of secs. 3, 4, 33 and 34.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 8 ins. in the ground, and in a mound of stone, 4 ft. base to top of post, with brass cap mkd.

T15N R11W

S33 | S34

S4 | S3

T14N

1958

Land, rough and broken.

Soil, rocky.

Timber, yellow paloverde.

Undergrowth, yucca, Saguaro cactus, and ocotillo.

West, bet. secs. 4 and 33.

Desc. 310 ft. over rocky W. to NW. slope.

14.50 Wash, 50 lks. wide, 6 ft. deep, drains S.; asc. over ledgy E. slope.

19.30 Base of vertical ledge, bears N. and S.; asc. 95 ft. over E. face of ledge.

North Boundary, T. 14 N., R. 11 W.

Chains	
19.30	E. rim of mesa, bears N. and S.
21.20	West rim of mesa, bears N. and S.; desc. 55 ft. over W. face of ledge
23.50	Wash, 50 lks. wide, 6 ft. deep, drains SSE.; asc. 90 ft. over rocky E. slope.
27.90	Power transmission line, bears S. 26° 30' E. and N. 26° 30' W.; asc. 395 ft. over steep rocky E. slope.
40.00	Point for the ¼ sec. cor. of secs. 4 and 33. Set an iron post, 30 ins. long, 2½ ins. diam., 8 ins. in the ground, and in a mound of stone, 4½ ft. base to top of post, with brass cap mkd. <div style="text-align: center;"> <p>T15N R11W $\frac{S33}{S4}$ T14N 1958</p> </div>
	Asc. 70 ft. over rocky E. slope.
42.20	E. rim of mesa, bears N. and S.; thence over nearly level land.
70.40	W. rim of mesa, bears NNW. and SSE.; desc. 330 ft. over rocky W. slope.
80.00	Point for the cor. of secs. 4, 5, 32 and 33, falls in wash; wash drains SSW., 30 lks. wide, 6 ft. deep. Land, rough. Soil, rocky. Timber, yellowpaloverde. Undergrowth, creosote bush.
	West, bet. secs. 5 and 32. Asc. 50 ft. over rocky E. slope.
2.30	Point selected for the witness cor. for secs. 4, 5, 32 and 33. Set an iron post, 30 ins. long, 2½ ins. diam., 8 ins. in the ground, and in a mound of stone, 5 ft. base to top of post, with brass cap mkd. <div style="text-align: center;"> <p>T15N R11W $\frac{S32 \mid S33}{S5 \mid S4 \mid C}$ T14N 1958</p> </div>
	Asc. 230 ft. over rocky E. slope.
5.60	E. rim of mesa, bears NNE. and SSW.; thence over nearly level land.

North Boundary, T. 14 N., R. 11 W.

Chains	
22.90	W. rim of mesa, bears N. and S.; desc. 215 ft. over rocky W. slope.
30.80	Wash, 50 lks. wide, 6 ft. deep, drains SSE.; asc. 305 ft. over rocky E. slope.
40.00	Point for the $\frac{1}{4}$ sec. cor. of secs. 5 and 32. Set an iron post, 30 ins. long, 2 $\frac{1}{2}$ ins. diam, on bedrock and in a mound of stone, 5 ft. base to top of post, with brass cap mkd. T15N R11W $\frac{1}{4}$ $\frac{S32}{S 5}$ T14N 1958 Asc. 130 ft. over rocky E. slope.
48.00	E. rim of mesa, bears NNE. and SSW.; asc. 100 ft. over rocky E. slope.
52.40	Top of ascent, bears NNE. and SSW., thence over nearly level land.
54.60	W. rim of mesa, bears NNW. and SSW.; desc. 210 ft. over W. face of rim.
58.00	Slope changes to SW.; desc. 290 ft. over rocky SW. slope.
80.00	Point for the cor. of secs. 5, 6, 31 and 32. Set an iron post, 30 ins. long, 2 $\frac{1}{2}$ ins. diam., 6 ins. in the ground, and in a mound of stone to top of post, with brass cap mkd. T15N R11W $\frac{S31}{S6}$ $\frac{S32}{S5}$ T14N 1958 Land, rough. Soil, rocky. Timber, yellow paloverde. Undergrowth, creosote bush.
	West, bet. secs. 6 and 31.
	Desc. 130 ft. over SW. slope.
13.70	Wash, 20 lks. wide, 5 ft. deep, drains S.; asc. 65 ft. over E. slope.
20.00	Ridge, bears NNW. and SSE.; desc. 90 ft. over W. slope.
25.60	Wash, 40 lks. wide, 4 ft. deep, drains SSE.; asc. 100 ft. over SE. slope.
40.00	Point for the $\frac{1}{4}$ sec. cor. of secs. 6 and 31, falls in small wash, drains SE.
43.28	Point selected for the witness $\frac{1}{4}$ sec. cor. of secs. 6 and 31. Set an iron post, 30 ins. long, 2 $\frac{1}{2}$ ins. diam., 12 ins. in the ground and in a mound of stone, 3 $\frac{1}{2}$ ft. base to top of post, with brass cap mkd. T15N R11W $\frac{1}{4}$ $\frac{S31}{S 6}$ W T14N C 1958

North Boundary, T. 14 N., R. 11 W.

<p>Chains</p> <p>73.77</p>	<p>Asc. 765 ft. over broken and rocky E. slope.</p> <p>Intersect the E. bdy. of sec. 36, T. 15 N., R. 12 W.</p> <p>Point for the closing cor. of Ts. 14 and 15 N., R. 11 W. falls on ledge where it is unsafe to place monument.</p> <p>Point selected for the closing cor. of Ts. 14 and 15 N., R. 11 W., 21 lks. S. of true point.</p> <p>Set an iron post, 30 ins. long, 2½ ins. diam., 8 ins. in the ground and in a mound of stone, 8 ft. base to top of post, with brass cap mkd.</p> <p style="text-align: center;"> T15N R12W R11W W C S36 S31 C S 6 C T15N T14N 1958 </p> <p>From the true point for the closing cor. of Ts. 14 and 15 N., R. 11 W. the cor. of Ts. 14 and 15 N., R. 12 W. bears S. 2.82 chs. dist. and is monumented with an iron post, 3 ins. diam., set, mkd. and witnessed as described in the official record.</p> <p>Land, rough and broken. Soil, rocky. Timber, yellow paloverde and juniper. Undergrowth, creosote bush.</p>
<p>Subdivision of Township 14 North, Range 11 West</p>	
<p>6.00</p> <p>19.70</p> <p>40.00</p> <p>45.40</p> <p>50.90</p> <p>80.00</p>	<p>From the cor. of secs. 1, 2, 35 and 36, on the S. bdy. of the Tp. N. 0° 01' W., bet. secs. 35 and 36.</p> <p>Over nearly level land.</p> <p>Draw, drains W.; leave level land; asc. 130 ft. over rocky and broken SSW. slope.</p> <p>Top of ascent, slope changes to broken W. slope.</p> <p>Point for the ¼ sec. cor. of secs. 35 and 36.</p> <p>Set an iron post, 30 ins. long, 2½ ins. diam., 8 ins. in the ground, and in a mound of stone, 4 ft. base to top of post, with brass cap mkd.</p> <p style="text-align: center;"> T14N R11W ¼ S35 S36 1958 </p> <p>Desc. 65 ft. over steep and rocky N. slope.</p> <p>Wash, drains W.; thence over nearly level land.</p> <p>Point for the cor. of secs. 25, 26, 35 and 36.</p> <p>Set an iron post, 30 ins. long, 2½ ins. diam., 14 ins. in the ground, and in a mound of stone, 3½ ft. base to top of post, with brass cap mkd.</p> <p style="text-align: center;"> T14N R11W S26 S25 S35 S36 1958 </p>

Subdivision of T. 14 N., R. 11 W.

Chains

Land, rough and broken.
Soil, rocky.
Timber, yellow paloverde and juniper.
Undergrowth, creosote bush, Saguaro cactus and buckhorn cholla.

From the cor. of secs. 25, 30, 31 and 36, on the E. bdy. of the Tp., which is monumented with a 2 ins. iron post, set, mkd. and witnessed as described in the official record.

West, bet. secs. 25 and 36.

Desc. 20 ft. over rolling and broken NW. slope.

24.10 Asc. 185 ft. over steep rocky and broken N. to NE. slope.

39.98 Point for the $\frac{1}{4}$ sec. cor. of secs. 25 and 36.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 6 ins. in the ground and in a mound of stone, 4 ft. base to top of post, with brass cap mkd.

T14N R11W

$\frac{1}{4}$ S25
S36

1958

Cor. falls in small saddle.

Thence over N. slope.

41.00 Desc. 110 ft. over NNW. slope.

56.00 Base of steep descent, bears NE. and SSE.; desc. 105 ft. over W. slope to cor.

79.96 The cor. of secs. 25, 26, 35 and 36.

Land, rough and broken.
Soil, rocky.
Timber, yellow poloverde and catclaw.
Undergrowth, creosote bush, yucca and Saguaro cactus.

N. $0^{\circ} 01'$ W., bet. secs. 25 and 26.

Over nearly level land.

22.20 Wash, drains W.; asc. 105 ft. over broken and rocky SSE. slope.

29.40 Ridge spur, slopes SW.; thence asc. along W. slope to cor.

40.00 Point for the $\frac{1}{4}$ sec. cor. of secs. 25 and 26.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam. on bedrock, and in a mound of stone, 5 ft. base to top of post, with brass cap mkd.

T14N R11W

$\frac{1}{4}$
S26 | S25

1958

Asc. 30 ft. over W. to SW. slope.

Subdivision of T. 14 N., R. 11 W.

Chains

45.50

Desc. over W. to NW. slope.

61.60

Desc. 85 ft. over N. slope.

75.80

Wash, drains SW.; asc. over rolling S. slope.

80.00

Point for the cor. of secs. 23, 24, 25 and 26.

Set an iron post, 30 ins. long, 2½ ins. diam., 8 ins. in the ground, and in a mound of stone, with brass cap mkd.

T14N R11W
 S23 | S24
 S26 | S25
 1958

Deposit broken glass alongside the iron post.

Land, rough and rolling.

Soil, rocky.

Timber, yellow paloverde and catclaw.

Undergrowth, creosote, yucca and Saguaro cactus.

From the cor. of secs. 19, 24, 25 and 30, on the E. bdy. of the Tp., which is monumented with an iron post, 2 ins. diam., 8 ins. above ground, set, mkd. and witnessed as described in the official record.

S. 89° 59' W., bet. secs. 24 and 25.

Over level sandy bottom land, of Banzai Wash.

21.15

Leave bottom land; asc. 90 ft. over rocky and broken N. slope.

25.80

Ridge spur, slopes N.; thence over rolling and broken N. slope.

37.90

Wash, drains N.; asc. 105 ft. over E. slope.

39.96

Point for the ¼ sec. cor. of secs. 24 and 25.

Set an iron post, 30 ins. long, 2½ ins. diam., on bedrock, and in a mound of stone, 5 ft. base to top of post, with brass cap mkd.

T14N R11W
 ¼ S24
 S25
 1958

Asc. 45 ft. over E. slope.

41.90

Ridge spur, slopes N.; desc. 80 ft. over NW. slope.

48.20

Wash, 50 lks. wide, 5 ft. deep, drains N.; asc. 300 ft. over rocky and broken E. slope.

68.90

Ridge, in saddle, bears N. and S.; desc. 20 ft. over rolling W. slope.

79.92

The cor. of secs. 23, 24, 25 and 26.

Land, rough and broken.

Soil, rocky.

Timber, yellow paloverde and juniper.

Undergrowth, creosote bush, yucca, catclaw and ocotillo.

Subdivision of T. 14 N., R. 11 W.

Chains

N. $0^{\circ} 01'$ W., bet. secs. 23 and 24.

Asc. 95 ft. over broken SSE. slope.

15.40 Ridge spur, slopes W.; desc. 210 ft. over broken NNW. slope.

40.00 Point for the $\frac{1}{4}$ sec. cor. of secs. 23 and 24.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 8 ins. in the ground to bedrock, and in a mound of stone, 5 ft. base to top of post, with brass cap mkd.

T14N R11W

$\frac{1}{4}$
S23 | S24
1958

Cor. falls on rim of canyon, rim bears E. and W.

Desc. 485 ft. over rocky and broken N. slope.

53.20 Banzai Wash in bottom of canyon, 2 chs. wide, drains W.; asc. 420 ft. over steep rocky and broken S. slope.

69.50 N. rim of canyon, bears E. and W.; asc. 50 ft. over S. slope.

80.00 Point for the cor. of secs. 13, 14, 23 and 24.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 8 ins. in the ground and in a mound of stone, 5 ft. base to top of post, with brass cap mkd.

T14N R11W

S14 | S13
S23 | S24
1958

Land, rough and broken.

Soil, rocky.

Timber, yellow paloverde and catclaw.

Undergrowth, yucca, Saguaro cactus, jumping and buckhorn cholla and ocotillo.

From the cor. of secs. 13, 18, 19 and 24, on the E. bdy. of the Tp., which is monumented with an iron post, 2 ins. diam., 10 ins. above ground, set, mkd. and witnessed as described in the official record.

S. $89^{\circ} 59'$ W., bet. secs. 13 and 24.

Asc. 140 ft. over steep rocky E. slope.

3.30 Ridge spur, slopes NE.; desc. 95 ft. over NW. slope.

12.60 Wash, 30 lks. wide, 10 ft. deep, drains NNE.; asc. 375 ft. over rocky and broken NE. slope.

34.90 Ridge, bears SE. and NW.; desc. 55 ft. over SW. slope.

39.99 Point for the $\frac{1}{4}$ sec. cor. of secs. 13 and 24.

Subdivision of T. 14 N., R. 11 W.

Chains

Set an iron post, 30 ins. long, 2½ ins. diam., 6 ins. in the ground to bedrock, and in a mound of stone to top of post, with brass cap mkd.

T14N R11W

¼ S13

S24

1958

Desc. 100 ft. over broken SSW. slope.

63.45 Fence, bears SE. and NW.

79.98 The cor. of secs. 13, 14, 23 and 24.

Land, rough and broken.

Soil, rocky.

Timber, yellow paloverde.

Undergrowth, Saguaro cactus, jumping buckhorn cholla and ocotillo.

N. 0° 01' W., bet. secs. 13 and 14.

Asc. 85 ft. over S. slope.

7.00 Spur, slopes SW.; thence over W. slope of cove.

11.70 Fence, bears NW. and SE.

21.10 Main ridge, bears W. and S. 80° E.; desc. 510 ft. over rocky and broken N. slope.

40.00 Point for the ¼ sec. cor. of secs. 13 and 14.

Set an iron post, 30 ins. long, 2½ ins. diam., 8 ins. in the ground to bedrock, and in a mound of stone, 5 ft. base to top of post, with brass cap mkd.

T14N R11W

¼ S14 | S13

1958

Desc. 240 ft. over rocky and broken N. slope.

63.60 Burro Creek, 2 chs. wide, 2 ft. deep, drains W.; asc. 335 ft. over rocky and broken S. slope.

79.80 Small wash, drains SE.

80.00 Point for the cor. of secs. 11, 12, 13 and 14, falls on ledge, unsafe place to monument.

Land, rough and broken.

Soil, rocky.

Timber, only in bottom of Burro Creek, catclaw and mesquite.

Undergrowth, none.

From the cor. of secs. 7, 12, 13 and 18, on the E. bdy. of the Tp., which is monumented with an iron post, 2 ins. diam., 10 ins. above ground, set, mkd. and witnessed as described in the official record.

N. 89° 53' W., bet. secs. 12 and 13.

Desc. over W. slope.

Subdivision of T. 14 N., R. 11 W.

Chains

9.20 Wash, 30 lks. wide, 4 ft. deep, drains S.; asc. 210 ft. over E. slope, broken.

39.97 Point for the ¼ sec. cor. of secs. 12 and 13.

Set an iron post, 30 ins. long, 2½ ins. diam., 8 ins. in the ground to bedrock, and in a mound of stone, 4 ft. base to top of post, with brass cap mkd.

T14N R11W

¼ S12
S13

1958

Asc. 160 ft. over rocky and broken SE. slope.

61.10 Ridge spur, slopes SSE.; desc. 75 ft. over SW. slope.

65.50 Wash, drains S.; asc. 105 ft. over broken and rocky SE. slope.

68.70 Ridge spur, slopes S.; desc. 155 ft. over rocky and broken SW. slope.

79.94 Point for the cor. of secs. 11, 12, 13 and 14.

Land, rough.
Soil, rocky.
Timber, none.
Undergrowth, creosote bush.

N. 0° 01' W., bet. secs. 11 and 12.

.60 Point selected for the witness cor. of secs. 11, 12, 13 and 14.

Set an iron post, 30 ins. long, 2½ ins. diam. on bedrock, and in a mound of stone, 4½ ft. base to top of pose, with brass cap mkd.

T14N R11W

S11 | S12
S14 | S13

W C

1958

Asc. 300 ft. over rocky S. to SW. slope.

20.90 Ridge, bears S. 80° E. and W.; desc. over broken NE. slope.

40.00 Point for the ¼ sec. cor. of secs. 11 and 12.

Set an iron post, 30 ins. long, 2½ ins. diam., on bedrock, and in a mound of stone, 5 ft. base to top of post, with brass cap mkd.

T14N R11W

¼
S11 | S12

1958

Desc. 210 ft. over broken and rocky NE. to N. Slope.

80.00 Point for the cor. of secs. 1, 2, 11 and 12.

Set an iron post, 30 ins. long, 2½ ins. diam., 18 ins. in the ground, and in a mound of stone, 4 ft. base to top of post, with brass cap mkd.

T14N R11W

S2 | S1
S11 | S12

1958

Subdivision of T. 14 N., R. 11 W.

Chains

Land, rough and broken.
Soil, rocky.
Timber, yellow paloverde and smokethorn.
Undergrowth, creosote bush and buckhorn cholla.

From the cor. of secs. 1, 6, 7 and 12, on the E. bdy. of the Tp., which is monumented with an iron post, 2 ins. diam., set, mkd. and witnessed as described in the official record.

N. 89° 59' W., bet. secs. 1 and 12.

Asc. over gently rolling SE. slope.

2.80 Power transmission line, bears N. 80° E. and S. 80° W.

23.70 Same power transmission line, bears N. 74° W. and S. 74° E.

31.70 Top of ascent, on the S. end of small hill; desc. 40 ft. over W. slope.

35.50 Road, bears N. and S.

36.90 Small wash, drains S.; asc. 25 ft. over rolling E. slope.

39.87 Point for the $\frac{1}{4}$ sec. cor. of secs. 1 and 12.

Set an iron post, 30 ins. long, 2½ ins. diam., 14 ins. in the ground and in a mound of stone, 4½ ft. base to top of post, with brass cap mkd.

T14N R11W

$\frac{1}{4}$ S1
S12
1958

Asc. 250 ft. over E. slope.

59.40 Top of ascent, N. side of hill; desc. 135 ft. to cor. over W. slope.

79.74 The cor. of secs. 1, 2, 11 and 12.

Land, rolling to rough.
Soil, rocky.
Timber, yellow paloverde and smokethorn.
Undergrowth, creosote bush.

N. 0° 17' W., bet. secs. 1 and 2.

Desc. 45 ft. over N. slope.

15.20 Power transmission line, bears S. 74° E. and N. 74° W.

18.60 Road, bears E. and W.; asc. over gently rolling S. slope.

40.00 Point for the $\frac{1}{4}$ sec. cor. of secs. 1 and 2.

Set an iron post, 30 ins. long, 2½ ins. diam., 18 ins. in the ground, and in a collar of stone, with brass cap mkd.

T14N R11W

$\frac{1}{4}$
S2|S1
1958

Subdivision of T. 14 N., R. 11 W.

Chains	
49.50	Asc. 70 ft. over gently rolling S. slope.
79.81	The cor. of secs. 1, 2, 35 and 36, on the N. bdy. of the Tp. Land, rolling. Soil, sandy and rocky. Timber, yellow paloverde, smokethorn and juniper. Undergrowth, creosote bush, Saguaro cactus, ocotillo and jumping and buckhorn cholla.
	From the true point for the cor. of secs. 2, 3, 34 and 35, on the S. bdy. of the Tp., which is witnessed E. 2.00 chs. dist. by an iron post, 2½ ins. diam., previously described. N. 0° 01' W., bet. secs. 34 and 35. Asc. 30 ft. over steep rocky SSW. slope.
.80	Rim of canyon, bears N. 70° W. and S. 70° E.; thence over nearly level land.
2.50	Rim of canyon, bears S. 60° W. and N. 60° E.; desc. 100 ft. over steep rocky NNW. slope.
4.70	Wash, 40 lks. wide, 4 ft. deep, drains SW.; asc. 120 ft. over rocky SSE. slope.
6.40	N. rim of canyon, bears SW. and NE.; asc. 45 ft. over rolling SE. slope.
28.00	N. end of ridge, from the SW.; desc. over gently rolling W. slope.
40.00	Point for the ¼ sec. cor. of secs. 34 and 35. Set an iron post, 30 ins. long, 2½ ins. diam., 8 ins. in the ground, and in a mound of stone, 4 ft. base to top of post, with brass cap mkd. T14N R11W ¼ S34 S35 1958 Over gently rolling W. slope.
80.00	Point for the cor. of secs. 26, 27, 34 and 35. Set an iron post, 30 ins. long, 2½ ins. diam., 14 ins. in the ground, and in a mound of stone, 4½ ft. base to top of post, with brass cap mkd. T14N R11W S27 S26 S34 S35 1958 Land, rolling. Soil, sandy and rocky. Timber, yellow paloverde. Undergrowth, creosote bush and buckhorn cholla.

Subdivision of T. 14 N., R. 11 W.

Chains	
	From the cor. of secs. 25, 26, 35 and 36.
	N. 89° 57' W., bet. secs. 26 and 35.
	Over nearly level land.
4.00	Small wash, drains S.; asc. 115 ft. over rocky E. slope.
12.20	East rim of mesa, bears N. 20° E. and S. 27° W.; thence over nearly level land.
18.50	West rim of mesa, bears N. and S. 10° E.; desc. 190 ft. over rocky W. slope.
24.10	Base of descent, bears SSE. and NNW.; thence over rolling W. slope.
40.00	Point for the $\frac{1}{4}$ sec. cor. of secs. 26 and 35.
	Set an iron post, 30 ins. long, 2½ ins. diam., 6 ins. in the ground, and in a mound of stone, 5 ft. base to top of post, with brass cap mkd.
	T14N R11W S26 $\frac{1}{4}$ S35 1958
	Asc. 30 ft. over E. slope.
58.80	Fence, bears N. and S.
60.90	Low ridge, bears SSW. and NNW.; desc. 50 ft. over W. slope.
80.00	The cor. of secs. 26, 27, 34 and 35.
	Land, rough to rolling. Soil, sandy and rocky. Timber, yellow paloverde. Undergrowth, creosote bush and Saguaro cactus.
	N. 0° 01' W., bet. secs. 26 and 27.
	Over gently rolling land.
29.20	Desc. 55 ft. over N. slope.
32.50	Fence, bears S. 80° W. and N. 80° E.
36.55	Wash, 30 lks. wide, 4 ft. deep, drains S. 70° W.; asc. 35 ft. over S. slope.
40.00	Point for the $\frac{1}{4}$ sec. cor. of secs. 26 and 27.
	Set an iron post, 30 ins. long, 2½ ins. diam., 8 ins. in the ground to bedrock, and in a mound of stone, 4 ft. base to top of post, with brass cap mkd.
	T14N R11W $\frac{1}{4}$ S27 S26 1958
	Asc. 125 ft. over SSW. slope.
53.90	Spur, slopes SW.; desc. 70 ft. over W. to NW. slope.

Subdivision of T. 14 N., R. 11 W.

Chains

67.50

Draw, drains SW.; asc. 145 ft. over SW. slope.

80.00

Point for the cor. of secs. 22, 23, 26 and 27.

Set an iron post, 30 ins. long, 2½ ins. diam., 18 ins. in the ground, and in a mound of stone, with brass cap mkd.

T14N R11W

S22 | S23

S27 | S26

1958

Land, rolling.

Soil, sandy and rocky.

Timber, yellow paloverde.

Undergrowth, creosote bush, buckhorn cholla and ocotilla.

From the cor. of secs. 23, 24, 25 and 26.

N. 89° 55' W., bet. secs. 23 and 26.

Desc. over S. slope.

9.20

Asc. 145 ft. over broken NNE. slope.

40.00

Point for the ¼ sec. cor. of secs. 23 and 26.

Set an iron post, 30 ins. long, 2½ ins. diam., 6 ins. in the ground, to bedrock, and in a mound of stone, 4½ ft. base to top of post, with brass cap mkd.

T14N R11W

¼ S23

S26

1958

Desc. 50 ft. over NNW. slope.

44.50

Wash, 30 lks. wide, 4 ft. deep, drains N.; asc. 320 ft. over broken NE. slope.

62.50

Ridge, bears SE. and NW.; desc. 110 ft. over broken SSW. slope.

80.00

The cor. of secs. 22, 23, 26 and 27.

Land, broken.

Soil, sandy and rocky.

Timber, yellow paloverde.

Undergrowth, creosote bush, buckhorn cholla and ocotillo.

N. 0° 01' W., bet. secs. 22 and 23.

Asc. 20 ft. over S. slope.

8.00

Ridge, bears W. and E.; desc. 90 ft. over N. slope.

34.20

Wash, drains N. 80° W.; asc. 40 ft. over S. slope.

36.90

Spur, slopes W.; desc. 210 ft. over rocky and broken N. slope.

Subdivision, T. 14 N., R. 11 W.

Chains 40.00	Point for the $\frac{1}{4}$ sec. cor. of secs. 22 and 23, falls on series of small ledges, and is unsafe to place the monument.
42.40	Point selected for the witness $\frac{1}{4}$ sec. cor. of secs. 22 and 23. Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., on bedrock, and in a mound of stone, $4\frac{1}{2}$ ft. base to top of post, with brass cap mkd.
	T14N R11W $\frac{1}{4}$ S22 S23 W C 1958
	Desc. 685 ft. over steep rocky and broken N. slope.
65.10	Base of descent, Burro Creek, 2 chs. wide, drains W.; thence across bottom land.
75.04	Recross Burro Creek, drains SSE., 2 chs. wide; asc. 55 ft. over rocky SW. slope.
80.00	Point for the cor. of secs. 14, 15, 22 and 23. Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 8 ins. in the ground and in a mound of stone, 5 ft. base to top of post, with brass cap mkd.
	T14N R11W S15 S14 S22 S23 1958
	Land, rough and broken. Soil, rocky. Timber, yellow paloverde. Undergrowth, creosote bush.
	From the cor. of secs. 13, 14, 23 and 24. N. $89^{\circ} 56'$ W., bet. secs. 14 and 23. Desc. 90 ft. over broken S. to SW. slope.
18.60	Rim of canyon, bears N. and S.; desc. 475 ft. over steep broken and rocky W. slope.
39.98	Point for the $\frac{1}{4}$ sec. cor. of secs. 14 and 23. Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 8 ins. in the ground, and in a mound of stone, $4\frac{1}{2}$ ft. base to top of post, with brass cap mkd.
	T14N R11W $\frac{1}{4}$ S14 S23 1958
	from which The mill of C. P. Zannaras, bears S. $5^{\circ} 03'$ W., 4.56 chs. dist. The bunkhouse, bears S. $64^{\circ} 41'$ W., 6.07 chs. dist.
48.20	Desc. 70 ft. over rocky W. slope. Banzai Wash, 1.50 chs. wide, 5 ft. deep, drains N.; asc. 75 ft. over E. slope.

Subdivision of T. 14 N., R. 11 W.

Chains 62.50	Ridge spur, slopes N.; desc. 220 ft. over broken and rocky W. slope.
79.96	The cor. of secs. 14, 15, 22 and 23. Land, rough. Soil, rocky. Timber, yellow paloverde. Undergrowth, creosote bush, Saguaro cactus, buckhorn cholla and ocotillo.
	N. 0° 01' W., bet. secs. 14 and 15. Asc. 245 ft. over rocky and broken SW. slope.
10.70	Top of ascent, ridge spur, slopes W.; desc. 230 ft. over rocky N. slope.
24.80	Burro Creek, 2 chs. wide, drains S. 75° W.; asc. 165 ft. over rocky S. slope.
36.90	Ridge, bears E. and W.; desc. 35 ft. over N. slope.
40.00	Point for the $\frac{1}{4}$ sec. cor. of secs. 14 and 15. Set an iron post, 30 ins. long, 2 $\frac{1}{2}$ ins. diam., 6 ins. in the ground, and in a mound of stone, 4 ft. base to top of post, with brass cap mkd. T14N R11W $\frac{1}{4}$ S15 S14 1958
	Asc. 65 ft. over S. slope.
47.20	Fence on ridge, bears along ridge, E. and W.; desc. 205 ft. over rolling NW. slope.
80.00	Point for the cor. of secs. 10, 11, 14 and 15. Set an iron post, 30 ins. long, 2 $\frac{1}{2}$ ins. diam., 12 ins. in the ground, and in a mound of stone, 4 ft. base to top of post, with brass cap mkd. T14N R11W S10 S11 S15 S14 1958
	Land, rolling to rough. Soil, sandy and rocky. Timber, yellow paloverde, and catclaw. Undergrowth, creosote bush, buckhorn cholla and ocotilla.
	From the true point for the cor. of secs. 11, 12, 13 and 14. N. 89° 59' W., bet. secs. 11 and 14.
.20	Small wash, drains SE.; asc. 255 ft. over broken and rocky SE. to S. slope.
22.00	Broken ridge spur, slopes S.; desc. 245 ft. over broken S. to SW. slope.
38.96	Point selected for the witness $\frac{1}{4}$ sec. cor. of secs. 11 and 14.

Subdivision of T. 14 N., R. 11 W.

Chains

Set an iron post, 30 ins. long, 2½ ins. diam., on bedrock, and in a mound of stone, 6 ft. base to top of post, with brass cap mkd.

T14N R11W

W. $\frac{1}{4}$ S11

C. $\frac{1}{4}$ S14

1958

39.98 True point for the $\frac{1}{4}$ sec. cor. of secs. 11 and 14, falls in wash, draining SSE.; asc. 65 ft. over rocky S. slope.

55.50 Ridge, bears NNE. and SSW.; desc. 230 ft. over NW. slope.

79.96 The cor. of secs. 10, 11, 14 and 15.

Land, rough and broken.

Soil, rocky.

Timber, yellow paloverde.

Undergrowth, creosote bush and ocotillo.

N. 0° 01' W., bet. secs. 10 and 11.

Desc. 60 ft. over rolling W. slope.

9.05 Wash, 30 lks. wide, 4 ft. deep, drains W.; asc. 145 ft. over SW. slope.

22.70 Ridge spur, slopes SW.; desc. over NW. slope.

30.70 Wash, drains SW.; asc. 150 ft. over broken and rocky SW. slope.

40.00 Point for the $\frac{1}{4}$ sec. cor. of secs. 10 and 11.

Set an iron post, 30 ins. long, 2½ ins. diam., on bedrock, and in a mound of stone, 5 ft. base to top of post, with brass cap mkd.

T14N R11W

$\frac{1}{4}$

S10 | S11

1958

Asc. 100 ft. over steep and rocky S. slope.

44.10 S. rim of bench, bears E. and W.; thence across rocky, level land.

49.80 N. rim of bench, bears W. and N. 80° E.; desc. 400 ft. over rocky NNW. slope.

75.10 Wash, 1 ch. wide, 8 ft. deep, drains W.; asc. S. slope to cor.

80.00 Point for the cor. of secs. 2, 3, 10 and 11.

Set an iron post, 30 ins. long, 2½ ins. diam., 14 ins. in the ground, and in a mound of stone, 5 ft. base to top of post, with brass cap mkd.

T14N R11W

S3 | S2

S10 | S11

1958

Land, rough and broken.

Soil, rocky.

Timber, yellow paloverde and smokethorn.

Undergrowth, creosote bush, ocotillo and buckhorn cholla.

Subdivision of T. 14 N., R. 11 W.

Chains	
	From the cor. of secs. 1, 2, 11 and 12.
	West, bet. secs. 2 and 11.
	Asc. 110 ft. over broken N: to NNE. slope.
12.70	Rocky ridge spur, slopes NNE.; desc. 150 ft. over N. to NNW. slope.
39.52	Point selected for the witness $\frac{1}{4}$ sec. cor. of secs. 2 and 11.
	Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 14 ins. in the ground, and in a mound of stone, $4\frac{1}{2}$ ft. base to top of post, with brass cap mkd.
	T14N R11W W $\frac{1}{4}$ S2 C S11 1958
40.01	True point for the $\frac{1}{4}$ sec. cor. of secs. 2 and 11, falls in small rocky wash; wash drains NNW.; asc. along N. slope.
41.50	Desc. 210 ft. over NW. slope.
69.00	Wash, 1 ch. wide, 6 ft. deep, drains S. 75° W.; asc. along S. slope.
80.02	The cor. of secs. 2, 3, 10 and 11.
	Land, rough.
	Soil, rocky.
	Timber, yellow paloverde and smokethron.
	Undergrowth, creosote bush and buckhorn cholla.
	N. $0^{\circ} 17'$ W., bet. secs. 2 and 3.
	Asc. 155 ft. over SSW. slope.
33.00	Power transmission line, bears S. $78^{\circ} 30'$ E., and N. $78^{\circ} 30'$ W.
40.00	Point for the $\frac{1}{4}$ sec. cor. of secs. 2 and 3.
	Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 16 ins. in the ground, and in a mound of stone to top of post, with brass cap mkd.
	T14N R11W $\frac{1}{4}$ S3 S2 1958
	Asc. 40 ft. over SSW. slope.
48.00	Desc. over NW. slope.
50.00	Wash, 50 lks. wide, 6 ft. deep, drains SW.; asc. 210 ft. over S. slope.
61.90	Road, bears E. and W.
79.60	Same road, bears N. 15° E. and S. 15° W.; desc. over NW. slope to cor.
79.89	The cor. of secs. 2, 3, 34 and 35 on the N. bdy. of the Tp.
	Land, rolling.
	Soil, sandy and rocky.
	Timber, yellow paloverde and juniper.
	Undergrowth, creosote bush, ocotillo, Saguaro cactus and jumping and buckhorn cholla.

Subdivision of T. 14 N., R. 11 W.

Chains	From the cor. of secs. 3, 4, 33 and 34, on the S. bdy. of the Tp. N. 0° 02' W., bet. secs. 33 and 34. Asc. over rocky and broken SW. to W. slope.
2.22	Arizona State Highway No. 93, bears N. 10° W. and S. 10° E.
40.00	Point for the $\frac{1}{4}$ sec. cor. of secs. 33 and 34. Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., on bedrock, and in a mound of stone, 5 ft. base to top of post, with brass cap mkd. T14N R11W $\frac{1}{4}$ S33 S34 1958
80.00	Asc. over SW. to W. slope. Point for the cor. of secs. 27, 28, 33 and 34. Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 8 ins. in the ground to bedrock, and in a mound of stone, 6 ft. base to top of post, with brass cap mkd. T14N R11W S28 S27 S33 S34 1958
	Land, rolling. Soil, rocky. Timber, yellow paloverde and catclaw. Undergrowth, creosote bush, Saguaro cactus, ocotillo.
20.90	From the cor. of secs. 26, 27, 34 and 35. West, bet. secs. 27 and 34. Desc. over W. slope. Wash, drains NNW.; asc. over E. slope.
29.90	Ridge, bears N. and S.; desc. over W. slope.
39.99	Point for the $\frac{1}{4}$ sec. cor. of secs. 27 and 34. Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., on bedrock and in a mound of stone, $4\frac{1}{2}$ ft. base to top of post, with brass cap mkd. T14N R11W $\frac{1}{4}$ S27 S34 1958
79.98	Desc. 237 ft. over W. slope. The cor. of secs. 27, 28, 33 and 34. Land, rolling. Soil, sandy and rocky. Timber, yellow paloverde. Undergrowth, creosote bush, ocotillo, buckhorn cholla and Saguaro cactus.

Subdivision of T. 14 N., R. 11 W.

Chains

N. 0° 02' W., bet. secs. 27 and 28.

.40 Wash, 30 lks. wide, 4 ft. deep, drains SSW.; asc. 155 ft. over rocky SSW. to SW. slope.

24.70 Thence over rolling W. slope to cor.

40.00 Point for the $\frac{1}{4}$ sec. cor. of secs. 27 and 28, falls in small pond.40.80 Point selected for the witness $\frac{1}{4}$ sec. cor. of secs. 27 and 28.Set an iron post, 30 ins. long, 2 $\frac{1}{2}$ ins. diam., 14 ins. in the ground, and in a mound of stone, 4 ft. base to top of post, with brass cap mkd.

T14N R11W

 $\frac{1}{4}$

S28 | S27

W C

1958

Over level land.

45.00 S. rim of small canyon, bears W.; desc. 110 ft. over rocky N. slope.

49.10 Wash in canyon, drains W.; asc. 115 ft. over rocky S. slope.

51.70 N. rim of canyon, bears W.; asc. along rolling W. slope.

80.00 Point for the cor. of secs. 21, 22, 27 and 28.

Set an iron post, 30 ins. long, 2 $\frac{1}{2}$ ins. diam., on bedrock, and in a mound of stone, 4 $\frac{1}{2}$ ft. base to top of post, with brass cap mkd.

T14N R11W

S21 | S22

S28 | S27

1958

Land, rolling.

Soil, sandy and rocky.

Timber, yellow paloverde.

Undergrowth, creosote bush, buckhorn and jumping cholla, ocotilla and Saguaro cactus.

From the cor. of secs. 22, 23, 26 and 27.

West, bet. secs. 22 and 27.

Desc. over SSW. slope.

4.60 Small draw, drains SSW.; thence over rolling S. to SSW. slope.

25.70 Ridge spur, slopes SSW.; desc. over rocky W. slope.

40.00 Point for the $\frac{1}{4}$ sec. cor. of secs. 22 and 27.Set an iron post, 30 ins. long, 2 $\frac{1}{2}$ ins. diam., on bedrock, and in a mound of stone, 4 $\frac{1}{2}$ ft. base to top of post, with brass cap mkd.

T14N R11W

 $\frac{1}{4}$ S22

S27

1958

Desc. over W. slope.

Subdivision of T. 14 N., R. 11 W.

Chains 55.40	Large wash, 40 lks. wide, 8 ft. deep, drains SSW.; asc. over SE. slope.
67.30	Low ridge spur, slopes S.; desc. over W. slope.
80.00	The cor. of secs. 21, 22, 27 and 28. Land, rolling. Soil, sandy and rocky. Timber, yellow paloverde. Undergrowth, creosote bush, buckhorn and jumping cholla, Saguaro cactus and ocotillo.
	N. 0° 02' W., bet. secs. 21 and 22. Over rolling W. slope.
19.70	Small wash, drains SW.; asc. 110 ft. over S. slope.
37.60	Ridge spur, slopes SSW.; desc. 35 ft. over rocky NNW. slope.
40.00	Point for the $\frac{1}{4}$ sec. cor. of secs. 21 and 22. Set an iron post, 30 ins. long, 2 $\frac{1}{2}$ ins. diam., on bedrock, and in a mound of stone, 6 ft. base to top of post, with brass cap mkd. T14N R11W $\frac{1}{4}$ S21 S22 1958
	Desc. 310 ft. over rocky NNW. slope.
46.60	Ledge, bears NNE. and SSW.; 140 ft. high.
53.40	Small draw, drains NNE.; asc. 130 ft. over E. slope.
64.50	Ridge spur, slopes NE.; desc. 310 ft. over NNE. slope.
80.00	Point for the cor. of secs. 15, 16, 21 and 22. Set an iron post, 30 ins. long, 2 $\frac{1}{2}$ ins. diam., 16 ins. in the ground, and in a mound of stone, 4 ft. base to top of post, with brass cap mkd. T14N R11W S16 S15 S21 S22 1958
	Land, rough. Soil, rocky. Timber, yellow paloverde. Undergrowth, creosote bush and ocotillo.
	From the cor. of secs. 14, 15, 22 and 23. N. 89° 58' W., bet. secs. 15 and 22. Desc. 45 ft. over W. slope.
3.50	Burro Creek, 1 ch. wide, drains SSE.; asc. 670 ft. over rocky E. slope.

Subdivision of T. 14 N., R. 11 W.

Chains	
28.70	E. rim of mesa, bears N. and S.; thence over nearly level land.
34.30	W. rim of mesa, bears N. and SSE.; desc. 240 ft. over ledgy W. slope.
40.02	Point for the $\frac{1}{4}$ sec. cor. of secs. 15 and 22. Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 8 ins. in the ground and in a mound of stone, 4 ft. base to top of post, with brass cap mkd.
	T14N R11W $\frac{1}{4}$ $\frac{S15}{S22}$ 1958
	Desc. 135 ft. over rocky SSW. slope.
44.30	Draw, drains SW.; asc. 60 ft. over rocky SSE. slope.
46.30	Desc. 135 ft. over S. slope.
59.60	Steep spur, slopes SW.; desc. 480 ft. over rocky W. slope.
74.40	Burro Creek, 2 chs. wide, drains NW.; asc. 115 ft. over rocky NNE. slope.
80.04	The cor. of secs. 15, 16, 21 and 22. Land, rough, Soil, rocky. Timber, none. Undergrowth, buckhorn and jumping cholla and ocotillo.
	N. $0^{\circ} 02'$ W., bet. secs. 15 and 16. Desc. 120 ft. over NNE. slope.
10.00	Burro Creek, 2 chs. wide, drains W.; asc. 560 ft. over rocky SSE. slope.
37.60	Steep rocky spur, slopes SE.; thence asc. 200 ft. over steep rocky and ledgy E. slope.
40.00	Point for the $\frac{1}{4}$ sec. cor. of secs. 15 and 16 falls on inaccessible slope.
49.61	Point selected for the witness $\frac{1}{4}$ sec. cor. of secs. 15 and 16. Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., on bedrock and in a mound of stone, $4\frac{1}{2}$ ft. base to top of post, with brass cap mkd.
	T14N R11W $\frac{1}{4}$ S16 ↓ S15 W C 1958
	Witness $\frac{1}{4}$ sec. cor. falls on steep rocky spur, slopes NE.; thence desc. over rocky NE. slope.
57.30	Draw, drains E.; asc. over rocky E. to SE. slope.
79.10	Rocky spur, slopes E.; desc. over rocky NE. slope.

Subdivision of T. 14 N., R. 11 W.

Chains	
80.00	<p>Point for the cor. of secs. 9, 10, 15 and 16.</p> <p>Set an iron post, 30 ins. long, 2½ ins. diam., 10 ins. in the ground to bedrock, and in a mound of stone, 4 ft. base to top of post, with brass cap mkd.</p> <p style="text-align: center;">T14N R11W <u>S 9 S10</u> <u>S16 S15</u> 1958</p> <p>Land, rough and broken. Soil, rocky. Timber, none. Undergrowth, buckhorn cholla and ocotillo.</p>
	<p>From the cor. of secs. 10, 11, 14 and 15.</p> <p>N. 89° 56' W., bet. secs. 10 and 15.</p> <p>Desc. 70 ft. over rolling W. slope.</p>
21.20	Wash, 50 lks. wide, 6 ft. deep, drains SSW.; asc. 30 ft. over E. slope.
29.60	N. end of small knob; desc. 40 ft. over W. slope.
38.00	Haley's Wash, 1 ch. wide, 4 ft. deep, drains S.
40.02	<p>Point for the ¼ sec. cor. of secs. 10 and 15.</p> <p>Set an iron post, 30 ins. long, 2½ ins. diam., on bedrock and in a mound of stone, 8 ft. base to top of post, with brass cap mkd.</p> <p style="text-align: center;">T14N R11W ¼ <u>S10</u> <u>S15</u> 1958</p> <p>Asc. over E. slope.'</p>
60.00	Asc. 210 ft. over E. slope.
68.70	Asc. 620 ft. over rocky E. slope.
77.20	Rim rock, bears S. 30° E. and N. 60° W.; asc. over rocky NE. slope.
80.04	<p>The cor. of secs. 9, 10, 15 and 16.</p> <p>Land, rough. Soil, rocky. Timber, only in E. 68.70 chs. dist., yellow paloverde and catclaw. Undergrowth, only in E. 68.70 chs. dist., creosote bush, ocotillo and buckhorn and jumping cholla.</p>
	<p>N. 0° 02' W., bet. secs. 9 and 10.</p> <p>Desc. 120 ft. over rocky N. slope.</p>
1.80	Rim of canyon, bears SE. and NW.; desc. 580 ft. over steep N. slope.
9.60	Draw, drains E.; asc. 390 ft. over broken and rocky SSE. to SE. slope.

Subdivision of T. 14 N., R. 11 W.

Chains	
31.40	Top of ledge and broken rim, bears NE. and SW.; asc. 140 ft. over SSE. slope.
40.00	Point for the $\frac{1}{4}$ sec. cor. of secs. 9 and 10. Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., on bedrock, and in a mound of stone, 5 ft. base to top of post, with brass cap mkd.
	T14N R11W $\frac{1}{4}$ S 9 S10 1958
	Asc. 130 ft. over rocky SSE. slope.
55.70	Top of ascent, in saddle, bears E. and W.; desc. 60 ft. over NW. slope.
63.90	Rocky ridge spur, slopes NW.; desc. 160 ft. over rocky N. slope.
68.30	Rocky ridge spur, slopes NE.; desc. 235 ft. over rocky N. slope.
74.00	Head of small draw, drains NE.; asc. 40 ft. over rocky SSE. slope.
77.80	Rim, bears E. and W.; desc. 30 ft. over N. slope.
79.00	Point selected for the witness cor. of secs. 3, 4, 9 and 10. Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., on bedrock, and in a mound of stone, 5 ft. base to top of post, with brass cap mkd.
	T14N R11W W C S 4 S 3 S 9 S10 1958
79.20	Rim, bears E. and W.; desc. 60 ft. over canyon wall.
80.00	True point for the cor. of secs. 3, 4, 9 and 10 falls on inaccessible slope. Land, rough and broken. Soil, rocky. Timber, yellow paloverde. Undergrowth, creosote bush and ocotillo.
	From the cor. of secs. 2, 3, 10 and 11.
	N. $89^{\circ} 51'$ W., bet. secs. 3 and 10.
	Over rolling S. slope.
20.00	Wash, 2 chs. wide, 5 ft. deep, drains S.
27.00	Wash, 2 chs. wide, 7 ft. deep, drains S.
40.01	Point for the $\frac{1}{4}$ sec. cor. of secs. 3 and 10. Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 14 ins. in the ground and in a mound of stone, 5 ft. base to top of post, with brass cap mkd.

Subdivision of T. 14 N., R. 11 W.

Chains	
	T14N R11W $\frac{1}{4}$ $\frac{S}{S10}$ 1958
	Thence over rolling S. slope.
52.30	Haley's Wash, 4 chs. wide, 8 ft. deep, drains SSE.; asc. 210 ft. over NE. slope.
72.20	Asc. 430 ft. over rocky NE. slope.
80.02	The true point for the cor. of secs. 3, 4, 9 and 10. Land, rolling to rough. Soil, sandy to rocky. Timber, yellow paloverde and catclaw. Undergrowth, creosote bush, ocotillo and Saguaro cactus.
	N. 0° 20' W., bet. secs. 3 and 4. Asc. 75 ft. across small canyon.
2.30	N. rim of canyon, bears W. and N. 75° E.; desc. 20 ft. over rocky NNE. slope.
7.20	Draw, drains E.; asc. 15 ft. over SE. slope.
10.70	Rim, bears E. and W.; desc. 540 ft. over cliff.
12.30	Desc. 170 ft. over N. slope.
23.70	Wash, drains E.
31.90	Haley's Wash, 3 chs. wide, 6 ft. deep, drains SE.; asc. over rolling SE. to E. slope.
40.00	Point for the $\frac{1}{4}$ sec. cor. of secs. 3 and 4. Set an iron post, 30 ins. long, 2½ ins. diam., 12 ins. in the ground, and in a mound of stone, 4 ft. base to top of post, with brass cap mkd. T14N R11W $\frac{1}{4}$ $\frac{S4}{S3}$ 1958
50.50	Power transmission line, bears S. 78° 30' E. and N. 78° 30' W.; asc. 305 ft. over broken and rocky S. slope.
64.00	Rocky spur, slopes SE.; thence over broken E. to SE. slope.
73.50	Top of ascent in saddle, bears NE. and SW.; desc. 65 ft. over rocky NNW. slope.
79.83	The cor. of secs. 3, 4, 33 and 34, on the N. bdy. of the Tp.

Subdivision of T. 14 N., R. 11 W.

Chains

Land, rough.
Soil, sandy to rocky.
Timber, yellow paloverde and catclaw.
Undergrowth, creosote bush, ocotillo, buckhorn cholla and Saguaro cactus.

40.00 From the cor. of secs. 4, 5, 32 and 33, on the S. bdy. of the Tp.
N. 0° 02' W., bet. secs. 32 and 33.

Desc. 135 ft. over NNE. slope.

Point for the $\frac{1}{4}$ sec. cor. of secs. 32 and 33.

Set an iron post, 30 ins. long, 2 $\frac{1}{2}$ ins. diam., on bedrock, and in a mound of stone, 5 ft. base to top of post, with brass cap mkd.

T14N. R11W

$\frac{1}{4}$

S32 | S33

1958

Cor. falls at the head of small wash, wash drains NNE.; desc. 25 ft. over NNE. slope.

51.60 Black Wash, 1.50 chs. wide, 6 ft. deep, drains NW.; asc. 40 ft. over SSW. slope.

80.00 Point for the cor. of secs. 28, 29, 32 and 33.

Set an iron post, 30 ins. long, 2 $\frac{1}{2}$ ins. diam., on bedrock and in a mound of stone, 4 $\frac{1}{2}$ ft. base to top of post, with brass cap mkd.

T14N R11W

S29 | S28

S32 | S33

1958

Land, rolling.
Soil, sandy.
Timber, yellow paloverde and catclaw.
Undergrowth, creosote bush, buckhorn cholla, ocotilla and Saguaro cactus.

From the cor. of secs. 27, 28, 33 and 34.

N. 89° 59' W., bet. secs. 28 and 33.

.20 Wash, drains SW.; desc. 215 ft. over rocky SW. to W. slope.

39.00 Wash, 30 lks. wide, 4 ft. deep, drains SW.

39.98 Point for the $\frac{1}{4}$ sec. cor. of secs. 28 and 33.

Set an iron post, 30 ins. long, 2 $\frac{1}{2}$ ins. diam., 14 ins. in the ground and in a mound of stone, 3 $\frac{1}{2}$ ft. base to top of post, with brass cap mkd.

T14N R11W

$\frac{1}{4}$ S28

S33

1958

Subdivision of T. 14 N., R. 11 W.

Chains	
43.30	Old fence line, bears N. and S.
44.80	Wash, drains SSW.; desc. 100 ft. over S. to SW. slope.
59.10	Fence, bears N. 45° W. and S. 45° E.
60.80	Arizona State Highway No. 93, bears N. 45° W. and S. 45° E.; thence over nearly level land.
79.96	The cor. of secs. 28, 29, 32 and 33.
	Land, rolling. Soil, sandy to rocky. Timber, yellow paloverde. Undergrowth, creosote bush, ocotillo and Saguaro cactus.
	N. 0° 02' W., bet. secs. 28 and 29.
	Asc. 70 ft. over SW. slope.
31.30	Arizona State Highway No. 93, bears N. 45° W. and S. 45° E.
34.10	Fence, bears N. 45° W. and S. 45° E.
40.00	Point for the $\frac{1}{4}$ sec. cor. of secs. 28 and 29.
	Set an iron post, 30 ins. long, 2½ ins. diam., 16 ins. in the ground, and in a mound of stone, 3½ ft. base to top of post, with brass cap mkd.
	<div style="text-align: center;"> T14N R11W $\frac{1}{4}$ S29 S28 1958 </div>
	Asc. 160 ft. over SW. to W. slope.
75.60	Wash, drains SW.; asc. 20 ft. over SW. slope.
80.00	Point for the cor. of secs. 20, 21, 28 and 29.
	Set an iron post, 30 ins. long, 2½ ins. diam., 8 ins. in the ground, and in a mound of stone, 4 ft. base to top of post, with brass cap mkd.
	<div style="text-align: center;"> T14N R11W <u>S20 S21</u> S29 S28 1958 </div>
	Land, rolling. Soil, sandy to rocky. Timber, yellow paloverde. Undergrowth, creosote bush, ocotillo, buckhorn cholla and Saguaro cactus.
	From the cor. of secs. 21, 22, 27 and 28.
	West, bet. secs. 21 and 28.
	Desc. 65 ft. over W. slope.

Subdivision of T. 14 N., R. 11 W.

Chains

- 23.90 Wash, 30 lks. wide, 4 ft. deep, drains SW.; thence over broken S. slope.
- 32.10 Small wash, drains S.; asc. 55 ft. over SE. slope.
- 39.96 Point for the $\frac{1}{4}$ sec. cor. of secs. 21 and 28.
Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 14 ins. in the ground and in a mound of stone, $3\frac{1}{2}$ ft. base to top of post, with brass cap mkd.
- T14N R11W
 $\frac{1}{4}$ $\frac{S21}{S28}$
1958
- 40.20 Ridge spur, slopes S.; desc. 74 ft. over SSW. to SW. slope.
- 64.00 Slope changes to W.; desc. 140 ft.
- 75.40 Wash, 30 lks. wide, 4 ft. deep, drains SW.; thence over rolling S. slope.
- 79.92 The cor. of secs. 20, 21, 28 and 29.
Land, rolling to rough.
Soil, sandy and rocky.
Timber, yellow paloverde.
Undergrowth, creosote bush, ocotillo and Saguaro cactus.
-
- N. $0^{\circ} 02'$ W., bet. secs. 20 and 21.
Asc. 190 ft. over rolling W. to S. slope.
- 32.80 Rim, bears E. and W.; desc. over cliff, 390 ft.
- 40.00 Point for the $\frac{1}{4}$ sec. cor. of secs. 20 and 21.
Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 16 ins. in the ground and in a mound of stone, $3\frac{1}{2}$ ft. base to top of post, with brass cap mkd.
- T14N R11W
 $\frac{1}{4}$
S20 | S21
1958
- Thence over nearly level land.
- 50.30 Desc. 295 ft. over rocky N. slope.
- 64.00 Base of descent, bears NW. and SE.; thence over rocky bottom land.
- 78.55 Burro Creek, 2.70 chs. wide, drains NW.
- 80.00 Point for the cor. of secs. 16, 17, 20 and 21, falls in flood area of Burro Creek.
Land, rough.
Soil, rocky.
Timber, yellow paloverde.
Undergrowth, creosote bush.

Subdivision of T. 14 N., R. 11 W.

Chains	From the cor. of secs. 15, 16, 21 and 22. S. 89° 57' W., bet. secs. 16 and 21. Desc. 60 ft. over N. to NW. slope.
15.90	Burro Creek, 2 chs. wide, drains SSW.; asc. 215 ft. over rough and broken SE. slope.
27.80	Ridge spur, slopes S.; desc. 60 ft. over SW. slope.
39.99	Point for the $\frac{1}{4}$ sec. cor. of secs. 16 and 21. Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., on bedrock and in a mound of stone, $4\frac{1}{2}$ ft. base to top of post, with brass cap mkd. T14N R11W $\frac{1}{4}$ S16 S21 1958
	Desc. 420 ft. over SW. slope.
73.40	Base of steep descent, bears NNW. and SSE.; thence over nearly level land to cor.
79.98	The true point for the cor. of secs. 16, 17, 20 and 21. Land, rough. Soil, rocky. Timber, yellow paloverde and catclaw. Undergrowth, creosote bush, ocotillo and Saguaro cactus.
	N. 0° 02' W., bet. secs. 16 and 17.
1.30	Point selected for the witness cor. of secs. 16, 17, 20 and 21. Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 20 ins. in the ground, and in a mound of stone, 6 ft. base to top of post, with brass cap mkd. T14N R11W S17 S16 S20 S21 W C 1958
	Thence over bottom land.
24.10	Leave bottom land, asc. 285 ft. over rocky SSW. slope.
40.00	Point for the $\frac{1}{4}$ sec. cor. of secs. 16 and 17. Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 10 ins. in the ground, and in a mound of stone, 4 ft. base to top of post, with brass cap mkd. T14N R11W $\frac{1}{4}$ S17 S16 1958
	Asc. 195 ft. over rocky SW. slope.
47.30	Ridge spur, slopes W.; desc. 390 ft. over rocky NW. slope.
72.70	Wash, 40 lks. wide, 4 ft. deep, drains W.; asc. over rocky W. slope.

Subdivision of T. 14 N., R. 11 W.

Chains

80.00

Point for the cor. of secs. 8, 9, 16 and 17.

Set an iron post, 30 ins. long, 2½ ins. diam., 13 ins. in the ground, and in a mound of stone, 3½ ft. base to top of post, with brass cap mkd.

T14N R11W
S8 | S9
 S17 | S16
 1958

Land, rough.

Soil, S. 24.10 chs. dist. sandy, remainder rocky.

Timber, yellow paloverde and catclaw.

Undergrowth, creosote bush, ocotillo and Saguaro cactus.

From the cor. of secs. 9, 10, 15 and 16.

West, bet. secs. 9 and 16.

Asc. 55 ft. over rocky N. slope.

4.50 Top of ascent, thence over broken N. slope.

10.90 Draw, drains N.; asc. 330 ft. over rocky N. to NE. slope.

37.00 Ridge, bears NNW. and SSE.; desc. over W. slope.

40.00 Point for the ¼ sec. cor. of secs. 9 and 16.

Set an iron post, 30 ins. long, 2½ ins. diam., on bedrock, and in a mound of stone, 4 ft. base to top of post, with brass cap mkd.

T14N R11W
S 9
 ¼ S16
 1958

Desc. over rocky W. slope.

45.00 Desc. over rim of cliff 320 ft. high.

49.70 Desc. 270 ft. over rocky W. slope.

80.00 The cor. of secs. 8, 9, 16 and 17.

Land, rough and broken.

Soil, rocky.

Timber, yellow paloverde.

Undergrowth, creosote bush, ocotillo and Saguaro cactus.

N. 0° 02' W., bet. secs. 8 and 9.

Over W. slope.

10.30 Wash, 40 lks. wide, 6 ft. deep, drains W.; asc. 355 ft. over rocky SSW. to SW. slope.

Subdivision of T. 14 N., R. 11 W.

Chains	
36.10	Ridge spur, slopes W.; desc. over rocky NW. slope.
40.00	Point for the $\frac{1}{4}$ sec. cor. of secs. 8 and 9. Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 12 ins. in the ground and in a mound of stone, 4 ft. base to top of post, with brass cap mkd. T14N R11W $\frac{1}{4}$ S8 S9 1958 Asc. along broken SW. slope, 135 ft.
54.00	Top of cliff, 270 ft. high, bears NNW. and SSE.
70.60	Desc. 230 ft. over cliff, bears E. and W., thence over broken N. slope.
77.00	Large rock, bears N., 3 chs. wide, 10.60 chs. long, 295 ft. high.
80.00	Point for the cor. of secs. 4, 5, 8 and 9 falls on inaccessible slope. Land, rough. Soil, rocky. Timber, yellow paloverde. Undergrowth, creosote bush, ocotillo, buckhorn cholla and Saguaro cactus.
	From the true point for the cor. of secs. 3, 4, 9 and 10. S. $89^{\circ} 57'$ W., bet. secs. 4 and 9. Asc. 40 ft. over ledge.
1.80	Leave small canyon,, asc. 60 ft. over NE. slope.
5.00	Low spur, slopes NE.; asc. 140 ft. over NNE. to N. slope.
21.30	Top of ascent, in saddle, bears N. and S.; desc. 130 ft. over rocky NW. slope.
40.02	Point for the $\frac{1}{4}$ sec. cor. of secs. 4 and 9. Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., on bedrock, and in a mound of stone, 4 ft. base to top of post, with brass cap mkd. T14N R11W $\frac{1}{4}$ $\frac{S4}{S9}$ 1958 Asc. 130 ft. over NE. slope.
50.00	Top of ascent, low flat spur, slopes N.; desc. 240 ft. over broken N. slope.
64.90	Desc. 275 ft. over broken and rocky W. slope.
72.80	Small draw, drains N.; asc. 45 ft. over E. slope.
79.10	Large rock, bears N. and S.
80.04	True point for the cor. of secs. 4, 5, 8 and 9.

Subdivision of T. 14 N., R. 11 W.

Chains

Land, rough and broken.
Soil, rocky.
Timber, yellow paloverde.
Undergrowth, creosote bush, ocotillo, jumping and buckhorn cholla and Saguaro cactus.

From the true point for the cor. of secs. 4, 5, 8 and 9.

N. 0° 19' W., bet. secs. 4 and 5.

Over broken top of large rock.

7.00 Desc. 230 ft. over N. face of rock.

7.43 Point selected for the witness cor. of secs. 4, 5, 8 and 9.

Set an iron post, 30 ins. long, 2½ ins. diam., on bedrock, and in a mound of stone, 4 ft. base to top of post, with brass cap mkd.

T14N R11W
S5|S4
S8|S9
W C
1958

Desc. 105 ft. over ledgy N. slope.

9.40 Wash, 1 ch. wide, 6 ft. deep, drains S. 80° W.; asc. 90 ft. over rocky SE. slope.

16.40 Rocky spur, slopes E.; desc. over rocky NE. slope.

31.20 Wash, 1 ch. wide, 5 ft. deep, drains SSE.; asc. over SW. slope.

40.00 Point for the ¼ sec. cor. of secs. 4 and 5.

Set an iron post, 30 ins. long, 2½ ins. diam., on bedrock, and in a mound of stone, 4 ft. base to top of post, with brass cap mkd.

T14N R11W
¼
S5|S4
1958

Asc. 150 ft. over steep and rocky SW. slope.

45.50 Rim of canyon, bears SE. and NW.; asc. over rocky W. slope.

56.20 Spur, slopes W.; thence over broken W. slope.

79.81 The true point for the cor. of secs. 4, 5, 32 and 33, on the N. bdy. of the Tp.

Land, rough.
Soil, rocky.
Timber, none.
Undergrowth, creosote bush, ocotillo and Saguaro cactus.

From the cor. of secs. 5, 6, 31 and 32, on the S. bdy. of the Tp.

N. 0° 03' W., bet. secs. 31 and 32.

Desc. 135 ft. over NNE. slope.

Subdivision of T. 14 N., R. 11 W.

Chains

40.00 Point for the $\frac{1}{4}$ sec. cor. of secs. 31 and 32.
Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 26 ins. in the ground and in a collar of stone, with brass cap mkd.

T14N R11W

$\frac{1}{4}$

S31|S32

1958

Raise a mound of stone, 3 ft. base, 2 ft. high, W. of cor.

Desc. 85 ft. over NNE. slope.

53.70 Wash, drains NE.; asc. 40 ft. over SE. slope.

56.30 Ridge spur, slopes NE.; desc. 140 ft. over N. slope.

80.00 Point for the cor. of secs. 29, 30, 31 and 32.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground with brass cap mkd.

T14N R11W

S30|S29

S31|S32

1958

Set a railroad rail, 6 ft. long, 4 ft. above ground, W. of cor.

Land, rolling.

Soil, sandy.

Timber, yellow paloverde and catclaw.

Undergrowth, creosote bush.

From the cor. of secs. 28, 29, 32 and 33.

West, bet. secs. 29 and 32.

Desc. 70 ft. over SW. slope.

23.60 Black wash, 1.70 chs. wide, 4 ft. deep, drains NW.; asc. 35 ft. over NE. slope.

39.99 Point for the $\frac{1}{4}$ sec. cor. of secs. 29 and 32.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 12 ins. in the ground and in a mound of stone, $4\frac{1}{2}$ ft. base to top of post, with brass cap mkd.

T14N R11W

$\frac{1}{4}$ S29

S32

1958

Thence over N. slope.

49.00 Wash, 30 lks. wide, 4 ft. deep, drains NNE.; asc. 75 ft. over NNE. slope.

79.98 The cor. of secs. 29, 30, 31 and 32.

Land, rolling.

Soil, sandy.

Timber, yellow paloverde and catclaw.

Undergrowth, creosote bush.

Subdivision of T. 14 N., R. 11 W.

Chains

West, bet. secs. 30 and 31.

Over N. slope.

8.20 Small ridge, bears NNE.; thence over broken N. slope.

40.00 Point for the $\frac{1}{4}$ sec. cor. of secs. 30 and 31, falls in wash, 40 lks. wide, 3 ft. deep, drains NNE.

40.54 Point selected for the witness $\frac{1}{4}$ sec. cor. of secs. 30 and 31.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 22 ins. in the ground and in a collar of stone, with brass cap mkd.

T14N R11W

$\frac{1}{4}$ S30 W
S31 C
1958

Asc. over rolling N. slope.

69.70 Asc. over 50 ft. E. slope.

73.10 Ridge, bears N. and S.; desc. over W. slope.

74.57 Intersect E. bdy. of sec. 25, T. 14 N., R. 12 W.

Point for the closing cor. of secs. 30 and 31.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 14 ins. in the ground and in a mound of stone, 5 ft. base to top of post, with brass cap mkd.

T14N

R12W R11W

S25 | S30 C
S31 C
1958

From this closing cor. the cor. of secs. 25 and 36, T. 14 N., R. 12 W. bears S. 3.36 chs. dist. and is monumented with an iron post, 2 ins. diam., set, mkd. and witnessed as described in the official record.

Land, rolling.

Soil, sandy.

Timber, yellow paloverde.

Undergrowth, creosote bush, ocotillo and buckhorn cholla.

Point for the W. $\frac{1}{4}$ sec. cor. of sec. 31, at midpoint on the W. bdy. of the sec.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 20 ins. in the ground and in a mound of stone to top of post, with brass cap mkd.

T14N

R12W R11W

$\frac{1}{4}$
| S31
1958

From this point the E. $\frac{1}{4}$ sec. cor. of sec. 36, T. 14 N., R. 12 W., bears S. 3.36 chs. dist., and is monumented with an iron post, 1 in. diam., set, mkd. and witnessed as described in the official record.

Subdivision of T. 14 N., R. 11 W.

Chains	From the cor. of secs. 29, 30, 31 and 32.
	N. 0° 03' W., bet. secs. 29 and 30.
	Desc. 120 ft. over rolling NE. slope.
27.20	Wash, 30 lks. wide, 7 ft. deep, drains NE.; asc. 60 ft. over SE. slope.
37.50	Ridge spur, slopes E.; thence over E. slope.
40.00	Point for the $\frac{1}{4}$ sec. cor. of secs. 29 and 30.
	Set an iron post, 30 ins. long, 2½ ins. diam., 8 ins. in the ground and in a mound of stone, 5 ft. base to top of post, with brass cap mkd.
	T14N R11W $\frac{1}{4}$ S30 S29 1958
	Desc. 105 ft. over NE. slope.
56.90	Black Wash, 2 chs. wide, 3 ft. deep, drains NW.; asc. 165 ft. over rocky SW. slope.
67.50	N. rim of canyon, bears E. and W.; thence over rolling SW. slope.
80.00	Point for the cor. of secs. 19, 20, 29 and 30.
	Set an iron post, 30 ins. long, 2½ ins. diam., 8 ins. in the ground, and in a mound of stone, 4 ft. base to top of post, with brass cap mkd.
	T14N R11W S19 S20 S30 S29 1958
	Land, rolling to broken. Soil, sandy and rocky. Timber, yellow paloverde and catclaw. Undergrowth, creosote bush, ocotillo and Saguaro cactus.
	From the cor. of secs. 20, 21, 28 and 29.
	S. 89° 56' W., bet. secs. 20 and 29.
	Desc. 125 ft. over rocky SW. slope.
22.10	Wash, 30 lks. wide, 5 ft. deep, drains SW.; asc. 20 ft. over rocky SE. slope.
23.00	Desc. 65 ft. over rocky S. slope.
27.80	Fence, bears N. 10° W. and S. 10° E.; base of descent; asc. over rolling SSE. slope.
29.60	Arizona State Highway No. 93, bears N. 10° W. and S. 10° E.

Subdivision of T. 14 N., R. 11 W.

Chains

40.00

Point for the $\frac{1}{4}$ sec. cor. of secs. 20 and 29.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 8 ins. in the ground and in a mound of stone, $4\frac{1}{2}$ ft. base to top of post, with brass cap mkd.

T14N R11W

 $\frac{1}{4}$ $\frac{S20}{S29}$

1958

Desc. 30 ft. over S. slope.

67.00

Wash, 30 lks. wide, 4 ft. deep, drains SW.; thence desc. 80 ft. over SW. slope.

80.00

The cor. of secs. 19, 20, 29 and 30.

Land, rolling.

Soil, sandy and rocky.

Timber, yellow paloverde.

Undergrowth, creosote bush, ocotillo and Saguaro cactus.

West, bet. secs. 19 and 30.

Desc. over W. slope.

15.90

Desc. over rim rock, bears N. and S.; desc. 185 ft. over rocky W. slope.

30.00

Black Wash, 2.50 chs. wide, 4 ft. deep, drains NW.; thence over bottom land.

33.60

Low ridge spur, slopes NE.; thence over bottom land.

40.00

Point for the $\frac{1}{4}$ sec. cor. of secs. 19 and 30.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 28 ins. in the ground, with brass cap mkd.

T14N R11W

 $\frac{1}{4}$ $\frac{S19}{S30}$

1958

Raise a mound of stone, 4 ft. base, 3 ft. high, N. of cor.

Thence over bottom land.

49.30

Burro Creek, 2 chs. wide, 4 ft. deep, drains S. 15° W.; thence over rolling S. slope.

55.30

Fence, bears N. and S.

74.52

Intersect E. bdy. of sec. 24, T. 14 N., R. 12 W.

Point for the closing cor. of secs. 19 and 30.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 22 ins. in the ground and in a collar of stone, with brass cap mkd.

T14N

T12W R11W

S24 $\frac{S19}{S30}$ C

1958

Subdivision of T. 14 N., R. 11 W.

Chains

From this closing cor. the cor. of secs. 24 and 25, T. 14 N., R. 12 W. bears S. 3.36 chs. dist., and is monumented with an iron post, 2 ins. diam., set, mkd. and witnessed as described in the official record.

Deposit broken glass alongside the iron post.

Land, rolling.

Soil, sandy.

Timber, yellow paloverde, catclaw, and mesquite.

Undergrowth, creosote and ocotillo.

Point for the W. $\frac{1}{4}$ sec. cor. of sec. 30, at midpoint and on the W. bdy. of the sec.

At a point 3.36 chs. dist., N. of the E. $\frac{1}{4}$ sec. cor. of sec. 25, T. 14 N., R. 12 W., which is monumented with an iron post, set, mkd. and witnessed as described in the official record.

Set an iron post, 30 ins. long, 2 $\frac{1}{2}$ ins. diam., 22 ins. in the ground, and in a collar of stone, with brass cap mkd.

T14N
R12W R11W
|
 $\frac{1}{4}$
|
S30
1958

From this point the E. $\frac{1}{4}$ sec. cor. of sec. 25, T. 14 N., R. 12 W. bears S. 3.36 chs. dist. and is monumented with an iron post, 1 in. diam., set, mkd. and witnessed as described in the official record.

From the cor. of secs. 19, 20, 29 and 30.

N. 0° 03' W., bet. secs. 19 and 20.

Asc. over rolling W. slope.

12.60 Arizona State Highway No. 93, bears S. 80° E. and N. 80° W.

13.40 Fence, bears S. 80° E. and N. 80° W.

40.00 Point for the $\frac{1}{4}$ sec. cor. of secs. 19 and 20.

Set an iron post, 30 ins. long, 2 $\frac{1}{2}$ ins. diam., 10 ins. in the ground, and in a mound of stone, 4 ft. base to top of post, with brass cap mkd.

T14N R11W
|
 $\frac{1}{4}$
S19 | S20
1958

Desc. over NW. slope.

57.00 S. rim of canyon, bears NE. and SW.; desc. 470 ft. over rim rock to Burro Creek.

59.00 Burro Creek, 2 chs. wide, drains W.; thence in bed of creek.

80.00 Point for the cor. of secs. 17, 18, 19 and 20 falls in Burro Creek and it is unsafe to monument.

Land, rolling.

Soil, rocky; timber, yellow paloverde and smokethorn.

Undergrowth, creosote bush, ocotillo and buckhorn cholla.

Subdivision of T. 14 N., R. 11 W.

Chains

From the true point for the cor. of secs. 16, 17, 20 and 21.

N. 89° 55' W., bet. secs. 17 and 20.

2.20 Burro Creek, 2.70 chs. wide, drains NW.; asc. over rocky NE. slope.

22.00 Asc. 520 ft. over rocky NE. slope.

39.99 Point for the $\frac{1}{4}$ sec. cor. of secs. 17 and 20.

Set an iron post, 30 ins. long, 2 $\frac{1}{2}$ ins. diam., on bedrock, and in a mound of stone, 4 $\frac{1}{2}$ ft. base to top of post, with brass cap mkd.

T14N R11W

$\frac{1}{4}$ S17
S20

1958

45.90 Top of ascent, rim, bears NNW. and SSE.; desc. 155 ft. over W. slope.

74.10 E. rim of canyon, bears N. and S.; desc. 460 ft. over rim of canyon.

79.98 The true point for the cor. of secs. 17, 18, 19 and 20 in Burro Creek.

Land, rough.

Soil, rocky.

Timber, yellow paloverde and catclaw.

Undergrowth, creosote brush, ocotillo, and Saguaro cactus.

West, bet. secs. 18 and 19.

Across Burro Creek, draining S.

3.00 Right bank of Burro Creek, bears N. 10° W. and S.; thence over bottom land of Burro Creek.

7.40 Asc. 490 ft. over rocky E. slope.

14.70 W. rim of canyon, bears N. and S.; desc. over rocky W. slope.

23.80 Road, bears NNW. and SSE.

28.10 Arizona State Highway No. 93, bears N. 20° E. and S. 20° W.

31.70 Asc. over rocky E. slope.

36.30 Top of ascent; desc. over rocky W. slope.

40.00 Point for the $\frac{1}{4}$ sec. cor. of secs. 18 and 19.

Set an iron post, 30 ins. long, 2 $\frac{1}{2}$ ins. diam., 8 ins. in the ground, and in a mound of stone, 5 ft. base to top of post, with brass cap mkd.

T14N R11W

$\frac{1}{4}$ S18
S19

1958

Desc. over W. slope.

62.80 Desc. 110 ft. over rocky W. slope.

Subdivision of T. 14 N., R. 11 W.

Chains

- 69.30 Base of descent; thence over nearly level land.
- 74.28 Intersect E. bdy. of sec. 13, T. 14 N., R. 12 W. of the Tp.
 Point for the closing cor. of secs. 18 and 19.
 Set an iron post, 30 ins. long, 2½ ins. diam., 14 ins. in the ground and in a mound of stone, 3½ ft. base to top of post, with brass cap mkd.
- T14N
 R12W R11W
 S13 | S18 C
 | S19 C
 1958
- From this closing cor. the cor. of secs. 13 and 24, T. 14 N., R. 12 W., bears S. 3.28 chs. dist. and is monumented with an iron post, 2 ins. diam., set, mkd. and witnessed as described in the official record.
- Land, rough to rolling.
 Soil, rocky.
 Timber, yellow paloverde and Saguaro cactus.
 Undergrowth, creosote bush and ocotillo.
-
- Point for the W. ¼ sec. cor. of sec. 19, at midpoint and on the W. bdy. of the sec., falls in wash; therefore, at a point S. 3.32 chs. dist. alongside the ¼ sec. cor. of sec. 24, T. 14 N., R. 12 W., which is monumented with an iron post, 1 in. diam., set, mkd. and witnessed as described in the official record.
- Point selected for the witness ¼ sec. cor. of sec. 19.
 Set an iron post, 30 ins. long, 2½ ins. diam., 6 ins. in the ground, and in a mound of stone, 5 ft. base to top of post, with brass cap mkd.
- T14N
 R12W R11W
 ¼
 ↑ WC
 | S19
 1958
-
- From the true point for the cor. of secs. 17, 18, 19 and 20...
 N. 0° 03' W., bet. secs. 17 and 18.
 Along rocky bottom land.
- 3.20 Point selected for the witness cor. of secs. 17, 18, 19 and 20.
 Set an iron post, 30 ins. long, 2½ ins. diam., on bedrock, and in a mound of stone, 4 ft. base to top of post, with brass cap mkd.
- T14N R11W
 S18 | S17
 S19 | S20
 ↓ WC
 1958

Subdivision of T. 14 N., R. 11 W.

Chains

- 36.10 Burro Creek, 2 chs. wide, drains S. 75° W.; asc. 40 ft. over rocky S. slope.
- 39.08 Point selected for the witness $\frac{1}{4}$ sec. cor. of secs. 17 and 18.
Set an iron post, 30 ins. long, 2½ ins. diam., on bedrock and in a mound of stone, 4½ ft. base to top of post, with brass cap mkd.
- T14N R11W
W C
 $\frac{1}{4}$
S18 | S17
1958
- Asc. 415 ft. over rocky S. slope.
- 40.00 True point for the $\frac{1}{4}$ sec. cor. of secs. 17 and 18 falls on inaccessible slope.
- 56.60 N. rim of canyon, bears S. 80° W. and N. 80° E.; asc. over S. slope.
- 69.60 Asc. 140 ft. over S. slope to cor.
- 80.00 Point for the cor. of secs. 7, 8, 17 and 18.
Set an iron post, 30 ins. long, 2½ ins. diam., 8 ins. in the ground, and in a mound of stone, 4 ft. base to top of post, with brass cap mkd.
- T14N R11W
S7 | S8
S18 | S17
1958
- Land, rough.
Soil, rocky.
Timber, none.
Undergrowth, creosote bush and ocotillo.
-
- From the cor. of secs. 8, 9, 16 and 17.
West, bet. secs. 8 and 17.
Desc. 140 ft. over W. slope.
- 39.99 Point for the $\frac{1}{4}$ sec. cor. of secs. 8 and 17.
Set an iron post, 30 ins. long, 2½ ins. diam., 10 ins. in the ground and in a mound of stone, 4 ft. base to top of post, with brass cap mkd.
- T14N R11W
 $\frac{1}{4}$ S8
S17
1958
- Desc. over W. slope.
- 44.70 Enter Raster Wash, 10 ft. deep, 3 chs. wide, drains W.
- 50.70 Leave wash, drains S.; asc. 580 ft. over rocky E. slope.
- 71.70 Rim, bears N. and S.; top of ascent; desc. 40 ft. over S. slope.
- 79.98 The cor. of secs. 7, 8, 17 and 18.

Subdivision of T. 14 N., R. 11 W.

Chains

Land, rough and broken.
Soil, rocky.
Timber, yellow paloverde.
Undergrowth, creosote bush and ocotillo.

West, bet. secs. 7 and 18.

Desc. 140 ft. over SSW. slope.

7.20 Wash, 40 lks. wide, 6 ft. deep, drains SW.; asc. 335 ft. over SE. slope.

31.40 Top of ascent, spur, slopes SSW.; desc. 55 ft. over SW. slope.

40.00 Point for the $\frac{1}{4}$ sec. cor. of secs. 7 and 18.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., on bedrock, and in a mound of stone, 5 ft. base to top of post, with brass cap mkd.

T14N R11W

$\frac{1}{4}$ $\frac{S 7}{S18}$
1958

Desc. 365 ft. over rocky SW. slope.

56.60 Wash, 12 ft. deep, 60 lks. wide, drains S.; asc. 150 ft. over E. slope.

66.20 Arizona State Highway No. 93, bears N. 18° W. and S. 18° E.

74.21 Intersect E. bdy. of sec. 12, T. 14 N., R. 12 W.

Point for the closing cor. of secs. 7 and 18.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 10 ins. in the ground, and in a mound of stone, 4 ft. base to top of post, with brass cap mkd.

T14N

R12W R11W

S12 $\frac{S 7}{S18}$ C
1958

From this closing cor. the cor. of secs. 12 and 13, T. 14 N., R. 12 W., bears S. 3.21 chs. dist. and is monumented with an iron post, 2 ins. diam., set, mkd. and witnessed as described in the official record.

Land, rough to rolling.
Soil, rocky.
Timber, yellow paloverde.
Undergrowth, creosote bush, ocotillo and Saguaro cactus.

Point for the W. $\frac{1}{4}$ sec. cor. of sec. 18, at midpoint and on the W. bdy. of the sec.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 8 ins. in the ground, and in a mound of stone, 4 ft. base to top of post, with brass cap mkd.

Subdivision of T. 14 N., R. 11 W.

Chains

T14N
R12W R11W
 $\frac{1}{4}$
|S18
1958

From this point the $\frac{1}{4}$ sec. cor. of sec. 13, T. 14 N., R. 12 W. bears S. 3.245 chs. dist. and is monumented with an iron post, 1 in. diam. Set, mkd. and witnessed as described in the official record.

From the cor. of secs. 7, 8, 17 and 18.

N. 0° 03' W., bet. secs. 7 and 8.

Asc. 60 ft. over rocky S. slope.

10.60 Small rocky ridge, bears E. and W.; desc. 55 ft. over rocky N. slope.

15.00 Draw, drains W.; asc. 120 ft. over S. slope.

26.90 Top of ascent, rock rim, bears NW. and SE.; desc. 415 ft. over rim, NE. slope.

40.00 Point for the $\frac{1}{4}$ sec. cor. of secs. 7 and 8.

Set an iron post, 30 ins. long, 2 $\frac{1}{2}$ ins. diam., on bedrock and in a mound of stone, 4 $\frac{1}{2}$ ft. base to top of post; with brass cap mkd.

T14N R11W
 $\frac{1}{4}$
S7|S8
1958

Desc. 130 ft. over rocky NE. slope.

52.30 Wash, 30 lks. wide, 4 ft. deep, drains S. 80° E.; asc. 120 ft. over rocky E. slope.

72.10 Ridge spur, slopes E.; desc. 130 ft. over rocky NE. slope.

80.00 Point for the cor. of secs. 5, 6, 7 and 8.

Set an iron post, 30 ins. long, 2 $\frac{1}{2}$ ins. diam., 18 ins. in the ground and in a mound of stone to top of post, with brass cap mkd.

T14N R11W
S6|S5
S7|S8
1958

Land, rough.

Soil, rocky.

Timber, yellow paloverde.

Undergrowth, creosote bush; ocotillo and Saguaro cactus.

From the true point for the cor. of secs. 4, 5, 8 and 9.

S. 89° 58' W., bet. secs. 5 and 8.

Over broken top of large rock.

Subdivision of T. 14 N., R. 11 W.

Chains	
2.30	W. edge of rock, bears N. and S.; desc. 270 ft. over W. face of rock.
2.30	Base of rock; desc. 120 ft. over W. slope.
15.90	Wash, 1 ch. wide, 5 ft. deep, drains SW.; thence over rolling to broken SSW. slope.
40.02	Point for the $\frac{1}{4}$ sec. cor. of secs. 5 and 8. Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 16 ins. in the ground, and in a mound of stone, 4 ft. base to top of post, with brass cap mkd. T14N R11W $\frac{1}{4}$ $\frac{S5}{S8}$ 1958
40.90	Wash, 40 lks. wide, 3 ft. deep, drains S.; thence over rolling S. slope.
54.30	Raster Wash, 2 chs. wide, 6 ft. deep, drains SSE.; asc. 115 ft. over E. slope.
80.04	The cor. of secs. 5, 6, 7 and 8. Land, rolling to broken. Soil, sandy and rocky. Timber, yellow paloverde and catclaw. Undergrowth, creosote bush.
	West, bet. secs. 6 and 7. Asc. 1260 ft. over rocky and broken E. slope to rim.
40.00	Point for the $\frac{1}{4}$ sec. cor. of secs. 6 and 7. Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 6 ins. in the ground and in a mound of stone, 5 ft. base to top of post, with brass cap mkd. T14N R11W $\frac{1}{4}$ $\frac{S6}{S7}$ 1958
47.15	Rim, bears NW. and SE.; desc. 190 ft. over W. slope.
73.99	Intersect E. bdy. of sec. 1, T. 14 N., R. 12 W. Point for the closing cor. of secs. 6 and 7. Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 10 ins. in the ground and in a mound of stone, 4 ft. base to top of post, with brass cap mkd. T14N R12W R11W S1 $\frac{S6}{S7}$ C 1958 From this closing cor. the cor. of secs. 1 and 12, T. 14 N., R. 12 W. bears S. 3.12 chs. dist. and is monumented by an iron post, 2 ins. diam., set, mkd. and witnessed as described in the official record. Land, rough.

Subdivision of T. 14 N., R. 11 W.

Chains

Soil, rocky.
 Timber, yellow paloverde.
 Undergrowth, creosote bush, ocotillo, jumping cholla and Saguaro cactus.

Point for the W. $\frac{1}{4}$ sec. cor. of sec. 7, at midpoint and on the W. bdy. of the sec.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., on bedrock, and in a mound of stone, 4 ft. base to top of post, with brass cap mkd.

T14N
 R12W R11W
 $\frac{1}{4}$
 |S7
 1958

From this point the $\frac{1}{4}$ sec. cor. of sec. 12, T. 14 N., R. 12 W. bears S. 3.165 chs. dist., and is monumented with an iron post, 1 in. diam., set, mkd. and witnessed as described in the official record.

Point for the W. $\frac{1}{4}$ sec. cor. of sec. 6, at a point 40.00 chs. dist. N. of the closing cor. of secs. 6 and 7, and on the W. bdy. of the Tp.

At the cor. point

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., on bedrock and in a mound of stone, 4 ft. base to top of post, with brass cap mkd.

T14N
 R12W R11W
 $\frac{1}{4}$
 |S6
 1958

From this point the $\frac{1}{4}$ sec. cor. of sec. 1, T. 14 N., R. 12 W., bears S. 3.12 chs. dist. and is monumented with an iron post, 1 in. diam., set, mkd. and witnessed as described in the official record.

From the cor. of secs. 5, 6, 7 and 8.

N. $0^{\circ} 21'$ W., bet. secs. 5 and 6.

- 3.20 Wash, 40 lks. wide, 6 ft. deep, drains E.; asc. 140 ft. over rocky SSW. slope.
- 26.70 Ridge spur, slopes SSE.; desc. 60 ft. over rocky E. to NE. slope.
- 40.00 Point for the $\frac{1}{4}$ sec. cor. of secs. 5 and 6.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 18 ins. in the ground and in a mound of stone, $3\frac{1}{2}$ ft. base to top of post, with brass cap mkd.

Subdivision of T. 14 N., R. 11 W.

Chains

T14N R11W

S6|S5

1958

Desc. 100 ft. E. to NE. slope.

56.70 Wash, 40 lks. wide, 8 ft. deep, drains SSE.; asc. 230 ft. over rocky SW. slope.

79.86 Intersect N. bdy. of the Tp., at the cor. of secs. 5, 6, 31 and 32.

Land, rough.

Soil, sandy and rocky.

Timber, yellow paloverde.

Undergrowth, creosote bush.

General Description

The land within T. 14 N., R. 11 W. is principally broken mesa and rock outcrops.

There is one large canyon extending through the township, Burro Creek, entering on the east boundary of section 13 and draining westerly, leaving on the west boundary of section 30.

Soil is principally a light shallow sand to sandy clay, and rocky. Timber, consists of yellow paloverde, smokethorn, juniper and catclaw. Undergrowth is creosote bush, ocotillo, jumping and buckhorn cholla, yucca and Saguaro cactus.

Arizona State Highway No. 93 enters at the south boundary of section 34 and leaving on the west boundary of section 7. There is one improved dirt road entering the north boundary of section 2 and leaving on the east boundary of section 12.

The only water noted in the township was Burro Creek. There probably are small intermittent seeps along the bottoms of the canyons, although none were noted during the progress of the survey.

CERTIFICATE OF CADASTRAL ENGINEER

I, DeWitt A. Crain, HEREBY CERTIFY upon honor that, in
pursuance of special instructions bearing date of the 29th day of November, 1957,
I have surveyed the south and north boundaries and subdivisional lines of T. 14 N.,
R. 11 W.

of the Gila and Salt Riv Meridian, in the State of Arizona, which are
represented in the foregoing field notes as having been executed by me and under my direction; and that
said survey has been made in strict conformity with said instructions, the Manual of Instructions for the
Survey of the Public Lands of the United States, and in the specific manner described in the foregoing
field notes.

October 30, 1958
Salt Lake City, Utah

DeWitt A. Crain
DeWitt A. Crain - Cadastral Surveyor

CERTIFICATE OF APPROVAL

BUREAU OF LAND MANAGEMENT,
Washington, D. C., FEB 18 1959, 19

The foregoing field notes of the survey of the south and north boundaries and subdivisional
lines, T. 14 N., R. 11 E., Gila and Salt River Meridian, Arizona

executed by DeWitt A. Crain, Cadastral Surveyor
having been critically examined and found correct, are hereby approved.

Earl G. Harrington
Cadastral Engineering Staff Officer.

~~CERTIFICATE OF TRANSCRIPT~~

~~I CERTIFY that the foregoing transcript of the field notes of the above-described surveys in T. 14 N.,
R. 11 W., G. & S. R. Mer., is a true copy of the original field notes.~~

~~Cadastral Engineering Staff Officer.~~