

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

ORIGINAL

FIELD NOTES

OF THE

SUBDIVISION OF

TOWNSHIP 12 NORTH,

RANGE 11 WEST

Of the Gila and Salt River Meridian,

In the State of Arizona

EXECUTED BY

DeWitt A. Crain - Cadastral Surveyor

Under special instructions dated November 17, 1958, which provided
for the surveys included under Group No. 332, approved December 1, 1958
and assignment instructions dated December 18, 1958

Survey commenced January 28, 1959

Survey completed April 9, 1959

BOOK 4571

INDEX DIAGRAM

Township 12 North, Range 11 West

•	41 5	31 4	24 3	16 2	8 1
41	40	31	24	15	8
7	40 8	30 9	23 10	15 11	7 12
39	39	30	22	14	6
18	38 17	29 16	21 15	13 14	6 18
37	37	28	21	13	5
19	36 20	28 21	20 22	12 23	4 24
35	35	27	19	12	4
30	34 29	26 28	19 27	11 26	3 25
33	33	26	18	10	2
31	32 32	25 33	17 34	10 35	1 36

Subdivision of Township 12 North, Range 11 West

Chains

The north boundary of T. 12 N., R. 11 W., the third standard parallel north, was surveyed by A. N. Oliver in 1911, and independently re-surveyed by D. E. Harding in 1958, in connection with the survey of T. 13 N., R. 11 W.. The south boundary of T. 12 N., R. 11 W., was surveyed by L. E. Wilkes in 1917. The east boundary of T. 12 N., R. 11 W., was surveyed by L. E. Wilkes in 1915, and the west boundary was surveyed by Smith and Harding in 1956.

The following field notes are those of the survey of the subdivisional lines of Township 12 North, Range 11 West.

The survey was executed with a W. and L. E. Gurley solar transit, serial number 541328, which conforms to the standard instrumental specification of the Bureau of Land Management. The instrument was maintained in precise adjustment throughout the progress of the survey.

The measurements were made with narrow steel tapes, 8 chains in length, graduated to tenths of links for the first link to links for the next 99 links, and thereafter at intervals of 10 links. The tapes were tested by comparison with a standard steel tape 1 chain in length and found correct. The measurements were made on the slope and the vertical angle of each interval was ascertained by two clinometers in good adjustment. The slope distances were properly reduced to horizontal equivalents which are entered in the field note record.

The geographic position of the southeast corner of this township is in latitude $34^{\circ}19'50''$ N., and longitude $113^{\circ}20'56''$ W., as determined from data furnished with the special instructions.

February 2, 1959, at the corner of secs. 1, 2, 35, and 36, south boundary, T12N R11W., in latitude $34^{\circ}19'50''$ N., and longitude $113^{\circ}22' W.$, at 10 h 23 m, am. mst. I made a series of 6 altitude observations upon the sun for azimuth 3 each with the telescope in direct and reversed positions and observe angle from a flag approximately 1 mile to the SE., to the right of the sun.

Time of observation, 105th meridian standard time.	$10^h 23^m$
Mean observed vertical angle	$28^{\circ}22'$
Horizontal angle to sun	$27^{\circ}23'$
Declination of sun	$16^{\circ}52'26''$
True bearing of section line	N. $0^{\circ}01' W.$

The magnetic declination was read at a number of stations throughout the township and the average of the several readings was found to be $14^{\circ}30' E.$

Beginning at the cor. of secs. 1, 2, 35, and 36, on the south boundary of T. 12 N., R. 11 W., an iron post, set, mkd., and witnessed as described in the official record.

N. $0^{\circ}01' W.$, bet. secs. 35, and 36.

Asc. 140 ft. over SW. slope, through desert vegetation.

10.20 Ridge, bears NW. and SE., desc. 80 ft. NE. slope.

25.20 Wash 4 ft. deep, 90 lks. wide, drains E.; asc. 100 ft. over SW. slope.

31.50 Ridge, bears NW. and SE.; desc. 40 ft. over broken E. slope.

39.50 Small wash, drains E.; asc. over S. slope.

Subdivision of Township 12 North, Range 11 West

Chains

40.00 Point for the $\frac{1}{4}$ sec. cor. of secs. 35, and 36.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 18 ins. in the ground, and in a mound of stone, 4 ft. base, to top of post, with brass cap mkd.

T12N R11W

$\frac{1}{4}$

S 35 | S 36

1959

Asc. 300 ft. over broken SE. slope.

70.20 Ridge, bears E. and W.; desc. 130 ft. over N. slope.

75.70 Wash, 5 ft. deep, 40 lks. wide, drains E.; asc. 50 ft. over steep S. slope.

78.10 Ridge spur, slopes E.; desc. 20 ft. over NE. slope.

80.00 Point for the cor. of secs. 25, 26, 35, and 36.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 22 ins. in the ground, and in a mound of stone, to top of post, with brass cap mkd.

T12N R11W

S 26 | S 25

S 35 | S 36

1959

Land, rough and broken.

Soil, sandy and rocky.

Timber, Yellow Paloverde and Catclaw Acacia.

Undergrowth, Saguaro Cactus, Yucca, and Ocotillo.

From the cor. of secs. 25, 30, 31, and 36, on the E. bdy. of the T., which is monumented with an iron post, set, marked and witnessed as described in the official record.

S. $89^{\circ}47'$ W., bet. secs. 25, and 36.

Asc. 305 ft. over rocky NE. slope; through desert vegetation.

9.30 Top of asc. on N. slope; desc. 280 ft. over rocky NW. slope.

32.10 Deep wash, 40 ft. deep, 90 ft. wide, drains S.; asc. 40 ft. over broken SE. slope.

39.87 Point for the $\frac{1}{4}$ sec. cor. of secs. 25, and 36.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 15 ins. in the ground, and in a mound of stone, to top of post, with brass cap mkd.

T12N R11W

$\frac{1}{4}$ S 25

S 36

1959

Asc. 510 ft. over rocky and broken E. slope.

Subdivision of Township 12 North, Range 11 West

Chains	
51.70	Ridge, bears N. and S.; desc. 490 ft. over rocky and broken W. slope.
72.00	Wash, 6 ft. deep, 110 lks. wide, drains SE.; asc. over SE. slope.
73.20	Ridge spur, slopes SE.; desc. over SW. slope.
76.40	Wash, 5 ft. deep, 130 lks. wide, drains SE.; asc. 80 ft. over NE. slope.
79.74	<p>The cor. of secs. 25, 26, 35, and 36.</p> <p>Land, rough and broken. Soil, sandy and rocky. No timber; undergrowth, Yucca, Saguaro Cactus, and Ocotillo.</p>
	N. 0°01' W., bet. secs. 25, and 26.
	Desc. 40 ft. over NE. slope, through desert vegetation.
2.70	Wash, 4 ft. deep, 30 lks. wide, drains SE.; asc. 70 ft. over broken SE. slope.
11.10	Wash, 3 ft. deep, 40 lks. wide, drains SE.; asc. 420 ft. over rocky and broken SE. slope.
39.00	Ridge, bears E. and W.; desc. 20 ft. over N. slope.
40.00	<p>Point for the $\frac{1}{4}$ sec. cor. of secs. 25, and 26.</p> <p>Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 8 ins. in the ground, and in a mound of stone, 4 ft. base, to top of post, with brass cap mkd.</p>
	<p style="text-align: center;">T12N R11W $\frac{1}{4}$ S 26 S 25 1959</p>
	Desc. 230 ft. over broken NE. slope.
60.30	Wash, 5 ft. deep, 40 lks. wide, drains E.; asc. 100 ft. over rocky and broken SSW. slope.
65.90	Ridge, bears NW. and SE.; desc. 220 ft. over rocky and broken NE. slope.
78.80	<p>Point selected for the witness cor. of secs. 23, 24, 25, and 26.</p> <p>Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 16 ins. in the ground, and in a mound of stone, 4 ft. base, to top of post, with brass cap mkd.</p>
	<p style="text-align: center;">T12N R11W w c S 23 S 24 S 26 S 25 1959</p>
80.00	<p>True point for the cor. of secs. 23, 24, 25, and 26, falls in bottom of wash, wash 10 ft. deep, 100 lks. wide, drains SE., unsafe place to monument.</p>

Subdivision of Township 12 North, Range 11 West

Chains

Land, rough and broken.
Soil, sandy and rocky.
Timber, Yellow Paloverde, and Catclaw Acacia.
Undergrowth, Yucca, Saguaro Cactus, and Ocotillo.

From the cor. of secs. 19, 24, 25, and 30, on the E. bdy. of the T., which is monumented with an iron post, set, marked and witnessed as described in the official record.

S. 89°46' W., bet. secs. 24, and 25.

Desc. 200 ft. over rough and broken W. slope, through desert vegetation.

17.50 Wash, 5 ft. deep, 40 lks. wide, drains S.; thence over broken S. slope.

22.10 Same wash, 6 ft. deep, 40 lks. wide, drains S.; asc. 100 ft, over rocky E. slope.

29.50 Ridge, bears N. and S.; thence desc. 110 ft. over rocky and broken SW. slope.

39.93 True point for the $\frac{1}{4}$ sec. cor. of secs. 24, and 25, falls in wash, wash 4 ft. deep, 30 lks. wide, drains S.; unsafe place to monument.

40.03 Point selected for the witness $\frac{1}{4}$ sec. cor. of secs. 24, and 25.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 10 ins. in the ground, and in a mound of stone, $3\frac{1}{2}$ ft. base, to top of post, with brass cap mkd.

T12N R11W

$\frac{1}{4}$ $\frac{S\ 24\ W}{S\ 25\ C}$

1959

Thence desc. over rough and broken SW. slope.

79.86 True point for the cor. of secs. 23, 34, 25, and 26.

Land, rough and broken.
Soil, sandy and rocky.
Timber, Catclaw Acacia, and Yellow Paloverde.
Undergrowth, Yucca, Ocotillo, Saguaro Cactus, and Creosote brush.

N. 0°01' W.; bet. secs. 23, and 24.

Asc. 265 ft. over rocky S. slope; through desert vegetation.

16.10 Ridge spur, slopes W.; asc. 240 ft. over rough and broken S. to SW. slope.

38.40 Ridge spur, slopes SE.; desc. 40 ft. over NE. slope.

40.00 True point for the $\frac{1}{4}$ sec. cor. of secs. 23, and 24, falls in small wash, wash drains E.; unsafe place to monument.

40.56 Point selected for the witness $\frac{1}{4}$ sec. cor. of secs. 23, and 24.

Subdivision of Township 12 North, Range 11 West

Chains

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., on bedrock, and in a mound of stone, 3 ft. base, to top of post, with brass cap mkd.

T12N R11W
 $\frac{1}{4}$
 S 23 | S 24
 ↓
 w c
 1959

Witness cor. falls in small ridge spur, slopes E., asc. 290 ft. over rough and broken S. slope.

69.20 Ridge spur, slopes SE.; desc. 50 ft. over NE. slope.

80.00 True point for the cor. of secs. 13, 14, 23, and 24, falls in small draw, draw drains E. to NE.; unsafe place to monument.

Land, rough and broken.

Soil, sandy and rocky.

Timber, Yellow Paloverde.

Undergrowth, Saguaro Cactus, Yucca, Creosote brush, and Ocotillo.

From the cor. of secs. 13, 18, 19, and 24, on the E. bdy. of the T., which is monumented with an iron post, set, marked and witnessed as described in the official record.

S. $89^{\circ}41'$ W., bet. secs. 13, and 24.

Desc. 115 ft. over rough and broken SW. slope, through desert vegetation.

39.91 Point for the $\frac{1}{4}$ sec. cor. of secs. 13, and 24.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 18 ins. in the ground, and in a mound of stone, 3 ft. base, to top of post, with brass cap mkd.

T12N R11W
 $\frac{1}{4}$ S 13
 S 24
 1959

Asc. 160 ft. over rocky and broken SE. slope.

50.00 Ridge spur, slopes SSW.; desc. 190 ft. over rough and broken N.W. slope.

66.60 Wash, 4 ft. deep, 2 chs. wide, drains S.; asc. 170 ft. over rocky NE. slope.

79.82 True point for the cor. of secs. 13, 14, 23, and 24.

Land, rough and broken.

Soil, sandy and rocky.

Timber, Catclaw.

Undergrowth, Yucca, Creosote brush, and Ocotillo.

Subdivision of Township 12 North, Range 11 West

Chains

N. 0°01' W., bet. secs. 13, and 14.

Desc. over broken NE. slope.

.49 Point selected for the witness cor. of secs. 13, 14, 23, and 24.

Set an iron post, 30 ins. long, 2½ ins. diam., 12 ins. in the ground, and in a mound of stone, to top of post, with brass cap mkd.

T12N	R11W
S 14	S 13
S 23	S 24
w c	
1959	

Desc. 100 ft. over rough and broken E. to NE. slope; through desert vegetation.

40.00 Point for the ¼ sec. cor. of secs. 13, and 14.

Set an iron post, 30 ins. long, 2½ ins. diam., on bedrock, and in a mound of stone, 4 ft. base, to top of post, with brass cap mkd.

T12N	R11W
¼	
S 14	S 13
1959	

Asc. 40 ft. over rocky SE. slope.

41.30 Ridge spur, slopes, E. by SE.; thence over rough, rocky, and broken NE. to E. slope.

54.30 Deep draw, 6 ft. deep, 30 lks. wide, drains SE.; asc. 60 ft. over rocky and broken SW. slope.

60.10 Rocky ridge spur, slopes SW.; desc. 40 ft. over broken W. to NW. slope.

71.10 Draw, 3 ft. deep, 30 lks. wide, drains SW.; asc. 170 ft. over broken and rocky S. slope.

80.00 True point for the cor. of secs. 11, 12, 13, and 14, falls on rocky outcrop, impossible to monument.

Land, rough and broken.

Soil, rocky.

Timber, Yellow Paloverde, and Catclaw Acacia.

Undergrowth, Saguaro Cactus, Yucca, and Ocotillo.

From cor. of secs. 7, 12, 13, and 18, on the E. bdy. of the T., which is monumented with an iron post, set, mkd., and witnessed as described in the official record.

S. 89°47' W., bet. secs. 12, and 13.

4.30 Asc. 40 ft. over rocky E. slope; through desert vegetation. Small ridge spur, slopes N.; desc. 310 ft. over rough and broken SW. slope.

22.20 Draw, 4 ft. deep, 30 lks. wide, drains SW.; asc. 220 ft. over rocky and broken SE. slope.

Subdivision of Township 12 North, Range 11 West

Chains

- 24.40 Ridge spur, slopes SW.; desc. over rocky and broken SW. slopes.
 28.20 Draw, drains SSE.; asc. 165 ft. over rocky and broken NE. slope.
 38.90 Ridge, bears NW. and SE.; desc. over rocky and broken SW. slope.
 39.93 Point for the $\frac{1}{4}$ sec. cor. of secs. 12, and 13.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 10 ins. in the ground, and in a mound of stone, 4 ft. base, to top of post, with brass cap mkd.

T12N R11W

$$\frac{1}{4} \begin{array}{c} S 12 \\ S 13 \end{array}$$

1959

Thence over rough and broken S. slope.

- 79.86 True point for the cor. of secs. 11, 12, 13, and 14.

Land, rough and broken.

Soil, sandy and rocky.

Timber, Catclaw Acacia, and Yellow Paloverde.

Undergrowth, Saguaro Cactus, Yucca, and Ocotillo.

N. 0°01' W., bet. secs. 11, and 12.

- .05 Point selected for the witness cor. of secs. 11, 12, 13, and 14.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 16 ins. in the ground, and in a mound of stone, 3 ft. base, to top of post, with brass cap mkd.

T12N R11W

$$\begin{array}{c} S 11 | S 12 \\ S 14 | S 13 \\ \downarrow \\ w c \end{array}$$

1959

Asc. 370 ft. over rough and broken SSE. slope; through desert vegetation.

- 29.80 Ridge spur, slopes SE.; asc. 70 ft. over broken E. slope.

- 37.60 Ridge spur, slopes NE.; desc. over rocky N. slope.

- 40.00 Point for the $\frac{1}{4}$ sec. cor. of secs. 11, and 12.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 15 ins. in the ground, and in a mound of stone, to top of post, with brass cap mkd.

T12N R11W

$$\frac{1}{4} \begin{array}{c} S 11 | S 12 \end{array}$$

1959

Desc. 40 ft. over N. slope.

- 41.80 Draw, drains NW.; asc. 40 ft. over SW. slope.

Subdivision of Township 12 North, Range 11 West

Chains	
47.80	Ridge, bears W. and NE.; desc. 110 ft. over NW. slope.
71.00	Draw, drains W.; asc. 60 ft. over rocky S. slope.
79.00	Point selected for the witness cor. of secs. 1, 2, 11, and 12.
	Set an iron post, 30 ins. long, 2½ ins. diam., on bedrock, and in a mound of stone, 4 ft. base, to top of post, with brass cap mkd.
	<p style="text-align: center;">T12N R11W W C S 2 S 1 S 11 S 12 1959</p>
80.00	True point for the cor. of secs. 1, 2, 11, and 12, falls in small draw, draw drains SW.; unsafe place to monument.
	<p>Land, rough and broken. Soil, sandy and rocky. Timber, Yellow Paloverde, and Catclaw Acacia. Undergrowth, Yucca, Saguaro Cactus, and Ocotillo.</p>
	<p>From the cor. of secs. 1, 6, 7, and 12, on the E. bdy. of the T., which is monumented with an iron post, set, marked and witnessed as described in the official record.</p>
	S. 89°40' W., bet. secs. 1, and 12.
	Asc. over rough and broken NNE. slope; through desert vegetation.
39.95	Point for the ¼ sec. cor. of secs. 1, and 12.
	Set an iron post, 30 ins. long, 2½ ins. diam., on bedrock, and in a mound of stone, 4 ft. base, to top of post, with brass cap mkd.
	<p style="text-align: center;">T12N R11W ¼ S 1 S 12 1959</p>
	Asc. over rough and broken NNE. slope.
52.00	Saddle, bears NW. and SE.; asc. 110 ft. over rough and broken S. slope.
69.20	Ridge spur, slopes SW.; desc. 165 ft. over rough and broken W. to SW. slope.
79.90	True point for the cor. of secs. 1, 2, 11, and 12.
	<p>Land, rough and broken. Soil, sandy and rocky. Timber, Juniper, Yellow Paloverde, and Catclaw Acacia. Undergrowth, Yucca, Saguaro Cactus, and Ocotillo.</p>
	N. 0°01' W., bet. secs. 1, and 2.
	Asc. 620 ft. over rough and broken S. slope; through desert vegetation.

Subdivision of Township 12 North, Range 11 West

Chains

23.80 E. end of ridge, bears E. and W.; desc. 180 ft. over N. slope.

40.00 True point for the $\frac{1}{4}$ sec. cor. of secs. 1, and 2, falls on large rock, unsafe location for monument.40.10 Point selected for the witness $\frac{1}{4}$ sec. cor. of secs. 1, and 2.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 8 ins. in the ground, and in a mound of stone, $3\frac{1}{2}$ ft. base, to top of post, with brass cap mkd.

T12N R11W

 $\frac{1}{4}$

S 2 | S 1

w c

1959

Desc. 360 ft. over broken N. slope.

60.52 Intersect the S. bdy. of T. 13 N., R. 11 W. (third standard parallel north)

Point for the closing cor. of secs. 1, and 2.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 16 ins. in the ground, and in a mound of stone, to top of post, with brass cap mkd.

T13N R11W

S 36

S 2 | S 1

c | c

T12N R11W

1959

From this point, the standard $\frac{1}{4}$ sec. cor. of sec. 36, which is monumented with an 1 inch diam., iron post, set, marked, and witnessed as described in the official record, dated 1958; bears N. $89^{\circ}58'$ E., .62 ch. dist.

Land, rough and broken.

Soil, sandy and rocky.

Timber, Yellow Paloverde, and Catclaw Acacia.

Undergrowth, Yucca, Saguaro Cactus and Ocotillo.

The point for the N. $\frac{1}{4}$ sec. cor. of sec. 1, at midpoint and in the N. bdy. of T., at 39.915 chs. dist. E. of the closing cor. of sec. 1, and 2.

At the cor. point.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 12 ins. in the ground, and in a mound of stone, $4\frac{1}{2}$ ft. base, to top of post, with brass cap mkd.

 $\frac{1}{4}$ S 1

T12N R11W

1959

From the cor. of secs. 2, 3, 34, and 35, on the S. bdy. of the T., which is monumented with an iron post, set, mkd., and witnessed as described in the official record:

Subdivision of Township 12 North, Range 11 West

Chains

N. 0°01' W., bet. secs. 34, and 35.

Asc. 300 ft. over rough and broken S. to SW. slope; through desert vegetation.

24.20 Ridge, bears E. and W.; desc. 255 ft. over N. slope.

30.50 Wash, 3 ft. deep, 40 lks. wide, drains W.; asc. 100 ft. over rocky SW. slope.

40.00 Point for the $\frac{1}{4}$ sec. cor. of secs. 34, and 35.Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 8 ins. in the ground, and in a mound of stone, 4 ft. base, to top of point, with brass cap mkd.

T12N R11W

S 34 | S 35

1959

Desc. 110 ft. over rough and broken NW. slope.

62.90 Wash, 4 ft. deep, 40 lks. wide, drains SW.; asc. 290 ft. over S. slope.

80.00 True point for the cor. of secs. 26, 27, 34, and 35, falls on unsafe location for monument.

Land, rough and broken.

Soil, sandy and rocky.

Timber, Yellow Paloverde, and Catclaw Acacia.

Undergrowth, Yucca, Saguaro Cactus, and Ocotillo.

From the cor. of secs. 25, 26, 36, and 35.

S. 89°40' W., bet. secs. 26, and 35.

Asc. 90 ft. over NE. slope; through desert vegetation.

11.00 Ridge spur, slopes SE.; asc. 100 ft. along S. slope.

21.00 Small wash, 2 ft. deep, 30 lks. wide, drains SE.; asc. 250 ft. over rocky NE. slope.

39.00 Ridge spur, slopes SE.; thence along S. slope.

39.96 Point for the $\frac{1}{4}$ sec. cor. of secs. 26, and 35.Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 6 ins. in the ground, and in a mound of stone, $4\frac{1}{2}$ ft. base, to top of post, with brass cap mkd.

T12N R11W

 $\frac{1}{4}$ S 26
S 35

1959

Thence along rough and broken S. slope.

79.92 True point for the cor. of secs. 26, 27, 34, and 35.

Subdivision of Township 12 North, Range 11 West

Chains

Land, rough and broken.
Soil, sandy and rocky.
Timber, Yellow Paloverde, and Catclaw Acacia.
Undergrowth, Yucca, Saguaro Cactus, and Ocotillo.

N. 0°01' W., bet. secs. 26, and 27.

.10 Point selected for the witness cor. of secs. 26, 27, 34, and 35.

Set an iron post, 30 ins. long, 2½ ins. diam., 8 ins. in the ground, and in a mound of stone, 4 ft. base, to top of post, with brass cap mkd.

T12N R11W	
S 27	S 26
S 34	S 35
w c	
1959	

Asc. 40 ft. over rocky SW. slope; through desert vegetation.

2.20 Ridge spur, slopes SW.; desc. 120 ft. over broken NW. slope.

15.50 Wash, 3 ft. deep, 40 lks. wide, drains SW.; asc. 100 ft. over broken and rocky SE. slope.

22.30 Spur, slopes E.; desc. 30 ft. over broken and rocky NE. slope.

30.50 Wash, 4 ft. deep, 30 lks. wide, drains SE.; asc. 210 ft. over broken and rocky S. slope.

40.00 Point for the ¼ sec. cor. of secs. 26, and 27.

Set an iron post, 30 ins. long, 2½ ins. diam., 10 ins. in the ground, and in a mound of stone, 4 ft. base, to top of post, with brass cap mkd.

T12N R11W	
¼	
S 27	S 26
1959	

Asc. 280 ft. over broken and rocky S. slope.

51.50 Ridge, bears SW. and NE.; asc. 50 ft. over broken W. slope.

64.90 Ridge, bears W. and SE.; desc. 230 ft. over broken and rocky NNW. slope.

80.00 Point for the cor. of secs. 22, 23, 26, and 27.

Set an iron post, 30 ins. long, 2½ ins. diam., 20 ins. in the ground, and in a mound of stone, 5 ft. base, to top of post, with brass cap mkd.

T12N R11W	
S 22	S 23
S 27	S 26
1959	

Land, rough and broken.
Soil, sandy and rocky.
Timber, Yellow Paloverde.
Undergrowth, Yucca, and Ocotillo.

Subdivision of Township 12 North, Range 11 West

Chains	
	From the true point for the cor. of secs. 23, 24, 25, and 26. S. 89°39' W., bet. secs. 23, and 26. Asc. 400' ft. over broken and rocky NE. slope; through desert vegetation.
21.70	Ridge, bears NW. and SE.; desc. over broken S. slope.
38.74	Point selected for the witness $\frac{1}{4}$ sec. cor. of secs. 23, and 26. Set an iron post, 30 ins. long, 2 $\frac{1}{2}$ ins. diam., 8 ins. in the ground, and in a mound of stone, to top of post, with brass cap mkd. <div style="text-align: center;"> T12N R11W $\frac{1}{4}$ W S 23 $\frac{1}{4}$ C S 26 1959 </div>
39.85	True point for the $\frac{1}{4}$ sec. cor. of secs. 23, and 26, falls in unsafe location for monument. Asc. 140 ft. over broken NNE. slope.
58.50	Ridge, bears NNW. and SSE.; desc. 170 ft. over broken W. slope.
79.70	The cor. of secs. 22, 23, 26, and 27. Land, rough and broken. Soil, sandy and rocky. Timber, Yellow Paloverde, and Catclaw Acacia. Undergrowth, Yucca, and Ocotillo.
	N. 0°01' W., bet. secs. 22, and 23. Desc. over N. slope.
.20	Wash, 3 ft. deep, 20 lks. wide, drains W.; asc. 650 ft. over broken and rocky SW. slope; through desert vegetation.
31.70	Ridge, bears NW. and SE.; desc. 140 ft. over broken and rocky NE. slope.
40.00	Point for the $\frac{1}{4}$ sec. cor. of secs. 22, and 23. Set an iron post, 30 ins. long, 2 $\frac{1}{2}$ ins. diam., on bedrock and in a mound of stone, 4 ft. base, to top of post, with brass cap mkd. <div style="text-align: center;"> T12N R11W $\frac{1}{4}$ S 22 S 23 1959 </div>
	Desc. 280 ft. over broken and rocky NE. slope.
58.50	Wash, 4 ft. deep, 30 lks. wide, drains W.; thence over rolling W. slope.
62.60	Wash, 4 ft. deep, 30 lks. wide, drains W.; thence over rolling W. slope.

Subdivision of Township 12 North, Range 11 West

Chains

77.90 Ridge spur, slopes W.; desc. 50 ft. over N. slope.

80.00 Point for the cor. of secs. 14, 15, 22, and 23.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 22 ins. in the ground, and in a mound of stone, to top of post, with brass cap mkd.

T12N	R11W
S 15	S 14
S 22	S 23
1959	

Land, rough and broken.

Soil, sandy and rocky.

Timber, Yellow Paloverde, and Catclaw Acacia.

Undergrowth, Yucca, Saguaro Cactus, and Ocotillo.

From the true point for the cor. of secs. 13, 14, 23, and 24.

S. $89^{\circ}42'$ W., bet. secs. 14, and 23.

Asc. 220 ft. over rocky NE. slope; through desert vegetation.

17.00 Top of ascent, on N. slope; desc. 470 ft. over rocky NW. slope.

33.90 Wash, 2 ft. deep, 30 lks. wide, drains SW.; asc. 70 ft. over broken SE. slope.

39.93 Point for the $\frac{1}{4}$ sec. cor. of secs. 14, and 23.Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 8 ins. in the ground, and in a mound of stone, $4\frac{1}{2}$ ft. base, to top of post, with brass cap mkd.

T12N	R11W
$\frac{1}{4}$ S 14	
S 23	
1959	

Desc. 50 ft. over broken SW. slope.

43.00 Wash, 2 ft. deep, 40 lks. wide, drains S.; asc. 60 ft. over E. slope.

47.20 Ridge spur, slopes SE.; desc. 90 ft. over SW. slope.

67.80 Wash, 4 ft. deep, 90 lks. wide, drains SE.; asc. 180 ft. over broken and rocky NE. slope.

79.86 The cor. of secs. 14, 15, 22, and 23.

Land, rough and broken.

Soil, sandy and rocky.

Timber, Yellow Paloverde and Catclaw Acacia.

Undergrowth, Yucca, Saguaro Cactus, and Ocotillo.

N. $0^{\circ}01'$ W., bet. secs. 14, and 15.

Desc. 75 ft. over N. slope, through desert vegetation.

Subdivision of Township 12 North, Range 11 West

Chains

2.40 Wash, 4 ft. deep, 30 lks. wide, drains E.; asc. 70 ft. over SE. slope.

9.90 Ridge spur, slopes SE.; desc. 90 ft. over NE. slope.

20.10 Wash, 4 ft. deep, 80 lks. wide, drains SE.; asc. 130 ft. over broken SW. slope.

27.90 Spur, slopes SW.; thence over broken W. slope.

40.00 Point for the $\frac{1}{4}$ sec. cor. of secs. 14 and 15.Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., on bedrock, and in a mound of stone, to top of post, with brass cap mkd.

T12N R11W

 $\frac{1}{4}$

S 15 | S 14

1959

Desc. 50 ft. over broken and rocky W. slope.

43.30 Wash, 3 ft. deep, 80 lks. wide, drains SSW.; asc. 330 ft. over broken and rocky SE. slope.

80.00 Point for the cor. of secs. 10, 11, 14, and 15.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 10 ins. in the ground, and in a mound of stone, 5 ft. base, to top of post, with brass cap mkd.

T12N R11W

S 10 | S 11

S 15 | S 14

1959

Land, rough and broken.

Soil, sandy and rocky.

Timber, Yellow Paloverde, and Catclaw Acacia.

Undergrowth, Yucca, Saguaro Cactus, and Ocotillo.

From the true point for the cor. of secs. 11, 12, 13, and 14.

S. $89^{\circ}47'$ W., bet. secs. 11, and 14.

Asc. 460 ft. over rough and broken NE. slope; through desert vegetation.

34.40 Ridge, bears NE. and SW.; desc. 180 ft. over rough and broken NW. slope.

39.77 Point for the $\frac{1}{4}$ sec. cor. of secs. 11, and 14.Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., on bedrock, and in a mound of stone, to top of post, with brass cap mkd.

T12N R11W

 $\frac{1}{4}$ S 11

S 14

1959

Subdivision of Township 12 North, Range 11 West

Chains

Desc. 450 ft. over rough and broken NW. slope.

68.10 Wash, 4 ft. deep, 1.20 chs. wide, drains SSW.; asc. 180 ft. over broken and rocky SE. slope.

79.54 The cor. of secs. 10, 11, 14, and 15.

Land, rough and broken.

Soil, sandy and rocky.

Timber, Yellow Paloverde, and Catclaw Acacia.

Undergrowth, Yucca, Saguaro Cactus, and Ocotillo.

N. 0°01' W., bet. secs. 10, and 11.

Asc. 500 ft. over rough and broken SE. slope; through desert vegetation.

27.50 Ridge, bears NE. and SW.; desc. 65 ft. over rough and broken NW. slope.

40.00 True point for the $\frac{1}{4}$ sec. cor. of secs. 10, and 11, falls on small vertical ledge, unsafe location for monument.

40.10 Point selected for the witness $\frac{1}{4}$ sec. cor. of secs. 10, and 11.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., on bedrock, and in a mound of stone, 4 ft. base, to top of post, with brass cap mkd.

T12N R11W

$\frac{1}{4}$
S 10 | S 11
w | c
1959

Desc. 70 ft. over broken and rocky NW. slope.

46.10 Draw, drains SW.; asc. 540 ft. over broken and rocky SE. slope.

64.70 Top of rocky peak; desc. 380 ft. over steep rocky and broken N. slope.

80.00 Point for the cor. of secs. 2, 3, 10, and 11.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., on bedrock, and in a mound of stone, 4 ft. base, to top of post, with brass cap mkd.

T12N R11W

S 3 | S 2
S 10 | S 11
1959

Land, rough and broken.

Soil, sandy and rocky.

Timber, Yellow Paloverde, Catclaw Acacia, and Smokethorn.

Undergrowth, Yucca, Saguaro Cactus, and Ocotillo.

From the true point for the cor. of secs. 1, 2, 11, and 12.

S. 89°43' W., bet. secs. 2, and 11.

Desc. 450 ft. over broken S. to SW. slope; through desert vegetation.

Subdivision of Township 12 North, Range 11 West

Chains

- 28.00 Wash, 3 ft. deep, 40 lks. wide, drains S.; asc. 40 ft. over broken S. slope.
- 39.81 Point for the $\frac{1}{4}$ sec. cor. of secs. 2, and 11.
Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 16 ins. in the ground, and in a mound of stone, to top of post, with brass cap mkd.
- T12N R11W
 $\frac{1}{4}$ S 2
S 11
1959
- Desc. 40 ft. over broken S. to SW. slope.
- 49.90 Wash, 3 ft. deep, 50 lks. wide, drains SE.; asc. 40 ft. over SE. slope.
- 55.20 Ridge spur, slopes SE.; desc. 40 ft. over W. slope.
- 62.10 Wash, 1 ft. deep, 30 lks. wide, drains SE.; asc. 200 ft. over broken E. slope.
- 72.70 Ridge spur, slopes NNE.; desc. 50 ft. over NW. slope.
- 79.62 The cor. of secs. 2, 3, 10, and 11.
Land, rough and broken.
Soil, sandy and rocky.
Timber, Catclaw Acacia, and Yellow Paloverde.
Undergrowth, Yucca, Saguaro Cactus, and Ocotillo.
-
- N. 0°01' W., bet. secs. 2, and 3.
Desc. 80 ft. over rocky, and broken NW. slope; through desert vegetation.
- 9.30 Wash, 3 ft. deep, 20 lks. wide, drains W.; asc. 90 ft. over broken S. slope.
- 18.00 Ridge, bears E. and W.; desc. 200 ft. over broken N. slope.
- 36.40 Wash, 3 ft. deep, 40 lks. wide, drains SW.; asc. 200 ft. over broken S. slope.
- 40.00 Point for the $\frac{1}{4}$ sec. cor. of secs. 2, and 3.
Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 10 ins. in the ground, and in a mound of stone, 4 ft. base, to top of post, with brass cap mkd.
- T12N R11W
 $\frac{1}{4}$
S 3 | S 2
1959
- Asc. 220 ft. over rough and broken S. slope.
- 54.10 Ridge spur, slopes W.; desc. 30 ft. over broken W. to NW. slope.

Subdivision of Township 12 North, Range 11 West

Chains

60.93

Intersect the S. bdy. of T. 13 N., R. 11 W., (third standard parallel north)

Point for the closing cor. of secs. 2, and 3.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 6 ins. in the ground, and in a mound of stone, 4 ft. base, to top of post, with brass cap mkd.

T13N R11W
 $\frac{S}{3}$ 35
 S 3 | S 2
 . c c
 T12N R11W
 1959

From this point, the standard $\frac{1}{4}$ sec. cor. of sec. 35, which is monumented with an 1 inch diam., iron post, set, marked, and witnessed as described in the official record, bears N. $89^{\circ}58'$ E., 14 lks. dist.

Land, rough and broken.

Soil, sandy and rocky.

Timber, Yellow Paloverde, and Catclaw Acacia.

Undergrowth, Yucca, Saguaro Cactus and Ocotillo.

Point for the N. $\frac{1}{4}$ sec. cor. of sec. 2, at midpoint and on the N. bdy. of T.

At the cor. point.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 8 ins. in the ground, and in a mound of stone, 4 ft. base, to top of post, with brass cap mkd.

$\frac{1}{4}$ S 2
 $\frac{1}{2}$ T12N R11W
 1959

From this point, the standard cor. of secs. 35, and 36, which is monumented with a 3 inch diam., iron post, set, marked, and witnessed as described in the official record, bears N. $89^{\circ}58'$ E., 38 lks. dist.

From the cor. of secs. 3, 4, 33, and 34, on the S. bdy. of the T., which is monumented with an iron post, set, mkd., and witnessed as described in the official record.

N. $0^{\circ}02'$ W., bet. secs. 33, and 34.

Asc. 105 ft. over broken S. slope; through desert vegetation.

7.00 Ridge spur, slopes SE.; desc. 110 ft. over broken E. slope.

18.00 Wash, 2 ft. deep, 40 lks. wide, drains SE.; asc. 250 ft. over rough and broken SE. slope.

32.80 Ridge spur, slopes E.; desc. 90 ft. over NE. slope.

Subdivision of Township 12 North, Range 11 West

Chains

39.92 Point selected for the witness $\frac{1}{4}$ sec. cor. of secs. 33, and 34.
 Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 12 ins. in the ground, and in a mound of stone, 4 ft. base, to top of post, with brass cap mkd.
 T12N R11W
 $\frac{1}{4}$
 S 33 | S 34
 1959

40.00 True point for the $\frac{1}{4}$ sec. cor. of secs. 33, and 34, falls unsafe location for monument.
 Desc. 40 ft. over broken E. slope.

45.60 Wash, 2 ft. deep, 30 lks. wide, drains E.; asc. 220 ft. over rolling to broken SE. slope.

62.50 Ridge spur, slopes SE.; desc. over rolling and broken E. slope.

80.00 Point for the cor. of secs. 27, 28, 33, and 34.
 Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 10 ins. in the ground, and in a mound of stone, 5 ft. base, to top of post, with brass cap mkd.
 T12N R11W
 S 28 | S 27
 S 33 | S 34
 1959

Land, rough and broken.
 Soil, sandy and rocky.
 Timber, Yellow Paloverde.
 Undergrowth, Yucca, Saguaro Cactus, and Cocotillo.

From the true point for the cor. of secs. 26, 27, 34, and 35.
 S. $89^{\circ}51'$ W., bet. secs. 27, and 34.
 Along S. slope; through desert vegetation.

3.00 Ridge spur, slopes SW.; desc. 320 ft. over rough and broken SW. slope.

13.00 Draw, drains SW.; cont. along S. slope.

36.90 Wash, 5 ft. deep, 1.10 chs. wide, drains SE.; asc. 20 ft. over E. slope.

40.05 Point for the $\frac{1}{4}$ sec. cor. of secs. 27, and 34.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., on bedrock, and in a mound of stone, 4 ft. base, to top of post, with brass cap mkd.

T12N R11W
 $\frac{1}{4}$ S 27
 S 34
 1959

Asc. over SE. slope.

47.30 Ridge spur, slopes SE.; thence desc. over rolling S. slope.

Subdivision of Township 12 North, Range 11 West

Chains

65.10 Wash, 3 ft. deep, 50 lks. wide, drains S.; asc. 120 ft. over rolling and broken S. to SE. slope.

79.70 Wash, 4 ft. deep, drains SE.

80.10 The cor. of secs. 27, 28, 33, and 34.

Land, rough and broken.

Soil, sandy and rocky.

Timber, Yellow Paloverde, and Catclaw Acacia.

Undergrowth, Yucca, Saguaro Cactus, and Ocotillo.

N. 0°02' W., bet. secs. 27, and 28.

.40 Wash, 4 ft. deep, 20 lks. wide, drains SE.; thence asc. 290 ft. over rough and broken SE. slope; through desert vegetation.

32.60 Ridge spur, slopes SE.; desc. 70 ft. over broken NE. slope.

40.00 Point for the $\frac{1}{4}$ sec. cor. of secs. 27, and 28.

Set an iron post, 30 ins. long, 2 $\frac{1}{2}$ ins. diam., 16 ins. in the ground, and in a mound of stone, 5 ft. base, to top of post, with brass cap mkd.

T12N R11W

$\frac{1}{4}$
S 28 | S 27

1959

Desc. 270 ft. over broken NE. slope.

57.60 Wash, 4 ft. deep, 3.50 chs. wide, drains SE.; asc. 120 ft. over broken SW. slope.

80.00 Point for the cor. of secs. 21, 22, 27, and 28.

Set an iron post, 30 ins. long, 2 $\frac{1}{2}$ ins. diam., on bedrock, and in a mound of stone, 5 ft. base, to top of post, with brass cap mkd.

T12N R11W

S 21 | S 22
S 28 | S 27

1959

Land, rough and broken.

Soil, sandy and rocky.

Timber, Yellow Paloverde, and Catclaw Acacia.

Undergrowth, Yucca, Saguaro Cactus, and Ocotillo.

From the cor. of secs. 22, 23, 26, and 27.

S. 89°54' W., bet. secs. 22, and 27.

Along N. slope, through desert vegetation.

10.20 Deep wash, 10 ft. deep, 30 lks. wide, drains S. 70° W.; desc. 270 ft. along SSW. slope.

40.05 Point for the $\frac{1}{4}$ sec. cor. of secs. 22, and 27.

Subdivision of Township 12 North, Range 11 West

Chains

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 8 ins. in the ground, and in a mound of stone, 4 ft. base, to top of post, with brass cap mkd.

T12N R11W

$\frac{1}{4}$ S 22
S 27

1959

Desc. 60 ft. over SSW. slope.

52.60 Wash, 2 ft. deep, 30 lks. wide, drains SSW.; asc. 90 ft. over SE. slope.

66.60 Ridge spur, slopes SE.; asc. 40 ft. over rocky S. slope.

73.90 Ridge spur, slopes SW.; desc. 30 ft. over rocky W. slope.

80.10 The cor. of secs. 21, 22, 27, and 28.

Land, rough and broken.

Soil, sandy and rocky.

Timber, Yellow Paloverde, and Catclaw Acacia.

Undergrowth, Yucca, Saguaro Cactus, and Ocotillo.

N. $0^{\circ}02'$ W., bet. secs. 21, and 22.

Desc. 40 ft. over rocky and broken NW. slope; through desert vegetation.

3.40 Wash, 4 ft. deep, 2.00 chs. wide, drains SW.; asc. 140 ft. over broken and rocky SE. slope.

25.40 Draw, drains SE. by S., from NW.; asc. 160 ft. over broken SE. slope.

40.00 True point for the $\frac{1}{4}$ sec. cor. of secs. 21, and 22, falls on small vertical ledge, unsafe location for monument.

41.00 Point selected for the witness $\frac{1}{4}$ sec. cor. of secs. 21, and 22.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 10 ins. in the ground, and in a mound of stone, 4 ft. base, to top of post, with brass cap mkd.

T12N R11W

$\frac{1}{4}$
S 21 S 22

w c

1959

Desc. 40 ft. over broken E. slope.

55.00 Wash, 4 ft. deep, 50 lks. wide, drains E.; asc. 140 ft. over broken SE. slope.

73.00 Ridge spur, slopes E.; desc. 30 ft. over broken NE. slope.

75.70 Draw, drains E.; asc. 60 ft. over broken SE. slope.

80.00 Point for the cor. of secs. 15, 16, 21, and 22.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., on bedrock, and in a mound of stone, 6 ft. base, to top of post, with brass cap mkd.

Subdivision of Township 12 North, Range 11 West

Chains

T12N R11W
 S 16 | S 15
 S 21 | S 22
 1959

Land, rough and broken.
 Soil, sandy and rocky.
 Timber, Yellow Paloverde, and Catclaw Acacia.
 Undergrowth, Yucca, Saguaro Cactus, and Ocotillo.

From the cor. of secs. 14, 15, 22, and 23.

S. $89^{\circ}44'$ W., bet. secs. 15, and 22.

Desc. 40 ft. over rough and broken SW. slope; through desert vegetation.

26.90 Wash, 3 ft. deep, 40 lks. wide, drains SSE.; asc. 100 ft. over broken NE. slope.

39.00 Top of asc. in saddle, bears NW. and SE.; desc. along rocky S. slope.

40.05 Point for the $\frac{1}{4}$ sec. cor. of secs. 15, and 22.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 10 ins. in the ground, and in a mound of stone, 4 ft. base, to top of post, with brass cap mkd.

T12N R11W
 $\frac{1}{4}$ S 15
 S 22
 1959

Desc. 175 ft. over broken W. slope.

52.00 Wash, 4 ft. deep, 40 lks. wide, drains SSW.; asc. 70 ft. over broken SE. slope.

62.30 Ridge spur, slopes S.; desc. 30 ft. over broken W. slope.

65.30 Wash, 3 ft. deep, 20 lks. wide, drains S.; asc. over broken S. slope.

70.20 Wash, 4 ft. deep, 30 lks. wide, drains S.; asc. 90 ft. over broken SE. slope.

80.10 The cor. of secs. 15, 16, 21, and 22.

Land, rough and broken.
 Soil, sandy and rocky.
 Timber, Yellow Paloverde, and Catclaw Acacia.
 Undergrowth, Yucca, Saguaro Cactus, and Ocotillo.

N. $0^{\circ}02'$ W., bet. secs. 15, and 16.

Asc. 130 ft. over rocky S. slope; through desert vegetation.

10.30 Ridge spur, slopes SE.; asc. 270 ft. over broken SE. slope.

19.10 Ridge, bears NE. and SW.; desc. 360 ft. over rocky and broken NW. slope.

40.00 Point for the $\frac{1}{4}$ sec. cor. of secs. 15, and 16.

Subdivision of Township 12 North, Range 11 West

Chains

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., on bedrock and in a mound of stone, to top of post, with brass cap mkd.

T12N R11W

$$\begin{array}{c} \frac{1}{4} \\ \text{S } 16 \text{ | } \text{S } 15 \end{array}$$

1959

Desc. 20 ft. over rocky NW. slope.

42.00 Wash, 2 ft. deep, 20 lks. wide, drains W.; desc. along broken W. slope.

54.00 Wash, 2 ft. deep, 30 lks. wide, drains W.; thence along broken W. slope.

56.30 Ridge spur, slopes W.; desc. 60 ft. over broken NW. slope.

69.40 Wash 2 ft. wide, 20 lks. wide, drains W., 2 chs. to main wash; asc. 50 ft. over broken W. slope.

75.50 Wash, 3 ft. deep, 20 lks., wide, drains W.; asc. over W. slope.

78.00 Point selected for the witness cor. of secs. 9, 10, 15, and 16.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., on bedrock and in a mound of stone, 5 ft. base, to top of post, with brass cap mkd.

T12N R11W

w c

$$\begin{array}{c} \text{S } 9 \text{ | } \text{S } 10 \\ \text{S } 16 \text{ | } \text{S } 15 \end{array}$$

1959

Witness cor. falls on rocky ridge spur, slopes W.; desc. 50 ft. over rocky N. slope.

80.00 True point for the cor. of secs. 9, 10, 15, and 16, falls in bottom of wash, 5 ft. deep, 40 lks. wide, drains W.; unsafe location for monument.

Land, rough and broken.

Soil, sandy and rocky.

Timber, Yellow Paloverde, and Catclaw Acacia.

Undergrowth, Yucca, Saguaro Cactus, and Ocotillo.

From the cor. of secs. 10, 11, 14, and 15.

S. $89^{\circ}39'$ W.; bet. secs. 10, and 15.

Asc. 440 ft. over rough and broken SE. slope; through desert vegetation.

24.40 Top of asc. ridge spurs, slopes SE., and SW.; desc. over SW. spur; desc. 340 ft. over broken NW. slope.

40.05 True point for the $\frac{1}{4}$ sec. cor. of secs. 10, and 15, falls on unsafe location for monument.

40.30 Point selected for the witness $\frac{1}{4}$ sec. cor. of secs. 10, and 15.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 12 ins. in the ground, and in a mound of stone, 4 ft. base, to top of post, with brass cap mkd.

Subdivision of Township 12 North, Range 11 West

Chains

T12N R11W
 $\frac{1}{4}$ S 10 W
 S 15 c
 1959

Desc. 260 ft. over broken NW. slope.

58.00 Wash, 2 ft. deep, 30 lks. wide, drains S. 80° W.; asc. along broken SE. slope.

76.70 Ridge spur, slopes SW.; desc. 20 ft. over W. slope.

78.50 Enter wash, 5 ft. deep, 40 lks. wide, drains W.

80.10 True point for the cor. of secs. 9, 10, 15, and 16.

Land, rough and broken.

Soil, sandy and rocky.

Timber, Yellow Paloverde, and Catclaw Acacia.

Undergrowth, Yucca, Saguaro Cactus, and Ocotillo.

N. 0°02' W., bet. secs. 9, and 10.

Asc. 320 ft. over rough and broken S. to SE. slope; through desert vegetation.

40.00 Point for the $\frac{1}{2}$ sec. cor. of secs. 9, and 10.

Set an iron post, 30 ins. long, 2 $\frac{1}{2}$ ins. diam., 16 ins. in the ground, and in a mound of stone, 4 ft. base, to top of post, with brass cap mkd.

T12N R11W
 $\frac{1}{2}$
 S 9 | S 10
 1959

Asc. 410 ft. over rough and broken SE. to S. slope.

80.00 Point for the cor. of secs. 3, 4, 9, and 10.

Set an iron post, 30 ins. long, 2 $\frac{1}{2}$ ins. diam., 10 ins. in the ground, and in a mound of stone, 5 ft. base to top of post, with brass cap mkd.

T12N R11W
 S 4 | S 3
 S 9 | S 10
 1959

Land, rough and broken.

Soil, sandy and rocky.

Timber, Yellow Paloverde, and Catclaw Acacia.

Undergrowth, Yucca, Saguaro Cactus, and Ocotillo.

From cor. of secs. 2, 3, 10, and 11.

Chains

S. 89°45' W., bet. secs. 3, and 10.

Along, broken N. slope, through desert vegetation.

24.80 Ridge spur, slopes NW.; desc. 190 ft. over broken and rocky W. slope.

40.06 Point for the $\frac{1}{4}$ sec. cor. of secs. 3, and 10.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 12 ins. in the ground, and in a mound of stone, $3\frac{1}{2}$ ft. base, to top of post, with brass cap mkd.

T12N R11W

$\frac{1}{4}$ S 3
S 10

1959

Desc. 175 ft. over W. to SW. slope.

52.30 Wash, 3 ft. deep, 50 lks. wide, drains S.; asc. 450 ft. over steep, rocky, and broken E. to SE. slope.

80.12 The cor. of secs. 3, 4, 9, and 10.

Land, rough and broken.

Soil, sandy and rocky.

Timber, Yellow Paloverde, and Catclaw Acacia.

Undergrowth, Yucca, Saguaro Cactus, and Ocotillo.

N. 0°02' W., bet. secs. 3, and 4.

Asc. 75 ft. over steep S. slope; through desert vegetation.

2.20 Ridge, bears E. and W.; desc. 220 ft. over broken N. slope.

11.30 Wash, 3 ft. deep, 20 lks. wide, drains E.; asc. 270 ft. over rough and broken SE. slope.

24.70 Ridge, bears SW. and NE.; desc. 150 ft. over broken NW. slope.

39.00 Wash, 3 ft. deep, 20 lks. wide, drains SW.; asc. over SW. slope.

40.00 Point for the $\frac{1}{4}$ sec. cor. of secs. 3, and 4.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 10 ins. in the ground, and in a mound of stone, 4 ft. base, to top of post, with brass cap mkd.

T12N R11W

$\frac{1}{4}$
S 4 | S 3

1959

Asc. 175 ft. over rough and broken SW. slope.

61.29 Intersect the S. bdy. of T. 13 N., R. 11 W., (third standard parallel north)

Point for the closing cor. of secs. 3, and 4.

Subdivision of Township 12 North, Range 11 West

Chains

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 6 ins. in the ground, and in a mound of stone, 4 ft. base, to top of post, with brass cap mkd.

T13N R11W

S 34

S 4 | S 3

c c

T12N R11W

1959

From this point, the standard $\frac{1}{4}$ sec. cor. of sec. 34, which is monumented with an 1 inch diam., iron post, set, marked, and witnessed as described in the official record, bears N. $89^{\circ}58'$ W., 26 lks. dist.

Land, rough and broken.

Soil, sandy and rocky.

Timber, Yellow Paloverde, and Catclaw Acacia.

Undergrowth, Yucca, Saguaro, Cactus, and Ocotillo.

Point for the N. $\frac{1}{4}$ sec. cor. of sec. 3; at midpoint and on the N. bdy. of T.

At the cor. point.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., on bedrock, and in a mound of stone, 5 ft. base, to top of post, with brass cap mkd.

 $\frac{1}{4}$ S 3

T12N R11W

1959

From this point, the standard cor. of secs. 34, and 35, which is monumented with a 3 inch diam., iron post, set, marked, and witnessed as described in the official record, bears N. $89^{\circ}58'$ E., 20 lks. dist.

From the cor. of secs. 4, 5, 32 and 33 on the S. bdy. of the T., monumented with an iron post, set, mkd. and witnessed as described in the official record.

N. $0^{\circ}02'$ W., bet. secs. 32 and 33.

Asc. 320 ft. over SW. slope, through desert vegetation.

24.50 Ridge, bears NW. and SE.; desc. 170 ft. over E. slope.

40.00 Point for the $\frac{1}{4}$ sec. cor. of secs. 32 and 33.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 15 ins. in the ground, and in a mound of stone, 3 ft. base to top with brass cap mkd.

T12N R11W

 $\frac{1}{4}$

S 32 | S 33

1958

Desc. 70 ft. over broken NE. slope.

57.20 Draw, drains SE.; asc. 490 ft. over broken SE. slope.

Subdivision of Township 12 North, Range 11 West

Chains

77.70 Rimrock, bears NE. and SW.; asc. 82 ft. over S. slope.

80.00 Point for the cor. of secs. 28, 29, 32 and 33.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., on bedrock and in a mound of stone, $\frac{1}{4}$ ft. base to top, with brass cap mkd.

T12N	R11W
S 29	S28
S 32	S33
1959	

Land, rough and broken.
 Soil, sandy and rocky.
 Timber, Yellow Paloverde.
 Undergrowth, Yucca, Saguaro Cacti and Ocotillo

From the cor. of secs. 27, 28, 33 and 34.

S. $89^{\circ}40'$ W., bet. secs. 28 and 33.

Asc. 210 ft. over broken NE. slope, through desert vegetation.

14.70 Ridge spur, slopes SE.; desc. 80 ft. over broken SW. slope.

19.50 Wash, 1 ft. deep, 20 lks. wide, drains SSE.; asc. 155 ft. over E. slope.

24.70 Ridge spur, slopes S.; desc. 70 ft. over W. slope.

34.80 Wash, 3 ft. deep, 30 lks. wide, drains S.; asc. 40 ft. over SE. slope.

39.97 Point for the $\frac{1}{4}$ sec. cor. of secs. 29 and 32.Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., on bedrock and in a mound of stone, $\frac{1}{4}$ ft. base to top, with brass cap mkd.

T12N	R11W
$\frac{1}{4}$ S29	
S32	
1959.	

Asc. 240 ft. over broken SE. slope.

78.40 Rimrock, bears N. and SW.; asc. 20 ft. over SE. slope.

79.94 The cor. of secs. 28, 29, 32 and 33.

Land, rough and broken.
 Soil, sandy and rocky.
 Timber, Yellow Paloverde.
 Undergrowth, Yucca, Saguaro Cacti and Ocotillo.

N. $0^{\circ}02'$ W., bet. secs. 28 and 29.

Desc. 190 ft. over NE. slope, through desert vegetation.

5.70 Small draw, drains W.; asc. 200 ft.

15.00 Ridge, bears E. and W.; desc. 270 ft. over N. slope.

21.80 Wash, 3 ft. deep, 20 lks. wide, drains W.; asc. 90 ft. over SW. slope.

Subdivision of Township 12 North, Range 11 West

Chains	
28.80	Ridge spur, slopes W. at W. side of mesa; desc. 70 ft. over NW. slope.
33.30	Head of draw, drains W.; asc. 110 ft. over rocky S. slope.
40.00	Point for the $\frac{1}{4}$ sec. cor. of secs. 28 and 29.
	Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., on bedrock, and in a mound of stone, 6 ft. base to top, with brass cap mkd.
	T12N R11W $\frac{1}{4}$ S29 S28 1959
	Asc. 30 ft. over rocky S. slope.
43.30	Rimrock, bears N. 80° W. and E.; desc. 260 ft. over rocky NNE. slope.
49.30	Wash, 3 ft. deep, 40 lks. wide, drains N. 80° W.; asc. 360 ft. over rocky SW. slope.
71.30	SW. rim of mesa, bears NW. and SE.; asc. 40 ft. over W. slope.
80.00	Point for the cor. of secs. 20, 21, 28 and 29.
	Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., on bedrock, and in a mound of stone, 5 ft. base to top, with brass cap mkd.
	T12N R11W S20 S21 S29 S28 1959
	Land, rough and broken. Soil, sandy and rocky. Timber, Yellow Paloverde. Undergrowth, Yucca, Saguaro Cacti and Ocotillo.
	From the cor. of secs. 21, 22, 27 and 28.
	S. 89°52' W., bet. secs. 21 and 28.
	Desc. 60 ft. over rocky W. slope; through desert vegetation.
3.70	Wash, 4 ft. deep, 1.10 chs. wide, drains S.; asc. 290 ft. over rough broken SE. slope.
39.94	Point for the $\frac{1}{4}$ sec. cor. of secs. 21 and 28.
	Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., on bedrock, and in a mound of stone, 4 ft. base to top, with brass cap mkd.
	T12N R11W $\frac{1}{4}$ S 21 S 28 1959
	Asc. 420 ft. over rough and broken E. slope.
67.70	E. rim of mesa, bears N. and SSE.; desc. 90 ft. over rocky W. slope.
79.88	The cor. of secs. 20, 21, 28 and 29.

Subdivision of Township 12 North, Range 11 West

Chains

Land, rough and broken.
Soil, sandy and rocky.
Timber, Yellow Paloverde.
Undergrowth, Yucca, Saguaro Cacti, Ocotillo and Catclaw.

N. 0°02' W., bet. secs. 20 and 21.

Desc. 90 ft. over rim of mesa and NW. slope, through desert vegetation.

2.30 Head of small draw, drains W.; asc. 160 ft. over rocky SW. slope.

8.00 Rim of mesa, bears W. and ...; asc. 80 ft. over rocky S. slope.

16.40 NW. rim of mesa, bears NE. and SW.; desc. 220 ft. over rocky and broken NW. slope.

40.00 True point for the $\frac{1}{4}$ sec. cor. of secs. 20 and 21 falls in small draw which drains NW., where cor. cannot be perpetuated.

41.90 Point selected for the witness $\frac{1}{4}$ sec. cor. of secs. 20 and 21.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 6 ins. in ground to bedrock, and in a mound of stone, 4 ft. base to top, with brass cap mkd.

T12N R11W

$\frac{1}{4}$
S20 | S21

W C

1959

Desc. 90 ft. over rocky and broken NW. slope.

56.00 Wash, 6 ft. deep, 80 lks. wide, drains SW.; asc. 140 ft. over broken SE. slope.

80.00 Point for the cor. of secs. 16, 17, 20 and 21.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., on bedrock and in a mound of stone, 4 ft. base to top, with brass cap mkd.

T12N R11W

S17 | S16
S20 | S21

1959

Land, rough and broken.
Soil, sandy and rocky.
Timber, Yellow Paloverde.
Undergrowth, Yucca, Saguaro Cacti, Ocotillo and Catclaw.

From the cor. of secs. 15, 16, 21 and 22.

S. 89°56' W., bet. secs. 16 and 21.

Asc. 120 ft. over rocky SE. slope.

8.40 Saddle, bears NNE. and SSW.; desc. 230 ft. along rough and broken NNW. slope.

Subdivision of Township 12 North, Range 11 West

Chains

- 39.95 Point for the $\frac{1}{4}$ sec. cor. of secs. 16 and 21.
Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 16 ins. in the ground, and in a mound of stone, 4 ft. base to top, with brass cap mkd.
- T12N R11W
 $\frac{1}{4}$ S16
S21
1959
- Desc. 80 ft. over rocky NW. slope
- 46.00 Wash, 4 ft. deep, 30 lks. wide, drains SW.; thence along broken S. slope.
- 63.40 Wash, 4 ft. deep, 60 lks. wide, drains S.; asc. 200 ft. over broken SE. slope.
- 79.90 The cor. of secs. 16, 17, 20 and 21:
Land, rough and broken.
Soil, sandy and rocky.
Timber, Yellow Paloverde.
Undergrowth, Yucca, Saguaro Cacti, Ocotillo and Catclaw.
-
- N. $0^{\circ}02'$ W., bet. secs. 16 and 17.
Asc. 110 ft. over rough and broken SE. slope, through desert vegetation.
- 8.50 Broken ridge, bears NE. and SW.; asc. 80 ft. over broken SE. slope.
- 40.00 Point for the $\frac{1}{4}$ sec. cor. of secs. 16 and 17.
Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., on bedrock, and in a mound of stone, 4 ft. base to top, with brass cap mkd.
- T12N R11W
 $\frac{1}{4}$
S17|S16
1959
- Asc. 90 ft. over broken SW. slope.
- 80.00 Point for the cor. of secs. 8, 9, 16 and 17.
Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 16 ins. in the ground, and in a mound of stone, 3 ft. base to top, with brass cap mkd.
- T12N R11W
S 8|S 9
S17|S16
1959
- Land, rough and broken.
Soil, sandy and rocky.
Timber, Yellow Paloverde.
Undergrowth, Yucca, Saguaro Cacti, Ocotillo and Catclaw.

Subdivision of Township 12 North, Range 11 West

Chains

From the true point for the cor. of secs. 9, 10, 15 and 16, in bottom of wash.

S. 89°59' W., bet. secs. 9 and 16.

Asc. 340 ft. over broken SE. slope, through desert vegetation.

16.70 Broken ridge spur, slopes SW.; desc. 80 ft. over rocky broken NW. slope.

27.80 Wash, 2 ft. deep, 40 lks. wide, drains SW.; asc. 60 ft. over rocky SE. slope.

36.10 Ridge spur, slopes S.; desc. 60 ft. over rocky SW. slope.

39.95 Point for the $\frac{1}{4}$ sec. cor. of secs. 9 and 16.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., on bedrock, and in a mound of stone, 4 ft. base to top, with brass cap mkd.

T12N R11W

$\frac{1}{4}$ S 9
S 16

1959

Asc. 130 ft. over rocky E. slope.

47.90 Top of round knoll; desc. 130 ft. over rocky W. slope.

62.90 Wash, 3 ft. deep, 90 lks. wide, drains S.; asc. 70 ft. over rocky SE. slope.

69.50 Broken ridge, bears N. and S.; desc. 30 ft. over broken SW. slope.

79.90 The cor. of secs. 8, 9, 16 and 17.

Land, rough and broken.

Soil, sandy and rocky.

Timber, Yellow Paloverde.

Undergrowth, Yucca, Saguaro Cacti, Ocotillo and Catclaw.

N. 0°02' W., bet. secs. 8, and 9.

Desc. 70 ft. over rocky NW. slope; through desert vegetation.

5.50 Wash, 2 ft. deep, 30 lks. wide, drains W.; asc. 320 ft. over rocky, and broken SSE. slope.

40.00 Point for the $\frac{1}{4}$ sec. cor. of secs. 8, and 9.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., on bedrock, and in a mound of stone, 4 ft. base, to top of post, with brass cap mkd.

T12N R11W

$\frac{1}{4}$
S 8 | S 9

1959

Asc. 250 ft. over rocky, and broken SSE. slope.

49.10 Ridge, bears NE. and SW.; desc. 280 ft. over rocky and broken NW. slope.

67.50 Draw, drains W.; asc. 190 ft. over rocky and broken S. slope.

Subdivision of Township 12 North, Range 11 West

Chains

77.20 Ridge, bears E. and W.; desc. 50 ft. over rocky N. slope.

80.00 Point for the cor. of secs. 4, 5, 8, and 9.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 8 ins. in the ground, and in a mound of stone, to top of post, with brass cap mkd.

T12N R11W

S 5 | S 4

S 8 | S 9

1959

Land, rough and broken.

Soil, sandy and rocky.

Timber, Yellow Paloverde, and Catclaw Acacia.

Undergrowth, Yucca, Saguaro Cactus, and Ocotillo.

From the cor. of secs. 3, 4, 9, and 10.

S. $89^{\circ}50'$ W., bet. secs. 4, and 9.

Asc. 90 ft. over rocky SE. slope; through desert vegetation.

5.50 Ridge, bears NE. and SW.; thence desc. 110 ft. over rocky and broken N. slope.

40.00 Point for the $\frac{1}{4}$ sec. cor. of secs. 4, and 9.Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 10 ins. in the ground, and in a mound of stone, to top of post, with brass cap mkd.

T12N R11W

 $\frac{1}{4}$ S 4

S 9

1959

Desc. 70 ft. over rough and broken N. slope.

80.00 The cor. of secs. 4, 5, 8, and 9.

Land, rough and broken.

Soil, sandy and rocky.

Timber, Yellow Paloverde, and Catclaw Acacia.

Undergrowth, Yucca, Saguaro Cactus, and Ocotillo.

N. $0^{\circ}02'$ W., bet. secs. 4, and 5.

Desc. 230 ft. over rocky and broken N. slope; through desert vegetation.

19.30 Wash, 5 ft. deep, 80 lks. wide, drains SW.; asc. 180 ft. over rocky and broken SW. slope.

40.00 Point for the $\frac{1}{4}$ sec. cor. of secs. 4, and 5.Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., on bedrock, and in a mound of stone, to top of post, with brass cap mkd.

Subdivision of Township 12 North, Range 11 West

Chains

T12N R11W
 $\frac{1}{4}$
 S 5 | S 4
 1959

Desc. over NW. slope, rough and broken.
 49.95 Draw, drains SW.; asc. over SW. slope.
 55.30 Ridge spur, slopes SW.; desc. 40 ft. over rocky NW. slope.
 59.90 Wash, 3 ft. deep, 40 lks. wide, drains SW.; asc. 70 ft. over E. slope.
 61.12 Intersect the S. bdy. of T. 13 N., R. 11 W., (third standard parallel north)

Point for the closing cor. of secs. 4, and 5.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 10 ins. in the ground, and in a mound of stone, to top of post, with brass cap mkd.

T13N R11W
 S 33
 S 5 | S 4
 c | c
 T12N R11W
 1959

From this point, the standard $\frac{1}{4}$ cor. of sec. 33, which is monumented with an 1 inch diam., iron post, set, marked, and witnessed as described in the official record, bears N. 89°58' E., 36 lks. dist.

Land, rough and broken.
 Soil, sandy and rocky.
 Timber, Yellow Paloverde, and Catclaw Acacia.
 Undergrowth, Yucca, Saguaro Cactus, and Ocotillo.

Point for the N. $\frac{1}{4}$ sec. cor. of sec. 4, at midpoint and on the N. bdy. of T.

At the cor. point.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 8 ins. in the ground, and in a mound of stone, to top of post, with brass cap mkd.

$\frac{1}{4}$ S 4
 T12N R11W
 1959

From this point, the standard cor. of secs. 33, and 34, which is monumented with a 3 inch diam., iron post, set, marked, and witnessed as described in the official record bears N. 89°58' E., 31 lks. dist.

From the cor. of secs. 5, 6, 31, and 32, on the S. bdy. of the T., monumented with an iron post, set, mkd., and witnessed as described in the official record.

N. 0°03' W., bet. secs. 31, and 32.

Asc. 390 ft. over rough, and broken S. slope; through desert vegetation.

Subdivision of Township 12 North, Range 11 West

Chains

40.00 Point for the $\frac{1}{4}$ sec. cor. of secs. 31, and 32.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 12 ins. in the ground, and in a mound of stone, 4 ft. base, to top of post, with brass cap mkd.

T12N R11W

$$\frac{1}{4}$$

S 31	S 32
------	------

1959

Asc. 680 ft. over rough, and broken S. to SW. slope.

70.90 Ridge spur, slopes W.; desc. 290 ft. over rocky and broken NW. slope.

80.00 Point for the cor. of secs. 29, 30, 31, and 32.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 14 ins. in the ground, and in a mound of stone, 4 ft. base, to top of post, with brass cap mkd.

T12N R11W

S 30	S 29
S 31	S 32

1959

Land, rough and broken.

Soil, sandy and rocky.

Timber, Yellow Paloverde.

Undergrowth, Yucca, Saguaro Cactus, and Ocotillo.

From the cor. of secs. 28, 29, 32, and 33.

S. $89^{\circ}40'$ W., bet. secs. 29, and 32.

Along rough, and broken N. slope; through desert vegetation.

39.97 Point for the $\frac{1}{4}$ sec. cor. of secs. 29, and 32.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 10 ins. in the ground, and in a mound of stone, 4 ft. base, to top of post, with brass cap mkd.

T12N R11W

$$\frac{1}{4}$$

S 29	S 32
------	------

1959

Along rough and broken N. slope.

79.94 The cor. of secs. 29, 30, 31, and 32.

Land, rough and broken.

Soil, sandy and rocky.

Timber, Yellow Paloverde.

Undergrowth, Yucca, and Saguaro Cactus.

S. $89^{\circ}53'$ W., bet. secs. 30, and 31.

Desc. 490 ft. over broken NW. slope; through desert vegetation.

Subdivision of Township 12 North, Range 11 West

Chains	
40.00	<p>Point for the $\frac{1}{4}$ sec. cor. of secs. 30, and 31.</p> <p>Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 12 ins. in the ground, and in a mound of stone, 4 ft. base, to top of post, with brass cap mkd.</p> <p style="text-align: center;">T12N R11W $\frac{1}{4}$ S 30 S 31 1959</p> <p>Desc. 90 ft. over broken NW. slope.</p>
50.90	<p>Wash, 4 ft. deep, 2.00 chs. wide, drains SW.; asc. 80 ft. over rocky SE. slope.</p>
70.90	<p>Ridge, bears NE. and SW.; rut road along top of ridge; desc. 50 ft. over rocky W. slope.</p>
79.10	<p>Intersect the W. bdy. of T. 12 N., R. 11 W., at the cor. of secs. 25, 30, 31, and 36, which is monumented with an iron post, set, marked, and witnessed as described in the official record.</p> <p>Land, rough, and broken. Soil, sandy and rocky. Timber, Yellow Paloverde, and Catclaw Acacia. Undergrowth, Yucca, Saguaro Cactus, and Cocotillo.</p>
	<p>From the cor. of secs. 29, 30, 31, and 32.</p>
	<p>N. 0°03' W., bet. secs. 29, and 30.</p>
	<p>Desc. 130 ft. over rocky NW. slope; through desert vegetation.</p>
7.50	<p>Draw, drains W.; asc. 80 ft. over SW. slope.</p>
12.60	<p>Ridge spur, slopes W.; desc. 340 ft. over broken NW. slope.</p>
30.40	<p>Wash, 4 ft. deep, 90 lks. wide, drains W.; asc. 260 ft. over rocky S. slope.</p>
40.00	<p>Point for the $\frac{1}{4}$ sec. cor. of secs. 29, and 30.</p> <p>Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., on bedrock, and in a mound of stone, to top of post, with brass cap mkd.</p> <p style="text-align: center;">T12N R11W $\frac{1}{4}$ S 30 S 29 1959</p> <p>Asc. 20 ft. over rocky S. slope.</p>
41.10	<p>Ridge spur, slopes S. 80° W.; desc. 270 ft. over rocky and broken NW. slope.</p>
70.00	<p>Wash, 15 ft. deep, 90 lks. wide, drains SW.; asc. 220 ft. over rocky SSE. slope.</p>
80.00	<p>Point for the cor. of secs. 19, 20, 29, and 30.</p>

Subdivision of Township 12 North, Range 11 West

Chains

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 6 ins. in the ground, to bedrock, and in a mound of stone, 4 ft. base, to top of post, with brass cap mkd.

T12N R11W
 S 19 | S 20
 S 30 | S 29
 1959

Land, rough, and broken.
 Soil, sandy and rocky.
 Timber, Yellow Paloverde, and Catclaw Acacia.
 Undergrowth, Yucca, Saguaro Cactus, and Ocotillo.

From the cor. of secs. 20, 21, 28 and 29.

S. $89^{\circ}40'$ W., bet. secs. 20 and 29.

Desc. along N. rim of mesa; through desert vegetation.

5.70 Desc. 270 ft. over rocky and broken NW. slope.

18.20 Draw, drains SW.; asc. 140 ft. over rocky and broken SE. slope.

21.60 Ridge, bears NE. and SW.; desc. 260 ft. over rocky and broken NW. slope.

39.95 Point for the $\frac{1}{4}$ sec. cor. of secs. 20, and 29.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 6 ins. in the ground, to bedrock, and in a mound of stone, 4 ft. base, to top of post, with brass cap mkd.

T12N R11W
 $\frac{1}{4}$ S 20
 S 29
 1959

Desc. 480 ft. over rocky and broken NW. slope.

68.90 Wash, 15 ft. deep, 90 lks. wide, drains SW.; asc. 160 over rocky and broken SE. slope.

79.90 The cor. of secs. 19, 20, 29, and 30.

Land, rough and broken.
 Soil, sandy and rocky.
 Timber, Yellow Paloverde, and Catclaw Acacia.
 Undergrowth, Yucca, Saguaro Cactus, and Ocotillo.

N. $89^{\circ}59'$ W., bet. secs. 19, and 30.

Asc. 40 ft. over rocky SE. slope; through desert vegetation.

10.00 Ridge, bears NE. and SW.; rut road along top of ridge; desc. 180 ft. over rocky NW. slope.

28.80 Wash, 3 ft. deep, 30 lks. wide, drains SW.; asc. 60 ft. over rocky SE. slope.

37.40 Ridge spur, slopes SW.; desc. 40 ft. over W. slope.

Subdivision of Township 12 North, Range 11 West

Chains

- 40.00 Point for the $\frac{1}{4}$ sec. cor. of secs. 19, and 30.
 Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 8 ins. in the ground, to bedrock, and in a mound of stone, to top of post, with brass cap mkd.
- T12N R11W
 $\frac{1}{4}$ S 19
 S 30
 1959
- Desc. 30 ft. over W. slope.
- 42.90 Wash, 2 ft. deep, 40 lks. wide, drains SW.; asc. 40 ft. over rocky SE. slope.
- 49.40 Ridge, bears NE. and SW.; desc. 160 ft. over rocky and broken NW. slope.
- 73.40 Wash, 3 ft. deep, 50 lks. wide, drains SW.; thence along broken S. slope.
- 79.19 Intersect the W. bdy. of T. at the cor. of secs. 19, 24, 25, and 30, which is monumented with an iron post, set, marked, and witnessed as described in the official record.
- Land, rough and broken.
 Soil, sandy and rocky.
 Timber, Yellow Paloverde, and Catclaw Acacia.
 Undergrowth, Yucca, Saguaro Cactus, and Ocotillo.
-
- From the cor. of secs. 19, 20, 29, and 30.
 N. 0°03' W., bet. secs. 19, and 20.
 Asc. 65 ft. over rocky SE. slope; through desert vegetation.
- 3.95 Ridge, bears E. and W.; rut road along top of ridge; desc. 120 ft. over rocky NW. slope.
- 13.00 Draw, drains SW.; asc. 190 ft. over rocky S. slope.
- 23.90 Ridge, bears S. 80° W. and N. 80° E.; desc. 160 ft. over rocky NW. slope.
- 36.50 Draw, drains SW.; asc. 70 ft. over SE. slope.
- 40.00 Point for the $\frac{1}{4}$ sec. cor. of secs. 19, and 20.
 Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.
- T12N R11W
 $\frac{1}{4}$
 S 19 | S 20
 1959
- Raise a mound of stone, W. of cor.
- Asc. 110-ft. over rocky and broken SE. slope.
- 44.70 Spur, slopes E.; desc. 130 ft. over broken NE. slope.

Subdivision of Township 12 North, Range 11 West

Chains

60.20 Ridge, bears E. and W.; desc. 40 ft. over N. slope.

70.60 Wash, 3 ft. deep, 1.30 chs. wide, drains W.; asc. 80 ft. over broken S. slope.

80.00 Point for the cor. of secs. 17, 18, 19, and 20.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 10 ins. in the ground, and in a mound of stone, to top of post, with brass cap mkd.

T12N	R11W
S 18	S 17
S 19	S 20
1959	

Land, rough and broken.
 Soil, sandy and rocky.
 Timber, Yellow Paloverde, and Catclaw Acacia.
 Undergrowth, Yucca, Saguaro Cactus, and Ocotillo.

From the cor. of secs. 16, 17, 20, and 21.

S. $89^{\circ}42'$ W., bet. secs. 17, and 20.

Thence along rocky and broken S. slope; through desert vegetation.

4.40 Desc. 120 ft. over rocky and broken NW. slope.

26.40 Rut road, bears NE. and SW.

33.00 Wash, 4 ft. deep, 1.20 chs. wide, drains SW.; asc. 60 ft. over rocky and broken S. slope.

39.93 Point for the $\frac{1}{4}$ sec. cor. of secs. 17, and 20.Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 14 ins. in the ground, and in a mound of stone, to top of post, with brass cap mkd.

T12N	R11W
$\frac{1}{4}$	S 17
	S 20
1959	

Desc. 80 ft. over rocky and broken S. to SW. slope.

79.86 The cor. of secs. 17, 18, 19, and 20.

Land, rough and broken.
 Soil, sandy and rocky.
 Timber, Yellow Paloverde, and Catclaw Acacia.
 Undergrowth, Yucca, Saguaro Cactus, and Ocotillo.

N. $89^{\circ}58'$ W., bet. secs. 18, and 19.

Desc. 80 ft. over rocky and broken NW. slope; through desert vegetation.

40.00 Point for the $\frac{1}{4}$ sec. cor. of secs. 18, and 19.Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., on bedrock, and in a mound of stone, 6 ft. base, to top of post, with brass cap mkd.

Subdivision of Township 12 North, Range 11 West

Chains

T12N R11W

$\frac{1}{4}$ S 18
S 19

1959

Desc. 90 ft. over rocky and broken NW. slope.

44.00 Wash, 3 ft. deep, 40 lks. wide, drains SSW.; thence desc. along broken and rocky S. slope.

79.27 Intersect the W. bdy. of T., at the cor. of secs. 13, 18, 19, and 24, which is monumented with an iron post, set, marked, and witnessed as described in the official record.

Land, rough and broken.
Soil, sandy and rocky.
Timber, Yellow Paloverde, and Catclaw Acacia.
Undergrowth, Yucca, Saguaro Cactus, and Ocotillo.

From the cor. of secs. 17, 18, 19, and 20.

N. 0°03' W., bet. sec. 17, and 18.

Desc. over rocky and broken W. to NW. slope; through desert vegetation.

13.50 Wash, 2 ft. deep, 30 lks. wide, drains SW; asc. 155 ft. over rocky and broken W. to SW. slope.

40.00 Point for the $\frac{1}{4}$ sec. cor. of secs. 17, and 18.

Set an iron post, 30 ins. long, 2 $\frac{1}{2}$ ins. diam., 10 ins. in the ground, and in a mound of stone, 4 ft. base, to top of post, with brass cap mkd.

T12N R11W

$\frac{1}{4}$
S 18 | S 17

1959

Asc. 70 ft. over rocky and broken SW. slope.

47.60 Spur, slopes W.; desc. 120 ft. over rough and broken NW. to W. slope.

58.20 Draw, drains SW.; asc. 130 ft. over rough and broken W. to SW. slope.

67.30 Ridge spur, slopes W.; desc. 20 ft. over broken NW. slope.

80.00 Point for the cor. of secs. 7, 8, 17, and 18.

Set an iron post, 30 ins. long, 2 $\frac{1}{2}$ ins. diam., 8 ins. in the ground, to bedrock, and in a mound of stone, 4 ft. base to top of post, with brass cap mkd.

T12N R11W

S 7 | S 8
S 18 | S 17

1959

Land, rough and broken.
Soil, sandy and rocky.
Timber, Yellow Paloverde, and Catclaw Acacia.
Undergrowth, Yucca, Saguaro Cactus, and Ocotillo.

Subdivision of Township 12 North, Range 11 West

Chains

From the cor. of secs. 8, 9, 16, and 17.

S. $89^{\circ}40'$ W., bet. secs. 8, and 17.

Desc. 90 ft. over broken NW. slope; through desert vegetation.

10.10 Wash, 2 ft. deep, 30 lks. wide, drains SW.; thence over rolling and broken S. slope.

23.30 Wash, 3 ft. deep, 20 lks. wide, drains SE.; asc. 150 ft. over broken NE. slope.

39.94 Point for the $\frac{1}{4}$ sec. cor. of secs. 8, and 17.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., on bedrock, and in a mound of stone, 4 ft. base, to top of post, with brass cap mkd.

T12N R11W

$\frac{1}{4}$ $\frac{S 8}{S 17}$

1959

Asc. 160 ft. over broken NE. slope.

62.00 Ridge spur, slopes N.; desc. 200 ft. over broken NW. slope.

79.88 The cor. of secs. 7, 8, 17, and 18.

Land, rough and broken.

Soil, sandy and rocky.

Timber, Yellow Paloverde, and Catclaw Acacia.

Undergrowth, Yucca, Saguaro Cactus, and Ocotillo.

S. $89^{\circ}57'$ W., bet. secs. 7, and 18.

Desc. 340 ft. over rough and broken W. to SW. slope; through desert vegetation.

25.80 Wash, 3 ft. deep, 30 lks. wide, drains SW.; asc. 110 ft. over rocky and broken SE. slope.

39.00 Ridge, bears NE. and SW.; desc. over NW. slope.

40.00 Point for the $\frac{1}{4}$ sec. cor. of secs. 7, and 18.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 8 ins. in the ground to bedrock, and in a mound of stone, 4 ft. base to top of post, with brass cap mkd.

T12N R11W

$\frac{1}{4}$ $\frac{S 7}{S 18}$

1959

Desc. 150 ft. over rough and broken W. to SW. slope.

79.37 Intersect the W. bdy. of T., at the cor. of secs. 7, 12, 13, and 18, which is monumented with an iron post, set, marked, and witnessed as described in the official record.

Land, rough and broken.

Soil, sandy and rocky.

Timber, Yellow Paloverde, and Catclaw Acacia.

Undergrowth, Yucca, Saguaro Cactus, and Ocotillo.

Subdivision of Township 12 North, Range 11 West

Chains

From the cor. of secs. 7, 8, 17, and 18.

N. 0°03' W., bet. secs. 7, and 8.

Desc. 60 ft. over broken W. to NW. slope; through desert vegetation.

15.20 Ridge spur, slopes N. 80° W.; desc. 70 ft. over broken N. slope.

20.00 Wash, 4 ft. deep, 30 lks. wide, drains W.; asc. over broken W. to SW. slope.

40.00 Point for the $\frac{1}{4}$ sec. cor. of secs. 7, and 8.Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 10 ins. in the ground, and in a mound of stone, $3\frac{1}{2}$ ft. base, to top of post, with brass cap mkd.

T12N R11W

 $\frac{1}{4}$

S 7 | S 8

1959

Asc. over rough and broken SW. slope.

75.80 Wash, 2 ft. deep, 30 lks. wide, drains SW.; asc. over rocky and broken SE. slope.

80.00 Point for the cor. of secs. 5, 6, 7, and 8.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., on bedrock, and in a mound of stone, 4 ft. base, to top of post, with brass cap mkd.

T12N R11W

S 6 | S 5

S 7 | S 8

1959

Land, rough and broken.

Soil, sandy and rocky.

Timber, Yellow Paloverde, and Catclaw Acacia.

Undergrowth, Yucca, Saguaro Cactus, and Ocotillo.

From the cor. of secs. 4, 5, 8, and 9.

S. 89°41' W., bet. secs. 5, and 8.

Thence along rough and broken N. slope; through desert vegetation.

34.30 Ridge, bears NW. and SE.; desc. 120 ft. over rocky and broken SW. slope.

39.94 Point for the $\frac{1}{4}$ sec. cor. of secs. 5, and 8.Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., on bedrock, and in a mound of stone, 5 ft. base, to top of post, with brass cap mkd.

T12N R11W

 $\frac{1}{4}$ S 5

S 8

1959

Desc. 310 ft. over rocky and broken SW. slope.

Subdivision of Township 12 North, Range 11 West

Chains	
77.20	Wash, 2 ft. deep, 30 lks. wide, drains SW.; asc. over rocky and broken SE. slope.
79.88	<p>The cor. of secs. 5, 6, 7, and 8.</p> <p>Land, rough and broken. Soil, sandy and rocky. Timber, Yellow Paloverde. Undergrowth, Yucca, Saguaro Cactus, and Ocotillo.</p>
	N. 89°53' W., bet. secs. 6, and 7.
	Asc. 20 ft. over rocky SE. slope; through desert vegetation.
.80	Ridge, bears NE. and SW.; desc. 220 ft. over broken SW. slope.
25.80	Wash, 2 ft. deep, 1.50 chs. wide, drains S.; thence over broken S. slope.
28.40	Wash, 2 ft. deep, 70 lks. wide, drains S.; asc. 70 ft. over broken NE. slope.
40.00	<p>Point for the $\frac{1}{4}$ sec. cor. of secs. 6, and 7.</p> <p>Set an iron post, 30 ins. long, 2$\frac{1}{2}$ ins. diam., on bedrock, and in a mound of stone, 4 ft. base, to top of post, with brass cap mkd.</p>
	<p style="text-align: center;">T12N R11W $\frac{1}{4}$ $\frac{S 6}{S 7}$ 1959</p>
	Asc. 470 ft. over rough and broken NE. slope.
79.48	<p>Intersect the W. bdy. of T., at the cor. of secs. 1, 6, 7, and 12, which is monumented with an iron post, set, marked, and witnessed as described in the official record.</p> <p>Land, rough and broken. Soil, sandy and rocky. Timber, Yellow Paloverde. Undergrowth, Yucca, Saguaro Cactus, and Ocotillo.</p>
	From the cor. of secs. 5, 6, 7, and 8.
	N. 0°03' W., bet. secs. 5, and 6.
	Asc. 20 ft. over rocky SE. slope; through desert vegetation.
5.40	Ridge, bears NE. and SW.; desc. over broken W. slope.
13.40	Desc. 50 ft. over broken N. slope.
17.80	Wash, 4 ft. deep, 1.30 chs. wide, drains W.; asc. 240 ft. over rocky and broken SE. slope.
40.00	<p>Point for the $\frac{1}{4}$ sec. cor. of secs. 5, and 6.</p> <p>Set an iron post, 30 ins. long, 2$\frac{1}{2}$ ins. diam., 20 ins. in the ground, and in a collar of stone, with brass cap mkd..</p>

Subdivision of Township 12 North, Range 11 West

Chains

T12N R11W

 $\frac{1}{4}$

S 6 | S 5

1959

Raise a mound of stone, W. of cor.

Asc. 70 ft. over rocky and broken SE. slope.

50.30 Ridge, bears NE. and SW.; desc. 70 ft. over rocky and broken NW. slope.

61.41 Intersect the N. bdy. of T. 12 N.; R. 11 W., (third standard parallel north)

Point for the closing cor. of secs. 5, and 6.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 6 ins. in the ground to bedrock, and in a mound of stone, 4 ft. base to top of post, with brass cap mkd.

T13N R11W

S 32

S 6 | S 5

c-c

T12N R11W

1959

From this point, the standard $\frac{1}{4}$ cor. of sec. 32, which is monumented with an 1 inch diam., iron post, set, marked and witnessed as described in the official record, bears N. $89^{\circ}58'$ E., 12 lks. dist.

Land, rough and broken.

Soil, sandy and rocky.

Timber, Yellow Paloverde.

Undergrowth, Yucca, Saguaro Cactus, and Ocotillo.

Point for the N. $\frac{1}{4}$ sec. cor. of sec. 5, at midpoint and on the N. bdy. of T.

At the cor. point.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 6 ins. in the ground to bedrock, and in a mound of stone, 4 ft. base to top of post, with brass cap mkd. $\frac{1}{4}$ S 5

T12N R11W

1959

From this point, the standard cor. of secs. 32, and 33, which is monumented with a 3 inch diam., iron post, set, marked, and witnessed as described in the official record, bears N. $89^{\circ}58'$ E., 24 lks. dist.Point for the N. $\frac{1}{4}$ sec. cor. of sec. 6, at 40.00 chains in departure west of the closing cor. of secs. 5 and 6, sec. 5, and 6.

At the cor. point.

Subdivision of Township 12 North, Range 11 West

Chains

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 8 ins. in the ground to bedrock, and in a mound of stone, $3\frac{1}{2}$ ft. base to top of post, with brass cap mkd.

$\frac{1}{4}$ S 6
 T12N R11W
 1959

From this cor. the standard cor. of secs. 31, and 32, which is monumented with an 3 inch diam., iron post, set, marked, and witnessed as described in the official record, bears N. $89^{\circ}58'$ E., 12 lks. dist.

General Description

The land within Township 12 North, Range 11 West, is principally rough and broken mountainous, with the land in secs. 3, 4, 5, 6, 7, 8, 9, 10, 16, 17, 18, 19, 20, 30, and NW $\frac{1}{4}$ sec. 21 with a westerly exposure and drainage towards the Big Sandy River, the remainder of township has a southerly exposure and drainage towards the Santa Maria River. The elevation of the township ranges from about 2500 ft. above sea level in the lowest point, to a maximum of 5600 ft.

The soil is principally sandy and rocky, with numerous rock outcrops, covered with desert vegetation, of timber, Yellow Paloverde, and Catclaw Acacia; undergrowth, of Yucca, Saguaro Cactus and Ocotillo.

There is one rut road bearing northeasterly from W. bdy. of sec. 31.

Chains

4-680
(Feb., 1950)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FIELD ASSISTANTS

NAMES	CAPACITY
Max E. Swindle	Transit
Darwin L. Turner	Notekeeper
James R. Munson	Chairman
Paul D. Hanson	Chainman and Flagman
Wallace R. Ott	Flagman
Leland C. Allan	Cornerman
George H. Cornell	Cornerman

CERTIFICATE OF CADASTRAL ENGINEER

I, DeWitt A. Crain, HEREBY CERTIFY upon honor that, in
pursuance of special instructions bearing date of the 17th day of November, 1958,
I have surveyed the subdivisional lines of Township 12 North, Range 11 West.

of the Gila & Salt River Meridian, in the State of Arizona, which are
represented in the foregoing field notes as having been executed by me and under my direction; and that
said survey has been made in strict conformity with said instructions, the Manual of Instructions for the
Survey of the Public Lands of the United States, and in the specific manner described in the foregoing
field notes.

Salt Lake City, Utah
July 21, 1959

DeWitt A. Crain
Cadastral Surveyor

CERTIFICATE OF APPROVAL

BUREAU OF LAND MANAGEMENT,
Washington, D. C., DEC 3 1959, 19

The foregoing field notes of the survey of the subdivisional lines of Township 12 North,
Range 11 West.

executed by DeWitt A. Crain

having been critically examined and found correct, are hereby approved.

Clark J. Gorman
Acting Cadastral Engineering Staff Officer.

CERTIFICATE OF TRANSCRIPT

~~I CERTIFY that the foregoing transcript of the field notes of the above-described surveys in~~
~~, is a true copy of the original field notes.~~

~~Cadastral Engineering Staff Officer.~~