

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FIELD NOTES

of the

 DEPENDENT RESURVEY

 of the

 EAST AND WEST BOUNDARIES

 and the

 SUBDIVISIONAL LINES

 and the

 RETRACEMENT

 of a portion of the

 NORTH BOUNDARY

 of

 TOWNSHIP 9 SOUTH, RANGE 27 EAST

Of the Gila and Salt River *Meridian*,

 In the State of Arizona

EXECUTED BY

Dell Cazier, Cadastral Surveyor

Alburn D. Griffin, Surveying Aide

Under special instructions dated November 8, 19 60, *which provided*
for the surveys included under Group No. 357, *approved* November 15, 1960
and assignment instructions dated February 13, 19 61

Survey commenced February 27, 19 61
Survey completed March 27, 19 61

(1A)

BOOK 4665

INDEX DIAGRAM

Township 9 South, Range 27 East

9					
8 6 39	40 5 39	32 4 31	26 3 26	20 2 20	14 1 14
7 7 38	38 8 37	31 9 30	25 10 25	19 11 18	13 12 13
7 18 36	37 17 36	30 16 29	24 15 24	18 14 17	12 18 12
6 19 35	35 20 34	29 21 28	23 22 23	17 23 17	11 24 11
6 30 33	34 29 33	28 28 27	22 27 22	16 26 15	10 25 9
5 31	32 32	27 33	21 34	15 35	9 36 1

BOOK 4665

Township 9 South, Range 27 East, Arizona

16

Chains

The north and west boundaries were surveyed in 1875 by T. F. White. The south and east boundaries were surveyed in 1885 by L. Wolfley. The subdivisional lines were surveyed in 1885 by J. C. Smith. The west boundary was resurveyed in 1904 by P. Contzen. The north boundary was resurveyed in 1957 by D. E. Harding. The south boundary was concurrently resurveyed under Group No. 351 Arizona.

The following field notes are those of the dependent resurvey of the east and west boundaries and the subdivisional lines of T. 9 S., R. 27 E., and a retracement of a portion of the north boundary.

This survey was executed in accordance with the specifications set forth in the Manual of Surveying Instructions, 1947, and the Special Instructions dated August 10, 1960.

Only the true line bearings and horizontal distances for the surveyed lines are given in the notes. Unless described, all corners were monumented with standard iron posts, 30 inches long, 2½ inches in diameter, flanged at the bases and with brass caps riveted to the tops.

The geographic position for the southeast corner of the township is in latitude 32°36'01.115" N. and longitude 109°31'40.110" W. as determined by direct tie to U.S.C. & G.S. triangulation station "Tan" located in section 36.

The magnetic declination was read at a number of stations throughout the township and the average of these readings was found to be 13° East.

Dependent Resurvey, E. Bdy., T. 9 S., R. 27 E., Arizona

Reestablishment of the Survey in 1885 by L. Wolfley

From the cor. of Ts. 9 and 10 S., Rs. 27 and 28 E., monumented by an iron post as described in the field notes of the resurvey of T. 10 S. R. 28 E., Group 351, from which

Triangulation Station TAN bears N. 64°34'30" W., 70.85 chs. distant.

N. 0°16' E., bet. secs. 31 and 36.

Over badly eroded land, with series of washes draining W.

17.50 Leave eroded land, cont. over nearly level land.

23.80 Fence, bears S. 75° E. and N. 75° W.

32.00 Road, bears E. and W.

33.60 Dyke, 3 ft. high, 12 ft. wide, bears irregularly E. and W., approximately 8 chs. on each side.

40.14 Point for the ½ sec. cor. of secs. 31 and 36, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 24 ins. in the ground, mound with stone to top, cap mkd.

T9S
R27E R28E
½
S36 | S31
1961

Chains

Deposit glass at base of iron post.

70.30

Fence, bears E. and W.

80.28

The corner of secs. 25, 30, 31 and 36, monumented by a badly deteriorated wood post.

At the corner point

Set the iron post 24 ins. in the ground, cap mkd.

T9S

R27E R28E

S25 | S30

S36 | S31

1961

Deposit glass at base of iron post.

Raise a mound of stone, 3 ft. base, W. of iron post.

Land, nearly level and partly eroded.

Soil, clay.

Timber, none; undergrowth, mesquite.

N. 0°04' E., bet. secs. 25 and 30.

Over gently rolling land.

28.00

West edge of small spur, bears E. and W.

40.00

Point for the $\frac{1}{4}$ sec. cor. of secs. 25 and 30, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 22 ins. in the ground, mound with stone to top, cap mkd.

T9S

R27E R28E

 $\frac{1}{4}$

S25 | S30

1961

Deposit glass at base of iron post.

80.00

Point for the cor. of secs. 19, 24, 25 and 30, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 24 ins. in the ground, cap mkd.

T9S

R27E R28E

S24 | S19

S25 | S30

1961

Deposit glass at base of iron post.

Land, gently rolling.

Soil, clay.

Timber, none; undergrowth, mesquite.

N. 0°04' E., bet. secs. 19 and 24.

Over nearly level land, through desert vegetation.

BOOK 4665

Dependent Resurvey, E. Bdy., T. 9 S., R. 27 E., Arizona 3.

Chains	
29.00	Wash, 80 lks. wide, drains NW.
40.00	<p>Point for the $\frac{1}{4}$ sec. cor. of secs. 19 and 24, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 20 ins. in the ground, mound with stone to top, cap mkd.</p>
	<p style="text-align: center;">T9S R27E R28E $\frac{1}{4}$ S24 S19 1961</p>
	Deposit glass at base of iron post.
50.70	Enter series of deep clay washes, draining irregularly W.
61.90	Leave wash area, cont. along nearly level land.
80.00	<p>Point for the sec. cor. of secs. 13, 18, 19 and 24, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 12 ins. in the ground, mound with stone to top, cap mkd.</p>
	<p style="text-align: center;">T9S R27E R28E S13 S18 S24 S19 1961</p>
	<p>Land, nearly level. Soil, sand and clay. Timber, none; undergrowth, mesquite and creosote.</p>
	N. 0°04' E., bet. secs. 13 and 18.
	Over nearly level land, through desert vegetation.
21.80	Road, unimproved, bears E. and W.
31.20	Wash, 30 lks. wide, 3 ft. deep, drains W.
39.10	Road, unimproved, bears NW. and SE.
40.00	<p>Point for the $\frac{1}{4}$ sec. cor. of secs. 13 and 18, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 10 ins. in the ground, mound with stone to top, cap mkd.</p>
	<p style="text-align: center;">T9S R27E R28E $\frac{1}{4}$ S13 S18 1961</p>
40.40	Wash, 30 lks. wide, 1 ft. deep, drains W.
45.10	Enter rolling land.
80.00	<p>Point for the cor. of secs. 7, 12, 13 and 18, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 18 ins. in the ground, mound with stone to top,</p>

BOOK 4665

Dependent Resurvey, E. Bdy., T. 9 S., R. 27 E., Arizona

4.

4

Chains

cap mkd.

T9S
R27E R28E
S12|S 7
S13|S18
1961

Deposit glass at base of iron post.

Land, nearly level to rolling.

Soil, sandy.

Timber, none; undergrowth, mesquite and creosote.

N. 0°04' E., bet. secs. 7 and 12.

Over rolling land, through desert vegetation.

15.90 Wash, 180 lks. wide, 3 ft. deep, drains W.

40.00 The $\frac{1}{4}$ sec. cor. of secs. 7 and 12, monumented by a volcanic stone as described in the official record.

At the corner point

Set the iron post 18 ins. in the ground, cap mkd.

T9S
R27E R28E
 $\frac{1}{4}$
S12|S 7
1961

Deposit glass at base of iron post.

Raise a mound of stone N. of corner.

N. 0°06' E., beginning new measurement.

37.90 Wash, 40 lks. wide, 3 ft. deep, drains W.

39.58 Point selected for the witness cor. of secs. 1, 6, 7 and 12.

Set the iron post 20 ins. in the ground, mound with stone to top, cap mkd.

T9S
R27E R28E
S 1|S 6
S12|S 7
WC
1961

Deposit glass at base of iron post.

39.78 Point for the cor. of secs. 1, 6, 7 and 12, at proportionate distance; there is no remaining evidence of the original corner. Point falls in a small wash draining W.

Land, rolling.

Soil, coarse sand.

Timber, none; undergrowth, mesquite and creosote.

BOOK 4665

Dependent Resurvey, E. Bdy., T. 9 S., R. 27 E., Arizona

5.

Chains

N. 0°06' E., bet. secs. 1 and 6.

Over rolling land, through desert vegetation.

39.78

Point for the $\frac{1}{4}$ sec. cor. of secs. 1 and 6, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 18 ins. in the ground, mound with stone to top, cap mkd.

T9S
R27E R28E

$\frac{1}{4}$
S1|S6
1961

Deposit glass at base of iron post.

73.99

The cor. of Ts. 8 and 9 S., Rs. 27 and 28 E., monumented by an iron post as described in the official record.

Land, rolling.

Soil, coarse sand and gravel.

Timber, none; undergrowth, mesquite and creosote brush.

Dependent Resurvey, W. Bdy., T. 9 S., R. 27 E., Arizona

Reestablishment of the Survey in 1904 by P. Contzen

From the cor. of Ts. 9 and 10 S., Rs. 26 and 27 E., monumented by an iron post as described in the official record.

N. 0°28' E., on the W. bdy. of sec. 31.

Over gently rolling land, through desert vegetation.

40.32

Point for the $\frac{1}{4}$ sec. cor. of sec. 31, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 20 ins. in the ground, cap mkd.

T9S
R27E

$\frac{1}{4}$
|S31
1961

80.20

Point for the cor. of secs. 30 and 31, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 24 ins. in the ground, in a tire collar, cap mkd.

T9S
R27E

|S30
|S31
1961

from which

B.M. 23 R.S. bears N. 0°57'30" E., 22.72 chs. dist.

Deposit glass at base of iron post.

BOOK 4665

Dependent Resurvey, W. Bdy., T. 9 S., R. 27 E., Arizona

6.

Chains

Land, gently rolling.
Soil, sandy.
Timber, none; undergrowth, mesquite and creosote brush.

N. 0°28' E., on the W. bdy. of sec. 30.

Over gently rolling land, through desert vegetation.

7.50 Road, unimproved, bears NE. and SW.

23.60 Road, unimproved, bears E. and W.

40.27 Point for the $\frac{1}{4}$ sec. cor. of sec. 30, at proportionate distance;
there is no remaining evidence of the original corner.

Set the iron post 10 ins. in the ground, mound with stones to top,
cap mkd.

T9S

R27E

$\frac{1}{4}$

| S30

1961

66.00 Wash, 200 lks. wide, 1 ft. deep, drains NE.

71.20 Fence, bears E. and W.

80.08 The cor. of secs. 19 and 30, monumented by a wood post, as
described in the official record.

At the corner point

Set the iron post 24 ins. in the ground, cap mkd.

T9S

R27E

| S19

| S30

1961

Deposit glass at base of iron post.

Land, rolling.

Soil, sandy.

Timber, none; undergrowth, mesquite and creosote brush.

N. 0°02' E., on the W. bdy. of sec. 19.

Over rolling land, through desert vegetation.

16.90 Wash, 50 lks. wide, 2 ft. deep, drains NE.

39.23 Point for the $\frac{1}{4}$ sec. cor. of sec. 19, at proportionate distance;
There is no remaining evidence of the original corner.

Set the iron post 20 ins. in the ground, cap mkd.

T9S

R27E

$\frac{1}{4}$

| S19

1961

Deposit glass at base of iron post.

BOOK 4665

Dependent Resurvey, W. Bdy., T. 9 S., R. 27 E., Arizona

7.

Chains

76.80

Wash, 300 lks. wide, 1 ft. deep, drains NE.

78.41

The cor. of secs. 18 and 19, monumented by a sandstone as described in the official record.

At the corner point

Set the iron post 24 ins. in the ground, cap mkd.

T9S
R27E
| S18
| S19
1961

Deposit glass at base of iron post.

Land, gently rolling.

Soil, sandy.

Timber, none; undergrowth, mesquite and creosote brush.

N. 0°12' E., on the W. bdy. of sec. 18.

Over gently rolling land, through desert vegetation.

39.78

The $\frac{1}{4}$ sec. cor. of sec. 18, monumented by a granite stone, as described in the official record.

At the corner point

Set the iron post 24 ins. in the ground, cap mkd.

T9S
R27E
 $\frac{1}{4}$
| S18
1961

Deposit glass at base of iron post.

N. 0°06' E., beginning new measurement.

39.83

The original cor. of secs. 7 and 18, monumented by a wood post, as described in the official record.

At the corner point

Set the iron post 24 ins. in the ground, cap mkd.

T9S
R27E
| S 7
| S18
1961

Deposit glass at base of iron post.

Land, gently rolling.

Soil, sandy.

Timber, none; undergrowth, mesquite and creosote.

N. 0°14' E., on the W. bdy. of sec. 7.

Over gently rolling land, through desert vegetation.

BOOK 4665

8 Dependent Resurvey; W. Bdy., T. 9 S., R. 27 E., Arizona

8.

Chains

- 2.17 The closing corner of secs. 12 and 13, T. 9 S., R. 26 E., monumented by a granite stone, as described in the official record.
- 23.60 Wash, 75 lks. wide, 2 ft. deep, drains NE.
- 39.61 The original $\frac{1}{4}$ sec. cor. of sec. 7, monumented by a wood post, as described in the official record.
- At the corner point
- Set the iron post 24 ins. in the ground, cap mkd.
- T9S
R27E
 $\frac{1}{4}$
| S 7
1961
- Deposit glass at base of iron post.
-
- N. 0°08' E., beginning new measurement.
- 39.69 Point for the sec. cor. of secs. 6 and 7, at proportionate distance; there is no remaining evidence of the original corner.
- Set the iron post 22 ins. in the ground, cap mkd.
- T9S
R27E
| S 6
| S 7
1961
- Deposit glass at base of iron post.
- Land, gently rolling.
Soil, coarse sand to gravel.
Timber, none; undergrowth, mesquite, cactus, and creosote brush.
-
- N. 0°08' E., on the W. bdy. of sec. 6.
- Over gently rolling land, through desert vegetation.
- 39.81 Point for the $\frac{1}{4}$ sec. cor. of sec. 6, at proportionate distance; there is no remaining evidence of the original corner.
- Set the iron post 20 ins. in the ground, cap mkd.
- T9S
R27E
 $\frac{1}{4}$
| S 6
1961
- Deposit glass at base of iron post.
- 78.40 Road, unimproved, bears S. 87°11' W. and N. 87°11' E.
- 79.50 The corner of Ts. 8 and 9 S., Rs. 26 and 27 E., monumented by an iron post, as described in the official record.
- Land, gently rolling.
Soil, coarse sand.
Timber, none; undergrowth, mesquite, creosote and cactus.
-

BOOK 4665

Retracement, Portion, N. Bdy., T. 9 S., R. 27 E., Arizona 9.

Chains

Retracement of the Resurvey in 1957 by D. E. Harding

From the cor. of secs. 3, 4, 33 and 34 on the N. bdy. of the township, monumented by an iron post as described in the official record.

N. 89°58' W., bet. secs. 4 and 33.

40.42

The $\frac{1}{4}$ sec. cor. of secs. 4 and 33, monumented by an iron post, as described in the official record.

Dependent Resurvey, Subdivisions, T. 9 S., R. 27 E., Arizona

Reestablishment of the Survey in 1885 by J. C. Smith

From the cor. of secs. 1, 2, 35 and 36, on the S. bdy. of the township.

N. 0°32' E., bet. secs. 35 and 36.

Over rolling land, through desert vegetation.

26.60

Road, unimproved, bears E. and W.

40.48

Point for the $\frac{1}{4}$ sec. cor. of secs. 35 and 36, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 20 ins. in the ground, cap mkd.

T 9S R27E
 $\frac{1}{4}$
 S 35|S 36
 1961

Deposit glass at base of iron post.

47.60

Road, bears NW. and E.

75.70

Wash, 40 lks. wide, 2 ft. deep, drains NE.

80.97

Point for the sec. cor. of secs. 25, 26, 35 and 36, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 20 ins. in the ground, cap mkd.

T 9S R27E
 S26|S25
 S35|S36
 1961

Deposit glass at base of iron post.

Land, rolling to nearly level.

Soil, sandy.

Timber, none; undergrowth, mesquite and creosote.

From the cor. of secs. 25, 30, 31 and 36, on the E. bdy. of the township.

N. 89°33' W., bet. secs. 25 and 36.

Chains

Over eroded land, through dense desert vegetation.

- 38.25 San Simon Wash, 200 lks. wide, 3 ft. deep, drains N.
- 40.00 Point for the $\frac{1}{4}$ sec. cor. of secs. 25 and 36, at proportionate distance; there is no remaining evidence of the original corner.
- Set the iron post 20 ins. in the ground, cap mkd.
- T 9S R27E
 $\frac{1}{4}$ $\frac{S\ 25}{S\ 36}$
1961
- Deposit glass at base of iron post.
- 50.35 Railroad track, single, bears N. 7°30' W. and S. 7°30' E.
- 50.85 Power transmission line, bears N. 7°30' W. and S. 7°30' E.
- 76.30 Wash, 50 lks. wide, 1 ft. deep, drains NE.
- 80.01 The corner of secs. 25, 26, 35 and 36.

Land, rolling and eroded.
Soil, clay and sand.
Timber, none; undergrowth, mesquite, creosote, sage and willows.

N. 1°50' W., bet. secs. 25 and 26.

Over level to rolling land, through desert vegetation.

- 4.10 Wash, 50 lks. wide, 12 ft. deep, drains NE.
- 40.51 The $\frac{1}{4}$ sec. cor. of secs. 25 and 26, monumented by a stone, as described in the official record.
- At the corner point
- Set the iron post 24 ins. in the ground, cap mkd.

T 9S R27E
 $\frac{1}{4}$
S26 | S25
1961

Deposit glass at base of iron post.

N. 0°51' E., beginning new measurement.

- 40.31 The corner of secs. 23, 24, 25 and 26, monumented by a stone, as described in the official record.
- At the corner point
- Set the iron post 24 ins. in the ground, cap mkd.

T 9S R27E
S23 | S24
S26 | S25
1961

from which

A windmill bears S. 55°59' W., 25.39 chs. dist.

BOOK 4665

Subdivisional Lines, T. 9 S., R. 27 E., Arizona

11.

Chains

Deposit glass at base of iron post.

Land, nearly level to rolling.

Soil, sandy.

Timber, none; undergrowth, mesquite and creosote.

From the cor. of secs. 19, 24, 25 and 30, on the E. bdy. of the township.

N. 88°59' W., bet. secs. 24 and 25.

Over nearly level land, through desert vegetation.

36.00 San Simon Wash, 200 lks. wide, 3 ft. deep, drains N.

40.37 Point for the $\frac{1}{4}$ sec. cor. of secs. 24 and 25, at proportionate distance. Point falls in San Simon Wash, not suitable for monumentation.

42.11 Point selected for the witness $\frac{1}{4}$ sec. cor. of secs. 24 and 25.

Set the iron post 22 ins. in the ground, cap mkd.

$$\begin{array}{c} \text{T 9S R27E} \\ \frac{1}{4} \begin{array}{c} \text{S 24} \\ \text{S 25} \end{array} \rightarrow \text{WC} \\ 1961 \end{array}$$

Deposit glass at base of iron post.

61.10 Southern Pacific Railroad track, bears N. 7°30' W. and S. 7°30' E.

61.70 Power transmission line, bears N. 7°30' W. and S. 7°30' E.

80.74 The corner of secs. 23, 24, 25 and 26.

Land, nearly level to rolling.

Soil, sandy.

Timber, none; undergrowth, mesquite.

N. 0°40' E., bet. secs. 23 and 24.

Over nearly level land, through desert vegetation.

18.80 Wash, 40 lks. wide, 3 ft. deep, drains NE.

40.23 The $\frac{1}{4}$ sec. cor. of secs. 23 and 24, monumented by a stone, as described in the official record.

At the corner point.

Set the iron post 20 ins. in the ground, cap mkd.

$$\begin{array}{c} \text{T 9S R27E} \\ \frac{1}{4} \\ \text{S23} | \text{S24} \\ 1961 \end{array}$$

Deposit glass at base of iron post.

N. 1°00' E., beginning new measurement.

40.15 The cor. of secs. 13, 14, 23 and 24, monumented by a stone, as described in the official record.

12

Chains

At the corner point

Set the iron post 20 ins. in the ground, mound with stone to top, cap mkd.

T 9S R27E
 S14 | S13
 S23 | S24
 1961

Deposit glass at base of iron post.

Land, level to gently rolling.

Soil, sandy.

Timber, none; undergrowth, mesquite and creosote brush.

From the corner of secs. 13, 18, 19 and 24, on the E. bdy. of the township.

N. 88°43' W., bet. secs. 13 and 24.

Over nearly level land, badly eroded; through desert vegetation.

39.81 Point for the $\frac{1}{4}$ sec. cor. of secs. 13 and 24, at proportionate distance; there is no remaining evidence of the original corner. Point falls in the bottom of San Simon Wash, course NW.

43.00 The center of San Simon Wash, about $\frac{1}{4}$ mile wide, 15 ft. deep, drains irregularly NW.

46.81 Point selected for the witness $\frac{1}{4}$ sec. cor. of secs. 13 and 24.

Set the iron post 18 ins. in the ground, mound with stone to top, cap mkd.

T 9S R27E
 $\frac{1}{4}$ $\frac{S 13}{S 24}$ WC
 1961

70.75 Southern Pacific Railroad track, bears N. 16°40' W. and S. 16°40' E.

71.35 Power transmission line, bears N. 7°30' W. and S. 7°30' E.

79.62 The corner of secs. 13, 14, 23 and 24.

Land, nearly level, badly eroded.

Soil, clay.

Timber, none; undergrowth, willows, mesquite, creosote and greasewood.

N. 0°24' W., bet. secs. 13 and 14.

Over rolling land, through desert vegetation.

26.40 Power transmission line, bears S. 19°05' E. and N. 19°05' W.

27.70 Southern Pacific Railroad track, bears S. 19°05' E., and N. 19°05' W.

32.30 Wash, 210 lks. wide, 15 ft. deep, drains NE.

38.69 Point for the $\frac{1}{4}$ sec. cor. of secs. 13 and 14, at proportionate distance; there is no remaining evidence of the original corner.

BOOK 4665

Subdivisional Lines, T. 9 S., R. 27 E., Arizona

13.

Chains	
	<p>Set the iron post 18 ins. in the ground, cap mkd.</p> <p style="text-align: center;">T 9S R27E $\frac{1}{4}$ S14 S13 1961</p> <p>Deposit glass at base of iron post.</p>
61.90	Center of San Simon Wash, about $\frac{1}{4}$ mile wide, 15 ft. deep, drains irregularly N.
77.38	<p>The corner of secs. 11, 12, 13 and 14, monumented by a stone, as described in the official record.</p> <p>At the corner point</p> <p>Set the iron post 20 ins. in the ground, cap mkd.</p> <p style="text-align: center;">T 9S R27E S11 S12 S14 S13 1961</p> <p>Land, nearly level, badly eroded. Soil, clay. Timber, none; undergrowth, willows, mesquite, creosote and greasewood.</p>
40.10	<p>From the corner of secs. 7, 12, 13 and 18, on the E. bdy. of the township.</p> <p>S. 89°28' W., bet. secs. 12 and 13.</p> <p>Over rolling and nearly level land, through desert vegetation.</p> <p>Point for the $\frac{1}{4}$ sec. cor. of secs. 12 and 13, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 20 ins. in the ground, mound with stone to top, cap mkd.</p> <p style="text-align: center;">T 9S R27E $\frac{1}{4}$ S 12 S 13 1961</p>
80.20	<p>The corner of secs. 11, 12, 13 and 14.</p> <p>Land, rolling to nearly level. Soil, sandy, light rock and clay. Timber, none; undergrowth, mesquite, creosote, cactus, catclaw, greasewood and yucca.</p>
40.07	<p>N. 0°24' E., bet. secs. 11 and 12.</p> <p>Over nearly level land, through desert vegetation.</p> <p>Point for the $\frac{1}{4}$ sec. cor. of secs. 11 and 12, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 20 ins. in the ground, mound with stone to top, cap mkd.</p> <p style="text-align: center;">T 9S R27E $\frac{1}{4}$ S11 S12 1961</p>

BOOK 4665

Subdivisional Lines, T. 9 S. R. 27 E., Arizona

14.

Chains	
	Deposit glass at base of iron post.
80.14	The corner of secs. 1, 2, 11 and 12, monumented by a stone as described in the official record.
	At the corner point
	Set the iron post 20 ins. in the ground, cap mkd.
	$\begin{array}{r} T\ 9S\ R27E \\ S\ 2\ S\ 1 \\ \hline S11\ S12 \\ 1961 \end{array}$
	Land, nearly level. Soil, sand and clay. Timber, none; undergrowth, mesquite, creosote and catclaw.
	From the true point for corner of secs. 1, 6, 7 and 12, on the E. bdy. of the township.
	N. 89°30' W., bet. secs. 1 and 12.
	Over rolling to level land, through desert vegetation.
32.00	Low ridge, bears NW. and SE.
39.37	The $\frac{1}{4}$ sec. cor. of secs. 1 and 12, monumented by a stone, as described in the official record.
	At the corner point
	Set the iron post 15 ins. in the ground, mound with stone to top, cap mkd.
	$\begin{array}{r} T\ 9S\ R27E \\ \frac{1}{4}\ \frac{S\ 1}{S\ 12} \\ 1961 \end{array}$
	S. 88°55' W., beginning new measurement.
30.50	Enter series of deep clay washes, draining NW. and W.
40.30	The corner of secs. 1, 2, 11 and 12.
	Land, level to rolling. Soil, sandy and clay. Timber, none; undergrowth, mesquite, creosote and catclaw.
	N. 0°01' E., bet. secs. 1 and 2.
	Over nearly level land, badly eroded, through desert vegetation.
11.20	Small rocky ridge, bears E. and W.
39.64	Point for $\frac{1}{4}$ sec. cor. of secs. 1 and 2, at proportionate distance; there is no remaining evidence of the original corner. Point falls in small wash draining SW., and is deemed unsafe for corner.
39.99	Point selected for witness $\frac{1}{4}$ cor. of secs. 1 and 2.
	Set the iron post 18 ins. in the ground, mound with stone to top, cap mkd.

BOOK 4665

Subdivisional Lines, T. 9 S., R. 27 E., Arizona

15

Chains

T 9S R27E

$$\frac{1}{4}$$

S2	S1
----	----

$$\downarrow$$
 WC

1961

74.63 The true point for the cor. of secs. 1, 2, 35 and 36, on the N. bdy. of the township. The witness cor. bears N. 89°58' W., 0.35 chs. dist., monumented by an iron post as described in the official record.

Land, gently rolling.
Soil, clay.
Timber, none; undergrowth, creosote brush.

From the corner of secs. 2, 3, 34 and 35 on the S. bdy. of the township.

N. 0°10' E., bet. secs. 34 and 35.

Over gently rolling land, through dense desert vegetation.

21.30 Wash, 150 lks. wide, 2 ft. deep, drains NE.

40.97 The $\frac{1}{4}$ sec. cor. of secs. 34 and 35, monumented by a stone as described in the official record.

At the corner point

Set the iron post 24 ins. in the ground, cap mkd.

T 9S R27E

$$\frac{1}{4}$$

S34	S35
-----	-----

1961

Deposit glass at base of iron post.

N. 1°13' E., beginning a new measurement.

37.70 Road, unimproved, bears SE. and NW.

39.91 Point for the cor. of secs. 26, 27, 34 and 35, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 20 ins. in the ground, mound with stone to top, cap mkd.

T 9S R27E

S27	S26
S34	S35

1961

Deposit glass at base of iron post.

Land, gently rolling.
Soil, gravel.
Timber, none; undergrowth, creosote brush.

From the corner of secs. 25, 26, 35 and 36.

S. 89°57' W., bet. secs. 26 and 35.

Over gently rolling land, through desert vegetation.

16

Chains

- 9.30 Wash, 75 lks. wide, 3 ft. deep, drains NE.
- 14.70 Wash, 20 lks. wide, 2 ft. deep, drains SE.
- 25.40 Road, unimproved, bears N. and S.
- 39.98 Point for the $\frac{1}{4}$ sec. cor. of secs. 26 and 35, at proportionate distance; there is no remaining evidence of the original corner.
- Set the iron post 20 ins. in the ground, cap mkd.

T 9S R27E

$$\frac{1}{4} \begin{array}{l} S 26 \\ S 35 \end{array}$$

1961

Deposit glass at base of iron post.

- 72.60 Road, unimproved, bears NW. and SE.
- 79.97 The cor. of secs. 26, 27, 34 and 35.

Land, gently rolling.
Soil, sand and gravel.
Timber, none; undergrowth, creosote and mesquite.

N. 0°43' E., bet. secs. 26 and 27.

Over gently rolling land, through desert vegetation.

- 4.90 Road, unimproved, bears N. 70° W. and SE.
- 17.80 Wash, 25 lks. wide, 2 ft. deep, drains E.
- 39.90 Point for the $\frac{1}{4}$ sec. cor. of secs. 26 and 27, at proportionate distance; there is no remaining evidence of the original corner.
- Set the iron post 22 ins. in the ground, cap mkd.

T 9S R27E

$$\frac{1}{4} \begin{array}{l} S27 | S26 \end{array}$$

1961

- 79.80 The corner of secs. 22, 23, 26 and 27, monumented by a wood stake, as described in the official record.

At the corner point

Set the iron post 24 ins. in the ground, cap mkd.

T 9S R27E

$$\begin{array}{l} S22 | S23 \\ S27 | S26 \end{array}$$

1961

Deposit glass at base of iron post.

Land, gently rolling.
Soil, rocky.
Timber, none; undergrowth, mesquite and creosote brush.

BOOK 4665

Subdivisional Lines, T. 9 S., R. 27 E., Arizona

17.

Chains

From the corner of secs. 23, 24, 25 and 26.

S. 89°08' W., bet. secs. 23 and 26.

Over gently rolling land, through desert vegetation.

19.60 Wash, 100 lks. wide, 8 ft. deep, drains NE.

39.19 Point for the $\frac{1}{4}$ sec. cor. of secs. 23 and 26, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 22 ins. in the ground, cap mkd.

T 9S R27E

$\frac{1}{4}$ $\frac{S\ 23}{S\ 26}$

1961

Deposit glass at base of iron post.

79.38 The corner of secs. 22, 23, 26 and 27.

Land, gently rolling.

Soil, clay.

Timber, none; undergrowth, mesquite, creosote and catclaw.

North, bet. secs. 22 and 23.

Over gently rolling land, through desert vegetation.

21.10 Wash, 40 lks. wide, 3 ft. deep, drains NE.

39.70 Point for the $\frac{1}{4}$ sec. cor. of secs. 22 and 23, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 22 ins. in the ground, cap mkd.

T 9S R27E

$\frac{1}{4}$
S22|S23

1961

79.40 Point for the cor. of secs. 14, 15, 22 and 23, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 24 ins. in the ground, cap mkd.

T 9S R27E

S15|S14
S22|S23

1961

Deposit glass at base of iron post.

Land, gently rolling.

Soil, sandy.

Timber, none; undergrowth, creosote brush.

From the cor. of secs. 13, 14, 23 and 24.

S. 88°30' W., bet. secs. 14 and 23.

Over nearly level land, through desert vegetation.

31.30 Wash, 120 lks. wide, 8 ft. deep, drains NE.

18

Chains	
38.20	Wash, 40 lks. wide, 8 ft. deep, drains NE.
39.79	Point for the $\frac{1}{4}$ sec. cor. of secs. 14 and 23 at proportionate distance; there is no remaining evidence of the original corner. Point falls in small wash draining NE., not monumented.
41.79	Point selected for the witness $\frac{1}{4}$ sec. cor. of secs. 14 and 23. Set the iron post 22 ins. in the ground, cap mkd.
	$T\ 9S\ R27E$ $\frac{1}{4} \begin{array}{c} S\ 14 \\ S\ 23 \end{array} \rightarrow WC$ <p style="text-align: center;">1961</p>
	Deposit glass at base of iron post.
79.58	The corner of secs. 14, 15, 22 and 23. Land, nearly level. Soil, sandy clay and rocky. Timber, none; undergrowth, mesquite, creosote, cactus and catclaw.
	N. $0^{\circ}07'$ W., bet. secs. 14 and 15.
	Over gently rolling land, through desert vegetation.
39.70	Point for the $\frac{1}{4}$ sec. cor. of secs. 14 and 15, at proportionate distance; there is no remaining evidence of the original corner. Set the iron post 24 ins. in the ground, cap mkd.
	$T\ 9S\ R27E$ $\frac{1}{4} \begin{array}{c} S15 \\ S14 \end{array}$ <p style="text-align: center;">1961</p>
	Deposit glass at base of iron post.
79.40	Point for the cor. of secs. 10, 11, 14 and 15, at proportionate distance; there is no remaining evidence of the original corner. Set the iron post 22 ins. in the ground, cap mkd.
	$T\ 9S\ R27E$ $\begin{array}{c} S10\ S11 \\ S15\ S14 \end{array}$ <p style="text-align: center;">1961</p>
	Deposit glass at base of iron post.
	Land, gently rolling. Soil, sandy clay. Timber, none; undergrowth, creosote brush.
	From the corner of secs. 11, 12, 13 and 14.
	S. $89^{\circ}57'$ W., bet. secs. 11 and 14.
	Over nearly level land, through desert vegetation.
7.00	Center of San Simon Wash, 500 lks. wide, 20 ft. deep, drains irregularly N.
16.40	Southern Pacific Railroad track, bears S. $18^{\circ}25'$ E. and N. $18^{\circ}25'$ W.

BOOK 4665

Subdivisional Lines, T. 9 S., R. 27 E., Arizona

19.

Chains	
16.80	Power transmission line, bears S. 18°25' E. and N. 18°25' W.
39.60	Point for the $\frac{1}{4}$ sec. cor. of secs. 11 and 14, at proportionate distance; there is no remaining evidence of the original corner. Set the iron post 24 ins. in the ground, cap mkd. T 9S R27E $\frac{1}{4}$ $\frac{S 11}{S 14}$ 1961 Deposit glass at base of iron post.
79.20	The cor. of secs. 10, 11, 14 and 15. Land, nearly level. Soil, clay and light rock. Timber, none; undergrowth, mesquite, willows, greasewood, creosote, cactus and yucca.
33.00	N. 0°06' W., bet. secs. 10 and 11. Over nearly level land, through desert vegetation.
33.00	Fence, bears N. 20° E. and S. 20° W.
39.70	Point for the $\frac{1}{4}$ sec. cor. of secs. 10 and 11, at proportionate distance; there is no remaining evidence of the original corner. Set the iron post 22 ins. in the ground, cap mkd. T 9S R27E $\frac{1}{4}$ S10 S11 1961 Deposit glass at base of iron post.
47.00	Enter deep clay washes draining NE.'
54.00	Leave washes.
77.60	Fence, bears E. and W.
78.90	Wash, 40 lks. wide, 7 ft. deep, drains E.
79.40	Point for the cor. of secs. 2, 3, 10 and 11, at proportionate distance; there is no remaining evidence of the original corner. Point falls in a wash and is not monumented.

Chains

Land, level, badly eroded.
Soil, sandy clay.
Timber, none; undergrowth, mesquite and creosote brush.

From the cor. of secs. 1, 2, 11 and 12.

S. 89°28' W., bet. secs. 2 and 11.

Over badly eroded level land, through desert vegetation.

18.10 Center of San Simon Wash, about $\frac{1}{4}$ mile wide, 30 ft. deep, drains irregularly N.

30.50 Southern Pacific Railroad track, bears S. 8°55' E. and N. 8°55' W.

31.10 Power transmission line, bears S. 8°55' E. and N. 8°55' W.

38.95 Point selected for the witness $\frac{1}{4}$ sec. cor. of secs. 2 and 11.

Set the iron post 20 ins. in the ground, cap mkd.

T 9S R 27E

$\frac{1}{4}$ ← $\frac{S 2}{S 11}$

WC

1961

Deposit glass at base of iron post.

39.95 Point for the $\frac{1}{4}$ sec. cor. of secs. 2 and 11, at proportionate distance; there is no remaining evidence of the original corner. Point falls in a wash, 220 lks. wide, 2 ft. deep, drains NE.

72.70 Fence, bears NE. and SW.

77.50 Wash, 40 lks. wide, 7 ft. deep, drains NE.

79.90 True point for the cor. of secs. 2, 3, 10 and 11.

Land, level and badly eroded.
Soil, sandy clay.
Timber, none; undergrowth, mesquite and creosote brush.

N. 0°03' E., bet. secs. 2 and 3.

Over level land, badly eroded.

1.00 Point selected for the witness cor. of secs. 2, 3, 10 and 11.

Set the iron post 20 ins. in the ground, cap mkd.

Chains

T 9S R27E
 S 3 | S 2
 S10 | S11
 ↓ WC
 1961

Deposit glass at base of iron post.

- 28.60 Leave series of washes draining E., continue over gently rolling land.
- 39.70 Point for the $\frac{1}{4}$ sec. cor. of secs. 2 and 3 at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 18 ins. in the ground, mound with stone to top, cap mkd.

T 9S R27E
 $\frac{1}{4}$
 S3 | S2
 1961

- 75.54 The cor. of secs. 2, 3, 34 and 35, on the N. bdy. of the township, monumented by an iron post, as described in the official record.

Land, level to gently rolling.
 Soil, clay.
 Timber, none; undergrowth, creosote brush.

From the cor. of secs. 3, 4, 33 and 34, on the S. bdy. of the township.

N. $2^{\circ}15'$ E., bet. secs. 33 and 34.

Over gently rolling land, through desert vegetation.

- 8.00 Wash, 100 lks. wide, 2 ft. deep, drains E.
- 17.80 Ridge bears NW. and E.
- 39.74 The $\frac{1}{4}$ sec. cor. of secs. 33 and 34, monumented by a stone, as described in the official record.

At the corner point

Set the iron post 20 ins. in the ground, cap mkd.

T 9S R27E
 $\frac{1}{4}$
 S33 | S34
 1961

Deposit glass at base of iron post.

N. $0^{\circ}30'$ W., beginning new measurement.

- 6.20 Ridge, bears E. and W.
- 36.60 Wash, 100 lks. wide, 2 ft. deep, drains E.
- 40.23 Point for the cor. of secs. 27, 28, 33 and 34, at proportionate distance; there is no remaining evidence of the original corner.
- Set the iron post 20 ins. in the ground, cap mkd.

BOOK 4665

22

Subdivisional Lines, T. 9 S., R. 27 E., Arizona

22.

Chains	
	<p style="text-align: center;">T 9S R27E $\frac{S28}{S33} \frac{S27}{S34}$ 1961</p>
	<p>Deposit glass at base of iron post.</p> <p>Land, gently rolling. Soil, sandy. Timber, none; undergrowth, mesquite and creosote.</p>
	<p>From the cor. of secs. 26, 27, 34 and 35.</p>
	<p>S. 89°16' W., bet. secs. 27 and 34.</p>
	<p>Over gently rolling land, through desert vegetation.</p>
2.50	<p>Road, unimproved, bears NW. and SE.</p>
28.50	<p>Wash, 70 lks. wide, 2 ft. deep, drains NE.</p>
39.96	<p>Point for the $\frac{1}{4}$ sec. cor. of secs. 27 and 34, at proportionate distance; there is no remaining evidence of the original corner.</p>
	<p>Set the iron post 20 ins. in the ground, cap mkd.</p>
	<p style="text-align: center;">T 9S R27E $\frac{1}{4} \frac{S 27}{S 34}$ 1961</p>
	<p>Deposit glass at base of iron post.</p>
79.92	<p>The corner of secs. 27, 28, 33 and 34.</p>
	<p>Land, gently rolling. Soil, sandy. Timber, none; undergrowth, heavy creosote, mesquite and catclaw.</p>
	<p>N. 0°19' E., bet. secs. 27 and 28.</p>
	<p>Over gently rolling land, through desert vegetation.</p>
19.00	<p>Wash, 30 lks. wide, 2 ft. deep, drains SE.</p>
32.10	<p>Road, unimproved, bears E. and W.</p>
40.23	<p>Point for the $\frac{1}{4}$ sec. cor. of secs. 27 and 28, at proportionate distance; there is no remaining evidence of the original corner.</p>
	<p>Set the iron post 16 ins. in the ground, cap mkd.</p>
	<p style="text-align: center;">T 9S R27E $\frac{1}{4} \frac{S28}{S28} \frac{S27}{S27}$ 1961</p>
80.46	<p>Point for the cor. of secs. 21, 22, 27 and 28, at proportionate distance; there is no remaining evidence of the original corner.</p>
	<p>Set the iron post 20 ins. in the ground, cap mkd.</p>
	<p style="text-align: center;">T 9S R27E $\frac{S21}{S28} \frac{S22}{S27}$ 1961</p>

Chains	
	<p>Deposit glass at base of iron post.</p> <p>Land, gently rolling. Soil, sandy. Timber, none; undergrowth, creosote, mesquite, Spanish Bayonet, and catclaw.</p>
	<hr/> <p>From the cor. of secs. 22, 23, 26 and 27.</p>
	<p>S. 89°46' W., bet. secs. 22 and 27.</p>
	<p>Over gently rolling land, through desert vegetation.</p>
18.20	<p>Wash, 35 lks. wide, 2 ft. deep, drains NE.</p>
40.24	<p>Point for the $\frac{1}{4}$ sec. cor. of secs. 22 and 27, at proportionate distance; there is no remaining evidence of the original corner.</p>
	<p>Set the iron post 20 ins. in the ground, cap mkd.</p>
	<p style="text-align: center;">T 9S R27E $\frac{1}{4}$ $\frac{S 22}{S27}$ 1961</p>
	<p>Deposit glass at base of iron post.</p>
80.48	<p>The cor. of secs. 21, 22, 27 and 28.</p>
	<p>Land, gently rolling. Soil, sandy. Timber, none; undergrowth, mesquite and creosote.</p>
	<hr/> <p>N. 0°38' E., bet. secs. 21 and 22,</p>
	<p>Over gently rolling land, through desert vegetation.</p>
2.00	<p>Low spur, slopes E.; desc. N. slope.</p>
33.80	<p>Wash, 100 lks. wide, 2 ft. deep, drains NE.</p>
40.23	<p>Point for the $\frac{1}{4}$ sec. cor. of secs. 21 and 22, at proportionate distance; there is no remaining evidence of the original corner.</p>
	<p>Set the iron post 20 ins. in the ground, cap mkd.</p>
	<p style="text-align: center;">T 9S R27E $\frac{1}{4}$ S21 S22 1961</p>
	<p>Deposit glass at base of iron post.</p>
42.80	<p>Spur, slopes E.; desc. N. slope.</p>
63.30	<p>Wash, 20 lks. wide, 2 ft. deep, drains E.</p>
69.40	<p>Spur, slopes E.; desc. N. slope.</p>
80.46	<p>The cor. of secs. 15, 16, 21, and 22, monumented by a wood stake, as described in the official record.</p>
	<p>At the corner point</p>
	<p>Set the iron post 18 ins. in the ground, mound with stone to top, cap mkd.</p>

Chains

T 9S R27E
 S16 | S15
 S21 | S22
 1961

Deposit glass at base of iron post.

Land, gently rolling.

Soil, light gravel.

Timber, none; undergrowth, yucca and dense chaparral.

From the cor. of secs. 14, 15, 22 and 23.

N. 89°30' W., bet. secs. 15 and 22.

Over gently rolling land, through desert vegetation.

35.90 Wash, 30 lks. wide, 2 ft. deep, drains NE.

39.80 Point for the $\frac{1}{4}$ sec. cor. of secs. 15 and 22, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 18 ins. in the ground, cap mkd.

T 9S R27E
 $\frac{1}{4}$ S 15
 S 22
 1961

Deposit glass at base of iron post.

79.59 The cor. of secs. 15, 16, 21 and 22.

Land, gently rolling.

Soil, sandy and rocky.

Timber, none; undergrowth, catclaw, creosote, yucca, greasewood and mesquite.

N. 0°04' E., bet. secs. 15 and 16.

Over gently rolling land, through desert vegetation.

24.00 Wash, 100 lks. wide, 2 ft. deep, drains NE.

36.00 Small rise, slopes E.

38.60 Wash, 80 lks. wide, 3 ft. deep, drains E.

39.56 Point for the $\frac{1}{4}$ sec. cor. of secs. 15 and 16, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 20 ins. in the ground, cap mkd.

T 9S R27E
 $\frac{1}{4}$ S 15
 S 16 | S 15
 1961

Deposit glass at base of iron post.

68.40 Trail road, bears NE. and SW.

74.60 Small wash, drains NE.

BOOK 4665

Subdivisional Lines, T. 9 S., R. 27 E., Arizona

25

Chains					
79.12	<p>The cor. of secs. 9, 10, 15 and 16, monumented by a cedar stake, as described in the official record.</p> <p>At the corner point</p> <p>Set the iron post 18 ins. in the ground, mound with stone to top, cap mkd.</p> <div style="text-align: center;"> <p>T 9S R27E</p> <table border="1" style="margin: auto;"> <tr> <td>S 9</td> <td>S 10</td> </tr> <tr> <td>S 16</td> <td>S 15</td> </tr> </table> <p>1961</p> </div> <p>Deposit glass at base of iron post.</p> <p>Land, gently rolling. Soil, sandy. Timber, none; undergrowth, mesquite, yucca, creosote.</p>	S 9	S 10	S 16	S 15
S 9	S 10				
S 16	S 15				
21.70	<hr/> <p>From the cor. of secs. 10, 11, 14 and 15.</p> <p>N. 89°41' W., bet. secs. 10 and 15.</p> <p>Over nearly level land, through desert vegetation.</p>				
39.67	<p>Wash, 30 lks. wide, 2 ft. deep, drains NE.</p> <p>Point for the $\frac{1}{4}$ sec. cor. of secs. 10 and 15, at proportionate distance, there is no remaining evidence of the original corner.</p> <p>Set the iron post 20 ins. in the ground, cap mkd.</p> <div style="text-align: center;"> <p>T 9S R27E</p> <table border="1" style="margin: auto;"> <tr> <td>$\frac{1}{4}$ S 10</td> </tr> <tr> <td>S 15</td> </tr> </table> <p>1961</p> </div> <p>Deposit glass at base of iron post.</p>	$\frac{1}{4}$ S 10	S 15		
$\frac{1}{4}$ S 10					
S 15					
79.34	<p>The cor. of secs. 9, 10, 15 and 16.</p> <p>Land, nearly level. Soil, light gravel. Timber, none; undergrowth, mesquite and creosote.</p>				
12.40	<hr/> <p>N. 0°04' E., bet. secs. 9 and 10.</p> <p>Over gently rolling land, through desert vegetation.</p>				
33.30	<p>Wash, 30 lks. wide, 4 ft. deep, drains NE.</p>				
40.97	<p>Spur, slopes E.</p> <p>The $\frac{1}{4}$ sec. cor. of secs. 9 and 10, monumented by a cedar stake, as described in the official record.</p> <p>At the corner point</p> <p>Set the iron post 20 ins. in the ground, mound with stone to top, cap mkd.</p> <div style="text-align: center;"> <p>T 9S R27E</p> <table border="1" style="margin: auto;"> <tr> <td>$\frac{1}{4}$ S 9</td> <td>S 10</td> </tr> </table> <p>1961</p> </div> <p>Deposit glass at base of iron post.</p>	$\frac{1}{4}$ S 9	S 10		
$\frac{1}{4}$ S 9	S 10				

Chains	N. 1°07' W., beginning new measurement.
7.50	Corral, bears W., about 2.50 chs. dist.
38.88	Point for the cor. of secs. 3, 4, 9 and 10, at proportionate distance; there is no remaining evidence of the original corner. Set the iron post 20 ins. in the ground, cap mkd. $\begin{array}{r} \text{T 9S R27E} \\ \text{S 4 S 3} \\ \text{S 9 S10} \\ \hline 1961 \end{array}$ Deposit glass at base of iron post. Land, gently rolling. Soil, light gravel. Timber, none; undergrowth, mesquite and creosote brush.
	From the corner of secs. 2, 3, 10 and 11. N. 89°21' W., bet. secs. 3 and 10. Over level land, through desert vegetation.
39.96	Point for the $\frac{1}{4}$ sec. cor. of secs. 3 and 10, at proportionate distance; there is no remaining evidence of the original corner. Set the iron post 20 ins. in the ground, cap mkd. $\begin{array}{r} \text{T 9S R27E} \\ \frac{1}{4} \frac{\text{S 3}}{\text{S10}} \\ \hline 1961 \end{array}$ Deposit glass at base of iron post.
77.30	Wash, 40 lks. wide, 5 ft. deep, drains NE.
79.92	The cor. of secs. 3, 4, 9 and 10. Land, level. Soil, sandy clay, rocky. Timber, none; undergrowth, creosote, catclaw, mesquite, cactus, greasewood, yucca.
	N. 0°17' E., bet. secs. 3 and 4.
23.90	Small wash, drains E.
38.87	Point for the $\frac{1}{4}$ sec. cor. of secs. 3 and 4, at proportionate distance; there is no remaining evidence of the original corner. Set the iron post 20 ins. in the ground, cap mkd. $\begin{array}{r} \text{T 9S R27E} \\ \frac{1}{4} \\ \text{S4 S3} \\ \hline 1961 \end{array}$
43.60	Spur, slopes E.
44.00	Small wash, 10 lks. wide, 2 ft. deep, drains SE.

BOOK 4665

Subdivisional Lines, T. 9 S., R. 27 E., Arizona

27.

Chains	
61.10	Spur, slopes E.
74.84	<p>The cor. of secs. 3, 4, 33 and 34, on the N. bdy. of the township, monumented by an iron post as described in the official record.</p> <p>Land, level to rolling. Soil, sand and light gravel. Timber, none; undergrowth, mesquite, catclaw, creosote and yucca.</p> <hr/> <p>From the cor. of secs. 4, 5, 32 and 33, on the S. bdy. of the township.</p> <p>N. 1°26' E., bet. secs. 32 and 33.</p> <p>Over gently rolling land, through desert vegetation.</p>
38.30	Wash, 50 lks. wide, 1 ft. deep, drains NE.
39.82	<p>Point for the $\frac{1}{4}$ sec. cor. of secs. 32 and 33, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 20 ins. in the ground, cap mkd.</p> <div style="text-align: center;"> <p>T 9S R27E</p> <p>$\frac{1}{4}$</p> <p>S32 S33</p> <p>1961</p> </div> <p>Deposit glass at base of iron post.</p>
41.20	Wash, 40 lks. wide, 1 ft. deep, drains E.
79.63	<p>Point for the cor. of secs. 28, 29, 32 and 33, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 20 ins. in the ground, cap mkd.</p> <div style="text-align: center;"> <p>T 8S R27E</p> <p>S29 S28</p> <p>S32 S33</p> <p>1961</p> </div> <p>Deposit glass at base of iron post.</p> <p>Land, gently rolling. Soil, sandy. Timber, none; undergrowth, creosote, mesquite, and Spanish Bayonet.</p> <hr/> <p>From the cor. of secs. 27, 28, 33 and 34.</p> <p>S. 89°25' W., bet. secs. 28 and 33.</p> <p>Over gently rolling land, through desert vegetation.</p>
39.92	<p>Point for the $\frac{1}{4}$ sec. cor. of secs. 28 and 33, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 18 ins. in the ground, cap mkd.</p> <div style="text-align: center;"> <p>T 9S R27E</p> <p>$\frac{1}{4}$ $\frac{S 28}{S 33}$</p> <p>1961</p> </div> <p>Deposit glass at base of iron post.</p>
79.84	The cor. of secs. 28, 29, 32 and 33.

Chains

Land, gently rolling.
Soil, sandy.
Timber, none; undergrowth, creosote, mesquite, cactus, and Spanish Bayonet.

N. 0°06' W., bet. secs. 28 and 29.

Over rolling land, through desert vegetation.

38.00 Road, unimproved, bears E. and W.

39.81 Point for the $\frac{1}{4}$ sec. cor. of secs. 28 and 29, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 22 ins. in the ground, cap mkd.

T 9S R27E

$\frac{1}{4}$
S29 | S28
1961

Deposit glass at base of iron post.

47.00 Wash, 30 lks. wide, 3 ft. deep, drains E.

63.30 Wash, 20 lks. wide, 2 ft. deep, drains E.

77.20 Wash, 30 lks. wide, 2 ft. deep, drains E.

79.62 Point for the cor. of secs. 20, 21, 28 and 29, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 20 ins. in the ground, mound with stone to top, cap mkd.

T 9S R27E

S20 | S21
S29 | S28
1961

Deposit glass at base of iron post.

Land, gently rolling.
Soil, gravel.
Timber, none; undergrowth, creosote and mesquite.

From the cor. of secs. 21, 22, 27 and 28.

S. 88°49' W., bet. secs. 21 and 28.

Over gently rolling land, through desert vegetation.

15.50 Wash, 25 lks. wide, 3 ft. deep, drains N.

40.22 Point for the $\frac{1}{4}$ sec. cor. of secs. 21 and 28, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 20 ins. in the ground, mound with stone to top, cap mkd.

T 9S R27E

$\frac{1}{4}$ $\frac{S 21}{S 28}$
1961

58.30 Wash, 40 lks. wide, 2 ft. deep, drains NE.

BOOK 4665

Subdivisional Lines, T. 9 S., R. 27 E., Arizona

29.

Chains

- 80.44 The cor. of secs. 20, 21, 28 and 29.
Land, gently rolling.
Soil, gravel.
Timber, none; undergrowth, creosote and mesquite.
-
- N. 0°24' E., bet. secs. 20 and 21.
Over rolling land, through desert vegetation.
- 17.40 Wash, 50 lks. wide, 5 ft. deep, drains NE.
- 24.40 Wash, 70 lks. wide, 3 ft. deep, drains NE.
- 39.81 Point for the $\frac{1}{4}$ sec. cor. of secs. 20 and 21, at proportionate distance; there is no remaining evidence of the original corner.
Set the iron post 20 ins. in the ground, cap mkd.
- T 9S R27E
 $\frac{1}{4}$
S20|S21
1961
- Deposit glass at base of iron post.
- 68.10 Wash, 60 lks. wide, 3 ft. deep, drains NE.
- 79.62 Point for the cor. of secs. 16, 17, 20 and 21, at proportionate distance; there is no remaining evidence of the original corner.
Set the iron post 20 ins. in the ground, mound with stone to top, cap mkd.
- T 9S R27E
S17|S16
S20|S21
1961
- Deposit glass at base of iron post.
- Land, rolling.
Soil, rocky and sandy.
Timber, none; undergrowth, creosote, catclaw, yucca, cactus.
-
- From the cor. of secs. 15, 16, 21 and 22.
S. 88°10' W., bet. secs. 16 and 21.
Over rolling land, through desert vegetation.
- 38.70 Wash, 30 lks. wide, 3 ft. deep, drains NE.
- 40.37 Point for the $\frac{1}{4}$ sec. cor. of secs. 16 and 21, at proportionate distance; there is no remaining evidence of the original corner.
Set the iron post 24 ins. in the ground, cap mkd.
- T 9S R27E
 $\frac{1}{4}$ S 16
S 21
1961
- Deposit glass at base of iron post.

Chains	
80.73	The cor. of secs. 16, 17, 20 and 21. Land, gently rolling. Soil, rocky and sandy. Timber, none; undergrowth, cactus, catclaw, mesquite, yucca and creosote.
	N. 0°14' E., bet. secs. 16 and 17. Over rolling land, through desert vegetation.
8.20	Wash, 60 lks. wide, 3 ft. deep, drains E.
19.60	Wash, flood area, 100 lks. wide, drains NE.
35.70	Road, unimproved, bears irregularly E. and W.
39.81	Point for the $\frac{1}{4}$ sec. cor. of secs. 16 and 17, at proportionate distance; there is no remaining evidence of the original corner. Set the iron post 24 ins. in the ground, cap mkd. T 9S R27E $\frac{1}{4}$ S17 S16 1961 Deposit glass at base of iron post.
75.50	Wash, 30 lks. wide, 5 ft. deep, drains E.
79.62	Point for the cor. of secs. 8, 9, 16 and 17, at proportionate distance; there is no remaining evidence of the original corner. Set the iron post 20 ins. in the ground, mound with stone to top, cap mkd. T 9S R27E S 8 S 9 S17 S16 1961 Deposit glass at base of iron post. Land, rolling. Soil, sandy and rocky. Timber, none; undergrowth, creosote, catclaw, yucca, cactus, and mesquite.
	From the cor. of secs. 9, 10, 15 and 16. S. 88°25' W., bet. secs. 9 and 16. Over rolling land, through desert vegetation.
3.70	Small knoll, bears N. and S.
8.90	Wash, 15 lks. wide, 2 ft. deep, drains NE.
11.80	Wash, 15 lks. wide, 2 ft. deep, drains NE.
40.24	Point for the $\frac{1}{4}$ sec. cor. of secs. 9 and 16, at proportionate distance; there is no remaining evidence of the original corner.

BOOK 4665

Subdivisional Lines, T. 9 S., R. 27 E., Arizona

31.

Chains	
	<p>Set the iron post 24 ins. in the ground, cap mkd.</p> <p style="text-align: center;">T 9S R27E $\frac{1}{4} \frac{S 9}{S16}$ 1961</p>
80.47	<p>Deposit glass at base of iron post.</p> <p>The cor. of secs. 8, 9, 16 and 17.</p> <p>Land, level to rolling. Soil, sand to light gravel. Timber, none; undergrowth, greasewood, creosote, catclaw, cactus and mesquite.</p>
23.40	<p>N. 0°09' W., bet. secs. 8 and 9.</p> <p>Over gently rolling land, through desert vegetation.</p> <p>Wash, 20 lks. wide, 3 ft. deep, drains NE.</p>
39.81	<p>Point for the $\frac{1}{4}$ sec. cor. of secs. 8 and 9, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 20 ins. in the ground, cap mkd.</p> <p style="text-align: center;">T 9S R27E $\frac{1}{4}$ S8 S9 1961</p>
42.20	<p>Deposit glass at base of iron post.</p> <p>Fence, bears N. 88°48' E. and S. 88°48' W.</p>
71.10	<p>Road, unimproved, bears NW. and SE.</p>
79.62	<p>Point for the cor. of secs. 4, 5, 8 and 9, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 22 ins. in the ground, cap mkd.</p> <p style="text-align: center;">T 9S R27E S5 S4 S8 S9 1961</p>
	<p>Deposit glass at base of iron post.</p> <p>Land, gently rolling. Soil, rocky and light gravel. Timber, none; undergrowth, greasewood, creosote, catclaw, yucca, cactus and mesquite.</p>
2.10	<p>From the cor. of secs. 3, 4, 9 and 10.</p> <p>S. 88°14' W., bet. secs. 4 and 9.</p> <p>Over gently rolling land, through desert vegetation.</p> <p>Wash, 40 lks. wide, 5 ft. deep, course NE.</p>
32.50	<p>Road, unimproved, bears NW. and SE.</p>

Chains	
39.98	<p>Point for the $\frac{1}{4}$ sec. cor. of secs. 4 and 9, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 20 ins. in the ground, cap mkd.</p> <p style="text-align: center;">T 9S R27E $\frac{1}{4}$ $\frac{S 4}{S 9}$ 1961</p> <p>Raise a mound of stones, 3 ft. base, N. of the corner.</p>
79.97	<p>The cor. of secs. 4, 5, 8 and 9.</p> <p>Land, gently rolling. Soil, sandy and light gravel. Timber, none; undergrowth, catclaw, creosote, yucca, cactus and mesquite.</p>
16.20	<p>Wash, 20 lks. wide, 1 ft. deep, drains NE.</p>
38.10	<p>Wash, 20 lks. wide, 2 ft. deep, drains NE.</p>
39.81	<p>Point for the $\frac{1}{4}$ sec. cor. of secs. 4 and 5, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 20 ins. in the ground, cap mkd.</p> <p style="text-align: center;">T 9S R27E $\frac{1}{4}$ S5 S4 1961</p> <p>Set a 4 x 4 wood post W. of corner.</p>
53.90	<p>Ridge, bears E. and W.</p>
77.56	<p>The cor. of secs. 4, 5, 32 and 33, on the N. bdy. of the township, monumented by an iron post as described in the official record.</p> <p>Land, rolling. Soil, sandy. Timber, none; undergrowth, mesquite, creosote and catclaw.</p>
39.78	<p>From the cor. of secs. 5, 6, 31 and 32, on the S. bdy. of the township.</p> <p>N. 1°23' E., bet. secs. 31 and 32.</p> <p>Over nearly level land, through desert vegetation.</p> <p>Point for the $\frac{1}{4}$ sec. cor. of secs. 31 and 32, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 20 ins. in the ground, cap mkd.</p> <p style="text-align: center;">T 9S R27E $\frac{1}{4}$ S31 S32 1961</p> <p>Deposit glass at base of iron post.</p>

BOOK 4665

Subdivisional Lines, T. 9 S., R. 27 E., Arizona

33.

Chains

- 45.00 Wash, 30 lks. wide, 2 ft. deep, drains E.
- 76.00 Wash, 150 lks. wide, 2 ft. deep, drains E.
- 79.56 Point for the cor. of secs. 29, 30, 31 and 32, at proportionate distance; there is no remaining evidence of the original corner.
- Set the iron post 20 ins. in the ground, cap mkd.

$$\begin{array}{r} \text{T 9S R27E} \\ \text{S30 | S29} \\ \text{S31 | S32} \\ \hline 1961 \end{array}$$

Deposit glass at base of iron post.

Land, nearly level.

Soil, sandy.

Timber, none; undergrowth, mesquite, yucca and cactus.

From the cor. of secs. 28, 29, 32 and 33.

S. 89°54' W., bet. secs. 29 and 32.

Over nearly level land, through desert vegetation.

- 39.96 The $\frac{1}{4}$ sec. cor. of secs. 29 and 32, monumented by a wood post, badly deteriorated.

At the corner point

Set the iron post 24 ins. in the ground, cap mkd.

$$\begin{array}{r} \text{T 9S R27E} \\ \frac{1}{4} \frac{\text{S 29}}{\text{S 32}} \\ \hline 1961 \end{array}$$

Deposit glass at base of iron post.

S. 89°14' W., beginning new measurement.

- 35.30 Wash, 60 lks. wide, 2 ft. deep, drains NE.

- 40.78 The cor. of secs. 29, 30, 31 and 32.

Land, nearly level.

Soil, sandy.

Timber, none; undergrowth, mesquite, yucca and cactus.

N. 89°57' W., bet. secs. 30 and 31.

Over gently rolling land, through desert vegetation.

- 40.80 Point for the $\frac{1}{4}$ sec. cor. of secs. 30 and 31, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 20 ins. in the ground, cap mkd.

$$\begin{array}{r} \text{T 9S R27E} \\ \frac{1}{4} \frac{\text{S 30}}{\text{S 31}} \\ \hline 1961 \end{array}$$

Deposit glass at base of iron post.

34

Chains

51.40 Wash, 30 lks. wide, 3 ft. deep, drains NE.

78.52 Fence, bears N. and S.

78.72 The cor. of secs. 30 and 31, on the W. bdy. of the township.

Land, gently rolling.
Soil, sandy.
Timber, none; undergrowth, mesquite.

From the cor. of secs. 29, 30, 31 and 32.

N. 0°04' E., bet. secs. 29 and 30.

Over gently rolling land, through desert vegetation.

39.40 Road, unimproved, bears S. 70° E., and N. 70° W. 4 chs., thence SW.

39.76 Point for the $\frac{1}{4}$ sec. cor. of secs. 29 and 30, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 24 ins. in the ground, cap mkd.

T 9S R27E

$\frac{1}{4}$
S30|S29
1961

Deposit glass at base of iron post.

58.70 Wash, 40 lks. wide, 1 ft. deep, drains NE.

79.53 Point for the cor. of secs. 19, 20, 29 and 30, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post, 24 ins. in the ground, cap mkd.

T 9S R27E

S19|S20
S30|S29
1961

Deposit glass at base of iron post.

Land, gently rolling.

Soil, sandy.

Timber, none; undergrowth, mesquite, yucca and cactus.

From the corner of secs. 20, 21, 28 and 29.

S. 89°30' W., bet. secs. 20 and 29.

Over gently rolling land, through desert vegetation.

40.27 Point for the $\frac{1}{4}$ cor. of secs. 20 and 29, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 24 ins. in the ground, mound with stone to top, cap mkd.

T 9S R27E

$\frac{1}{4}$ $\frac{S 20}{S 29}$
1961

Deposit glass at base of iron post.

BOOK 4665

Subdivisional Lines, T. 9 S., R. 27 E., Arizona

35

Chains	
52.30	Road, unimproved, bears NW. and SE.
80.54	<p>The cor. of secs. 19, 20, 29 and 30.</p> <p>Land, gently rolling. Soil, sandy and fine rock. Timber, none; undergrowth, creosote, catclaw and yucca.</p>
40.23	<p>S. 89°33' W., bet. secs. 19 and 30.</p> <p>Over gently rolling land, through desert vegetation.</p> <p>Point for the $\frac{1}{4}$ sec. cor. of secs. 19 and 30, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 20 ins. in the ground, cap mkd.</p>
	<p>T 9S R27E $\frac{1}{4}$ $\frac{S 19}{S 30}$ 1961</p>
	Deposit glass at base of iron post.
54.92	Wash, 60 lks. wide, 1 ft. deep, drains NE.
78.09	Fence, bears N. and S.
78.12	<p>The cor. of secs. 19 and 30, on the W. bdy. of the township.</p> <p>Land, gently rolling. Soil, sandy. Timber, none; undergrowth, mesquite and creosote.</p>
39.76	<p>From the cor. of secs. 19, 20, 29 and 30.</p> <p>N. 0°22' E., bet. secs. 19 and 20.</p> <p>Over gently rolling land, through desert vegetation.</p> <p>Point for the $\frac{1}{4}$ sec. cor. of secs. 19 and 20, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 24 ins. in the ground, cap mkd.</p>
	<p>T 9S R27E $\frac{1}{4}$ S19 S20 1961</p>
	Deposit glass at base of iron post.
42.80	Wash, 30 lks. wide, 1 ft. deep, drains NE.
55.40	Wash, 200 lks. wide, 4 ft. deep, drains E.
78.00	Road, bears SE. and NW.
79.53	<p>Point for the cor. of secs. 17, 18, 19 and 20, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 20 ins. in the ground, mound with stone to top, cap mkd.</p>

Chains

T 9S R27E
 $\frac{S18}{S19} | \frac{S17}{S20}$
 1961

Deposit glass at base of iron post.

Land, gently rolling.
 Soil, sandy.
 Timber, none; undergrowth, catclaw and mesquite.

From the cor. of secs. 16, 17, 20 and 21.

S. 89°30' W., bet. secs. 17 and 20.

Over gently rolling land, through desert vegetation.

22.60 Wash, 30 lks. wide, 1 ft. deep, drains NE.

40.30 Point for the $\frac{1}{4}$ sec. cor. of secs. 17 and 20, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 20 ins. in the ground, mound with stone to top, cap mkd.

T 9S R27E
 $\frac{1}{4} \frac{S 17}{S 20}$
 1961

Deposit glass at base of iron post.

40.40 Wash, 100 lks. wide, 2 ft. deep, drains NE.

76.20 Road, unimproved, bears NE. and SW.

80.60 The cor. of secs. 17, 18, 19 and 20.

Land, gently rolling,
 Soil, sandy and rocky.
 Timber, none; undergrowth, creosote, catclaw, yucca, cactus,
 mesquite and greasewood.

S. 89°39' W., bet. secs. 18 and 19.

Over gently rolling land, through desert vegetation.

36.90 Wash, 20 lks. wide, 1 ft. deep, drains NE.

39.80 Wash, 20 lks. wide, 1 ft. deep, drains NE.

40.32 Point for the $\frac{1}{4}$ sec. cor. of secs. 18 and 19, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 18 ins. in the ground, mound with stone to top, cap mkd.

T 9S R27E
 $\frac{1}{4} \frac{S 18}{S 19}$
 1961

42.10 Wash, 20 lks. wide, 3 ft. deep, drains NE.

43.50 Wash, 20 lks. wide, 3 ft. deep, drains NE.

Chains	
78.60	Fence, bears N. and S.
78.63	<p>The cor. of secs. 18 and 19, on the W. bdy. of the township.</p> <p>Land, gently rolling. Soil, sandy and rocky. Timber, none; undergrowth, catclaw, creosote, yucca, cactus and mesquite.</p>
	<p>From the cor. of secs. 17, 18, 19 and 20.</p>
	<p>N. 0°17' E., bet. secs. 17 and 18.</p>
	<p>Over gently rolling land, through desert vegetation.</p>
21.20	<p>Road, unimproved, bears NE. and SW.</p>
26.40	<p>Wash, 150 lks. wide, 2 ft. deep, drains NE.</p>
39.76	<p>Point for the $\frac{1}{4}$ sec. cor. of secs. 17 and 18, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 24 ins. in the ground, cap mkd.</p>
	<p style="text-align: center;">T 9S R27E $\frac{1}{4}$ S18 S17 1961</p>
	<p>Deposit glass at base of iron post.</p>
54.70	<p>Flood barrier, bears E. and W.</p>
60.80	<p>Wash, main channel of flood area, 40 lks. wide, 2 ft. deep, drains NE.</p>
79.53	<p>Point for the cor. of secs. 7, 8, 17 and 18, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 18 ins. in the ground, mound with stone to top, cap mkd.</p>
	<p style="text-align: center;">T 9S R27E S 7 S 8 S18 S17 1961</p>
	<p>Deposit glass at base of iron post.</p>
	<p>Land, gently rolling.</p>
	<p>Soil, sandy.</p>
	<p>Timber, none; undergrowth, mesquite and catclaw.</p>
	<p>From the corner of secs. 8, 9, 16 and 17.</p>
	<p>S. 89°29' W., bet. secs. 8 and 17.</p>
	<p>Over nearly level land, through desert vegetation.</p>
40.22	<p>Point for the $\frac{1}{4}$ sec. cor. of secs. 8 and 17, at proportionate distance; there is no remaining evidence of the original corner.</p>
	<p>Set the iron post 24 ins. in the ground, cap mkd.</p>
	<p style="text-align: center;">T 9S R27E $\frac{1}{4}$ $\frac{S 8}{S17}$ 1961</p>
	<p>Deposit glass at base of iron post.</p>

Chains	
41.00	Wash, 10 lks. wide, 2 ft. deep, drains NE.
80.45	The cor. of secs. 7, 8, 17 and 18. Land, nearly level. Soil, sandy. Timber, none; undergrowth, mesquite and creosote brush.
40.20	<hr/> S. 89°40' W., bet. secs. 7 and 18. Over nearly level land, through desert vegetation. Point for the ¼ sec. cor. of secs. 7 and 18, at proportionate distance; there is no remaining evidence of the original corner. Set the iron post 22 ins. in the ground, cap mkd.
78.74	<div style="text-align: center;"> T 9S R27E ¼ <u> </u> S 7 S18 1961 </div> The cor. of secs. 7 and 18, on the W. bdy. of the township. Land, nearly level. Soil, sandy. Timber, none; undergrowth, mesquite, catclaw and yucca.
15.60	<hr/> From the cor. of secs. 7, 8, 17 and 18. N. 0°11' E., bet. secs. 7 and 8. Over nearly level land, through desert vegetation.
15.60	Wash, 50 lks. wide, 2 ft. deep, drains NE.
39.76	Point for the ¼ sec. cor. of secs. 7 and 8, at proportionate distance; there is no remaining evidence of the original corner. Set the iron post 22 ins. in the ground, mound with stone to top, cap mkd.
43.20	<div style="text-align: center;"> T 9S R27E ¼ <u> </u> S7 S8 1961 </div> Deposit glass at base of iron post.
43.20	Fence, bears E. and W.
58.00	Leave dense growth of mesquite, bears E. and W., enter rolling land, covered with creosote brush.
79.53	Point for the cor. of secs. 5, 6, 7 and 8, at proportionate distance; there is no remaining evidence of the original corner. Set the iron post 24 ins. in the ground, cap mkd.
	<div style="text-align: center;"> T9S R27E S6 S5 S7 S8 1961 </div> Deposit glass at base of iron post.

Chains

Land, level to gently rolling.
Soil, rocky.
Timber, none; undergrowth, mesquite, catclaw, creosote.

From the cor. of secs. 4, 5, 8 and 9.

S. 89°24' W., bet. secs. 5 and 8.

Over gently rolling land, through desert vegetation.

15.40 Wash, 20 lks. wide, 1 ft. deep, drains NE.

20.00 Road, unimproved, bears SE. and NW.

39.99 Point for the $\frac{1}{4}$ sec. cor. of secs. 5 and 8, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 20 ins. in the ground, cap mkd.

T. 9S R27E

$\frac{1}{4}$ $\frac{S 5}{S 8}$

1961

48.90 Wash, 20 lks. wide, 1 ft. deep, drains N.

79.98 The cor. of secs. 5, 6, 7 and 8.

Land, gently rolling.
Soil, sandy and rocky.
Timber, none; undergrowth, mesquite, yucca, cactus, catclaw, creosote and Spanish bayonet.

S. 89°28' W., bet. secs. 6 and 7.

Over rolling land, through desert vegetation.

34.80 Wash, 20 lks. wide, 1 ft. deep, drains N.

39.99 Point for the $\frac{1}{4}$ sec. cor. of secs. 6 and 7, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 24 ins. in the ground, cap mkd.

T 9S R27E

$\frac{1}{4}$ $\frac{S 6}{S 7}$

1961

Deposit glass at base of iron post.

40.60 Old road, bears NW. and SE.

45.70 Wash, 60 lks. wide, 2 ft. deep, drains NE.

76.00 Wash, 30 lks. wide, 1 ft. deep, drains NE.

78.72 Fence, bears N. and S.

78.77 The cor. of secs. 7 and 8, on the W. bdy. of the township.

Land, rolling.
Soil, sandy and rocky.
Timber, none; undergrowth, mesquite, creosote, catclaw, yucca and cactus.

Chains

From the cor. of secs. 5, 6, 7 and 8.

N. 0°10' E., bet. secs. 5 and 6.

Over gently rolling land, through desert vegetation.

13.50 Road, unimproved, bears NW. and SE.

39.77 Point for the $\frac{1}{4}$ sec. cor. of secs. 5 and 6, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 22 ins. in the ground; cap mkd.

T 9S R27E

$\frac{1}{4}$
S6 | S5

1961

Raise a mound of stones 3 ft. base, W. of corner.

73.60 Fence, bears N. 69° W. and S. 69° E.

78.56 The cor. of secs. 31, 32, 5 and 6, on the N. bdy. of the township. monumented by an iron post as described in the official record.

Land, gently rolling.

Soil, sandy and rocky.

Timber, none, undergrowth, mesquite, creosote, catclaw, yucca and cactus.

General Description

T. 9 S., R. 27 E., is located in the northern portion of San Simon Valley of Graham County, Arizona, with the northwest corner of the township being four and one-half miles east of the village of Artesia, Arizona.

The land within T. 9 S., R. 27 E., is low rolling to nearly level with a general northeast slope. The elevation of the township ranges from about 3,200 feet above sea level along the bottom of San Simon Wash in section 2 to about 3,700 feet above sea level in the southwest quarter of section 31.

The drainage system of the township is a rejuvenated system, composed of intermittent streams and washes. San Simon Wash, the main stream in the valley, has cut-banks which average about 20 feet high throughout its length. The San Simon enters the township at the southeast corner, draining northerly across the township to leave at a point near the quarter section corner of sections 2 and 35 on the north boundary. The remainder of the drainage is smaller washes, with cut-banks which are one or two feet high at their heads, but some are as high as 20 feet where the washes join the San Simon.

There are two types of soil found in the township. Along the stream valley of the San Simon there is a deep, well-developed loam. With the rejuvenation of the drainage system and the consequent lowering of the water table this soil produces nothing and appears as a mud flat and is being rapidly eroded and carried downstream. The remainder and major portion of the soil found in the township is a rocky, sandy clay which supports a vegetation cover of mesquite and catclaw trees, creosote bush, cacti and grasses. The creosote bush, cacti and grasses are found over most of the area, while the mesquite and catclaw trees are found mostly along the dry stream bed.

BOOK 4665

Township 9 South, Range 27 East, Arizona

41.

Chains

A branch line of the Southern Pacific Railroad crosses the township from a point near the quarter section corner of sections 1 and 36 on the south boundary to a point near the quarter section corner of sections 2 and 35 on the north boundary. An improved dirt road crosses the township from a point near the quarter section corner of section 30 on the west boundary, in an easterly direction, to a point near the quarter section corner of sections 1 and 36 on the south boundary. There are enough track roads scattered throughout the township so that any portion can be reached easily.

The only source of water with any apparent permanence is that produced from a well by the windmill located in section 26. There are numerous stock ponds scattered throughout the township and there are a few natural ponds along the bottom of the San Simon Wash. The only improvements other than those noted are the cabin, shed, tank and corral located at the well in section 26 and the range fences along allotment boundaries.

There is no evidence of any mineralization in the area of T. 9 S., R. 27 E., and at the present time the only apparent interest and utilization of the land and its resources is in access, cattle grazing and some small game hunting.

(42)

BOOK 4665

Chains

