

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

# FIELD NOTES

of the  
 -----  
 Dependent Resurvey  
 -----  
 of the  
 -----  
 Second Standard Parallel South, through Range 27 East  
 -----  
 and the  
 -----  
 North Boundary  
 -----  
 and the  
 -----  
 Subdivisional Lines  
 -----  
 of  
 -----  
 Township 10 South, Range 27 East  
 -----  
 -----  
 -----

*Of the* ..... Gila and Salt River ..... *Meridian,*  
*In the State of* ..... Arizona .....

### EXECUTED BY

..... Dell Cazier, Cadastral Surveyor  
 -----  
 ..... Glen Hatch, Surveying Aide  
 -----  
 ..... A. D. Griffin, Surveying Aide  
 -----

*Under special instructions dated* ..... August 10 ....., 19 60, *which provided*  
*for the surveys included under Group No.* ..... 351 ....., *approved* August 16, 1960  
*and assignment instructions dated* ..... November 23 ....., 19 60

*Survey commenced* ..... December 10 ....., 19 60  
*Survey completed* ..... February 21 ....., 19 61

1A

BOOK 4666

# INDEX DIAGRAM

Township 10 South, Range 27 East

5	4	3	3	2	1
6	40 5	33 4	27 8	22 2	17 1
40	40	32	27	22	16
7	39 8	32 9	27 10	21 11	15 12
39	38	31	26	21	15
18	38 17	31 16	26 15	20 14	14 13
37	37	31	25	20	14
19	36 20	30 21	25 22	19 23	13 24
36	35	30	24	19	13
30	35 29	29 28	24 27	18 26	12 25
34	34	28	23	18	11
31	33 32	28 33	23 34	17 35	11 36
10	9	8	7	6	5

## BOOK 4666

Township 10 South, Range 27 East, Arizona

16

## Chains

The west boundary was surveyed in 1875 by T. F. White. The south boundary, which is the Second Standard Parallel South, was surveyed in 1882 by T. F. White. The east and north boundaries were surveyed in 1884 by L. Wolfley. In 1884 L. Wolfley retraced the south boundary, establishing closing corners for the sections in T. 11 S., R. 27 E. The subdivisional lines were surveyed in 1885 by J. C. Smith. The west boundary was dependently resurveyed in 1917 by W. B. Kimmel. The east boundary was dependently resurveyed concurrently under Group 351, Arizona, and the record appears in the field notes of the dependent resurvey of T. 10 S., R. 28 E.

The following field notes are those of the dependent resurvey or reestablishment of the survey of the north boundary, the subdivisional lines and the south boundary, Second Standard Parallel South, in T. 10 S., R. 27 E., with the reestablishment of the closing corners and the establishment of the quarter section corners of T. 11 S., R. 27 E., on the Second Standard Parallel South.

This survey was executed in accordance with the specifications set forth in the Manual of Surveying Instructions, 1947, and the Special Instructions dated August 10, 1960.

Only the true line bearings and horizontal distances for the surveyed lines are given in the notes. Unless described, all corners were monumented with standard iron posts, 30 inches long, 2½ inches in diameter, flanged at the bases and with brass caps riveted to the tops.

The geographic position for the southeast corner of the township is latitude 32°30'46.3" N. and longitude 109°31'38.5" W. as determined by section line ties to U.S.C. & G.S. triangulation station TAN located in section 36, T. 9 S., R. 27 E.

The magnetic declination was read at a number of stations throughout the township and the average of these readings was found to be 13° East.

---

DEPENDENT RESURVEY OF THE NORTH BOUNDARY,  
T. 10 S., R. 27 E., ARIZONA

---

Reestablishment of the Survey in 1884 by L. Wolfley

---

From the cor. of Ts. 9 and 10 S., Rs. 27 and 28 E., monumented by an iron post as described in the field notes of the concurrent resurvey of T. 10 S., R. 28 E.

S. 89°57' W., bet. secs. 1 and 36.

Over nearly level land, through desert vegetation.

7.50	San Simon Wash, 250 lks. wide, drains irregularly N.
38.50	Road, bears N. and S.
39.60	Southern Pacific Railroad track, bears N. and S.
40.10	Power line, bears N. and S.
40.30	Point for the ¼ sec. cor. of secs. 1 and 36, at proportionate distance; there is no remaining evidence of the original corner.

## BOOK 4666

2

Dep. Resur., N. Bdy., T. 10 S., R. 27 E., Arizona

2.

## Chains

Set the iron post 24 ins. in the ground, cap mkd.

T 9S R27E

$$\frac{1}{4} \frac{S \ 36}{S \ 1}$$

T10S

1960

63.40 Road, bears SW. and NE.

64.70 Wash, 300 lks. wide, 4 ft. deep, drains N. 20° E.

67.30 Wash, 100 lks. wide, 4 ft. deep, drains N. 50° E.

70.20 Wash, 60 lks. wide, 4 ft. deep, drains N. 80° E.

80.60 The cor. of secs. 1, 2, 35 and 36, monumented by badly deteriorated redwood stake, 4 x 4 ins.

At the corner point

Set the iron post 20 ins. in the ground, cap mkd.

T 9S R27E

$$\frac{S35 \ S36}{S \ 2 \ S \ 1}$$

T10S

1960

Deposit glass at base of iron post.

Land, gently rolling.

Soil, sandy.

Timber, none; undergrowth, greasewood, yucca, catclaw, buckhorn and cactus.

S. 89°58' W., bet. secs. 2 and 35.

Over gently rolling land, through desert vegetation.

13.50 Wash, 20 lks. wide, 6 ins. deep, drains N. 80° E.

40.11 Point for the  $\frac{1}{4}$  sec. cor. of secs. 2 and 35, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post, 20 ins. in the ground, cap mkd.

T 9S R27E

$$\frac{1}{4} \frac{S \ 35}{S \ 2}$$

T10S

1960

Deposit glass at base of iron post.

80.23 Point for the cor. of secs. 2, 3, 34 and 35, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 24 ins. in the ground, cap mkd.

T 9S R27E

$$\frac{S34 \ S35}{S3 \ S2}$$

T10S

1960

Deposit glass at base of iron post.

## BOOK 4666

Dep. Resur., N. Bdy., T. 10 S., R. 27 E., Arizona

3.

## Chains

Land, gently rolling.  
Soil, sandy.  
Timber, none; undergrowth, cactus, catclaw, yucca and greasewood.

S. 89°58' W., bet. secs. 3 and 34.

Over gently rolling land, through desert vegetation.

39.90 Wash, 40 lks. wide, 1 ft. deep, drains NE.

40.11 Point for the  $\frac{1}{4}$  sec. cor. of secs. 3 and 34, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 18 ins. in the ground, mound with stone to top, cap mkd.

T 9S R27E  
 $\frac{1}{4} \frac{S 34}{S 3}$   
T10S  
1960

Deposit glass at base of iron post.

80.23 The cor. of secs. 3, 4, 33 and 34, monumented by a cedar stake, 4 x 4 ins., mkd. and set as described in the official record.

At the corner point

Set the iron post 20 ins. in the ground, cap mkd.

T 9S R27E  
 $\frac{S33}{S4} \frac{S34}{S3}$   
T10S  
1960

Deposit glass at base of iron post.

Land, gently rolling.  
Soil, sand and fine gravel.  
Timber, none; undergrowth, greasewood.

S. 89°35' W., bet. secs. 4 and 33.

Over gently rolling land, through desert vegetation.

7.70 Wash, 60 lks. wide, 2 ft. deep, drains NE.

30.20 Wash, 20 lks. wide, 6 ins. deep, drains N. 70° E.

39.40 Wash, 20 lks. wide, 1 ft. deep, drains NE.

40.40 Point for the  $\frac{1}{4}$  sec. cor. of secs. 4 and 33, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 24 ins. in the ground, cap mkd.

T 9S R27E  
 $\frac{1}{4} \frac{S 4}{S 33}$   
T10S  
1960

Deposit glass at base of iron post.

## BOOK 4666

Dep. Resur., N. Bdy., T. 10 S., R. 27 E., Arizona

4.

4

## Chains

- 80.00 Wash, 15 lks. wide, 1 ft. deep, drains NE.
- 80.80 Point for the cor. of secs. 4, 5, 32 and 33, at proportionate distance; there is no remaining evidence of the original corner.
- Set the iron post 26 ins. in the ground, cap mkd.
- |           |     |
|-----------|-----|
| T 9S R27E |     |
| S32       | S33 |
| S5        | S4  |
| T10S      |     |
| 1960      |     |
- Deposit glass at base of iron post.
- Land, gently rolling.  
Soil, sandy clay and gravel.  
Timber, none; undergrowth, greasewood and catclaw.
- 
- S. 89°35' W., bet. secs. 5 and 32.
- Over gently rolling land, through desert vegetation.
- 13.00 Wash, 100 lks. wide, 1 ft. deep, drains NE.
- 31.50 Wash, 10 lks. wide, 6 ins. deep, drains NE.
- 39.30 Wash, 60 lks. wide, 2 ft. deep, drains NE.
- 40.40 Point for the  $\frac{1}{4}$  sec. cor. of secs. 5 and 32, at proportionate distance; there is no remaining evidence of the original corner.
- Set the iron post 24 ins. in the ground, cap mkd.
- |                    |  |
|--------------------|--|
| T 9S R27E          |  |
| $\frac{1}{4}$ S 32 |  |
| S 5                |  |
| T10S               |  |
| 1960               |  |
- Deposit glass at base of iron post.
- 42.30 Wash, 70 lks. wide, 2 ft. deep, drains NE.
- 43.50 Wash, 20 lks. wide, 3 ft. deep, drains NE.
- 74.80 Wash, 40 lks. wide, 2 ft. deep, drains N. 70° E.
- 80.80 Point for the cor. of secs. 5, 6, 31 and 32, at proportionate distance; there is no remaining evidence of the original corner.
- Set the iron post 24 ins. in the ground, cap mkd.
- |           |     |
|-----------|-----|
| T 9S R27E |     |
| S31       | S32 |
| S6        | S5  |
| T10S      |     |
| 1960      |     |
- Deposit glass at base of iron post.
- Land, gently rolling.  
Soil, sandy clay and gravel.  
Timber, none; undergrowth, catclaw and yucca.

## BOOK 4666

Dep. Resur., N. Bdy., T. 10 S., R. 27 E., Arizona

5.

Chains	
	S. 89°35' W., bet. secs. 6 and 31.
	Over gently rolling land, through desert vegetation.
26.40	Wash, 10 lks. wide, 4 ft. deep, drains NE.
30.20	Wash, 40 lks. wide, 1 ft. deep, drains NE.
39.90	Wash, 15 lks. wide, 6 ins. deep, drains NE.
40.40	Point for the $\frac{1}{4}$ sec. cor. of secs. 6 and 31 at proportionate distance; there is no remaining evidence of the original corner.
	Set the iron post 20 ins. in the ground, cap mkd.
	T 9S R27E $\frac{1}{4}$ $\frac{S\ 31}{S\ 6}$ T10S 1960
	Deposit glass at base of iron post.
51.60	Wash, 30 lks. wide, 8 ins. deep, drains NE.
59.40	Wash, 10 lks. wide, 6 ins. deep, drains NE.
69.60	Wash, 30 lks. wide, 1 ft. deep, drains NE.
77.55	Corner of Ts. 9 and 10 S., Rs. 26 and 27 E., monumented by an iron post as described in the official record. Corner falls in fence bearing N. and S.
	Land, gently rolling. Soil, sandy. Timber, none; undergrowth, catclaw and yucca.
<hr/> DEPENDENT RESURVEY OF THE SECOND STANDARD PARALLEL SOUTH THROUGH R. 27 E., ARIZONA <hr/>	
Reestablishment of the Survey in 1884 by L. Wolfley <hr/>	
	From the stan. cor. of T. 10 S., Rs. 27 and 28 E., monumented by an iron post as described in the field notes of the concurrent resurvey of T. 10 S., R. 28 E.
	N. 89°50' W., on the S. bdy. of sec. 36.
4.70	Fence, bears NE. and SW.
17.30	Road, unimproved, bears N. and S.
17.80	Wash, 20 lks. wide, 2 ft. deep, drains NE.
18.70	Southern Pacific Railroad track, bears N. 2°25' E.
19.30	Telegraph line, parallels tracks.
29.10	Wash, 30 lks. wide, 2 ft. deep, drains NE.
36.52	The closing corner of T. 11 S., Rs. 27 and 28 E., monumented by badly deteriorated wood post, 4 x 4 inches.

## BOOK 4666

Dependent Resurvey, 2nd Stan. Par. S., R. 27 E., Arizona

6.

Chains											
	<p>At the corner point</p> <p>Set the iron post 24 ins. in the ground, cap mkd.</p> <div style="text-align: center;"> <table border="1"> <tr><td>S1</td><td>S6</td></tr> <tr><td>c</td><td>c</td></tr> <tr><td>R27E</td><td>R28E</td></tr> <tr><td colspan="2">T11S</td></tr> <tr><td colspan="2">1960</td></tr> </table> </div> <p>Deposit glass at the base of iron post.</p>	S1	S6	c	c	R27E	R28E	T11S		1960	
S1	S6										
c	c										
R27E	R28E										
T11S											
1960											
40.14	<p>Point for the stan. <math>\frac{1}{4}</math> sec. cor. of sec. 36 at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 24 ins. in the ground, cap mkd.</p> <div style="text-align: center;"> <table border="1"> <tr><td>S</td><td>C</td></tr> <tr><td>T10S</td><td>R27E</td></tr> <tr><td><math>\frac{1}{4}</math></td><td>S36</td></tr> <tr><td colspan="2">1960</td></tr> </table> </div>	S	C	T10S	R27E	$\frac{1}{4}$	S36	1960			
S	C										
T10S	R27E										
$\frac{1}{4}$	S36										
1960											
46.20	Small wash, drains NE.										
65.40	Small wash, drains NE.										
76.68	<p>Point for <math>\frac{1}{4}</math> sec. cor. of sec. 1, at mid-point between the closing corners.</p> <p>Set the iron post 18 ins. in the ground, cap mkd.</p> <div style="text-align: center;"> <table border="1"> <tr><td><math>\frac{1}{4}</math></td><td>S 1</td></tr> <tr><td colspan="2">T11S R27E</td></tr> <tr><td colspan="2">1960</td></tr> </table> </div>	$\frac{1}{4}$	S 1	T11S R27E		1960					
$\frac{1}{4}$	S 1										
T11S R27E											
1960											
79.66	Fence, bears N. and S.										
80.10	Small wash, drains NE.										
80.28	<p>Point for the stan. cor. of secs. 35 and 36, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 22 ins. in the ground, cap mkd.</p> <div style="text-align: center;"> <table border="1"> <tr><td colspan="2">SC</td></tr> <tr><td>T10S</td><td>R27E</td></tr> <tr><td>S35</td><td>S36</td></tr> <tr><td colspan="2">1960</td></tr> </table> </div> <p>Deposit glass at base of iron post.</p> <p>Land, gently rolling. Soil, sandy. Timber, none; undergrowth, greasewood, yucca.</p>	SC		T10S	R27E	S35	S36	1960			
SC											
T10S	R27E										
S35	S36										
1960											
36.55	<p>N. 89°50' W., on the S. bdy. of sec. 35.</p> <p>Point for the closing cor. of secs. 1 and 2, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 20 ins. in the ground, cap mkd.</p> <div style="text-align: center;"> <table border="1"> <tr><td>S2</td><td>S1</td></tr> <tr><td>c</td><td>c</td></tr> <tr><td>T11S</td><td>R27E</td></tr> <tr><td colspan="2">1960</td></tr> </table> </div>	S2	S1	c	c	T11S	R27E	1960			
S2	S1										
c	c										
T11S	R27E										
1960											



## BOOK 4666

Dependent Resurvey, 2nd Stan. Par. S., R. 27 E., Arizona 7.

## Chains

Deposit glass at base of iron post.

40.14

Point for the Stan.  $\frac{1}{4}$  sec. cor. of sec. 35, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 20 ins. in the ground, cap mkd.

SC  
T10S R27E  
     $\frac{1}{4}$  S 35  
1960

76.57

Point for the  $\frac{1}{4}$  cor. of sec. 2, at mid-point between the closing corners.

Set the iron post 20 ins. in the ground, cap mkd.

     $\frac{1}{4}$  S 2  
T11S R27E  
1960

Deposit glass at base of iron post.

80.28

Point for Stan. cor. of secs. 34 and 35, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 22 ins. in the ground, cap mkd.

SC  
T10S R27E  
S34|S35  
1960

Deposit glass at base of iron post.

Land, gently rolling.

Soil, sandy.

Timber, none; undergrowth, greasewood, yucca.

N. 89°50' W., on the S. bdy. of sec. 34.

11.80

Desc. 30 ft. over W. slope.

14.20

Small wash, drains NE.; asc. E. slope.

34.00

Fence, bears N. and S.

36.32

Point for the closing cor., secs. 2 and 3, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 18 ins. in the ground, cap mkd.

    S3|S2  
cc  
T11S R27E  
1960

Deposit glass at base of iron post.

38.60

Small wash, drains N.; asc. NE. slope.

40.14

Point for Stan.  $\frac{1}{4}$  sec. cor. of sec. 34, at proportionate distance; there is no remaining evidence of the original corner.

## BOOK 4666

Dependent Resurvey, 2nd Stan. Par. S., R. 27 E., Arizona 8.

Chains	
	<p>Set the iron post 18 ins. in the ground, cap mkd.</p> <p style="text-align: center;">SC T10S R27E <u>½ S 34</u> 1960</p> <p>Deposit glass at base of iron post.</p>
44.60	Spur, slopes N.; desc. NW. slope.
58.00	Wash, 80 lks. wide, 3 ft. deep, drains NE.; asc. E. slope.
76.36	<p>Point for the ¼ sec. cor. of sec. 3, at mid-point between the closing corners.</p> <p>Set the iron post 24 ins. in the ground, cap mkd.</p> <p style="text-align: center;"><u>½ S 3</u> T11S R27E 1960</p> <p>Deposit glass at base of iron post.</p>
80.28	<p>Point for the Stan. cor. of secs. 33 and 34, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 20 ins. in the ground, cap mkd.</p> <p style="text-align: center;">SC T10S R27E <u>S33 S34</u> 1960</p> <p>Deposit glass at base of iron post.</p> <p>Land, gently rolling. Soil, sandy. Timber, none; undergrowth, creosote and mesquite.</p>
36.13	<p>N. 89°50' W., on the S. bdy. of sec. 33.</p> <p>Point for the closing corner of secs. 3 and 4, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 18 ins. in the ground, cap mkd.</p> <p style="text-align: center;"><u>S4 S3</u> cc T11S R27E 1960</p> <p>Deposit glass at base of iron post.</p>
40.14	<p>Point for the Stan. ¼ sec. cor. of sec. 33, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 20 ins. in the ground, cap mkd.</p> <p style="text-align: center;">SC T10S R27E <u>½ S 33</u> 1960</p> <p>Deposit glass at base of iron post.</p>

## BOOK 4666

Dependent Resurvey, 2nd Stan. Par. S., R. 27 E., Arizona

9.

Chains	
76.20	<p>Point for the <math>\frac{1}{4}</math> sec. cor. of sec. 4, at mid-point between the closing corners.</p> <p>Set the iron post 20 ins. in the ground, cap mkd.</p> <p style="text-align: center;"> <u>                    </u>  <math>\frac{1}{4}</math> S 4  T11S R27E  1961 </p>
78.70	<p>Old road, bears NW. and SE.</p>
80.28	<p>Point for the stan. cor. of secs. 32 and 33, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 20 ins. in the ground, cap mkd.</p> <p style="text-align: center;"> SC  T10S R27E  <u>S32 S33</u>  1960 </p> <p>Land, gently rolling.  Soil, sandy.  Timber, none; undergrowth, mesquite and cactus.</p> <hr/>
	<p>N. 89°50' W., on the S. bdy. of sec. 32.</p>
1.00	<p>Wash, 30 lks. wide, 2 ft. deep, drains NE.</p>
12.70	<p>Small wash, drains NE.</p>
32.80	<p>Small wash, drains NE.</p>
35.99	<p>Point for the closing cor. of secs. 4 and 5, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 20 ins. in the ground, cap mkd.</p> <p style="text-align: center;"> <u>                    </u>  S5 S4  cc  T11S R27E  1960 </p>
36.50	<p>Wash, 30 lks. wide, 2 ft. deep, drains N. 80° E.</p>
40.14	<p>Point for the stan. <math>\frac{1}{4}</math> sec. cor. of sec. 32, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 20 ins. in the ground, cap mkd.</p> <p style="text-align: center;"> SC  T10S R27E  <u>          </u>  <math>\frac{1}{4}</math> S 32  1960 </p>
	<p>Deposit glass at base of iron post.</p>
43.50	<p>Wash, 20 lks. wide, 2 ft. deep, drains NE.</p>
67.20	<p>Wash, 20 lks. wide, 1 ft. deep, drains NE.</p>
76.09	<p>Point for the <math>\frac{1}{4}</math> sec. cor. of sec. 5, at mid-point between the closing corners.</p>

## BOOK 4666

10

Dependent Resurvey, 2nd Stan. Par. S., R. 27 E., Arizona

10.

Chains	
	Set the iron post 20 ins. in the ground, cap mkd.
	$\begin{array}{c} \hline \frac{1}{4} S 5 \\ T11S R27E \\ 1960 \end{array}$
79.30	Wash, 20 lks. wide, 2 ft. deep, drains N. 80° E.
80.28	Point for the Stan. cor. of secs. 31 and 32, at proportionate distance; there is no remaining evidence of the original corner.
	<p>Set the iron post 20 ins. in the ground, cap mkd.</p> $\begin{array}{c} SC \\ T10S R27E \\ \hline S31 S32 \\ 1960 \end{array}$
	<p>Deposit glass at base of iron post.</p> <p>Land, gently rolling. Soil, sandy. Timber, none; undergrowth, mesquite, greasewood, cactus.</p>
	N. 89°50' W., on the S. bdy. of sec. 31.
19.00	Low ridge, bears NE. and SW.; desc. NW. slope.
23.20	Wash, 20 lks. wide, 2 ft. deep, drains NE.; asc. E. slope.
35.90	Point for the closing cor. for secs. 5 and 6, at proportionate distance; there is no remaining evidence of the original corner.
	<p>Set the iron post 24 ins. in the ground, cap mkd.</p> $\begin{array}{c} \hline S6 S5 \\ T11S R27E \\ CC \\ 1960 \end{array}$
40.14	<p>Point for the Stan. <math>\frac{1}{4}</math> sec. cor. of sec. 31, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 20 ins. in the ground, mound with stone to top, cap mkd.</p>
	$\begin{array}{c} SC \\ T10S R27E \\ \hline \frac{1}{4} S 31 \\ 1960 \end{array}$
40.30	Fence, bears N. and S.
42.40	Wash, 30 lks. wide, 2 ft. deep, drains N.
68.00	Wash, 20 lks. wide, 2 ft. deep, drains NE.
76.04	<p>Point for the <math>\frac{1}{4}</math> sec. cor. of sec. 6, at proportionate distance based upon the theoretical position indicated by the lotting as shown on the plat of T. 11 S., R. 27 E., approved June 5, 1885.</p> <p>Set the iron post 18 ins. in the ground, mound with stone to top, cap mkd.</p>

## BOOK 4666

Dependent Resurvey, 2nd Stan. Par. S., R. 27 E., Arizona 11.

## Chains

$\frac{1}{4}$  S 6  
 T11S R27E  
 1960

80.28 The Stan. corner of T. 10 S., Rs. 26 and 27 E., monumented by an iron post as described in the official record.

Land, gently rolling.  
 Soil, sandy.  
 Timber, none; undergrowth, mesquite.

DEPENDENT RESURVEY OF THE SUBDIVISIONAL LINES  
 TOWNSHIP 10 SOUTH, RANGE 27 EAST

Reestablishment of the Survey in 1885 by J. C. Smith

From the standard cor. of secs. 35 and 36, on the south boundary of the township.

N. 0°57' W., between secs. 35 and 36.

Over gently rolling land, through desert vegetation.

3.35 Wash, 30 lks. wide, 1 ft. deep, drains N. 70° E.

7.55 Fence, barbed wire, bears S. 10° E., and N. 10° W.

40.13 Point for the  $\frac{1}{4}$  sec. cor. of secs. 35 and 36, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 26 ins. in the ground, cap mkd.

T10S R27E  
 $\frac{1}{4}$   
 S35|S36  
 1961

Deposit broken glass at base of iron post.

80.25 Point for the corner of secs. 25, 26, 35 and 36, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 26 ins. in the ground, cap mkd.

T10S R27E  
 $\frac{1}{4}$   
 S26|S25  
 S35|S36  
 1961

Land, gently rolling.  
 Soil, sandy.  
 Timber, none; undergrowth, cactus, greasewood and catclaw.

From the cor. of secs. 25, 30, 31 and 36, on the E. bdy. of the township, described in the field notes of the concurrent survey of T. 10 S., R. 28 E.

N. 89°59' W., between sections 25 and 36.

Asc. over gently rolling land, through desert vegetation.

20.70 Road, bears S. 15° W., and N. 15° E.

## BOOK 4666

Subdivisional Lines, T. 10 S., R. 27 E., Arizona

12.

12

## Chains

22.40 Railroad tracks, bear N. 2°24' W. and S. 2°24' E.

23.40 Wash, 75 lks. wide, 1 ft. deep, drains N. 40° E.

40.69 Point for the  $\frac{1}{4}$  sec. cor. of secs. 25 and 36, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 18 ins. in the ground, mound with stone to top, cap mkd.

T10S R27E

 $\frac{1}{4}$   $\frac{S\ 25}{S36}$ 

1961

Deposit broken glass at base of iron post.

81.39 The cor. of secs. 25, 26, 35 and 36.

Land, gently rolling.

Soil, sandy.

Timber, none; undergrowth, cactus and greasewood.

N. 0°09' E., bet. secs. 25 and 26.

Over gently rolling land containing a series of small washes, through desert vegetation.

11.00 Wash, 30 lks. wide, 1 ft. deep, drains E.

20.70 Wash, 30 lks. wide, 1 ft. deep, drains N. 70° E.

40.13 Point for the  $\frac{1}{4}$  sec. cor. of secs. 25 and 26 at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post, 26 ins. in the ground, cap mkd.

T10S R27E

 $\frac{1}{4}$   $\frac{S26\ S25}{S26\ S25}$ 

1961

Deposit broken glass at base of iron post.

47.60 Wash, 50 lks. wide, 1 ft. deep, drains N. 40° E.

80.26 Point for the cor. of secs. 23, 24, 25 and 26, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 20 ins. in the ground, mound with stone to top, cap mkd.

T10S R27 E

 $\frac{S23\ S24}{S26\ S25}$ 

1961

Deposit broken glass at base of post.

Land, gently rolling.

Soil, sandy.

Timber, none; undergrowth, cactus and greasewood.

## BOOK 4666

Subdivisional Lines, T. 10 S., R. 27 E., Arizona

13.

## Chains

From the cor. of secs. 19, 24, 25 and 30 on the E. bdy. of the township, monumented by an iron post as described in the field notes of the concurrent survey of T. 10 S., R. 28 E.

N. 89°53' W., bet. secs. 24 and 25.

Over gently rolling land, through desert vegetation.

35.60 Road, bears N. and S.

36.50 Railroad track, bears N. 2°30' W., and S. 2°30' E.

36.70 Powerline, bears N. and S.

40.55 Point for the  $\frac{1}{4}$  sec. cor. of secs. 24 and 25, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 26 ins. in the ground, cap mkd.

T10S R27E

$\frac{1}{4}$   $\frac{S\ 24}{S25}$

1961

Deposit broken glass at base of iron post.

70.70 Wash, 40 lks. wide, 1 ft. deep, drains N. 10° W.

81.10 The cor. of secs. 23, 24, 25 and 26.

Land, gently rolling.

Soil, sandy.

Timber, none; undergrowth, cactus and greasewood.

N. 0°09' E., bet. secs. 23 and 24.

Desc. gentle N. slope, over a series of small washes draining N., through dense growth of mesquite.

18.30 Wash, 20 lks. wide, 3 ft. deep, drains NE.

40.13 Point for the  $\frac{1}{4}$  sec. cor. of secs. 23 and 24, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 26 ins. in the ground, cap mkd.

T10S R27E

$\frac{1}{4}$   
S23|S24

1961

Deposit broken glass at base of post.

80.25 The cor. of secs. 13, 14, 23 and 24, monumented by a cedar post, badly deteriorated.

At the cor. point

Set the iron post 22 ins. in the ground, cap mkd.

T10S R27E

S14|S13  
S23|S24

1961

Land, gently rolling.

Soil, sandy gravel.

Timber, none; undergrowth, mesquite, cactus and greasewood.

## BOOK 4666

Subdivisional Lines, T. 10 S., R. 27 E., Arizona

14.

14

## Chains

From the cor. of secs. 13, 18, 19 and 24 on the E. bdy. of the township, monumented by an iron post as described in the field notes of the concurrent survey of T. 10 S., R. 28 E.

S. 89°37' W., bet. secs. 13 and 24.

Desc. slight E. slope over nearly level ground, through desert vegetation.

18.00 Wash, 30 lks. wide, 1 ft. deep, drains NE.

29.20 Road, bears N. and S.

30.00 Railroad track, bears N. 2°53' W., and S. 2°53' E.

30.50 Power line, bears N. 2°50' W. and S. 2°50' E.

30.80 Wash, 40 lks. wide, 4 ft. deep, drains N. for 8.00 chains, thence NE.

40.41 Point for the  $\frac{1}{4}$  sec. cor. of secs. 13 and 24, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 26 ins. in the ground, cap mkd.

T10S R27E

$\frac{1}{4}$   $\frac{S\ 13}{S\ 24}$

1961

Deposit broken glass at base of iron post.

77.80 Wash, 40 lks. wide, 1 ft. deep, drains NE.

80.82 The cor. of secs. 13, 14, 23 and 24.

Land, nearly level.

Soil, sand and gravel.

Timber, none; undergrowth, mesquite, cactus and greasewood.

N. 0°25' W., bet. secs. 13 and 14.

Over gently rolling land, through creosote and mesquite bush.

2.00 Wash, 70 lks. wide, 2 ft. deep, drains NE.

40.05 Point for the  $\frac{1}{4}$  sec. cor. of secs. 13 and 14, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 27 ins. in the ground, cap mkd.

T10S R27E

$\frac{1}{4}$  S14 | S13

1961

Deposit broken glass at base of iron post.

46.00 Wash, 60 lks. wide, 2 ft. deep, drains E.

52.20 Road, bears N. 48° E. and S. 48° W.

61.70 Wash, 20 lks. wide, 1 ft. deep, drains E.

77.20 Wash, 50 lks. wide, 1 ft. deep, drains NE.



## BOOK 4666

Subdivisional Lines, T. 10 S., R. 27 E., Arizona

15.

Chains					
80.10	<p>The cor. of secs. 11, 12, 13 and 14, monumented by a 4 x 4 wooden post in a fence corner.</p> <p>At the corner point</p> <p>Set the iron post 20 ins. in the ground, mound with stone to top, cap mkd.</p> <div style="text-align: center;"> <p>T10S R27E</p> <table border="1" style="margin: auto;"> <tr> <td>S11</td> <td>S12</td> </tr> <tr> <td>S14</td> <td>S13</td> </tr> </table> <p>1961</p> </div> <p>Land, gently rolling. Soil, sandy gravel. Timber, none; undergrowth, mesquite, creosote brush and cactus.</p>	S11	S12	S14	S13
S11	S12				
S14	S13				
4.10	<p>From the cor. of secs. 7, 12, 13 and 18, on the E. bdy. of the township, monumented by an iron post as described in the field notes of the concurrent survey of T. 10 S., R. 28 E.</p> <p>S. 89°33' W., bet. secs. 12 and 13.</p> <p>Asc. gentle E. slope through moderate growth of creosote and mesquite brush.</p>				
31.40	Wash, 20 lks. wide, 1 ft. deep, drains NE.				
33.30	Road, bears N. and S.				
33.80	Railroad track, bears N. 2°53' W. and S. 2°53' E.				
40.48	Powerline, bears N. 2°53' W. and S. 2°53' E.				
40.48	<p>The <math>\frac{1}{4}</math> sec. cor. of secs. 12 and 13, monumented by a cedar post.</p> <p>At the cor. point</p> <p>Set the iron post 27 ins. in the ground, cap mkd.</p> <div style="text-align: center;"> <p>T10S R27E</p> <table border="1" style="margin: auto;"> <tr> <td><math>\frac{1}{4}</math> S 12</td> </tr> <tr> <td>S 13</td> </tr> </table> <p>1961</p> </div> <p>Deposit broken glass at base of iron post.</p>	$\frac{1}{4}$ S 12	S 13		
$\frac{1}{4}$ S 12					
S 13					
12.10	<p>N. 89°42' W., beginning new measurement.</p> <p>Asc. along slight NE. slope over nearly level land containing a series of small washes draining NE.</p>				
39.30	Road, bears N. 40°20' E. and S. 40°20' W.				
39.30	<p>The cor. of secs. 11, 12, 13 and 14.</p> <p>Land, gently rolling. Soil, sand and small rocks. Timber, none; undergrowth, creosote brush and cactus.</p> <hr/> <p>N. 0°18' E., bet. secs. 11 and 12.</p> <p>Over nearly level land, through desert undergrowth.</p>				

## BOOK 4666

Subdivisional Lines, T. 10 S., R. 27 E., Arizona

16.

16

Chains	
40.29	<p>The <math>\frac{1}{4}</math> sec. cor. of secs. 11 and 12, determined from the remains of the red cedar stake in N. pit, described in the official record.</p> <p>At the corner point</p> <p>Set the iron post 26 ins. in the ground, cap mkd.</p> <p style="text-align: center;">T10S R27E <math>\frac{1}{4}</math> S11 S12 1961</p> <p>Deposit broken glass at base of iron post.</p> <hr/> <p>N. <math>0^{\circ}26'</math> E., beginning new measurement.</p>
40.15	<p>The cor. of secs. 1, 2, 11 and 12, determined by the remains of the red cedar stake in N. pit, as described in the official record.</p> <p>At the corner point</p> <p>Set the iron post 24 ins. in the ground, cap mkd.</p> <p style="text-align: center;">T10S R27E S 2 S 1 S11 S12 1961</p> <p>Deposit broken glass at base of iron post.</p> <p>Land, gently rolling. Soil, sandy. Timber, none; undergrowth, mesquite and creosote brush.</p> <hr/> <p>From the cor. of secs. 1, 6, 7 and 12, on the E. bdy. of the township, monumented by an iron post as described in the field notes of the concurrent survey of T. 10 S., R. 28 E.</p> <p>N. <math>89^{\circ}58'</math> W., bet. secs. 1 and 12.</p> <p>Ascend gradually through medium undergrowth.</p>
18.60	<p>Fence, barbed wire, bears S. <math>10^{\circ}</math> E. and N. <math>10^{\circ}</math> W., for 8 chs., thence easterly.</p>
39.94	<p>Point for the <math>\frac{1}{4}</math> sec. cor. of secs. 1 and 12, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 24 ins. in the ground, cap mkd.</p> <p style="text-align: center;">T10S R27E <math>\frac{1}{4}</math> <math>\frac{S 1}{S12}</math> 1961</p> <p>Deposit broken glass at base of iron post.</p>
40.20	<p>Road, bears N. <math>1^{\circ}</math> W. and S. <math>3\frac{1}{2}^{\circ}</math> E.</p>
41.00	<p>Railroad track, bears N. <math>1^{\circ}</math> W. and S. <math>3\frac{1}{2}^{\circ}</math> E.</p>
41.80	<p>Powerline, bears S. <math>3\frac{1}{2}^{\circ}</math> E. and N. <math>1^{\circ}</math> W. for 8 chs. thence northeasterly.</p>
46.40	<p>Wash, 30 lks. wide, 1 ft. deep, drains E.</p>

## BOOK 4666

Subdivisional Lines, T. 10 S., R. 27 E., Arizona

17.

## Chains

- 79.88 The cor. of secs. 1, 2, 11 and 12.  
Land, gently rolling.  
Soil, sandy.  
Timber, none; undergrowth, mesquite and creosote brush.
- 
- N. 0°48' W., bet. secs. 1 and 2.  
Over rolling land, through undergrowth.
- 40.44 Point for the  $\frac{1}{4}$  sec. cor. of secs. 1 and 2, at proportionate distance; there is no remaining evidence of the original corner.  
Set the iron post 26 ins. in the ground, cap mkd.
- T10S R27E  
 $\frac{1}{4}$   
S2|S1  
1961
- Deposit broken glass at base of iron post.
- 76.70 Wash, 30 lks. wide, 4 ft. deep, drains NE.
- 77.20 Wash, 30 lks. wide, 4 ft. deep, drains NE.
- 80.07 The cor. of secs. 1, 2, 35 and 36 on the N. bdy. of the township.  
Land, rolling.  
Soil, sandy.  
Timber, none; undergrowth, mesquite and creosote brush.
- 
- From the standard cor. of secs. 34 and 35, on the S. bdy. of the township.  
N. 1°28' W., bet. secs. 34 and 35.  
Over gently rolling land, through desert undergrowth.
- 11.70 Wash, 50 lks. wide, 2 ft. deep, drains N. 70° E.
- 16.50 Wash, 75 lks. wide, 2 ft. deep, drains N 70° E.
- 31.70 Wash, 100 lks. wide, 1 ft. deep, drains N. 60° E.
- 40.13 Point for the  $\frac{1}{4}$  sec. cor. of secs. 34 and 35, at proportionate distance; there is no remaining evidence of the original corner.  
Set the iron post 26 ins. in the ground, cap mkd.
- T10S R27E  
 $\frac{1}{4}$   
S34|S35  
1961
- Deposit broken glass at base of iron post.
- 71.58 Fence, barbed wire, bears E. and W.
- 80.27 Point for the cor. of secs. 26, 27, 34 and 35, at proportionate distance; there is no remaining evidence of the original corner.  
Set the iron post 26 ins. in the ground, cap mkd.

## BOOK 4666

Subdivisional Lines, T. 10 S., R. 27 E., Arizona

18.

Chains

T10S R27E  
 S27|S26  
 S34|S35  
 1961

Deposit broken glass at base of iron post.

Land, rolling.

Soil, sandy.

Timber, none; undergrowth, mesquite and creosote brush.

From the cor. of secs. 25, 26, 35 and 36.

S. 89°04' W., bet. secs. 26 and 35.

Over rolling land with a series of small washes, general NE. drainage, through desert undergrowth.

2.00 Fence, barbed wire, bears S. 2° E. and North.

39.20 Wash, 100 lks. wide, 3 ft. deep, drains N. 45° E.

40.73 The original  $\frac{1}{4}$  sec. cor. of secs. 26 and 35, as described in the official record.

At the corner point

Set the iron post 26 ins. in the ground, cap mkd.

T10S R27E  
 $\frac{1}{4}$  S 26  
 S 35  
 1961

Deposit broken glass at base of iron post.

N. 88°43' W., beginning new measurement.

40.29 The cor. of secs. 26, 27, 34 and 35.

Land, rolling.

Soil, sandy.

Timber, none; undergrowth, mesquite, cactus and creosote brush.

N. 0°07' E., bet. secs. 26 and 27.

Over slightly rolling land containing a series of small washes with general NE. drainage, through desert undergrowth.

40.12 Point for the  $\frac{1}{4}$  sec. cor. of secs. 26 and 27, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 26 ins. in the ground, cap mkd.

T10S R27E  
 $\frac{1}{4}$   
 S27|S26  
 1961

80.24 Point for the cor. of secs. 22, 23, 26 and 27, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 26 ins. in the ground, cap mkd.

Chains	
	<p style="text-align: center;">T10S R27E  <math>\frac{S22}{S27}   \frac{S23}{S26}</math>  1961</p> <p>Deposit broken glass at base of iron post.</p> <p>Land, rolling.  Soil, sandy.  Timber, none; undergrowth, mesquite, cactus and greasewood.</p> <hr/>
0.70	<p>From the cor. of secs. 23, 24, 25 and 26.</p> <p>S. 89°37' W., bet. secs. 23 and 26.</p> <p>Over gently rolling land containing a series of small washes, general NE. drainage, through desert undergrowth.</p>
40.61	<p>Fence, barbed wire, bears N. 1° W. and S. 1° E.</p>
40.61	<p>The original <math>\frac{1}{4}</math> sec. cor. of secs. 23 and 26 as described in the official record.</p> <p>At the corner point</p> <p>Set the iron post 26 ins. in the ground, cap mkd.</p> <p style="text-align: center;">T10S R27E  <math>\frac{1}{4} \frac{S 23}{S 26}</math>  1961</p>
40.31	<p>Deposit broken glass at base of iron post.</p> <hr/> <p>N. 89°19' W., beginning new measurement.</p>
40.31	<p>The cor. of secs. 22, 23, 26 and 27.</p> <p>Land, gently rolling.  Soil, sandy.  Timber, none; undergrowth, cactus, mesquite and greasewood.</p> <hr/>
40.12	<p>N. 0°31' E., bet. secs. 22 and 23.</p> <p>Descend along gentle NE. slope over a series of small washes, general NE. drainage, through a dense growth of mesquite and brush.</p>
40.12	<p>The original <math>\frac{1}{4}</math> sec. cor. of secs. 22 and 23 as described in the official record.</p> <p>At the corner point</p> <p>Set the iron post 24 ins. in the ground, cap mkd.</p> <p style="text-align: center;">T10S R27E  <math>\frac{1}{4} \frac{S22}{S23}</math>  1961</p> <hr/>
40.56	<p>N. 0°40' E., beginning new measurement.</p> <p>Point for the cor. of secs. 14, 15, 22 and 23, at proportionate distance; there is no remaining evidence of the original corner.</p>

## Chains

Set the iron post 10 ins. in the ground, mound with stone to top, cap mkd.

$$\begin{array}{r} \text{T10S R27E} \\ \text{S15|S14} \\ \hline \text{S22|S23} \\ 1961 \end{array}$$

Deposit broken glass at base of iron post.

Land, gently rolling.

Soil, sandy.

Timber, none; undergrowth, mesquite, yucca and cactus.

---

From the cor. of secs. 13, 14, 23 and 24.

N. 89°30' W., bet. secs. 14 and 23.

Ascend along gentle E. slope, over a series of small washes, general NE. drainage, through a dense growth of creosote and mesquite.

40.18 Point for the  $\frac{1}{4}$  sec. cor. of secs. 14 and 23, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 26 ins. in the ground, cap mkd.

$$\begin{array}{r} \text{T10S R27E} \\ \frac{1}{4} \frac{\text{S 14}}{\text{S 23}} \\ 1961 \end{array}$$

Deposit broken glass at base of iron post.

80.37 The cor. of secs. 14, 15, 22 and 23.

Land, gently rolling.

Soil, sandy.

Timber, none; undergrowth, creosote and mesquite.

---

N. 0°43' W., bet. secs. 14 and 15.

Descend along gentle NE. slope.

3.70 Road, bears NE. and SW.

40.56 Point for the  $\frac{1}{4}$  sec. cor. of secs. 14 and 15, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 26 ins. in the ground, cap mkd.

$$\begin{array}{r} \text{T10S R27E} \\ \frac{1}{4} \\ \text{S15|S14} \\ 1961 \end{array}$$

Deposit broken glass at base of iron post.

81.12 The original cor. of secs. 10, 11, 14 and 15 as described in the official record.

At the corner point

Set the iron post 24 ins. in the ground, cap mkd.

## Chains

T10S R27E  
 $\frac{S10}{S15} | \frac{S11}{S14}$   
 1961

Land, gently rolling.  
 Soil, sand.  
 Timber, none; undergrowth, mesquite and cactus.

From the cor. of secs. 11, 12, 13 and 14.

N. 89°03' W., bet. secs. 11 and 14.

Over gently rolling land, through scattered mesquite brush.

4.70 Fence, barbed wire, bears N. 88°27' W., and S. 88°27' E.

24.90 Wash, 40 lks. wide, 1½ ft. deep, drains N. 70° E.

33.80 Road, bears NE. and SW.

40.22 The original ¼ sec. cor. of secs. 11 and 14 as described in the official record.

At the corner point

Set the iron post 24 ins. in the ground, cap mkd.

T10S R27E  
 $\frac{1}{4} \frac{S11}{S14}$   
 1961

Cor. falls S. of barbed wire fence, bearing S. 88°27' E.

N. 88°29' W., beginning new measurement.

13.60 Leave dense growth of creosote brush.

40.64 The cor. of secs. 10, 11, 14 and 15.

Land, gently rolling.  
 Soil, sand.  
 Timber, none; undergrowth, mesquite and creosote.

N. 0°45' E., bet. secs. 10 and 11.

Descend along gentle NE. slope.

38.26 Point for the ¼ sec. cor. of secs. 10 and 11 at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 26 ins. in the ground, cap mkd.

T10S R27E  
 $\frac{1}{4} \frac{S10}{S11}$   
 1961

Deposit broken glass at base of iron post.

76.52 The original cor. of secs. 2, 3, 10 and 11 as described in the official record.

At the corner point

## Chains

Set the iron post 24 ins. in the ground, cap mkd.

$$\begin{array}{r} \text{T10S R27E} \\ \text{S } 3 | \text{S } 2 \\ \hline \text{S10} | \text{S11} \\ 1961 \end{array}$$

Deposit broken glass at base of iron post.

Land, gently rolling.

Soil, sandy.

Timber, none; undergrowth, mesquite and creosote.

From the cor. of secs. 1, 2, 11 and 12.

N. 89°10' W., bet. secs. 2 and 11.

Ascend over gentle E. slope, through dense growth of creosote brush.

40.18 The original  $\frac{1}{4}$  sec. cor. of secs. 2 and 11 as described in the official record.

At the corner point

Set the iron post 20 ins. in the ground, mound with stone to top, cap mkd.

$$\begin{array}{r} \text{T10S R27E} \\ \frac{1}{4} \frac{\text{S } 2}{\text{S11}} \\ 1961 \end{array}$$

Deposit broken glass at base of iron post.

S. 85°53' W., beginning new measurement.

40.21 The cor. of secs. 2, 3, 10 and 11.

Land, nearly level.

Soil, sandy.

Timber, none; undergrowth, mesquite.

N. 0°31' W., bet. secs. 2 and 3.

Over gently rolling land containing a series of small washes, general NE. drainage.

6.60 Wash, 40 lks. wide, 1 ft. deep, drains N. 70° E.

16.10 Wash, 30 lks. wide,  $1\frac{1}{2}$  ft. deep, drains E.

29.80 Wash, 30 lks. wide, 1 ft. deep, drains E.

39.00 Wash, 35 lks. wide,  $1\frac{1}{2}$  ft. deep, drains E.

41.99 Point for the  $\frac{1}{4}$  sec. cor. of secs. 2 and 3 at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 26 ins. in the ground, cap mkd.

$$\begin{array}{r} \text{T10S R27E} \\ \frac{1}{4} \\ \text{S3} | \text{S2} \\ 1961 \end{array}$$



Chains	
82.33	<p>Deposit broken glass at base of iron post.</p> <p>The cor. of secs. 2, 3, 34 and 35 on the N. bdy. of the township.</p> <p>Land, nearly level. Soil, rocky. Timber, none; undergrowth, creosote bush.</p>
39.22	<p>From the standard cor. of secs. 33 and 34, on the south boundary of the township.</p> <p>N. 3°10' W., bet. secs. 33 and 34.</p> <p>Over nearly level land, through dense undergrowth.</p> <p>The original <math>\frac{1}{4}</math> sec. cor. of secs. 33 and 34 as described in the official record.</p> <p>At the corner point</p> <p>Set the iron post 24 ins. in the ground, cap mkd.</p> <p style="text-align: center;">T10S R27E <math>\frac{1}{4}</math> S33 S34 1961</p>
14.60	<p>Wash, 15 lks. wide, 1 ft. deep, drains NE.</p>
40.40	<p>Point for the sec. cor. of secs. 27, 28, 33 and 34 at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 26 ins. in the ground, cap mkd.</p> <p style="text-align: center;">T10S R27E S28 S27 S33 S34 1961</p>
40.24	<p>Deposit broken glass at base of iron post.</p> <p>From the cor. of secs. 26, 27, 34 and 35.</p> <p>S. 89°43' W., bet. secs. 27 and 34.</p> <p>Ascend slightly over nearly level land, through dense undergrowth.</p> <p>Point for the <math>\frac{1}{4}</math> sec. cor. of secs. 27 and 34, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 26 ins. in the ground, cap mkd.</p> <p style="text-align: center;">T10S R27E <math>\frac{1}{4}</math> <math>\frac{S 27}{S 34}</math> 1961</p>
58.80	<p>Wash, 40 lks. wide, <math>1\frac{1}{2}</math> ft. deep, drains NE.</p>
80.48	<p>The cor. of secs. 27, 28, 33 and 34.</p>

24

Chains	
	<p>Land, nearly level. Soil, sandy. Timber, none; undergrowth, creosote and mesquite.</p>
	<p>N. 0°05' E., bet. secs. 27 and 28.</p> <p>Descend slightly over nearly level land, through medium growth of brush.</p>
14.40	Wash, 25 lks. wide, 2 ft. deep, drains NE.
40.40	<p>Point for the <math>\frac{1}{4}</math> sec. cor. of secs. 27 and 28, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 26 ins. in the ground, cap mkd.</p> <p style="text-align: center;">T10S R27E <math>\frac{1}{4}</math> S28 S27 1961</p> <p>Deposit broken glass at base of iron post.</p>
45.50	Road, bears NE. and SW.
69.60	Wash, 40 lks. wide, 1 ft. deep, drains NE.
80.80	<p>Point for the cor. of secs. 21, 22, 27 and 28, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 26 ins. in the ground, cap mkd.</p> <p style="text-align: center;">T10S R27E S21 S22 S28 S27 1961</p> <p>Deposit broken glass at base of iron post.</p>
	<p>From the cor. of secs. 22, 23, 26 and 27.</p> <p>N. 89°58' W., bet. secs. 22 and 27.</p> <p>Ascend over nearly level land, through scattered desert undergrowth.</p>
15.60	Wash, 30 lks. wide, 1 ft. deep, drains NE.
40.20	<p>Point for the <math>\frac{1}{4}</math> sec. cor. of secs. 22 and 27, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 26 ins. in the ground, cap mkd.</p> <p style="text-align: center;">T10S R27E <math>\frac{1}{4}</math> <math>\frac{S\ 22}{S\ 27}</math> 1961</p> <p>Deposit broken glass at base of iron post.</p>
56.30	Road, bears NE. and SW.
80.40	The cor. of secs. 21, 22, 27 and 28.

## Chains

Land, nearly level.  
Soil, sandy.  
Timber, none; undergrowth, mesquite and creosote.

N. 0°16' E., bet. secs. 21 and 22.

Descend over nearly level land, through desert undergrowth.

40.40 The original  $\frac{1}{4}$  sec. cor. of secs. 21 and 22 as described in the official record.

At the corner point

Set the iron post 24 ins. in the ground, cap mkd.

$$\begin{array}{c} \text{T10S, R27E} \\ \frac{1}{4} \\ \text{S21 | S22} \\ \text{1961} \end{array}$$

N. 0°41' E., beginning new measurement.

12.70 Wash, 20 lks. wide, 3 ft. deep, drains NE.

23.70 Wash, 10 lks. wide, 1 ft. deep, drains NE.

40.36 The original cor. of secs. 15, 16, 21 and 22, as described in the official record.

At the corner point

Set the iron post 24 ins. in the ground, cap mkd.

$$\begin{array}{c} \text{T10S R27E} \\ \text{S16 | S15} \\ \text{S21 | S22} \\ \text{1961} \end{array}$$

Land, nearly level.  
Soil, sandy.  
Timber, none; undergrowth, mesquite and creosote.

From the cor. of secs. 14, 15, 22 and 23.

N. 89°47' W., bet. secs. 15 and 22.

Ascend over rolling land, containing a series of small washes, general NE. drainage, through desert growth.

4.90 Road, bears N. 20° E., and S. 20° W.

40.23 Point for the  $\frac{1}{4}$  sec. cor. of secs. 15 and 22, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 20 ins. in the ground, cap mkd.

$$\begin{array}{c} \text{T10S R27E} \\ \frac{1}{4} \frac{\text{S 15}}{\text{S 22}} \\ \text{1961} \end{array}$$

Deposit broken glass at base of iron post.

80.46 The cor. of secs. 15, 16, 21 and 22.

## Chains

Land, rolling.  
Soil, sandy.  
Timber, none; undergrowth, mesquite and creosote brush.

N. 0°23' W., bet. secs. 15 and 16.

Descend over gently rolling land, through desert vegetation.

40.39 Point for the  $\frac{1}{4}$  sec. cor. of secs. 15 and 16, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post, 20 ins. in the ground, cap mkd.

T10S R27E

$\frac{1}{4}$

S16 | S15

1961

42.00 Wash, 15 lks. wide, 1 ft. deep, drains NE.

80.78 Point for the cor. of secs. 9, 10, 15 and 16, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 20 ins. in the ground, cap mkd.

T10S R27E

S 9 | S10

S16 | S15

1961

Deposit broken glass at base of iron post.

Land, gently rolling.

Soil, sandy.

Timber, none; undergrowth, mesquite and creosote.

From the cor. of secs. 10, 11, 14 and 15.

West, bet. secs. 10 and 15.

Ascend over gently rolling land containing a series of small washes, general NE. drainage, through desert vegetation.

35.80 Wash, 30 lks. wide, 1 ft. deep, drains N. 50° E.

39.91 Point for the  $\frac{1}{4}$  sec. cor. of secs. 10 and 15, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 20 ins. in the ground, cap mkd.

T10S R27E

$\frac{1}{4}$  S10

S15

1961

Deposit glass at base of iron post.

79.82 The cor. of secs. 9, 10, 15 and 16.

Land, gently rolling.

Soil, sandy.

Timber, none; undergrowth, mesquite and creosote.

## BOOK 4666

Subdivisional Lines, T. 10 S., R. 27 E., Arizona

27.

## Chains

N. 0°28' W., bet. secs. 9 and 10.

Over gently rolling land, through undergrowth of brush.

0.20 Fence, barbed wire, bears S. 89°15' W., and N. 89°15' E.

40.39 Point for the  $\frac{1}{4}$  sec. cor. of secs. 9 and 10, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post, 20 ins. in the ground, cap mkd.

T10S R27E

 $\frac{1}{4}$ 

S 9 | S10

1961

Deposit broken glass at base of iron post.

80.78 The original cor. of secs. 3, 4, 9 and 10 as described in the official record.

At the corner point

Set the iron post 24 ins. in the ground, cap mkd.

T10S R27E

S 4 | S 3

S 9 | S10

1961

Land, rolling.

Soil, sandy.

Timber, none; undergrowth, mesquite and creosote.

From the cor. of secs. 2, 3, 10 and 11.

N. 87°00' W., between secs. 3 and 10.

Ascend along gentle E. slope.

40.74 Point for the  $\frac{1}{4}$  sec. cor. of secs. 3 and 10, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 20 ins. in the ground, cap mkd.

T10S R27E

 $\frac{1}{4}$  S 3

S10

1961

Deposit broken glass at base of iron post.

81.48 The cor. of secs. 3, 4, 9 and 10.

Land, gently rolling.

Soil, coarse sand.

Timber, none; undergrowth, mesquite and creosote.

N. 0°15' E., bet. secs. 3 and 4.

Over rolling land, through desert vegetation.

24.00 Wash, 25 lks. wide, 2 ft. deep, drains NE.

40.12 The original  $\frac{1}{4}$  sec. cor. of secs. 3 and 4 as described in the official record.

## Chains

At the corner point

Set the iron post 24 ins. in the ground, cap mkd.

T10S R27E

$\frac{1}{2}$   
S4 | S3  
1961

North, beginning new measurement.

11.70 Wash, 20 lks. wide, 2 ft. deep, drains NE.

37.98 The cor. of secs. 3, 4, 33 and 34, on the N. bdy. of the township.

Land, gently rolling.

Soil, coarse sand.

Timber, none; undergrowth, mesquite and creosote.

From the Stan. cor. of secs. 32 and 33, on the S. bdy. of the township.

N. 1°43' W., bet. secs. 32 and 33.

Over gently rolling land, through desert undergrowth.

39.93 Point for the  $\frac{1}{2}$  sec. cor. of secs. 32 and 33, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 8 ins. in the ground, mound with stone to top, cap mkd.

T10S R27 E

$\frac{1}{2}$   
S32 | S33  
1961

41.80 Wash, 50 lks. wide, 1 ft. deep, drains E.

78.20 Dirt road, bears S. 80° W. and N. 80° E.

79.86 The original cor. of secs. 28, 29, 32 and 33, as described in the official record.

At the corner point

Set the iron post 24 ins. in the ground, mound with stone to top, cap mkd.

T10S R27E

S29 | S28  
S32 | S33  
1961

Land, gently rolling.

Soil, sandy.

Timber, none; undergrowth, mesquite and cactus.

From the cor. of secs. 27, 28, 33 and 34.

N. 89°44' W., bet. secs. 28 and 33.

Over gently rolling land, through scattered mesquite brush.

20.40 Wash, 15 lks. wide, 2 ft. deep, drains NE.

## Chains

- 24.30 Fence, enclosure around windmill.
- 26.10 Windmill, bears 19 lks. N.
- 28.80 Fence, around windmill.
- 31.20 Road, unimproved, bears generally E. and W.
- 40.20 Point for the  $\frac{1}{4}$  sec. cor. of secs. 28 and 33, at proportionate distance; there is no remaining evidence of the original corner.
- Set the iron post, 20 ins. in the ground, cap mkd.

T10S R27E

$$\frac{1}{4} \begin{array}{l} \text{S 28} \\ \text{S 33} \end{array}$$

1961

Deposit glass at base of iron post.

- 43.70 Road, unimproved, winding generally E. and W.
- 80.40 The cor. of secs. 28, 29, 32 and 33.

Land, gently rolling.

Soil, sandy.

Timber, none; undergrowth, mesquite and cactus.

North, bet. secs. 28 and 29.

- 9.30 Wash, 40 lks. wide, 2 ft. deep, drains S. 70° E.
- 40.35 Point for the  $\frac{1}{4}$  sec. cor. of secs. 28 and 29, at proportionate distance; there is no remaining evidence of the original corner.
- Set the iron post 20 ins. in the ground, cap mkd.

T10S R27E

$$\frac{1}{4} \begin{array}{l} \text{S29} | \text{S28} \end{array}$$

1961

Deposit glass at base of iron post.

- 71.20 Wash, 20 lks. wide, 3 ft. deep, drains N. 30° E.
- 80.70 The original corner of secs. 20, 21, 28 and 29, as described in the official record.

At the corner point.

Set the iron post 24 ins. in the ground, cap mkd.

T10S R27E

$$\begin{array}{l} \text{S20} | \text{S21} \\ \text{S29} | \text{S28} \end{array}$$

1960

Deposit glass at base of iron post.

Land, gently rolling.

Soil, sandy.

Timber, none; undergrowth, mesquite and cactus.

## Chains

From the cor. of secs. 21, 22, 27 and 28.

N. 89°51' W., bet. secs. 21 and 28.

33.70 Wash, 30 lks. wide, 3 ft. deep, drains NE.

40.21 Point for the  $\frac{1}{4}$  sec. cor. of secs. 21 and 28, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 20 ins. in the ground, cap mkd.

T10S R27E

$\frac{1}{4}$   $\frac{S\ 21}{S\ 28}$

1961

Deposit glass at base of iron post.

63.50 Wash, 40 lks. wide, 3 ft. deep, drains NE.

80.42 The cor. of secs. 20, 21, 28 and 29.

Land, gently rolling.

Soil, sandy.

Timber, none; undergrowth, mesquite and cactus.

N. 0°31' E., bet. 20 and 21.

39.92 The original  $\frac{1}{4}$  sec. cor. of secs. 20 and 21, as described in the official record.

At the corner point

Set the iron post 26 ins. in the ground, cap mkd.

T10S R27E

$\frac{1}{4}$   $\frac{S20|S21}{S20|S21}$

1961

Deposit glass at base of iron post.

N. 1°14' E., beginning new measurement.

40.33 Point for the cor. of secs. 16, 17, 20 and 21, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 20 ins. in the ground, cap mkd.

T10S R27E

$\frac{S17|S16}{S20|S21}$

1961

Deposit glass at base of iron post.

Land, gently rolling.

Soil, sandy.

Timber, none; undergrowth, mesquite and cactus.



## Chains

From the cor. of secs. 15, 16, 21 and 22.

S. 89°46' W., bet. secs. 16 and 21.

Over gently rolling land, through desert vegetation.

39.94

Point for the  $\frac{1}{4}$  sec. cor. of secs. 16 and 21, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 20 ins. in the ground, cap mkd.

T10S R27E

$$\frac{1}{4} \begin{array}{l} \text{S 16} \\ \text{S 21} \end{array}$$

1961

Deposit glass at base of iron post.

79.88

The cor. of secs. 16, 17, 21 and 22.

Land, gently rolling.

Soil, sandy.

Timber, none; undergrowth, mesquite and cactus.

N. 0°20' W., bet. secs. 16 and 17.

Over gently rolling land, through desert vegetation.

40.32

Point for the  $\frac{1}{4}$  sec. cor. of secs. 16 and 17, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 20 ins. in the ground, cap mkd.

T10S R27E

$$\frac{1}{4} \begin{array}{l} \text{S 17} | \text{S 16} \\ \text{S 17} | \text{S 16} \end{array}$$

1961

Deposit glass at base of iron post.

80.42

Fence, bears S. 89°15' W. and N. 89°15' E.

80.64

Point for the cor. of secs. 8, 9, 16 and 17, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 22 ins. in the ground, cap mkd.

T10S R27E

$$\begin{array}{l} \text{S 8} | \text{S 9} \\ \text{S 17} | \text{S 16} \end{array}$$

1961

Deposit glass at base of iron post.

Land, gently rolling.

Soil, sandy.

Timber, none; undergrowth, mesquite and creosote.

From the cor. of secs. 9, 10, 15 and 16.

S. 89°40' W., bet. secs. 9 and 16.

Over gently rolling land, through desert vegetation.

Chains					
39.90	<p>Point for the <math>\frac{1}{4}</math> sec. cor. of secs. 9 and 16, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 18 ins. in the ground, mound with stone to top, cap mkd.</p> <div style="text-align: center;"> <p>T10S R27E</p> <table style="margin-left: auto; margin-right: auto;"> <tr> <td style="padding: 0 10px;"><math>\frac{1}{4}</math></td> <td style="border: 1px solid black; padding: 2px;">S 9</td> </tr> <tr> <td style="padding: 0 10px;"></td> <td style="border: 1px solid black; padding: 2px;">S 16</td> </tr> </table> <p>1961</p> </div> <p>Deposit glass at base of iron post.</p>	$\frac{1}{4}$	S 9		S 16
$\frac{1}{4}$	S 9				
	S 16				
79.80	<p>The cor. of secs. 8, 9, 16 and 17.</p> <p>Land, gently rolling. Soil, sandy. Timber, none; undergrowth, mesquite and creosote.</p>				
40.32	<p>N. 0°20' W., bet. secs. 8 and 9.</p> <p>Over gently rolling land, through desert vegetation.</p> <p>Point for the <math>\frac{1}{4}</math> sec. cor. for secs. 8 and 9, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 20 ins. in the ground, cap mkd.</p> <div style="text-align: center;"> <p>T10S R27E</p> <table style="margin-left: auto; margin-right: auto;"> <tr> <td style="padding: 0 10px;"><math>\frac{1}{4}</math></td> <td style="border: 1px solid black; padding: 2px;">S8   S9</td> </tr> </table> <p>1961</p> </div> <p>Deposit glass at base of iron post.</p>	$\frac{1}{4}$	S8   S9		
$\frac{1}{4}$	S8   S9				
80.64	<p>Point for the sec. cor. for secs. 4, 5, 8 and 9, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 20 ins. in the ground, cap mkd.</p> <div style="text-align: center;"> <p>T10S R27E</p> <table style="margin-left: auto; margin-right: auto;"> <tr> <td style="border: 1px solid black; padding: 2px;">S5</td> <td style="border: 1px solid black; padding: 2px;">S4</td> </tr> <tr> <td style="border: 1px solid black; padding: 2px;">S8</td> <td style="border: 1px solid black; padding: 2px;">S9</td> </tr> </table> <p>1961</p> </div> <p>Deposit glass at base of iron post.</p> <p>Land, gently rolling. Soil, sandy. Timber, none; undergrowth, mesquite and creosote.</p>	S5	S4	S8	S9
S5	S4				
S8	S9				
32.20	<p>From the cor. of secs. 3, 4, 9 and 10.</p> <p>S. 89°37' W., bet. secs. 4 and 9.</p> <p>Ascend over gently rolling land, through desert vegetation.</p>				
39.79	<p>Wash, 35 lks. wide, 2 ft. deep, drains NE.</p> <p>Point for the <math>\frac{1}{4}</math> sec. cor. of secs. 4 and 9, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 20 ins. in the ground, cap mkd.</p>				

Chains	
79.58	<p style="text-align: center;">T10S R27E  <math>\frac{1}{4}</math> <math>\frac{S\ 4}{S\ 9}</math>  1961</p> <p>Deposit glass at base of iron post.</p> <p>The cor. of secs. 4, 5, 8 and 9.</p> <p>Land, gently rolling.  Soil, sandy.  Timber, none; undergrowth, mesquite and creosote.</p>
40.32	<p>N. 0°39' W., bet. secs. 4 and 5.</p> <p>Over gently rolling land, through desert vegetation.</p> <p>Point for the <math>\frac{1}{4}</math> sec. cor. of secs. 4 and 5 at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 18 ins. in the ground, mound with stone to top, cap mkd.</p>
78.02	<p style="text-align: center;">T10S R27E  <math>\frac{1}{4}</math>  S5   S4  1961</p> <p>Deposit glass at base of iron post.</p> <p>The cor. of secs. 4, 5, 32 and 33, on the N. bdy. of the township.</p> <p>Land, gently rolling.  Soil, sandy.  Timber, none; undergrowth, mesquite and creosote.</p>
15.10	<p>From the Stan. cor. of secs. 31 and 32, on the S. bdy. of the township.</p> <p>N. 1°52' W., bet. secs. 31 and 32.</p> <p>Over gently rolling land, through light desert vegetation.</p> <p>Wash, 50 lks. wide, 3 ft. deep, drains E.</p>
20.00	<p>Wash, 40 lks. wide, 3 ft. deep, drains E.</p>
39.91	<p>Point for the <math>\frac{1}{4}</math> sec. cor. of secs. 31 and 32, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 15 ins. in the ground, mound with stone to top, cap mkd.</p> <p style="text-align: center;">T10S R27E  <math>\frac{1}{4}</math>  S31   S32  1961</p> <p>Deposit glass at base of iron post.</p> <p>The original cor. of secs. 29, 30, 31 and 32, as described in the official record.</p> <p>At the corner point</p>
79.82	

## Chains

Set the iron post 12 ins. in the ground, mound with stone to top, cap mkd.

T10S R27E

S30|S29

S31|S32

1961

Deposit glass at base of iron post.

Land, gently rolling.

Soil, coarse sand.

Timber, none; undergrowth, mesquite.

From the cor. of secs. 28, 29, 32 and 33.

N. 89°56' W., bet. secs. 29 and 32.

Ascend over gently rolling land, through desert vegetation.

15.50 Wash, 20 lks. wide, 4 ins. deep, drains NE.

28.20 Wash, 30 lks. wide, 4 ins. deep, drains NE.

40.26 Point for the  $\frac{1}{4}$  sec. cor. of secs. 29 and 32, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 20 ins. in the ground, cap mkd.

T10S R27E

$\frac{1}{4}$  S 29

S 32

1961

Deposit glass at base of iron post.

50.70 Wash, 20 lks. wide, 2 ft. deep, drains NE.

62.10 Wash, 30 lks. wide, 2 ft. deep, drains NE.

80.52 The cor. of secs. 29, 30, 31 and 32.

Land, gently rolling.

Soil, sandy.

Timber, none; undergrowth, mesquite.

N. 89°57' W., bet. secs. 30 and 31.

Over gently rolling land, through desert vegetation.

7.60 Fence, bears S. 3°55' W. and N. 3°55' E.

24.30 Wash, 90 lks. wide, 3 ft. deep, drains NE.

38.85 Point for the  $\frac{1}{4}$  sec. cor. of secs. 30 and 31, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 24 ins. in the ground, cap mkd.

T10S R27E

$\frac{1}{4}$  S 30

S 31

1961

Deposit glass at base of iron post.

## Chains

- 77.61 The corner of secs. 30 and 31, on the W. bdy. of the township, monumented by an iron post as described in the official record.
- Land, gently rolling.  
Soil, sandy.  
Timber, none; undergrowth, mesquite and creosote.
- 
- From the cor. of secs. 29, 30, 31 and 32.
- Over gently rolling NE. slope, through desert vegetation.
- N. 0°10' E., bet. secs. 29 and 30.
- 17.80 Wash, 35 lks. wide, 3 ft. deep, drains NE.
- 40.24 Point for the  $\frac{1}{4}$  sec. cor. of secs. 29 and 30, at proportionate distance; there is no remaining evidence of the original corner.
- Set the iron post 20 ins. in the ground, cap mkd.
- T10S R27E  
 $\frac{1}{4}$   
S30|S29  
1961
- Deposit glass at base of iron post.
- 51.60 Wash, 50 lks. wide, 2 ft. deep, drains NE.
- 79.40 Wash, 35 lks. wide, 2 ft. deep, drains E. for 8 chains, then NE.
- 80.48 The original cor. of secs. 19, 20, 29 and 30, monumented by a granite stone as described in the official record.
- At the cor. point
- Set the iron post 24 ins. in the ground, cap mkd.
- T10S R27E  
S19|S20  
-----  
S30|S29  
1961
- Deposit glass at base of iron post.
- Land, nearly level.  
Soil, coarse sand.  
Timber, none; undergrowth, mesquite.
- 
- From the cor. of secs. 20, 21, 28 and 29.
- S. 89°54' W., bet. secs. 20 and 29.
- Over nearly level land, through desert vegetation.
- 40.14 Point for the  $\frac{1}{4}$  sec. cor. of secs. 20 and 29, at proportionate distance; there is no remaining evidence of the original corner. Point falls in a wash draining NE. where a permanent monument cannot be established.
- 40.44 Point selected for the witness  $\frac{1}{4}$  sec. cor. of secs. 20 and 29.
- Set the iron post 20 ins. in the ground, cap mkd.

Chains

T10S R27E

WC

$\frac{1}{4}$   $\frac{S\ 20}{S\ 29}$  →

1961

Deposit glass at base of iron post.

57.60 Wash, 30 lks. wide, 2 ft. deep, drains NE.

73.80 Wash, 50 lks. wide, 3 ft. deep, drains NE.

80.28 The cor. of secs. 19, 20, 29 and 30.

Land, nearly level.

Soil, coarse sand.

Timber, none; undergrowth, mesquite and creosote.

S. 89°02' W., bet. secs. 19 and 30.

Ascend over gently rolling land, through desert vegetation.

40.19 The original  $\frac{1}{4}$  sec. cor. of secs. 19 and 30, monumented by a wood stake as described in the official record.

At the corner point

Set the iron post 24 ins. in the ground, cap mkd.

T10S R27E

$\frac{1}{4}$   $\frac{S\ 19}{S\ 30}$

1961

N. 89°58' W., beginning new measurement.

37.56 The corner of secs. 19 and 30 on the W. bdy. of the township, monumented by an iron post as described in the official record.

Land, gently rolling.

Soil, coarse sand.

Timber, none; undergrowth, mesquite and catclaw.

From the cor. of secs. 19, 20, 29 and 30.

N. 1°11' E., bet. secs. 19 and 20.

Over gently rolling land, through desert vegetation.

40.31 Point for the  $\frac{1}{4}$  sec. cor. of secs. 19 and 20, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 18 ins. in the ground, cap mkd.

T10S R27E

$\frac{1}{4}$  S19 | S20

1961

Deposit glass at base of iron post.

44.60 Wash, 50 lks. wide, 1 ft. deep, drains NE.

78.80 Wash, 50 lks. wide, 1 ft. deep, drains E.

## BOOK 4666

Subdivisional Lines, T. 10 S., R. 27 E., Arizona

37.

Chains	
80.62	<p>Point for the cor. of secs. 17, 18, 19 and 20, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 20 ins. in the ground, cap mkd.</p> <p style="text-align: center;">T10S R27E  <math>\frac{S18}{S19}   \frac{S17}{S20}</math>  1961</p> <p>Deposit glass at base of iron post.</p> <p>Land, gently rolling.  Soil, sandy.  Timber, none; undergrowth, mesquite and catclaw.</p>
3.70	<p>From the corner of secs. 16, 17, 20 and 21.</p> <p>N. 89°51' W., bet. secs. 17 and 20.</p> <p>Over nearly level land, through desert vegetation.</p>
39.91	<p>Wash, 70 lks. wide, 2 ft. deep, drains NE.</p> <p>Point for the <math>\frac{1}{4}</math> sec. cor. of secs. 17 and 20, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 20 ins. in the ground, cap mkd.</p> <p style="text-align: center;">T10S R27E  <math>\frac{1}{4} \frac{S 17}{S 20}</math>  1961</p> <p>Deposit glass at base of iron post.</p>
40.10	<p>Wash, 30 lks. wide, 1 ft. deep, drains NE.</p>
74.60	<p>Wash, 20 lks. wide, 2 ft. deep, drains NE.</p>
79.82	<p>The corner of secs. 17, 18, 19 and 20.</p> <p>Land, nearly level.  Soil, sandy.  Timber, none; undergrowth, mesquite, catclaw and creosote.</p>
39.96	<p>S. 88°54' W., bet. secs. 18 and 19.</p> <p>Over nearly level land, through desert vegetation.</p> <p>Point for the <math>\frac{1}{4}</math> sec. cor. of secs. 18 and 19, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 20 ins. in the ground, cap mkd.</p> <p style="text-align: center;">T10S R27E  <math>\frac{1}{4} \frac{S 18}{S 19}</math>  1961</p> <p>Deposit glass at base of iron post.</p>
79.55	<p>Fence, bears N. and S.</p>

Chains	
79.62	The corner of secs. 18 and 19 on the W. bdy. of the township, monumented by an iron post as described in the official record.
	Land, nearly level. Soil, sandy. Timber, none; undergrowth, mesquite and catclaw.
	<hr/> From the cor. of secs. 17, 18, 19 and 20. N. 0°12' W., bet. secs. 17 and 18. Over nearly level land, through desert vegetation.
40.30	Point for the $\frac{1}{4}$ sec. cor. of secs. 17 and 18, at proportionate distance; there is no remaining evidence of the original corner.
	Set the iron post 20 ins. in the ground, cap mkd.
	T10S R27E $\frac{1}{4}$ S18 S17 1961
	Deposit glass at base of iron post.
79.25	Fence, bears E. and W.
80.60	Point for the sec. cor. of secs. 7, 8, 17 and 18, at proportionate distance; there is no remaining evidence of the original corner.
	Set the iron post 20 ins. in the ground, cap mkd.
	T10S R27E S 7   S 8 S18   S17 1961
	Deposit glass at base of iron post.
	Land, nearly level. Soil, sandy. Timber, none; undergrowth, mesquite and yucca.
	<hr/> From the corner of secs. 8, 9, 16 and 17. N. 89°46' W., bet. secs. 8 and 17. Over gently rolling land, through desert vegetation.
39.86	Point for the $\frac{1}{4}$ sec. cor. of secs. 8 and 17, at proportionate distance; there is no remaining evidence of the original corner.
	Set the iron post 20 ins. in the ground, cap mkd.
	T10S R27E $\frac{1}{4}$ S 8 S17 1961
	Deposit glass at base of iron post.
71.20	Fence, bears E. and W.
79.72	The corner of secs. 7, 8, 17 and 18.
	Land, gently rolling. Soil, sandy. Timber, none; undergrowth, yucca and mesquite.



## BOOK 4666

Subdivisional Lines, T. 10 S., R. 27 E., Arizona

39.

## Chains

S. 88°21' W., bet. secs. 7 and 18.

Over gently rolling land, through desert vegetation.

26.90 Wash, 50 lks. wide, 2 ft. deep, drains NE.

39.95 Point for the  $\frac{1}{4}$  sec. cor. of secs. 7 and 18, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 20 ins. in the ground, cap mkd.

T10S R27E

 $\frac{1}{4}$   $\frac{S}{S}$   $\frac{7}{18}$ 

1961

Deposit glass at base of iron post.

42.80 Wash, 20 lks. wide, 2 ft. deep, drains NE.

74.60 Wash, 50 lks. wide, 1 ft. deep, drains E.

79.58 The corner of secs. 7 and 18 on the W. bdy. of the township, monumented by an iron post as described in the official record.

Land, gently rolling.

Soil, sandy.

Timber, none; undergrowth, mesquite and Yucca.

From the cor. of secs. 7, 8, 17 and 18.

N. 0°16' W., bet. secs. 7 and 8.

Over nearly level land, through desert vegetation.

33.60 Wash, 30 lks. wide, 4 ft. deep, drains NE.

40.30 Point for the  $\frac{1}{4}$  sec. cor. of secs. 7 and 8, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 20 ins. in the ground, cap mkd.

T10S R27E

 $\frac{1}{4}$  S7|S8

1961

Deposit glass at base of iron post.

73.10 Wash, 50 lks. wide, 3 ft. deep, drains NE.

80.60 Point for the cor. of secs. 5, 6, 7 and 8, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 20 ins. in the ground, cap mkd.

T10S R27E

S6|S5  
S7|S8

1961

Deposit glass at base of iron post.

Land, nearly level.

Soil, sandy.

Timber, none; undergrowth, yucca and mesquite.

Chains	From the corner of secs. 4, 5, 8 and 9.
	N. 89°51' W., bet. secs. 5 and 8.
	Over nearly level land, through desert vegetation.
39.82	Point for the $\frac{1}{4}$ sec. cor. of secs. 5 and 8, at proportionate distance; there is no remaining evidence of the original corner.
	Set the iron post 20 ins. in the ground, cap mkd.
	<p style="text-align: center;">T10S R27E  <math>\frac{1}{4} \frac{S 5}{S 8}</math>                  1961</p>
	Deposit glass at base of iron post.
41.70	Wash, 15 lks. wide, 2 ft. deep, drains NE.
70.90	Wash, 50 lks. wide, 3 ft. deep, drains NE.
79.65	The corner of secs. 5, 6, 7 and 8.
	Land, nearly level. Soil, coarse sand. Timber, none; undergrowth, yucca, mesquite.
	S. 87°46' W., bet. secs. 6 and 7.
	Over nearly level land, through desert vegetation.
39.85	Point for the $\frac{1}{4}$ sec. cor. of secs. 6 and 7, at proportionate distance; there is no remaining evidence of the original corner.
	Set the iron post 20 ins. in the ground, cap mkd.
	<p style="text-align: center;">T10S R27E  <math>\frac{1}{4} \frac{S 6}{S 7}</math>                  1961</p>
	Deposit glass at base of iron post.
51.20	Wash, 15 lks. wide, 1 ft. deep, drains NE.
79.26	The corner of secs. 6 and 7 on the W. bdy. of the township, monumented by an iron post as described in the official record.
	Land, nearly level. Soil, sandy. Timber, none; undergrowth, yucca and mesquite.
	From the cor. of secs. 5, 6, 7 and 8.
	N. 1°22' W., bet. secs. 5 and 6.
	Over nearly level land, through desert vegetation.
29.60	Wash, 40 lks. wide, 1 ft. deep, drains N. 10° E.
40.31	Point for the $\frac{1}{4}$ sec. cor. of secs. 5 and 6, at proportionate distance; there is no remaining evidence of the original corner.

## BOOK 4666

Subdivisional Lines, T. 10 S., R. 27 E., Arizona

41.

## Chains

Set the iron post 20 ins. in the ground, cap mkd.

T10S R27E

$\frac{1}{4}$

S6|S5

1961

Deposit glass at base of iron post.

64.70 Wash, 30 lks. wide, 2 ft. deep, drains E.

66.20 Wash, 50 lks. wide, 3 ft. deep, drains E.

77.24 The cor. of secs. 5 and 6<sup>31 5 32</sup> on the N. bdy. of the township.

Land, nearly level.

Soil, coarse sand.

Timber, none; undergrowth, mesquite and yucca.

#### General Description

T. 10 S., R. 27 E. is in Graham County, Arizona, with the southeast corner of the township being about 25 air line miles southeast of the city of Safford, Arizona.

The land within the township is low rolling to nearly level, with a general northeast slope. The elevation of the township ranges from about 3,000 feet above sea level in the northeast quarter of section 1 to about 4,100 feet in the southwest quarter of section 31.

The drainage of the township consists of numerous intermittent streams and washes which drain northeast to San Simon Wash. The San Simon Wash, the main drainage line in the area, cuts through the northeast quarter of section 1, draining from the southeast to the northwest.

A rocky, sandy clay soil covering most of the township supports a vegetative cover of mesquite trees, creosote brush, cacti and grasses. The creosote brush, cacti and grasses are found over most of the area, while the mesquite trees are found mostly along the dry stream beds.

A branch line of the Southern Pacific Railroad crosses the township from a point near the quarter corner of sections 36 and 1 on the north boundary to a point about 19.00 chains west of the southeast corner of the township. An improved access road parallels the railroad from the north boundary to a point near the center of section 12; thence the road bears southwest to a windmill in the northeast quarter of section 33. There are a few other track roads scattered throughout the township.

The only water source noted during this survey was that produced by the windmill in section 33. The improvements noted during this survey were the railroad, road, windmill with corral and metal tank and some range fences constructed along allotment boundaries.

There is no evidence of any mineralization in the area of T. 10 S., R. 27 E. and at the present time the only utilization of the land and its resources is in access, cattle grazing and some small game hunting.



43

CERTIFICATE OF CADASTRAL SURVEYOR

Dell Cazier  
Alburn D. Griffin

~~We~~ <sup>Wg</sup> ~~X~~ <sup>K</sup> Glen Hatch, HEREBY CERTIFY upon honor that, in

pursuance of special instructions bearing date of the 10th day of August, 1960.

~~We~~ <sup>Wg</sup> ~~X~~ <sup>K</sup> have ~~surveyed~~ <sup>independently resurveyed</sup> the Second Standard Parallel South through Range 27 East and the north boundary and subdivisional lines of Township 10 South, Range 27 East

of the G&SR Meridian, in the State of Arizona, which are represented in the foregoing field notes as having been executed by ~~me~~ <sup>us</sup> and under ~~my~~ <sup>our</sup> direction; and that said survey has been made in strict conformity with said instructions, the Manual of Instructions for the Survey of the Public Lands of the United States, and in the specific manner described in the foregoing field notes.

Feb. 21, 1961  
(Date)

Dell Cazier  
Dell Cazier, Cadastral Surveyor

Feb. 21, 1961  
(Date)

Alburn D. Griffin  
Alburn D. Griffin (Cadastral Surveyor) Surveying Aide

Feb. 21, 1961  
(Date)

Glen Hatch  
Glen Hatch (Cadastral Surveyor) Surveying Aide

CERTIFICATE OF APPROVAL

BUREAU OF LAND MANAGEMENT,

Washington, D. C., JUL 30 1963, 1963

The foregoing field notes of the ~~survey of~~ <sup>dependent resurvey of</sup> the Second Standard Parallel South through Range 27 East, and the north boundary and subdivisional lines of T. 10 S., R. 27 E., G&SR Meridian, Arizona,

executed by Dell Cazier, Cadastral Surveyor, and Alburn D. Griffin and Glen Hatch, Surveying Aides, having been critically examined and found correct, are hereby approved.

[Signature]  
(Cadastral Engineering Staff Officer)  
Chief, Division of Engineering

CERTIFICATE OF TRANSCRIPT

I CERTIFY that the foregoing transcript of the field notes of the above-described surveys in \_\_\_\_\_ is a true copy of the original field notes.

(Date)

(Cadastral Engineering Staff Officer)