

1

Form 4-679  
(January 1963)

BOOK 4751  
UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

FIELD NOTES

DEPENDENT RESURVEY

South and East Boundaries

and

Subdivisional Lines

Township 11 South, Range 27 East

Of the Gila and Salt River Meridian,

In the State of Arizona

EXECUTED BY

Leonard W. Murphy, Cadastral Surveyor

Under special instructions dated March 9, 19 64, which provided for the surveys  
included under Group Number 408, approved March 11, 1964,  
and assignment instructions dated October 22, 19 64.

Survey commenced October 27, 19 64

Survey completed December 17, 19 64

1A

# BOOK 4751 INDEX DIAGRAM

Township 11 South, Range 27 East,

<b>6</b> 40 40	<b>5</b> 31 40	<b>4</b> 26 31	<b>3</b> 20 25	<b>2</b> 14 20	<b>1</b> 5 14
<b>7</b> 39 38	<b>8</b> 30 38	<b>9</b> 25 30	<b>10</b> 19 24	<b>11</b> 13 19	<b>12</b> 4 13
<b>18</b> 37 36	<b>17</b> 29 36	<b>16</b> 24 29	<b>15</b> 18 23	<b>14</b> 12 18	<b>13</b> 4 12
<b>19</b> 35 35	<b>20</b> 28 34	<b>21</b> 23 28	<b>22</b> 17 22	<b>23</b> 11 17	<b>24</b> 3 11
<b>30</b> 34 33	<b>29</b> 27 33	<b>28</b> 22 27	<b>27</b> 16 21	<b>26</b> 10 15	<b>25</b> 2 10
<b>31</b> 32	<b>32</b> 26	<b>33</b> 21	<b>34</b> 15	<b>35</b> 9	<b>36</b> 2
9 8	8	7	6	6	5 1

BOOK 4751

Township 11 South, Range 27 East, G&SRM, Arizona

1.β

CHAINS

The west boundary of the township and a portion of the north boundary of section 6 were surveyed by T. F. White in 1875. The remainder of the north boundary was surveyed by T. F. White in 1882. The east and south boundaries were surveyed by L. Wolfley in 1884. The subdivisional lines were surveyed by J. C. Smith in 1885. The west boundary of the township and a portion of the north boundary of section 6 were dependently resurveyed by Kimmel and Campbell in 1917. The north boundary was dependently resurveyed by D. Cazier in 1960.

The following field notes are those of the dependent resurvey of the east and south boundaries and the subdivisional lines of Township 11 South, Range 27 East, Gila and Salt River Meridian, Arizona.

The survey was executed in accordance with the specifications as set forth in the Manual of Surveying Instructions, 1947, and the Special Instructions dated March 9, 1964.

An extensive retracement was necessary to identify positively the corners as only a very small percentage of the corners was found.

Only the true line bearings and horizontal distances for the surveyed lines are given in these notes. Unless described, each corner was monumented with a standard iron post 30 inches long, 2½ inches in diameter, flanged at the base, with a brass cap riveted to the top. The original corner monument is buried alongside the iron post unless otherwise described.

The geographic position of the southeast corner of the township as computed from U.S.C.&G.S., Triangulation Station ESCALA is: Latitude 32°25'37" N. and Longitude 109°32'06" W.

The average magnetic declination was found to be 13° East.

Dependent Resurvey, East Boundary, T11S, R27E, Arizona

Reestablishment of the Survey in 1884  
executed by L. Wolfley

The cor. of Tps. 11 and 12 S., Rs. 27 and 28 E., is determined by the original 4x4-inch redwood post, set in a mound of stone and dimly mkd.

At the corner point

Set the iron post 24 ins. in the ground, cap mkd.

T11S  
R27E R28E  
S36|S31  
S 1|S 6  
T12S  
1964

BOOK 4751

Dependent Resurvey, East Bdy., T. 11 S., R. 27 E., Arizona

2

2.

CHAINS	
	<p>N. 0°13' E., bet. secs. 31 and 36.</p>
	<p>Over nearly level land, through scattered undergrowth.</p>
15.10	<p>Dial Wash, 15 lks. wide, 5 ft. deep, drains E.</p>
39.90	<p>The ¼ sec. cor. of secs. 31 and 36, monumented by a redwood post 3 ft. long, 3 ins. sq., firmly set and mkd. ¼ on W. face, as described in the official record.</p>
	<p>At the corner point</p>
	<p>Set the iron post 24 ins. in the ground, cap mkd.</p>
	<p style="text-align: center;">T11S R27E R28E ¼ S36 S31 1964</p>
	<p>Destroy the original post. The corner falls on a gentle N. slope.</p>
	<hr/> <p>N. 0°11' W., beginning new measurement</p>
	<p>Over nearly level land, through scattered undergrowth.</p>
6.70	<p>Track road, bears N. 70° W. and S. 70° E.</p>
11.90	<p>Wash, 30 lks. wide, 2 ft. deep, drains S. 75° E.</p>
26.90	<p>Bladed road, bears N. 75° W. and S. 75° E.</p>
39.90	<p>The cor. of secs. 25, 30, 31 and 36, monumented by the remains of the original redwood post, 4 ins. sq., faintly mkd.</p>
	<p>At the corner point</p>
	<p>Set the iron post 24 ins. in the ground, cap mkd.</p>
	<p style="text-align: center;">T11S R27E R28E S25 S30 S36 S31 1964</p>
	<p>Land, nearly level. Soil, sandy. Timber, none; undergrowth, creosote brush and cacti.</p>
	<hr/> <p>N. 0°32' E., bet. secs. 25 and 30.</p>
	<p>Over level land, through sparse vegetation.</p>
39.93	<p>The ¼ sec. cor. of secs. 25 and 30, monumented by the remains of the original redwood post, firmly set and faintly mkd. ¼ on W. face.</p>
	<p>At the corner point</p>
	<p>Set the iron post 24 ins. in the ground, cap mkd.</p>

CHAINS	
	T11S R27E R28E $\frac{1}{4}$ S25 S30 1964
	<hr/> N. 0°14' W., beginning new measurement.  Over level land, through sparse vegetation.
21.30	Wash, 10 lks. wide, 1 ft. deep, drains E.
40.13	Point for the cor. of secs. 19, 24, 25 and 30, at proportionate distance; there is no remaining evidence of the original corner.  Set the iron post 24 ins. in the ground, cap mkd.
	T11S R27E R28E S24 S19 S25 S30 1964
	Land, level. Soil, sandy. Timber, none; undergrowth, creosote brush and cacti.
	<hr/> N. 0°14' W., bet. secs. 19 and 24.  Over level land, through sparse undergrowth.
33.30	Wash, 15 lks. wide, 1 ft. deep, drains SE.
40.12	The $\frac{1}{4}$ sec. cor. of secs. 19 and 24, monumented by a redwood post, firmly set and mkd. with $\frac{1}{4}$ on W. face.  At the corner point  Set the iron post 24 ins. in the ground, cap mkd.
	T11S R27E R28E $\frac{1}{4}$ S24 S19 1964
	Destroy the original corner post.
	<hr/> N. 0°03' E., beginning new measurement.  Over level land, through sparse undergrowth.
16.40	Wash, 10 lks. wide, 2 ft. deep, drains S. 80° E.
35.50	Wash, 10 lks. wide, 1 ft. deep, drains E.
40.03	The cor. of secs. 13, 18, 19 and 24, monumented by the remains of the original redwood post, firmly set in small mound of stone, mks. no longer visible.  At the corner point

BOOK 4751

Dependent Resurvey, East Bdy., T. 11 S., R. 27 E., Arizona

4

4.

CHAINS		
	<p>Set the iron post 24 ins. in the ground, cap mkd.</p> <p style="text-align: center;">T11S R27E R28E <u>S13 S18</u> <u>S24 S19</u> 1964</p> <p>Land, level. Soil, sandy. Timber, none; undergrowth, creosote brush and cacti.</p>	
	<p>N. 0°14' W., bet. secs. 13 and 18.</p> <p>Over level land, through sparse undergrowth.</p>	
15.90	<p>Small wash, drains N. 50° E.</p>	
39.91	<p>Point for the <math>\frac{1}{4}</math> cor. of secs. 13 and 18, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 24 ins. in the ground, cap mkd.</p> <p style="text-align: center;">T11S R27E R28E <math>\frac{1}{4}</math> S13 S18 1964</p>	
63.00	<p>Wash, 20 lks. wide, 2 ft. deep, drains N. 70° E.</p>	
64.70	<p>Fence, bears N. 42<math>\frac{1}{2}</math>° W., and S. 42<math>\frac{1}{2}</math>° E.</p>	
77.80	<p>Wash, 20 lks. wide, 1 ft. deep, drains NE.</p>	
79.82	<p>Point for the cor. of secs. 7, 12, 13 and 18, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 24 ins. in the ground, cap mkd.</p> <p style="text-align: center;">T11S R27E R28E <u>S12 S 7</u> <u>S13 S18</u> 1964</p> <p>Land, level. Soil, sandy. Timber, none; undergrowth, creosote brush and cacti.</p>	
	<p>N. 0°14' W., bet. secs. 7 and 12.</p> <p>Over level land, through sparse undergrowth.</p>	
39.91	<p>Point for the <math>\frac{1}{4}</math> sec. cor. of secs. 7 and 12, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 24 ins. in the ground, cap mkd.</p> <p style="text-align: center;">T11S R27E R28E <math>\frac{1}{4}</math> S12 S 7 1964</p>	

BOOK 4751

Dependent Resurvey East Bdy., T. 11 S., R. 27 E., Arizona

CHAINS	
48.40	Small wash, drains N. 70° E.
79.82	Point for the cor. of secs. 1, 6, 7 and 12, at proportionate distance; there is no remaining evidence of the original corner.
	Set the post 24 ins. in the ground, cap mkd.
	<p style="text-align: center;">T11S R27E R28E S 1   S 6 S12   S 7 1964</p>
	Land, level. Soil, sandy. Timber, none; undergrowth, creosote brush and cacti.
	N. 0°14' W., bet. secs. 1 and 6.
	Over level land, through sparse undergrowth.
39.91	Point for the ¼ sec. cor. of secs. 1 and 6, at proportionate distance; there is no remaining evidence of the original corner.
	Set the iron post 24 ins. in the ground, cap mkd.
	<p style="text-align: center;">T11S R27E R28E ¼ S 1   S 6 1964</p>
49.70	Barbed wire fence, bears N. 54° E. and S. 54° W.
73.95	The closing corner of secs. 1 and 6 on the N. bdy. of the Tp., an iron post, 2½ ins. diam., firmly set and properly mkd. as described in the official record.
	Land, level. Soil, sandy. Timber, none; undergrowth, creosote brush and cacti.
	Dependent Resurvey, South Bdy., T11S, R27E, Arizona
	Reestablishment of the Survey in 1884 executed by L. Wolfley
	From the cor. of Tps. 11 and 12 S., Rs. 27 and 28 E.
	S. 89°34' W., bet. secs. 1 and 36.
	Over nearly level land, through sparse undergrowth.
22.20	Small wash, drains NE.
40.11	Point for the ¼ sec. cor. of secs. 1 and 36, at proportionate distance; there is no remaining evidence of the original corner.
	Set the iron post 24 ins. in the ground, cap mkd.
	<p style="text-align: center;">T11S R27E ¼ S36 S 1 T12S 1964</p>

BOOK 4751

Dependent Resurvey, South Bdy., T. 11 S., R. 27 E., Arizona

6

6.

CHAINS		
	<p>Raise a mound of stone, 2 ft. base, 2 ft. high, W. of the corner.</p>	
52.60	<p>Small wash, drains NE.</p>	
80.22	<p>Point for the cor. of secs. 1, 2, 35 and 36, at proportionate distance; there is no remaining evidence of the original corner.</p>	
	<p>Set the iron post 22 ins. in the ground, cap mkd.</p>	
	<p style="text-align: center;">                     T11S R27E  <u>S35   S36</u>                      S 2   S 1                      T12S                      1964                 </p>	
	<p>Land, nearly level. Soil, sandy. Timber, none; undergrowth, creosote brush and cacti.</p>	
	<p>S. 89°34' W., bet. secs. 2 and 35.</p>	
	<p>Over nearly level land, through sparse undergrowth.</p>	
18.07	<p>Dial Wash, 100 lks. wide, 2 ft. deep, drains N. 70° E.</p>	
40.11	<p>Point for the <math>\frac{1}{4}</math> sec. cor. of secs. 2 and 35, at proportionate distance; there is no remaining evidence of the original corner.</p>	
	<p>Set the iron post 24 ins. in the ground, cap mkd.</p>	
	<p style="text-align: center;">                     T11S R27E  <math>\frac{1}{4}</math> <u>S35</u>                      S 2                      T12S                      1964                 </p>	
	<p>Raise a mound of stone, 4 ft. base, 3 ft. high, W. of the corner. A mound of stone N. would fall in a small wash, draining N. 70° E.</p>	
80.22	<p>Point for the cor. of secs. 2, 3, 34 and 35, at proportionate distance; there is no remaining evidence of the original corner.</p>	
	<p>Set the iron post 24 ins. in the ground, cap mkd.</p>	
	<p style="text-align: center;">                     T11S R27E  <u>S34   S35</u>                      S 3   S 2                      T12S                      1964                 </p>	
	<p>Land, nearly level. Soil, sandy. Timber, none; undergrowth, creosote brush and cacti.</p>	
	<p>S. 89°34' W ., bet. secs. 3 and 34.</p>	
	<p>Over nearly level land, through sparse undergrowth.</p>	



BOOK 4751

Dependent Resurvey, South Bdy., T. 11 S., R. 27 E., Arizona

7.

CHAINS

- 40.11 Point for the  $\frac{1}{4}$  sec. cor. of secs. 3 and 34, at proportionate distance; there is no remaining evidence of the original corner.
- Set the iron post 15 ins. in the ground to hardpan, and in a mound of stone, 4 ft. base to top, cap mkd.
- T11S R27E  
 $\frac{1}{4} \frac{S34}{S 3}$   
 T12S  
 1964
- 46.55 Small wash, drains N. 30° E.
- 80.22 The cor. of secs. 3, 4, 33 and 34, monumented by the remains of the original redwood post, firmly set in a small mound of stone, some notches clearly visible.
- At the corner point
- Set the iron post 18 ins. in the ground to bedrock in a collar of stone, cap mkd.
- T11S R27E  
 $\frac{S33}{S 4} | \frac{S34}{S 3}$   
 T12S  
 1964
- Raise a mound of stone, 3 ft. base, 2 ft. high, W. of the corner.
- Land, nearly level.  
 Soil, sandy gravel.  
 Timber, none; undergrowth, creosote brush and cacti.
- 
- S. 89°44' W., bet. secs. 4 and 33.
- Over nearly level land, through sparse undergrowth.
- 40.12 Point for the  $\frac{1}{4}$  sec. cor. of secs. 4 and 33, at proportionate distance; there is no remaining evidence of the original corner.
- Set the iron post 24 ins. in the ground, cap mkd.
- T11S R27E  
 $\frac{1}{4} \frac{S33}{S 4}$   
 T12S  
 1964
- 62.42 Small wash, drains N. 20° E.
- 80.24 Point for the cor. of secs. 4, 5, 32 and 33, at proportionate distance; there is no remaining evidence of the original corner.
- Set the iron post 24 ins. in the ground, cap mkd.
- T11S R27E  
 $\frac{S32}{S 5} | \frac{S33}{S 4}$   
 T12S  
 1964

BOOK 4751

Dependent Resurvey, South Bdy., T. 11 S., R. 27 E., Arizona

8.

8

CHAINS

Land, nearly level.  
Soil, sandy gravel.  
Timber, none; undergrowth, creosote brush and cacti.

S. 89°44' W., bet. secs. 5 and 32.

Over nearly level land, through sparse undergrowth.

40.12 Point for the  $\frac{1}{4}$  sec. cor. of secs. 5 and 32, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 24 ins. in the ground, cap mkd.

T11S R27E

$\frac{1}{4}$   $\frac{S32}{S 5}$

T12S

1964

80.24 The cor. of secs. 5, 6, 31 and 32, determined by remains of wooden post set in an old mound of stone, mks. faintly visible.

At the corner point

Set the iron post 20 ins. in the ground in a small rock collar, cap mkd.

T11S R27E

$\frac{S31}{S 6}$  |  $\frac{S32}{S 5}$

T12S

1964

Raise a mound of stone, 4 ft. base, 3 ft. high, W. of the corner.

Land, nearly level.  
Soil, sandy gravel.  
Timber, none; undergrowth, creosote brush and cacti.

S. 89°45' W., bet. secs. 6 and 31.

Over nearly level land, through sparse undergrowth.

37.40 Barbed wire fence, bears N. and S., thence along the N. side of a barbed wire fence extending W.

39.87 Point for the  $\frac{1}{4}$  sec. cor. of secs. 6 and 31, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 24 ins. in the ground, cap mkd.

T11S R27E

$\frac{1}{4}$   $\frac{S31}{S 6}$

T12S

1964

Raise a mound of stone, 3 ft. base, 2 ft. high, W. of the corner.

BOOK 4751

Dependent Resurvey, South Bdy., T. 11 S., R. 27 E., Arizona

CHAINS	
	Corner falls 4 lks. N. of fence bearing E. and W.
58.70	Wash, 60 lks. wide, 1 ft. deep, drains S. 20° E.
68.60	Dial Wash, 100 lks. wide, 8 ins. deep, drains SE.
76.88	The cor. of secs. 1, 6, 31 and 36, Ts. 11 and 12 S., Rs. 26 and 27 E., monumented by an iron post, 3 ins. diam., firmly set and properly mkd. as described in the official record.
	Land, nearly level. Soil, sandy gravel. Timber, none; undergrowth, creosote brush and cacti.
<hr/> Dependent Resurvey of the Subdivisional Lines Township 11 South, Range 27 East, Arizona	
<hr/> Reestablishment of the Survey in 1885 executed by J. C. Smith	
<hr/> From the cor. of secs. 1, 2, 35 and 36 on the S. bdy. of the township.	
N. 0°25' E., bet. secs. 35 and 36.	
Over nearly level land, through sparse undergrowth.	
18.20	Dial Wash, 80 lks. wide, 1 ft. deep, drains N. 65° E.
40.19	Point for the ¼ sec. cor. of secs. 35 and 36, at proportionate distance; there is no remaining evidence of the original corner.
Set the iron post 24 ins. in the ground, cap mkd.	
T11S R27E $\frac{1}{4}$ S35 S36 1964	
44.96	Wash, 100 lks. wide, 2 ft. deep, drains N. 80° E.
80.38	The cor. of secs. 25, 26, 35 and 36, monumented by the original granite stone, 16x12x8 ins., firmly set in large mound of stone and properly mkd. by one notch on S. and E. edges.
At the corner point	
Set the iron post 24 ins. in the ground, cap mkd.	
T11S R27E $\frac{1}{4}$ S26 S25 S35 S36 1964	
Bury the original corner alongside the iron post and raise a mound of stone, 3 ft. base, 2 ft. high, W. of the corner.	

BOOK 4751

Dependent Resurvey of the Subdivisional Lines  
Township 11 South, Range 27 East, Arizona

10

CHAINS		
	<p>Land, nearly level. Soil, sandy gravel. Timber, none; undergrowth, creosote brush, catclaw and cacti.</p>	
	<p>From the cor. of secs. 25, 30, 31 and 36 on the E. bdy. of the township.</p>	
	<p>N. 89°58' W., bet. secs. 25 and 36.</p>	
	<p>Over nearly level land, through sparse undergrowth.</p>	
39.80	<p>Point for the <math>\frac{1}{4}</math> sec. cor. of secs. 25 and 36, at proportionate distance; there is no remaining evidence of the original corner.</p>	
	<p>Set the iron post 24 ins. in the ground, cap mkd.</p>	
	<p style="text-align: center;">T11S R27E <math>\frac{1}{4}</math> <math>\frac{S25}{S36}</math> 1964</p>	
	<p>from which</p>	
	<p style="text-align: center;">The U.S. Geological Survey Triangulation Station ESCALA bears S. 6°22' W., 6.59 chs. distant. This is a standard disk set in concrete projecting about 5 inches above the ground and is 44 feet S. of the center of a road.</p>	
47.29	<p>Bladed road, bears N. 60° W. and S. 60° E.</p>	
79.61	<p>The cor. of secs. 25, 26, 35 and 36.</p>	
	<p>Land, nearly level. Soil, sandy gravel. Timber, none; undergrowth, creosote brush and cacti.</p>	
	<p>N. 0°19' W., bet. secs. 25 and 26.</p>	
	<p>Over nearly level land, through sparse undergrowth.</p>	
9.05	<p>Bladed road, bears S. 85° E. and S. 85° W.</p>	
39.90	<p>Point for the <math>\frac{1}{4}</math> sec. cor. of secs. 25 and 26, at proportionate distance; there is no remaining evidence of the original corner.</p>	
	<p>Set the iron post 20 ins. in the ground, cap mkd.</p>	
	<p style="text-align: center;">T11S R27E <math>\frac{1}{4}</math> S26 S25 1964</p>	
55.51	<p>Wash, 30 lks. wide, 1 ft. deep, drains N. 70° E.</p>	
79.80	<p>Point for the cor. of secs. 23, 24, 25 and 26 at proportionate distance; there is no remaining evidence of the original corner.</p>	
	<p>Set the iron post 20 ins. in the ground, cap mkd.</p>	

CHAINS	
	<p style="text-align: center;">T11S R27E  <math>\frac{S23}{S26}   \frac{S24}{S25}</math>                      1964</p>
	<p>Land, nearly level.                      Soil, sandy gravel.                      Timber, none; undergrowth, creosote brush, catclaw,                      mesquite and cacti.</p>
	<p>From the cor. of secs. 19, 24, 25 and 30, on the E. bdy.                      of the township.</p> <p>S. 89°50' W., bet. secs. 24 and 25.</p> <p>Over nearly level land, through sparse undergrowth.</p>
13.20	<p>Wash, 30 lks. wide, 1 ft. deep, drains NE.</p>
40.12	<p>Point for the <math>\frac{1}{4}</math> sec. cor. of secs. 24 and 25, at pro-                      portionate distance; there is no remaining evidence of                      the original corner.</p> <p>Set the iron post 22 ins. in the ground, cap mkd.</p>
	<p style="text-align: center;">T11S R27E  <math>\frac{1}{4} \frac{S24}{S25}</math>                      1964</p>
80.24	<p>The cor. of secs. 23, 24, 25 and 26.</p> <p>Land, nearly level.                      Soil, sandy gravel.                      Timber, none; undergrowth, creosote brush and cacti.</p>
	<p>N. 0°06' W., bet. secs. 23 and 24.</p> <p>Over nearly level land, through sparse undergrowth.</p>
25.46	<p>Wash, 50 lks. wide, 4 ft. deep, drains N. 70° E.</p>
29.46	<p>Wash, 50 lks. wide, 4 ft. deep, drains N. 80° E.</p>
39.90	<p>Point for the <math>\frac{1}{4}</math> sec. cor. of secs. 23 and 24, at pro-                      portionate distance; there is no remaining evidence of                      the original corner.</p> <p>Set the iron post 22 ins. in the ground, cap mkd.</p>
	<p style="text-align: center;">T11S R27E  <math>\frac{1}{4} \frac{S23}{S24}</math>                      1964</p>
	<p>Raise a small mound of stone W. of the corner.</p>
79.80	<p>Point for the cor. of secs. 13, 14, 23 and 24 at pro-                      portionate distance; there is no remaining evidence of                      the original corner.</p> <p>Set the iron post 22 ins. in the ground, cap mkd.</p>

BOOK 4751

Dependent Resurvey of the Subdivisional Lines  
Township 11 South, Range 27 East, Arizona

12.

12

CHAINS	
	<p style="text-align: center;">T11S R27E  <math>\frac{S14}{S23}   \frac{S13}{S24}</math>                      1964</p> <p>Land, nearly level. Soil, sandy gravel. Timber, none; undergrowth, creosote brush, mesquite, catclaw and cacti.</p>
	<p>From the cor. of secs. 13, 18, 19 and 24 on the E. bdy. of the township.</p> <p>S. 89°39' W., bet. secs. 13 and 24.</p> <p>Over nearly level land, through sparse undergrowth.</p>
10.10	Wash, 25 lks. wide, 1 ft. deep, drains S.
40.13	<p>Point for the <math>\frac{1}{4}</math> sec. cor. of secs. 13 and 24 at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 18 ins. in the ground to bedrock, with a small rock collar to top, cap mkd.</p>
	<p style="text-align: center;">T11S R27E  <math>\frac{1}{4} \frac{S13}{S24}</math>                      1964</p>
80.27	<p>The cor. of secs. 13, 14, 23 and 24.</p> <p>Land, nearly level. Soil, sandy gravel. Timber, none; undergrowth, creosote brush and cacti.</p>
	<p>N. 0°04' W., bet. secs. 13 and 14.</p> <p>Over nearly level land, through sparse undergrowth.</p>
39.90	<p>Point for the <math>\frac{1}{4}</math> sec. cor. of secs. 13 and 14, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 20 ins. in the ground, cap mkd.</p>
	<p style="text-align: center;">T11S R27E  <math>\frac{1}{4}</math>  <math>S14   S13</math>                      1964</p>
43.14	Wash, 40 lks. wide, 1 ft. deep, drains N. 60° E.
60.14	Wash, 50 lks. wide, 2 ft. deep, drains irregularly SE.
78.54	Wash, 30 lks. wide, 2 $\frac{1}{2}$ ft. deep, drains N. 80° E.
79.80	<p>Point for the cor. of secs. 11, 12, 13 and 14 at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 24 ins. in the ground, cap mkd.</p>

CHAINS	
	<p style="text-align: center;">T11S R27E  <math>\frac{S11}{S14}   \frac{S12}{S13}</math>                      1964</p> <p>Raise a small mound of stone W. of the corner.</p> <p>Land, nearly level. Soil, sandy gravel. Timber, none; undergrowth, creosote brush and cacti.</p> <hr/> <p>From the cor. of secs. 7, 12, 13 and 18 on the E. bdy. of the township.</p> <p>S. 89°40' W., bet. secs. 12 and 13.</p> <p>Over nearly level land, through sparse undergrowth.</p>
12.80	Mesh and barbed wire fence, bears N. 35° W. and S. 35° E.
28.30	Wash, 3 chs. wide, 1 ft. deep, drains NE.
40.01	Point for the $\frac{1}{2}$ sec. cor. of secs. 12 and 13, at proportionate distance; there is no remaining evidence of the original corner.
	Set the iron post 24 ins. in the ground, cap mkd.
	<p style="text-align: center;">T11S R27E  <math>\frac{1}{2} \frac{S12}{S13}</math>                      1964</p>
80.02	The cor. of secs. 11, 12, 13 and 14.
	<p>Land, nearly level. Soil, sandy gravel. Timber, none; undergrowth, creosote brush and cacti.</p> <hr/> <p>N. 0°04' W., bet. secs. 11 and 12.</p> <p>Over nearly level land, through sparse undergrowth.</p>
3.10	Wash, 30 lks. wide, 2 ft. deep, drains N. 80° E.
25.80	Wash, 40 lks. wide, 1 ft. deep, drains N. 40° E.
39.90	Point for the $\frac{1}{2}$ sec. cor. of secs. 11 and 12 at proportionate distance; there is no remaining evidence of the original corner.
	Set the iron post 20 ins. in the ground, cap mkd.
	<p style="text-align: center;">T11S R27E  <math>\frac{1}{2} \frac{S11}{S12}</math>                      1964</p>
67.90	Wash, 30 lks. wide, 1 ft. deep, drains S. 80° E.
73.50	Mesh and barbed wire fence, bears E. and W.
79.80	Point for the cor. of secs. 1, 2, 11 and 12 at proportionate distance; there is no remaining evidence of the original corner.

BOOK 4751

Dependent Resurvey of the Subdivisional Lines  
Township 11 South, Range 27 East, Arizona

14

14.

CHAINS	
	Set the iron post 20 ins. in the ground, cap mkd.
	<p style="text-align: center;">T11S R27E  <math>\frac{S\ 2}{S11}   \frac{S\ 1}{S12}</math>                      1964</p>
	<p>Land, nearly level.                      Soil, sandy gravel.                      Timber, none; undergrowth, creosote brush and cacti.</p>
	From the cor. of secs. 1, 6, 7 and 12 on the E. bdy. of the township.
	S. 89°37' W., bet. secs. 1 and 12.
	Over nearly level land, through sparse undergrowth.
39.90	Point for the $\frac{1}{4}$ sec. cor. of secs. 1 and 12, at proportionate distance; there is no remaining evidence of the original corner.
	Set the iron post 20 ins. in the ground, cap mkd.
	<p style="text-align: center;">T11S R27E  <math>\frac{1}{4} \frac{S\ 1}{S12}</math>                      1964</p>
41.20	Barbed wire fence, bears N. and S.
46.80	Wash, 30 lks. wide, 1 ft. deep, drains irregularly N.
79.81	The cor. of secs. 1, 2, 11 and 12.
	<p>Land, nearly level.                      Soil, sandy gravel.                      Timber, none; undergrowth, creosote brush, catclaw and cacti.</p>
	N. 0°43' W., bet. secs. 1 and 2.
	Over nearly level land, through sparse undergrowth.
36.00	Wash, 50 lks. wide, 1 ft. deep, drains N. 60° E.
39.90	Point for the $\frac{1}{4}$ sec. cor. of secs. 1 and 2, at proportionate distance; there is no remaining evidence of the original corner.
	Set the iron post 20 ins. in the ground, cap mkd.
	<p style="text-align: center;">T11S R27E  <math>\frac{1}{4} \frac{S\ 2}{S11}   \frac{S\ 1}{S12}</math>                      1964</p>
42.90	Wash, 30 lks. wide, 2 ft. deep, drains N. 55° E.
74.77	The closing corner of secs. 1 and 2 on the N. bdy. of the Tp., monumented by an iron post $2\frac{1}{2}$ ins. diam., firmly set and properly mkd. as described in the official record.



CHAINS	
	<p>Land, nearly level. Soil, sandy gravel. Timber, none; undergrowth, creosote brush, catclaw and cacti.</p> <hr/> <p>From the cor. of secs. 2, 3, 34 and 35 on the S. bdy. of the township.</p> <p>N. 0°10' W., bet. secs. 34 and 35.</p> <p>Over nearly level land, through sparse undergrowth.</p>
19.50	Wash, 30 lks. wide, 2 ft. deep, drains N. 85° E.
40.38	<p>Point for the ¼ sec. cor. of secs. 34 and 35, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 24 ins. in the ground, cap mkd.</p> <p style="text-align: center;">T11S R27E ¼ S34 S35 1964</p>
	<p>Raise a mound of stone, 2 ft. base, 2 ft. high, W. of the corner.</p>
47.80	Wash, 40 lks. wide, 2 ft. deep, drains E.
62.80	Wash, 100 lks. wide, 1 ft. deep, drains SE.
80.76	<p>The cor. of secs. 26, 27, 34 and 35, determined by the remains of a mound of earth, from which the original redwood stake, 2 ft. long, 2 ins. sq., firmly set, bears S. 45° E., 5½ ft. distant.</p> <p>At the corner point</p> <p>Set the iron post 22 ins. in the ground, cap mkd.</p> <p style="text-align: center;">T11S R27E S27 S26 S34 S35 1964</p>
	<p>Bury the original stake alongside the iron post.</p> <p>Land, nearly level. Soil, sandy gravel. Timber, none; undergrowth, scrub mesquite, creosote brush and cacti.</p> <hr/> <p>From the cor. of secs. 25, 26, 35 and 36.</p> <p>S. 89°54' W., bet. secs. 26 and 35.</p> <p>Over nearly level land, through sparse undergrowth.</p>
8.50	Wash, 20 lks. wide, 1 ft. deep, drains NE.
17.40	Wash, 20 lks. wide, 1 ft. deep, drains NE.

BOOK 4751

Dependent Resurvey of the Subdivisional Lines  
Township 11 South, Range 27 East, Arizona

CHAINS		
40.50	<p>Point for the <math>\frac{1}{4}</math> sec. cor. of secs. 26 and 35, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 24 ins. in the ground, cap mkd.</p> <p style="text-align: center;">T11S R27E <math>\frac{1}{4}</math> <math>\frac{S26}{S35}</math> 1964</p> <p>Raise a mound of stone, 3 ft. base, 2 ft. high, N. of the corner.</p>	
81.00	<p>The cor. of secs. 26, 27, 34 and 35.</p> <p>Land, nearly level. Soil, rocky. Timber, none; undergrowth, creosote brush and cacti.</p> <hr/> <p>N. 0°04' E., bet. secs. 26 and 27.</p> <p>Over nearly level land, through sparse undergrowth.</p>	
.80	<p>Bladed road, bears N. 80° E. and S. 80° W.</p>	
29.90	<p>Wash, 15 lks. wide, 1 ft. deep, drains N. 75° E.</p>	
39.95	<p>Point for the <math>\frac{1}{4}</math> sec. cor. of secs. 26 and 27, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 24 ins. in the ground, cap mkd.</p> <p style="text-align: center;">T11S R27E <math>\frac{1}{4}</math> <math>\frac{S27}{S26}</math> 1964</p>	
55.40	<p>Wash, 20 lks. wide, 1 ft. deep, drains NE.</p>	
70.60	<p>Wash, 15 lks. wide, 1 ft. deep, drains N. 80° E.</p>	
79.90	<p>The cor. of secs. 22, 23, 26 and 27, determined by the remains of a mound of earth, from which the original redwood stake, 2 ft. long, 2 ins. sq., loosely set and mkd. with 2 notches on S. and E. edges, bears S. 45° E., 5<math>\frac{1}{2}</math> ft. distant.</p> <p>At the corner point</p> <p>Set the iron post 22 ins. in the ground, cap mkd.</p> <p style="text-align: center;">T11S R27E <math>\frac{S22}{S27}</math> <math>\frac{S23}{S26}</math> 1964</p> <p>Bury the original stake alongside the iron post.</p> <p>Land, nearly level. Soil, sandy. Timber, none; undergrowth, creosote brush and cacti.</p> <hr/>	

BOOK 4751  
 Dependent Resurvey of the Subdivisional Lines  
 Township 11 South, Range 27 East, Arizona

CHAINS	
	<p>From the cor. of secs. 23, 24, 25 and 26.</p> <p>S. 89°58' W., bet. secs. 23 and 26.</p> <p>Over nearly level land, through sparse undergrowth.</p>
33.94	Wash, 25 lks. wide, 1 ft. deep, drains NE.
40.26	<p>Point for the <math>\frac{1}{4}</math> sec. cor. of secs. 23 and 26, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 20 ins. in the ground, cap mkd.</p> <div style="text-align: center;"> <p>T11S R27E</p> <p><math>\frac{1}{4}</math> <math>\frac{S23}{S26}</math></p> <p>1964</p> </div>
80.52	<p>The cor. of secs. 22, 23, 26 and 27.</p> <p>Land, nearly level.          Soil, sandy gravel.          Timber, none; undergrowth, creosote brush, mesquite and cacti.</p> <hr/> <p>N. 0°04' E., bet. secs. 22 and 23.</p> <p>Over nearly level land, through sparse undergrowth.</p>
3.80	Wash, 150 lks. wide, 4 ft. deep, drains E.
28.90	Wash, 30 lks. wide, 1 ft. deep, drains N. 75° E.
37.00	Wash, 50 lks. wide, 1 ft. deep, drains E.
39.95	<p>Point for the <math>\frac{1}{4}</math> sec. cor. of secs. 22 and 23, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 24 ins. in the ground, cap mkd.</p> <div style="text-align: center;"> <p>T11S R27E</p> <p><math>\frac{1}{4}</math></p> <p>S22   S23</p> <p>1964</p> </div>
61.00	Wash, 50 lks. wide, 1 ft. deep, drains NE.
75.80	Wash, 100 lks. wide, 1 ft. deep, drains N. 80° E.
79.90	<p>The cor. of secs. 14, 15, 22 and 23, determined by the remains of a mound of earth, from which the original redwood stake, 2 ft. long, 2 ins. sq., loosely set and properly mkd. with 3 notches on S. and 2 notches on E. edges, bears S. 45° E., <math>5\frac{1}{2}</math> ft. distant.</p> <p>At the corner point</p> <p>Set the iron post 22 ins. in the ground, cap mkd.</p> <div style="text-align: center;"> <p>T11S R27E</p> <p>S15   S14</p> <p>S22   S23</p> <p>1964</p> </div>

BOOK 4751

Dependent Resurvey of the Subdivisional Lines  
Township 11 South, Range 27 East, Arizona

18

CHAINS		
40.08	<p>Bury the original redwood stake alongside the iron post.</p> <p>Land, nearly level. Soil, sandy. Timber, none; undergrowth, creosote brush and cacti.</p> <hr/> <p>From the cor. of secs. 13, 14, 23 and 24.</p> <p>West, bet. secs. 14 and 23.</p> <p>Over nearly level land, through sparse undergrowth.</p> <p>Point for the <math>\frac{1}{4}</math> sec. cor. of secs. 14 and 23, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the post 20 ins. in the ground, cap mkd.</p> <p style="text-align: center;">T11S R27E <math>\frac{1}{4}</math> <math>\frac{S14}{S23}</math> 1964</p>	
80.17	<p>The cor. of secs. 14, 15, 22 and 23.</p> <p>Land, nearly level. Soil, sandy gravel. Timber, none; undergrowth, creosote brush, mesquite and cacti.</p> <hr/> <p>N. <math>0^{\circ}04'</math> E., bet. secs. 14 and 15.</p> <p>Over nearly level land, through sparse undergrowth.</p>	
40.15	<p>Point for the <math>\frac{1}{4}</math> sec. cor. of secs. 14 and 15, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 24 ins. in the ground, cap mkd.</p> <p style="text-align: center;">T11S R27E <math>\frac{1}{4}</math> S15 S14 1914</p>	
56.50	<p>Wash, 50 lks. wide, 4 ft. deep, drains NE.</p>	
72.70	<p>Wash, 30 lks. wide, 2 ft. deep, drains SE.</p>	
80.30	<p>The cor. of secs. 10, 11, 14 and 15, determined by the remains of a mound of earth, from which the original redwood stake, 2 ft. long, 2 ins. sq., firmly set, bears S. <math>45^{\circ}</math> E., <math>5\frac{1}{2}</math> ft. distant. The markings are faintly visible.</p> <p>At the corner point</p> <p>Set the iron post 22 ins. in the ground, cap mkd.</p> <p style="text-align: center;">T11S R27E S10 S11 S15 S14 1964</p>	

CHAINS	
	<p>Bury the original redwood stake alongside the iron post.</p> <p>Land, nearly level. Soil, sandy gravel. Timber, none; undergrowth, creosote brush and cacti.</p>
39.97	<p>From the cor. of 11, 12, 13 and 14.</p> <p>N. 89°44' W., bet. secs. 11 and 14.</p> <p>Over nearly level land, through sparse undergrowth.</p> <p>Point for the <math>\frac{1}{4}</math> sec. cor. of secs. 11 and 14, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 20 ins. in the ground, cap mkd.</p> <p style="text-align: center;">T11S R27E <math>\frac{1}{4}</math> <math>\frac{S11}{S14}</math> 1964</p>
45.20	<p>Wash, 25 lks. wide, 1 ft. deep, drains NE. toward Gold Gulch Wash.</p>
79.94	<p>The cor. of secs. 10, 11, 14 and 15.</p> <p>Land, nearly level. Soil, sandy gravel. Timber, none; undergrowth, creosote brush and cacti.</p>
16.70	<p>N. 0°02' W., bet. secs. 10 and 11.</p> <p>Over nearly level land, through sparse undergrowth.</p>
40.35	<p>Wash, 20 lks. wide, 1 ft. deep, drains E.</p> <p>Point for the <math>\frac{1}{4}</math> sec. cor. of secs. 10 and 11 at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 20 ins. in the ground, cap mkd.</p> <p style="text-align: center;">T11S R27E <math>\frac{1}{4}</math> S 10   S 11 1964</p>
74.20	<p>Barbed wire fence, bears E. and W.</p>
80.70	<p>Point for the corner of secs. 2, 3, 10 and 11, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 20 ins. in the ground, cap mkd.</p> <p style="text-align: center;">T11S R27E <math>\frac{S 3   S 2}{S 10   S 11}</math> 1964</p>

BOOK 4751

Dependent Resurvey of the Subdivisional Lines  
Township 11 South, Range 27 East, Arizona

20

20.

CHAINS		
	<p>Land, nearly level. Soil, sandy gravel. Timber, none; undergrowth, creosote brush and cacti.</p>	
	<p>From the cor. of secs. 1, 2, 11 and 12. N. 89°06' W., bet. secs. 2 and 11. Over nearly level land, through sparse undergrowth.</p>	
39.93	<p>Point for the <math>\frac{1}{4}</math> sec. cor. of secs. 2 and 11, at proportionate distance; there is no remaining evidence of the original corner. Set the iron post 20 ins. in the ground, cap mkd.</p> <p style="text-align: center;">T11S R27E <math>\frac{1}{4}</math> <math>\frac{S 2}{S 11}</math> 1964</p>	
69.60	<p>Barbed wire fence, bears N. and S.</p>	
79.87	<p>The cor. of secs. 2, 3, 10 and 11. Land, nearly level. Soil, sandy gravel. Timber, none; undergrowth, creosote brush, mesquite and cacti.</p>	
	<p>N. 0°16' E., bet. secs. 2 and 3. Over nearly level land, through sparse undergrowth.</p>	
7.70	<p>Wash, 20 lks. wide, 1 ft. deep, drains N. 80° E.</p>	
40.35	<p>The <math>\frac{1}{4}</math> sec. cor. of secs. 2 and 3, determined by the remains of a mound of earth, from which the original redwood stake, 2 ft. long, 2 ins. sq., firmly set, mkd. <math>\frac{1}{4}</math> on W. face, bears North <math>5\frac{1}{2}</math> ft. distant. At the corner point Set the iron post 22 ins. in the ground, cap mkd.</p> <p style="text-align: center;">T11S R27E <math>\frac{1}{4}</math> S 3   S 2 1964</p>	
	<p>Bury the original stake alongside the iron post.</p> <hr style="width: 20%; margin: auto;"/> <p>N. 2°18' W., beginning new measurement. Over nearly level land, through sparse undergrowth.</p>	
33.38	<p>The closing corner of secs. 2 and 3, on the N. bdy. of the Tp., monumented by an iron post <math>2\frac{1}{2}</math> ins. diam., firmly set and properly mkd. as described in the official record.</p>	

CHAINS	
	<p>Land, nearly level. Soil, sandy gravel. Timber, none; undergrowth, creosote brush and cacti.</p>
	<p>From the cor. of secs. 3, 4, 33 and 34, on the S. bdy. of the township.</p>
	<p>N. 0°13' W., bet. secs. 33 and 34.</p>
	<p>Over nearly level land, through sparse undergrowth.</p>
20.80	<p>Wash, 30 lks. wide, 1 ft. deep, drains E.</p>
40.10	<p>Point for the <math>\frac{1}{4}</math> sec. cor. of secs. 33 and 34, at proportionate distance; there is no remaining evidence of the original corner.</p>
	<p>Set the iron post 24 ins. in the ground, cap mkd.</p>
	<p style="text-align: center;">T11S R27E <math>\frac{1}{4}</math> S33 S34 1964</p>
58.70	<p>Right bank of wash, bears E. and W.</p>
62.80	<p>Left bank of wash, bears E. and W., wash drains E.</p>
80.21	<p>Point for the cor. of secs. 27, 28, 33 and 34 at proportionate distance; there is no remaining evidence of the original corner.</p>
	<p>Set the iron post 24 ins. in the ground, cap mkd.</p>
	<p style="text-align: center;">T11S R27E <u>S28</u> <u>S27</u> S33 S34 1964</p>
	<p>Corner falls on S. edge of bladed road bearing generally E. and W.</p>
	<p>Land, nearly level. Soil, sandy gravel. Timber, none; undergrowth, creosote brush and cacti.</p>
	<p>From the cor. of secs. 26, 27, 34 and 35.</p>
	<p>S. 89°12' W., bet. secs. 27 and 34.</p>
	<p>Over nearly level land, through sparse undergrowth.</p>
16.00	<p>Bladed road, bears N. 85° E. and irregularly W.</p>
40.17	<p>Point for the <math>\frac{1}{4}</math> sec. cor. of secs. 27 and 34, at proportionate distance; there is no remaining evidence of the original corner.</p>
	<p>Set the post 24 ins. in the ground, cap mkd.</p>
	<p style="text-align: center;">T11S R27E <math>\frac{1}{4}</math> <u>S27</u> S34 1964</p>

BOOK 4751

Dependent Resurvey of the Subdivisional Lines  
Township 11 South, Range 27 East, Arizona

22

22.

CHAINS	
47.90	Same bladed road, bears E. and S. 85° W.
80.34	<p>The cor. of secs. 27, 28, 33 and 34.</p> <p>Land, nearly level. Soil, sandy gravel. Timber, none; undergrowth, creosote brush and cacti.</p>
	<p>N. 0°02' E., bet. secs. 27 and 28.</p>
	<p>Over nearly level land, through sparse undergrowth.</p>
.11	<p>Bladed road, bears E. and W.</p>
40.10	<p>Point for the ¼ sec. cor. of secs. 27 and 28, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 20 ins. in the ground, cap mkd.</p>
	<p style="text-align: center;">T11S R27E ¼ S28 S27 1964</p>
48.90	<p>Wash, 50 lks. wide, 4 ft. deep, drains E.</p>
63.30	<p>Wash, 40 lks. wide, 2 ft. deep, drains SE.</p>
70.40	<p>Wash, 30 lks. wide, 2 ft. deep, drains SE.</p>
80.21	<p>Point for the cor. of secs. 21, 22, 27 and 28, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 20 ins. in the ground, cap mkd.</p> <p style="text-align: center;">T11S R27E S21 S22 S28 S27 1964</p>
	<p>Land, nearly level. Soil, sandy gravel. Timber, none; undergrowth, creosote brush, mesquite and cacti.</p>
	<p>From the cor. of secs. 22, 23, 26 and 27.</p>
	<p>S. 89°26' W., bet. secs. 22 and 27.</p>
	<p>Over nearly level land, through sparse undergrowth.</p>
13.70	<p>Wash, 220 lks. wide, 1 ft. deep, drains NE.</p>
22.85	<p>Track road, bears N. 10° W. and S. 10° E.</p>
40.23	<p>Point for the ¼ sec. cor. of secs. 22 and 27, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 22 ins. in the ground, cap mkd.</p>



BOOK 4751

Dependent Resurvey of the Subdivisional Lines  
Township 11 South, Range 27 East, Arizona

CHAINS	
80.46	<p style="text-align: center;">T11S R27E <math>\frac{1}{4}</math> <math>\frac{S22}{S27}</math> 1964</p> <p>The cor. of secs. 21, 22, 27 and 28.</p> <p>Land, nearly level. Soil, sandy gravel. Timber, none; undergrowth, creosote brush, catclaw and cacti.</p>
40.10	<p>N. 0°06' W., bet. secs. 21 and 22.</p> <p>Over nearly level land, through sparse undergrowth.</p> <p>Point for the <math>\frac{1}{4}</math> sec. cor. of secs. 21 and 22, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 20 ins. in the ground, cap mkd.</p> <p style="text-align: center;">T11S R27E <math>\frac{1}{4}</math> S21 S22 1964</p>
49.90	<p>Wash, 30 lks. wide, 2 ft. deep, drains SE.</p>
72.10	<p>Wash, 20 lks. wide, 1 ft. deep, drains E.</p>
80.21	<p>The cor. of secs. 15, 16, 21 and 22, determined by the remains of a mound of earth, from which the original redwood stake, 2 ft. long, 2 ins. sq., firmly set and mkd. with faint scribe mks., bears S. 45° E., 5<math>\frac{1}{2}</math> ft. distant.</p> <p>At the corner point</p> <p>Set the iron post 22 ins. in the ground, cap mkd.</p> <p style="text-align: center;">T11S R27E S16 S15 S21 S22 1964</p> <p>Bury the original stake alongside the iron post.</p> <p>Land, nearly level. Soil, sandy gravel. Timber, none; undergrowth, creosote brush and cacti.</p>
40.34	<p>From the cor. of secs. 14, 15, 22 and 23.</p> <p>S. 89°40' W., bet. secs. 15 and 22.</p> <p>Over nearly level land, through sparse undergrowth.</p> <p>Point for the <math>\frac{1}{4}</math> sec. cor. of secs. 15 and 22, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 20 ins. in the ground, cap mkd.</p>

BOOK 4751

Dependent Resurvey of the Subdivisional Lines  
Township 11 South, Range 27 East, Arizona

24

CHAINS		
	<p style="text-align: center;">T11S R27E <math>\frac{1}{4}</math> <math>\frac{S15}{S22}</math> 1964</p>	
41.00	Track road, bears N. 15° W. and S. 15° E.	
80.68	The cor. of secs. 15, 16, 21 and 22.	
	<p>Land, nearly level. Soil, sandy gravel. Timber, none; undergrowth, creosote brush and cacti.</p>	
	<p>N. 0°03' E., bet. secs. 15 and 16.</p>	
	<p>Over nearly level land, through sparse undergrowth.</p>	
25.10	Wash, 180 lks. wide, 2 ft. deep, drains N. 80° E.	
39.72	Point for the $\frac{1}{4}$ sec. cor. of secs. 15 and 16, at proportionate distance; there is no remaining evidence of the original corner.	
	<p>Set the iron post 20 ins. in the ground, cap mkd.</p>	
	<p style="text-align: center;">T11S R27E <math>\frac{1}{4}</math> S16 S15 1964</p>	
78.60	Wash, 40 lks. wide, 4 ft. deep, drains NE.	
79.44	Point for the cor. of secs. 9, 10, 15 and 16, at proportionate distance; there is no remaining evidence of the original corner.	
	<p>Set the iron post 16 ins. in the ground to bedrock, with a small rock collar to top, cap mkd.</p>	
	<p style="text-align: center;">T11S R27E S 9 S10 S16 S15 1964</p>	
	<p>Land, nearly level. Soil, rocky. Timber, none; undergrowth, creosote brush and cacti.</p>	
	<p>From the cor. of secs. 10, 11, 14 and 15.</p>	
	<p>S. 89°01' W., bet. secs. 10 and 15.</p>	
	<p>Over nearly level land, through sparse undergrowth.</p>	
40.36	Point for the $\frac{1}{4}$ sec. cor. of secs. 10 and 15, at proportionate distance; there is no remaining evidence of the original corner.	
	<p>Set the iron post 18 ins. in the ground, with a small rock collar to top, cap mkd.</p>	
	<p style="text-align: center;">T11S R27E <math>\frac{1}{4}</math> <math>\frac{S10}{S15}</math> 1964</p>	

CHAINS		
69.00	Track road, bears N. 15° W. and S. 15° E.	
78.70	Wash, 40 lks. wide, 2 ft. deep, drains NE.	
80.72	The cor. of secs. 9, 10, 15 and 16.	
	Land, nearly level. Soil, rocky. Timber, none; undergrowth, creosote brush and cacti.	
	N. 0°33' E., bet. secs. 9 and 10.	
	Over nearly level land, through sparse undergrowth.	
24.90	Wash, 20 lks. wide, 2 ft. deep, drains NE.	
39.72	Point for the ¼ sec. cor. of secs. 9 and 10, at proportionate distance; there is no remaining evidence of the original corner.	
	Set the iron post 22 ins. in the ground, cap mkd.	
	T11S R27E $\frac{1}{4}$ S 9   S10 1964	
77.90	Barbed wire fence, bears E. and W.	
79.44	Point for the cor. of secs. 3, 4, 9 and 10, at proportionate distance; there is no remaining evidence of the original corner.	
	Set the iron post 20 ins. in the ground, cap mkd.	
	T11S R27E $\frac{S 4   S 3}{S 9   S10}$ 1964	
	Land, nearly level. Soil, sandy gravel. Timber, none; undergrowth, creosote brush, catclaw and cacti.	
	From the cor. of secs. 2, 3, 10 and 11.	
	S. 88°06' W., bet. secs. 3 and 10.	
	Over nearly level land, through sparse undergrowth.	
40.01	Point for the ¼ sec. cor. of secs. 3 and 10, at proportionate distance; there is no remaining evidence of the original corner.	
	Set the iron post 14 ins. in the ground to hardpan, and in a mound of stone, 3 ft. base to top, cap mkd.	
	T11S R27E $\frac{1}{4} \frac{S 3}{S10}$ 1964	

BOOK 4751

Dependent Resurvey of the Subdivisional Lines  
Township 11 South, Range 27 East, Arizona

26

26.

CHAINS		
76.06	Dim track road, bears N. and S.	
80.02	The cor. of secs. 3, 4, 9 and 10.  Land, nearly level. Soil, sandy gravel. Timber, none; undergrowth, creosote brush and cacti.	
10.22	N. 0°59' W., bet. secs. 3 and 4.  Over nearly level land, through sparse undergrowth.	
12.92	Descend to valley, bears NE.	
19.22	Dim track road, bears N. 50° W. and S. 50° E.	
35.22	Willow Spring Wash, 30 lks. wide, 4 ft. deep, drains NE.; bottom of descent.	
39.73	Wash, 40 lks. wide, 3 ft. deep, drains SE.	
47.73	Point for the ¼ sec. cor. of secs. 3 and 4, at proportionate distance; there is no remaining evidence of the original corner.  Set the iron post 22 ins. in the ground, cap mkd.	
76.51	T11S R27E ¼ S 4   S 3 1964	
28.00	Leave valley, bears NE.; thence over level land.  The closing corner of secs. 3 and 4, an iron post, 2½ ins. diam., firmly set and properly mkd. as described in the official record.  Land, nearly level. Soil, sandy gravel. Timber, none; undergrowth, creosote brush and cacti.	
40.19	From the cor. of secs. 4, 5, 32 and 33 on the S. bdy. of the township.  N. 0°15' W., bet. secs. 32 and 33.  Over nearly level land, through sparse undergrowth.	
28.00	Wash, 20 lks. wide, 4 ft. deep, drains S. 80° E.	
40.19	Point for the ¼ sec. cor. of secs. 32 and 33, at proportionate distance; there is no remaining evidence of the original corner.  Set the iron post 22 ins. in the ground, cap mkd.	
	T11S R27E ¼ S32   S33 1964	

BOOK 4751

Dependent Resurvey of the Subdivisional Lines  
Township 11 South, Range 27 East, Arizona

CHAINS		
61.50	Wash, 30 lks. wide, 1 ft. deep, drains N. 80° E.	
73.30	Wash, 10 lks. wide, 2 ft. deep, drains E.	
80.38	The cor. of secs. 28, 29, 32 and 33, monumented by the original granite stone 12x7x7 ins., firmly set and mkd. with 1 notch on S. and 4 notches on E. edges.	
	At the corner point	
	Set the iron post 24 ins. in the ground, cap mkd.	
	<p>T11S R27E  <u>S29</u>   <u>S28</u>  <u>S32</u>   <u>S33</u>                      1964</p>	
	Bury the original stone alongside the iron post.	
	Land, nearly level. Soil, sandy gravel. Timber, none; undergrowth, creosote brush and cacti.	
	From the cor. of secs. 27, 28, 33 and 34.	
	S. 89°53' W., bet. secs. 28 and 33.	
	Over nearly level land, through sparse undergrowth.	
5.50	Bladed road, bears N. 87° W. and E.	
38.00	Wash, 10 lks. wide, 1 ft. deep, drains SE.	
40.13	Point for the ¼ sec. cor. of secs. 28 and 33, at proportionate distance; there is no remaining evidence of the original corner.	
	Set the iron post 24 ins. in the ground, cap mkd.	
	<p>T11S R27E                      ¼ <u>S28</u>  <u>S33</u>                      1964</p>	
52.72	Wash, 30 lks. wide, 2 ft. deep, drains SE.	
80.26	The cor. of secs. 28, 29, 32 and 33.	
	Land, nearly level. Soil, sandy gravel. Timber, none; undergrowth, creosote brush, catclaw and cacti.	
	N. 0°18' W., bet. secs. 28 and 29.	
	Over nearly level land, through sparse undergrowth.	
13.39	Wash, 50 lks. wide, 5 ft. deep, drains S. 75° E.	
23.09	Bladed road, bears N. 70° W. and S. 70° E.	
39.81	Point for the ¼ sec. cor. of secs. 28 and 29, at proportionate distance; there is no remaining evidence of the original corner.	

BOOK 4751

Dependent Resurvey of the Subdivisional Lines  
Township 11 South, Range 27 East, Arizona

28

28.

CHAINS		
	<p>Set the iron post 20 ins. in the ground, cap mkd.</p> <p style="text-align: center;">T11S R27E <math>\frac{1}{4}</math> S29 S28 1964</p> <p>Raise a small mound of stone W. of the corner.</p>	
67.19	Wash, 30 lks. wide, 2 ft. deep, drains N. 80° E.	
79.62	<p>Point for the cor. of secs. 20, 21, 28 and 29, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 20 ins. in the ground, cap mkd.</p> <p style="text-align: center;">T11S R27E S20 S21 S29 S28 1964</p> <p>Raise a small mound of stone W. of the corner.</p> <p>Land, nearly level. Soil, sandy gravel. Timber, none; undergrowth, creosote brush and cacti.</p>	
	<p>From the cor. of secs. 21, 22, 27 and 28.</p> <p>S. 89°29' W., bet. secs. 21 and 28.</p> <p>Over nearly level land, through sparse undergrowth.</p>	
40.36	<p>Point for the <math>\frac{1}{4}</math> sec. cor. of secs. 21 and 28, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 20 ins. in the ground, cap mkd.</p> <p style="text-align: center;">T11S R27E <math>\frac{1}{4}</math> <math>\frac{S21}{S28}</math> 1964</p>	
43.20	Wash, 30 lks. wide, 1 ft. deep, drains S.	
52.00	Wash, 30 lks. wide, 2 ft. deep, drains S. 80° E.	
80.72	<p>The cor. of secs. 20, 21, 28 and 29.</p> <p>Land, nearly level. Soil, sandy gravel. Timber, none; undergrowth, creosote brush and cacti.</p>	
	<p>N. 0°15' W., bet. secs. 20 and 21.</p> <p>Over nearly level land, through sparse undergrowth.</p>	
11.46	Wash, 40 lks. wide, 5 ft. deep, drains N. 80° E.	
39.81	Point for the $\frac{1}{4}$ sec. cor. of secs. 20 and 21, at proportionate distance; there is no remaining evidence of the original corner.	

BOOK 4751

Dependent Resurvey of the Subdivisional Lines  
Township 11 South, Range 27 East, Arizona

CHAINS	
	<p>Set the iron post 20 ins. in the ground, cap mkd.</p> <p style="text-align: center;">T11S R27E <math>\frac{1}{4}</math> S20 S21 1964</p> <p>Raise a small mound of stone W. of the corner.</p>
56.00	Wash, 30 lks. wide, 1 ft. deep, drains NE.
72.10	Wash, 10 lks. wide, 1 ft. deep, drains N. 80° E.
79.62	Point for the cor. of secs. 16, 17, 20 and 21, at proportionate distance; there is no remaining evidence of the original corner.
	<p>Set the iron post 24 ins. in the ground, cap mkd.</p> <p style="text-align: center;">T11S R27E S17 S16 S20 S21 1964</p> <p>Raise a small mound of stone W. of the corner.</p> <p>Land, nearly level. Soil, rocky. Timber, none; undergrowth, creosote brush, mesquite and cacti.</p>
	<p>From the cor. of secs. 15, 16, 21 and 22.</p> <p>S. 89°04' W., bet. secs. 16 and 21.</p> <p>Over nearly level land, through sparse undergrowth.</p>
36.50	Wash, 35 lks. wide, 1 ft. deep, drains NE.
40.42	Point for the $\frac{1}{4}$ sec. cor. of secs. 16 and 21, at proportionate distance; there is no remaining evidence of the original corner.
	<p>Set the iron post 20 ins. in the ground, cap mkd.</p> <p style="text-align: center;">T11S R27E <math>\frac{1}{4}</math> S16 S21 1964</p> <p>Raise a small mound of stone N. of the corner.</p>
80.84	<p>The cor. of secs. 16, 17, 20 and 21.</p> <p>Land, nearly level. Soil, sandy gravel. Timber, none; undergrowth, creosote brush and cacti.</p>
	<p>N. 0°13' E., bet. secs. 16 and 17.</p> <p>Over nearly level land, through sparse undergrowth.</p>
24.44	Wash, 50 lks. wide, 6 ft. deep, drains N. 80° E.
39.81	Point for the $\frac{1}{4}$ sec. cor. of secs. 16 and 17, at proportionate distance; there is no remaining evidence of the original corner.
	<p>Set the iron post 20 ins. in the ground, cap mkd.</p> <p style="text-align: center;">T11S R27E <math>\frac{1}{4}</math> S17 S16 1964</p>

BOOK 4751

Dependent Resurvey of the Subdivisional Lines  
Township 11 South, Range 27 East, Arizona

CHAINS	Raise a small mound of stone W. of the corner.
79.63	Point for the cor. of secs. 8, 9, 16 and 17, at proportionate distance; there is no remaining evidence of the original corner.
	Set the iron post 14 ins. in the ground to hardpan, and in a mound of stone, 3 ft. base to top, cap mkd.
	$\begin{array}{r} \text{T11S R27E} \\ \text{S } 8   \text{S } 9 \\ \hline \text{S17   S16} \\ 1964 \end{array}$
	Land, nearly level.
	Soil, rocky.
	Timber, none; undergrowth, creosote brush and cacti.
	<hr/>
	From the cor. of secs. 9, 10, 15 and 16.
	S. 89°13' W., bet. secs. 9 and 16.
	Over nearly level land, through sparse undergrowth.
40.30	Point for the $\frac{1}{4}$ sec. cor. of secs. 9 and 16, at proportionate distance; there is no remaining evidence of the original corner.
	Set the iron post 20 ins. in the ground, cap mkd.
	$\begin{array}{r} \text{T11S R27E} \\ \frac{1}{4} \text{ S } 9 \\ \hline \text{S16} \\ 1964 \end{array}$
	Raise a small mound of stone N. of the corner.
45.66	Wash, 60 lks. wide, 1 ft. deep, drains S.
80.60	The cor. of secs. 8, 9, 16 and 17.
	Land, nearly level.
	Soil, sandy gravel.
	Timber, none; undergrowth, creosote brush and cacti.
	<hr/>
	N. 0°49' E., bet. secs. 8 and 9.
	Over nearly level land, through sparse undergrowth.
28.00	Enter valley, bears N. 80° E. and S. 80° W.
37.20	Willow Spring Wash, 15 lks. wide, 1 ft. deep, drains NE.
39.81	Point for the $\frac{1}{4}$ sec. cor. of secs. 8 and 9 at proportionate distance; there is no remaining evidence of the original corner.
	Set the iron post 20 ins. in the ground and in a small rock collar, cap mkd.
	$\begin{array}{r} \text{T11S R27E} \\ \frac{1}{4} \\ \text{S } 8   \text{S } 9 \\ \hline 1964 \end{array}$
44.60	Wash, 50 lks. wide, 3 ft. deep, drains N. 75° E.
48.00	Leave valley, bears N. 55° E. and S. 55° W.; asc. gentle S. slope.
77.05	Barbed wire fence, bears E. and W.
79.63	Point for the cor. of secs. 4, 5, 8 and 9, at proportionate distance; there is no remaining evidence of the original corner.
	Set the iron post 20 ins. in the ground, cap mkd.
	$\begin{array}{r} \text{T11S R27E} \\ \text{S } 5   \text{S } 4 \\ \hline \text{S } 8   \text{S } 9 \\ 1964 \end{array}$



CHAINS		
	<p>Raise a small mound of stone W. of the corner.</p> <p>Land, nearly level. Soil, rocky. Timber, none; undergrowth, creosote brush, mesquite and cacti.</p>	
	<p>From the cor. of secs. 3, 4, 9 and 10.</p> <p>S. 89°19' W., bet. secs. 4 and 9.</p> <p>Over nearly level land, through sparse undergrowth.</p>	
7.50	Enter valley, bears NE. and SW.	
22.45	Willow Spring Wash, 60 lks. wide, 1 ft. deep, drains NE.	
40.05	Point for the ¼ sec. cor. of secs. 4 and 9, at proportionate distance; there is no remaining evidence of the original corner.	
	Set the iron post 20 ins. in the ground, cap mkd.	
	<p style="text-align: center;">T11S R27E ¼ <math>\frac{S\ 4}{S\ 9}</math> 1964</p>	
	Raise a small mound of stone N. of the corner.	
45.50	Leave valley, bears NE. and SW.	
47.30	Wash, 20 lks. wide, 1 ft. deep, drains SE.	
80.10	The cor. of secs. 4, 5, 8 and 9.	
	<p>Land, nearly level. Soil, rocky. Timber, none; undergrowth, creosote brush and cacti.</p>	
	<p>N. 0°57' W., bet. secs. 4 and 5.</p> <p>Over nearly level land, through sparse undergrowth.</p>	
37.90	Wash, 40 lks. wide, 4 ft. deep, drains E.	
39.82	Point for the ¼ sec. cor. of secs. 4 and 5, at proportionate distance; there is no remaining evidence of the original corner.	
	Set the iron post 20 ins. in the ground, cap mkd.	
	<p style="text-align: center;">T11S R27E ¼ S 5   S 4 1964</p>	
	Raise a small mound of stone W. of the corner.	
77.64	The closing corner of secs. 4 and 5, on the N. bdy. of the Tp., monumented by an iron post 2½ ins. diam., firmly set and properly mkd. as described in the official record.	

BOOK 4751

Dependent Resurvey of the Subdivisional Lines  
Township 11 South, Range 27 East, Arizona

CHAINS		
	<p>Land, nearly level. Soil, sandy gravel. Timber, none; undergrowth, creosote brush and cacti.</p> <hr/> <p>From the cor. of secs. 5, 6, 31 and 32 on the S. bdy. of the township.</p> <p>N. 0°16' W., bet. secs. 31 and 32.</p> <p>Over nearly level land, through sparse undergrowth.</p>	
12.10	Track road, bears N. 80° W. and SE.	
23.40	Track road, bears N. 75° W. and S. 75° E.	
29.90	Wash, 20 lks. wide, 1 ft. deep, drains S. 75° E.	
40.17	<p>The ¼ sec. cor. of secs. 31 and 32, monumented by the original limestone 14x7x3 ins., firmly set and mkd. ¼ on W. face.</p> <p>At the corner point</p> <p>Set the iron post 22 ins. in the ground, cap mkd.</p> <div style="text-align: center;"> <p>T11S R27E</p> <p>¼</p> <p>S31 S32</p> <p>1964</p> </div> <p>Bury the original stone alongside the iron post.</p> <p>Raise a small mound of stone W. of the corner.</p> <hr/> <p>N. 0°26' W., beginning new measurement.</p> <p>Over nearly level land, through sparse undergrowth.</p>	
16.10	Wash, 20 lks. wide, 2 ft. deep, drains N. 80° E.	
38.70	Wash, 40 lks. wide, 4 ft. deep, drains N. 80° E.	
40.22	<p>The cor. of secs. 29, 30, 31 and 32, monumented by the original granite stone 24x12x6 ins., firmly set and mkd. with 1 notch on S. and 5 notches on E. edges.</p> <p>At the corner point</p> <p>Set the iron post 22 ins. in the ground, cap mkd.</p> <div style="text-align: center;"> <p>T11S R27E</p> <p>S30 S29</p> <p>S31 S32</p> <p>1964</p> </div> <p>Bury the original stone alongside the iron post.</p> <p>Raise a small mound of stone W. of the corner.</p> <p>Land, nearly level. Soil, rocky. Timber, none; undergrowth, creosote brush and cacti.</p> <hr/>	

CHAINS		
	<p>From the cor. of secs. 28, 29, 32 and 33.</p>	
	<p>S. 89°44' W., bet. secs. 29 and 32.</p>	
	<p>Over nearly level land, through sparse undergrowth.</p>	
40.22	<p>Point for the <math>\frac{1}{4}</math> sec. cor. of secs. 29 and 32, at proportionate distance; there is no remaining evidence of the original corner.</p>	
	<p>Set the iron post 24 ins. in the ground, cap mkd.</p>	
	<p style="text-align: center;">T11S R27E</p>	
	<p style="text-align: center;"><math>\frac{1}{4}</math> <math>\frac{S29}{S32}</math></p>	
	<p style="text-align: center;">1964</p>	
70.10	<p>Wash, 80 lks. wide, 2 ft. deep, drains NE.</p>	
70.90	<p>Wash, 50 lks. wide, 2 ft. deep, drains N. 75° E.</p>	
80.44	<p>The cor. of secs. 29, 30, 31 and 32.</p>	
	<p>Land, nearly level.</p>	
	<p>Soil, sandy gravel.</p>	
	<p>Timber, none; undergrowth, creosote brush and cacti.</p>	
	<hr/>	
	<p>S. 88°55' W., bet. secs. 30 and 31.</p>	
	<p>Over nearly level land, through sparse undergrowth.</p>	
25.00	<p>Barbed wire fence, bears irregularly N. and S.</p>	
34.20	<p>Wash, 70 lks. wide, 2 ft. deep, drains S. 75° E.</p>	
39.18	<p>Point selected as the witness point for the <math>\frac{1}{4}</math> sec. cor. of secs. 30 and 31.</p>	
	<p>Set the iron post 22 ins. in the ground, cap mkd.</p>	
	<p style="text-align: center;">T11S R27E</p>	
	<p style="text-align: center;">WC <math>\frac{1}{4}</math> <math>\frac{S30}{S31}</math></p>	
	<p>Raise a mound of stone, 3 ft. base, 2 ft. high, N. of the corner.</p>	
39.58	<p>True point for the <math>\frac{1}{4}</math> sec. cor. of secs. 30 and 31, at proportionate distance; falls in a wash 70 lks. wide, 2 ft. deep, draining NE. There is no remaining evidence of the original corner.</p>	
51.34	<p>Track road, bears NW. and SE.</p>	
56.40	<p>Wash, 40 lks. wide, 4 ft. deep, drains SE.</p>	
76.31	<p>The cor. of secs. 30 and 31, on the W. bdy. of the Tp., monumented by an iron post 3 ins. diam., firmly set and properly mkd. as described in the official record.</p>	
	<p>Land, nearly level.</p>	
	<p>Soil, sandy gravel.</p>	
	<p>Timber, none; undergrowth, creosote brush and cacti.</p>	
	<hr/>	

BOOK 4751

Dependent Resurvey of the Subdivisional Lines  
Township 11 South, Range 27 East, Arizona

34

CHAINS	
	<p>From the cor. of secs. 29, 30, 31 and 32.</p>
	<p>N. 0°25' W., bet. secs. 29 and 30.</p>
	<p>Over nearly level land, through sparse undergrowth.</p>
18.80	<p>Wash, 20 lks. wide, 2 ft. deep, drains N. 60° E., approximately 7.60 chs. distant to a reservoir, 3 chs. diam.</p>
34.80	<p>Bladed road, bears E. and W.</p>
40.23	<p>The <math>\frac{1}{4}</math> sec. cor. of secs. 29 and 30, monumented by the original granite stone 14x8x6 ins., loosely set and mkd. <math>\frac{1}{4}</math> on W. face, as described in the official record.</p>
	<p>At the corner point</p>
	<p>Set the iron post 22 ins. in the ground, cap mkd.</p>
	<p style="text-align: center;">T11S R27E <math>\frac{1}{4}</math> S30 S29 1964</p>
	<p>from which</p>
	<p style="padding-left: 40px;">A reservoir bears S. 21° E., 19.20 chs. distant.</p>
	<p>Bury the original stone alongside the iron post.</p>
	<p>Raise a small mound of stone W. of the corner.</p>
	<hr style="width: 20%; margin: auto;"/> <p>N. 0°12' W., beginning new measurement.</p>
	<p>Over nearly level land, through sparse undergrowth.</p>
4.40	<p>Wash, 20 lks. wide, 2 ft. deep, drains N. 75° E.</p>
40.27	<p>The cor. of secs. 19, 20, 29 and 30, monumented by the original granite stone 14x6x6 ins., firmly set and mkd. with 2 notches on S. and 5 notches on E. edges.</p>
	<p>At the corner point</p>
	<p>Set the iron post 22 ins. in the ground, cap mkd.</p>
	<p style="text-align: center;">T11S R27E <u>S19 S20</u> S30 S29 1964</p>
	<p>Bury the original stone alongside the iron post.</p>
	<p>Land, nearly level.</p>
	<p>Soil, rocky.</p>
	<p>Timber, none; undergrowth, creosote brush, mesquite and cacti.</p>
	<hr style="width: 80%; margin: auto;"/> <p>From the cor. of secs. 20, 21, 28 and 29.</p>
	<p>N. 89°37' W., bet. secs. 20 and 29.</p>

BOOK 4751

Dependent Resurvey of the Subdivisional Lines  
Township 11 South, Range 27 East, Arizona

CHAINS	
	Over nearly level land, through sparse undergrowth.
16.78	Wash, 25 lks. wide, 1 ft. deep, drains irregularly S.
40.24	Point for the $\frac{1}{4}$ sec. cor. of secs. 20 and 29, at proportionate distance; there is no remaining evidence of the original corner.
	Set the iron post 20 ins. in the ground, cap mkd.
	<p style="text-align: center;">T11S R27E <math>\frac{1}{4}</math> <math>\frac{S20}{S29}</math> 1964</p>
	Raise a small mound of stone N. of the corner.
80.48	The cor. of secs. 19, 20, 29 and 30.
	Land, nearly level.
	Soil, rocky.
	Timber, none; undergrowth, creosote brush and cacti.
	S. 88°14' W., bet. secs. 19 and 30.
	Over nearly level land, through sparse undergrowth.
20.00	Mesh and barbed wire fence, bears N. and S.
39.26	Point for the $\frac{1}{4}$ sec. cor. of secs. 19 and 30, at proportionate distance; there is no remaining evidence of the original corner.
	Set the iron post 20 ins. in the ground, cap mkd.
	<p style="text-align: center;">T11S R27E <math>\frac{1}{4}</math> <math>\frac{S19}{S30}</math> 1964</p>
75.74	The cor. of secs. 19 and 30, on the W. bdy. of the Tp., monumented by an iron post 3 ins. diam., firmly set and properly mkd. as described in the official record.
	Land, nearly level.
	Soil, sandy gravel.
	Timber, none; undergrowth, creosote brush and cacti.
	From the cor. of secs. 19, 20, 29 and 30.
	N. 0°20' W., bet. secs. 19 and 20.
	Over nearly level land, through sparse undergrowth.
21.80	Wash, 40 lks. wide, 2 ft. deep, drains E.
35.10	Wash, 30 lks. wide, 2 ft. deep, drains S. 75° E.
40.21	Point for the $\frac{1}{4}$ sec. cor. of secs. 19 and 20, at proportionate distance; there is no remaining evidence of the original corner.

BOOK 4751

Dependent Resurvey of the Subdivisional Lines  
Township 11 South, Range 27 East, Arizona

36

36.

CHAINS		
	Set the iron post 22 ins. in the ground, cap mkd.	
	T11S R27E	
	$\frac{1}{4}$	
	S19 S20	
	1964	
54.31	Wash, 30 lks. wide, 2 ft. deep, drains N. 75° E.	
76.41	Wash, 20 lks. wide, 6 ft. deep, drains SE.	
80.42	The cor. of secs. 17, 18, 19 and 20, monumented by the original granite stone 10x8x8 ins., firmly set and mkd. with 3 notches on S. and 5 notches on E. edges.	
	At the corner point	
	Set the iron post 22 ins. in the ground, cap mkd.	
	T11S R27E	
	S18 S17	
	S19 S20	
	1964	
	Bury the original stone alongside the corner.	
	Raise a small mound of stone W. of the corner.	
	Land, nearly level.	
	Soil, rocky.	
	Timber, none; undergrowth, creosote brush and cacti.	
	From the cor. of secs. 16, 17, 20 and 21.	
	N. 89°04' W., bet. secs. 17 and 20.	
	Over nearly level land, through sparse undergrowth.	
40.30	Point for the $\frac{1}{4}$ sec. cor. of secs. 17 and 20, at proportionate distance; there is no remaining evidence of the original corner.	
	Set the iron post 16 ins. in the ground to hardpan, and in a mound of stone, 3 ft. base to top, cap mkd.	
	T11S R27E	
	$\frac{1}{4}$ $\frac{S17}{S20}$	
	1964	
60.72	Wash, 25 lks. wide, 1 ft. deep, drains NE.	
80.60	The cor. of secs. 17, 18, 19 and 20.	
	Land, nearly level.	
	Soil, rocky.	
	Timber, none; undergrowth, creosote brush and cacti.	
	S. 87°49' W., bet. secs. 18 and 19.	
	Over nearly level land, through sparse undergrowth.	

BOOK 4751

Dependent Resurvey of the Subdivisional Lines  
Township 11 South, Range 27 East, Arizona

37.

CHAINS		
15.40	Mesh and barbed wire fence, bears N. and S.	
39.03	Point for the $\frac{1}{4}$ sec. cor. of secs. 18 and 19, at proportionate distance; there is no remaining evidence of the original corner.  Set the iron post 20 ins. in the ground, cap mkd.	
	T11S R27E $\frac{1}{4}$ $\frac{S18}{S19}$ 1964	
	Raise a small mound of stone N. of the corner.	
75.18	The cor. of secs. 18 and 19, on the W. bdy. of the Tp., monumented by an iron post 3 ins. diam., firmly set and mkd. as described in the official record.  Land, nearly level. Soil, sandy gravel. Timber, none; undergrowth, creosote brush and cacti.	
	From the cor. of secs. 17, 18, 19 and 20.	
	N. $0^{\circ}09'$ E., bet. secs. 17 and 18.	
	Over nearly level land, through sparse undergrowth.	
36.50	Wash, 100 lks. wide, 1 ft. deep, drains E.	
40.43	The $\frac{1}{4}$ sec. cor. of secs. 17 and 18, monumented by the original granite stone 8x6x6 ins., firmly set and mkd. $\frac{1}{4}$ on W. face.  At the corner point  Set the iron post 22 ins. in the ground, cap mkd.	
	T11S R27E $\frac{1}{4}$ S18   S17 1964	
	Bury the original stone alongside the iron post.	
	N. $0^{\circ}11'$ W., beginning new measurement.	
	Over nearly level land, through sparse undergrowth.	
28.50	Enter valley, bears N. $75^{\circ}$ E. and S. $75^{\circ}$ W.	
31.80	Wash, 20 lks. wide, 1 ft. deep, drains NE.	
40.18	The cor. of secs. 7, 8, 17 and 18, monumented by a badly weathered granite stone 12x8x6 ins., loosely set in a mound of earth and stone, dimly mkd.  At the corner point  Set the iron post 22 ins. in the ground, cap mkd.	

BOOK 4751

Dependent Resurvey of the Subdivisional Lines  
Township 11 South, Range 27 East, Arizona

38

38.

CHAINS	
	<p style="text-align: center;">T11S R27E S 7   S 8 S18   S17 1964</p> <p>Bury the original stone alongside the iron post.</p> <p>Land, nearly level. Soil, sandy gravel. Timber, none; undergrowth, creosote brush and cacti.</p>
40.50	<hr/> <p>From the cor. of secs. 8, 9, 16 and 17.</p> <p>N. 88°23' W., bet. secs. 8 and 17.</p> <p>Over nearly level land, through sparse undergrowth.</p> <p>Point for the <math>\frac{1}{4}</math> sec. cor. of secs. 8 and 17, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 14 ins. in the ground to hardpan, and in a mound of stone, 3 ft. base to top, cap mkd.</p>
	<p style="text-align: center;">T11S R27E <math>\frac{1}{4}</math> <math>\frac{S 8}{S17}</math> 1964</p>
56.00	<p>Enter valley, bears NE. and SW.</p>
65.04	<p>Branch of Willow Spring Wash, 60 lks. wide, 1 ft. deep, drains NE.</p>
81.00	<p>The cor. of secs. 7, 8, 17 and 18.</p> <p>Land, nearly level. Soil, sandy gravel. Timber, none; undergrowth, creosote brush and cacti.</p>
	<hr/> <p>S. 86°56' W., bet. secs. 7 and 18.</p> <p>Over nearly level land, through sparse undergrowth.</p>
6.20	<p>Willow Spring Wash, 50 lks. wide, 1 ft. deep, drains NE.</p>
11.90	<p>Mesh and barbed wire fence, bears N. and S.</p>
26.50	<p>Leave valley, bears NE. and SW.</p>
38.96	<p>Point for the <math>\frac{1}{4}</math> sec. cor. of secs. 7 and 18, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 18 ins. in the ground, in a small rock collar, cap mkd.</p>
	<p style="text-align: center;">T11S R27E <math>\frac{1}{4}</math> <math>\frac{S 7}{S18}</math> 1964</p>
73.90	<p>Wash, 30 lks. wide, 1 ft. deep, drains NE.</p>



BOOK 4751

Dependent Resurvey of the Subdivisional Lines  
Township 11 South, Range 27 East, Arizona

CHAINS	
75.05	<p>The cor. of secs. 7 and 18, on the W. bdy. of the Tp., monumented by an iron post 3 ins. diam., firmly set and properly mkd. as described in the official record.</p> <p>Land, nearly level. Soil, rocky. Timber, none; undergrowth, creosote brush and cacti.</p> <hr/>
	<p>From the cor. of secs. 7, 8, 17 and 18.</p> <p>N. 0°03' W., bet. secs. 7 and 8.</p> <p>Over nearly level land, through sparse undergrowth.</p>
7.40	<p>Branch of Willow Spring Wash, 60 lks. wide, 2 ft. deep, drains N. 75° E.</p>
8.00	<p>Leave valley, bears N. 75° E. and S. 75° W.</p>
36.70	<p>Wash, 40 lks. wide, 1 ft. deep, drains E.</p>
40.00	<p>The <math>\frac{1}{4}</math> sec. cor. of secs. 7 and 8, monumented by the original granite stone 8x6x5 ins., firmly set and mkd. <math>\frac{1}{4}</math> on W. face.</p>
	<p>At the corner point</p> <p>Set the iron post 22 ins. in the ground, cap mkd.</p>
	<p style="text-align: center;">T11S R27E <math>\frac{1}{4}</math> S 7   S 8 1964</p>
	<p>Bury the original stone alongside the iron post.</p> <hr/>
	<p>N. 3°04' E., beginning new measurement.</p> <p>Over nearly level land, through sparse undergrowth.</p>
34.58	<p>Barbed wire fence, bears E. and W.</p>
38.74	<p>Point for the cor. of secs. 5, 6, 7 and 8, at proportionate distance; there is no remaining evidence of the original corner.</p>
	<p>Set the iron post 20 ins. in the ground, cap mkd.</p>
	<p style="text-align: center;">T11S R27E S 6   S 5 S 7   S 8 1964</p>
	<p>Raise a small mound of stone W. of the corner.</p> <p>Land, nearly level. Soil, sandy gravel. Timber, none; undergrowth, creosote brush and cacti.</p> <hr/>
	<p>From the cor. of secs. 4, 5, 8 and 9.</p> <p>N. 89°05' W., bet. secs. 5 and 8.</p>

BOOK 4751

Dependent Resurvey of the Subdivisional Lines  
Township 11 South, Range 27 East, Arizona

40

40.

CHAINS		
	Over nearly level land, through sparse undergrowth.	
40.04	<p>Point for the <math>\frac{1}{4}</math> sec. cor. of secs. 5 and 8, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 20 ins. in the ground, cap mkd.</p> <p style="text-align: center;">T11S R27E <math>\frac{1}{4} \frac{S 5}{S 8}</math> 1964</p> <p>Raise a small mound of stone N. of the corner.</p>	
80.08	<p>The cor. of secs. 5, 6, 7 and 8.</p> <p>Land, nearly level. Soil, sandy gravel. Timber, none; undergrowth, creosote brush and cacti.</p>	
	S. 87°40' W., bet. secs. 6 and 7.	
	Over nearly level land, through sparse undergrowth.	
9.50	Barbed wire fence, bears N. and S.	
40.01	<p>Point for the <math>\frac{1}{4}</math> sec. cor. of secs. 6 and 7, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 18 ins. in the ground in a small rock collar, cap mkd.</p> <p style="text-align: center;">T11S R27E <math>\frac{1}{4} \frac{S 6}{S 7}</math> 1964</p>	
76.94	<p>The cor. of secs. 6 and 7 on the W. bdy. of the Tp., monumented by an iron post 3 ins. diam., firmly set and properly mkd. as described in the official record.</p> <p>Land, nearly level. Soil, sandy gravel. Timber, none; undergrowth, creosote brush and cacti.</p>	
	From the cor. of secs. 5, 6, 7 and 8.	
	N. 1°02' W., bet. secs. 5 and 6.	
	Over nearly level land, through sparse undergrowth.	
38.69	<p>Point for the <math>\frac{1}{4}</math> sec. cor. of secs. 5 and 6, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set the iron post 20 ins. in the ground, cap mkd.</p> <p style="text-align: center;">T11S R27E <math>\frac{1}{4} \frac{S 6}{S 5}</math> 1964</p>	

BOOK 4751

Township 11 South, Range 27 East, G&SRM, Arizona

<p>CHAINS</p> <p>76.51</p>	<p>Raise a small mound of stone W. of the corner.</p> <p>The closing corner of secs. 5 and 6, on the N. bdy. of the Tp., monumented by an iron post 2½ ins. diam., firmly set and properly mkd. as described in the official record.</p> <p>Land, nearly level. Soil, sandy gravel. Timber, none; undergrowth, creosote brush and cacti.</p> <hr/> <p style="text-align: center;">General Description</p> <hr/> <p>The land within Township 11 South, Range 27 East, is level to gently rolling, varying from 3770 feet to 4227 feet above sea level. The soil varies from sandy and sandy gravel to rocky. There is no timber in the township.</p> <p>There are numerous washes within the township, including three major ones, of which two are in the south half and the other in the northwest quarter. The washes drain into San Simon Creek.</p> <p>Most of the township is privately owned, with the government land being in the north half of the township. There is one principal road in the township; it exits in Section 30, one and one-half miles east of U.S. Highway No. 666. The south boundary of the township is the approximate county line between Graham and Cochise counties. The southeast corner of the township is approximately 7 miles north and 3 miles west of Bowie, Arizona.</p> <p>There is no land under cultivation in the township; it is being used exclusively for grazing. There are two stockponds, one in Section 22 and the other in Section 29. There are no other man-made improvements, and there appears to be no mineral activity.</p>
----------------------------	---

47

BOOK 4751

Form 4-680  
(June 1963)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

FIELD ASSISTANTS

NAMES	CAPACITY
Donald W. Beauchamp	Cornerman
Charles J. Kriz	Chainman
Orrin V. Lee	Cornerman
Frank W. Rogers	Transitman
Loyal E. Steele	Flagman
Victor E. Templeton	Chainman

43

BOOK 4751

CERTIFICATE OF SURVEY

I, Leonard W. Murphy, HEREBY CERTIFY upon honor that, in pursuance of special instructions bearing date of the 9th day of March, 19 64, I have dependently resurveyed the south and east boundaries and the subdivisional lines of Township 11 South, Range 27 East,

of the Gila and Salt River Meridian, in the State of Arizona, which are represented in the foregoing field notes as having been executed by me and under my direction; and that said survey has been made in strict conformity with said special instructions, the Manual of Instructions for the Survey of the Public Lands of the United States, and in specific manner described in the foregoing field notes.

May 18, 1965  
(Date)

Leonard W. Murphy  
(Cadastral Surveyor)

(Date)

(Cadastral Surveyor)

CERTIFICATE OF APPROVAL

SUBMITTED FOR APPROVAL  
Date OCT 15 1965

BUREAU OF LAND MANAGEMENT,  
Washington, D. C.

The foregoing field notes of the dependent resurvey of the south and east boundaries and subdivisional lines of Township 11 South, Range 27 East, of the Gila and Salt River Meridian in the State of Arizona,

executed by Leonard W. Murphy, Cadastral Surveyor, having been critically examined and found correct, are hereby approved.

JAN 3 1966  
(Date)

E. L. Remington  
(Chief, Division of Engineering) NES

CERTIFICATE OF TRANSCRIPT

~~I CERTIFY That the foregoing transcript of the field notes of the above-described surveys in, is a true copy of the original field notes.~~

~~(Date)~~

~~(Chief, Division of Engineering)~~