

UNITED STATES
DEPARTMENT OF THE INTERIOR
~~GENERAL LAND OFFICE~~
BUREAU OF LAND MANAGEMENT

MINERAL SURVEY NO. 4397

Arizona Land District.

FIELD NOTES

Of The Survey Of The Mining Claim Of

Arnulfo Pena

Known As The

CINCAS VISTAS LODGE

Greaterville Mining District,

Pima County, Arizona

Sections 24 and 25, Township 19 South, Range 15 East, G. & S. R. Mer.

Surveyed under instructions dated April 15, 1955

by T. N. Stevens
Mineral Surveyor.

Claim located October 1, 1929


Survey commenced May 10, 1955

Survey completed May 12, 1955

Address of claimant Sydney Block, Attorney for Claimant
270 N. Church St., Tucson, Arizona

DATES OF AMENDED LOCATIONS

April 4, 1955



Survey No. 4397

This survey was made with a C.L. Berger & Son transit with horizontal limb $6\frac{1}{4}$ ins. diam., and vertical circle 5 ins. diam., each having two opposite verniers; the verniers read to one minute of arc.

The instrument was in good condition at the time of the survey and all adjustments were in good order.

All azimuths in this record were determined by the method of deflection angles referred to the meridian determined by the following observation.

Thursday, May 12, 1955 at corner No. 4 Cincas Vistas lode in latitude $31^{\circ} 45' 52''$ N., and longitude $110^{\circ} 45'$ W., I made a series of altitude observations upon the sun for azimuth at approximately equal time intervals. Three each with the telescope in direct and reversed positions, bisecting the sun and reading the horizontal angle from Cor. No. 1 clockwise to the sun.

Mean time of observation 105th meridian
standard time

2h 48m 30s P.M.

Declination of sun at mean time of
observation

$18^{\circ} 06' 38''$

Mean observed vertical angle to sun's center

$53^{\circ} 44' 23''$

Mean horizontal angle from reference point

$77^{\circ} 10' 30''$

True bearing of reference point

S. $0^{\circ} 14'$ E.

The lines were measured with a Keuffel & Esser steel tape 300 ft. in length, the first foot graduated to tenths and hundredths; and a 100 ft. Lufkin steel tape, graduated to feet, tenths and hundredths; both tapes were compared with a standard and were correct at the time of the survey.

All lines and connections of this survey were run by direct methods.

The magnetic declination observed at each corner of the survey gave a uniform value of $13^{\circ} 30'$ E.

Feet

CINCAS VISTAS LODGE

At Cor. No. 1 of the Cincas Vistas lode, identical with the Cor. of Secs. 24 and 25, on the east boundary of T. 19 S., R. 15 E.

Set an iron post, $3\frac{1}{2}$ ft. long, 2 ins. diam., 18 ins. in the ground alongside the section corner, surrounded by a mound of stone, with leaden cap mkd. 1 C V-4397; from which

An oak, 6 ins. diam., bears N. 83° W., 36.95 ft. dist.

An oak, 7 ins. diam., bears S. 27° W., 28.38 ft. dist., each mkd. C V 1-4397 BT in addition to the markings as described in the official record.

From this cor., the cor. of secs. 19 and 30, T. 19 S., R. 16 E., bears S. $0^{\circ} 14'$ E., 62.04 ft. dist.

Thence S. $89^{\circ} 46'$ W.,

300.0 Lode line; discovery point bears N. $0^{\circ} 14'$ W., 580.0 ft. dist.

Set an oak post, 3 ins. diam., firmly in the ground and surrounded by a mound of stone, mkd. S EC CV.

350.00 Wash, 1 ft. wide, course north.

Survey No. 4397

Feet	
	Thence N. 0° 14' W.
3.49	Intersect section line between Secs. 24 and 25 at a point from which the cor. of Secs. 24 and 25, on the east boundary of the township, bears S. 89° 54' E., 600.0 ft. dist.
330.00	Wash, 20 ft. wide, course easterly.
395.00	Road to Greaterville bears northeasterly and southwesterly.
1500.00	Cor. No. 3 <div style="text-align: center;">•</div> Set an iron post, 3½ ft. long, 2 ins. diam., 18 ins. in the ground, surrounded by a mound of stone to top, with leaded cap mkd. 3 C V-4397 No bearing objects are available.
	Thence N. 89° 46' E.,
300.00	Lode line; discovery point bears S. 0° 14' E., 920.0 ft. dist. Set a juniper post, 3 ft. long, 3 ins. diam., firmly set in the ground and surrounded by a mound of stone, mkd. N.E.C.CV.
342.00	Road bears northwesterly and southeasterly.
600.00	Cor. No. 4. Set an iron post, 3½ ft. long, 2 ins. diam., 18 ins. in the ground, surrounded by a mound of stone to top, with leaden cap mkd. 4 CV-4397. No bearing objects are available. From this cor., the ¼ sec. cor. of sec. 19, T. 19 S., R. 16 E., bears N. 0° 14' W., 1075.32 ft. dist.
	Thence S. 0° 14' E.,
213.00	Road bears southeasterly and northwesterly.
899.0	Road to Greaterville bears east and west.
1500.00	Cor. No. 1 and place of beginning.

AREA

	Acres
Total area Cincas Vistas lode - - - - -	-20.661

LOCATION

This survey is located in the SE¼ of Sec. 24, and the NE¼ of Sec. 25, T. 19 S., R. 15 E., G. & S.R.M., in the Coronado National Forest.

This survey is identical with the amended location as marked on the ground.

Section 1. 1917. 1917. 1917.

Section 2. 1917. 1917. 1917.

Section 3. 1917. 1917. 1917.

Section 4. 1917. 1917. 1917.

Section 5. 1917. 1917. 1917.

Section 6. 1917. 1917. 1917.

Section 7. 1917. 1917. 1917.

Section 8. 1917. 1917. 1917.

Section 9. 1917. 1917. 1917.

Section 10. 1917. 1917. 1917.

Section 11. 1917. 1917. 1917.

Section 12. 1917. 1917. 1917.

Section 13. 1917. 1917. 1917.

Section 14. 1917. 1917. 1917.

Section 15. 1917. 1917. 1917.

Section 16. 1917. 1917. 1917.

Section 17. 1917. 1917. 1917.

Section 18. 1917. 1917. 1917.

Section 19. 1917. 1917. 1917.

Section 20. 1917. 1917. 1917.

Section 21. 1917. 1917. 1917.

Section 22. 1917. 1917. 1917.

Section 23. 1917. 1917. 1917.

Section 24. 1917. 1917. 1917.

Section 25. 1917. 1917. 1917.

Section 26. 1917. 1917. 1917.

Section 27. 1917. 1917. 1917.

Section 28. 1917. 1917. 1917.

Section 29. 1917. 1917. 1917.

Section 30. 1917. 1917. 1917.

Section 31. 1917. 1917. 1917.

Section 32. 1917. 1917. 1917.

Section 33. 1917. 1917. 1917.

Survey No. 4397

EXPENDITURES

The improvements and the value of the labor and improvements made upon or for the benefit of the lode location embraced in said mining claim by the claimant or his grantors are as follows:

- No. 1 The discovery shaft of the Cincas Vistas lode, the SW. cor. of which is on the lode line 580 ft. from the center of line 1-2, 12 x 20 ft., 8 ft. deep.
Value \$800.
- No. 2 A shaft, the center of which bears N. 29° 18' E., 660 ft. from Cor. No. 2 Cincas Vistas lode, 6 x 6 ft., 6 ft. deep.
Value \$100.
- No. 3 A cut, the mouth of which bears N. 52° 26' E., 728 ft. from Cor. No. 2 Cincas Vistas lode, 5 ft. wide, 10 ft. face, running South 10 ft. to face.
Value \$100.
- No. 4 A cut, the mouth of which bears N. 45° 36' E., 738 ft. from Cor. No. 2 Cincas Vistas lode, 6 ft. wide, 3 ft. face, running North 20 ft. to face.
Value \$50.
- No. 5 A shaft, the center of which bears N. 35° 46' E., 630 ft. from Cor. No. 2 Cincas Vistas lode, 6 x 6 ft., 7 ft. deep.
Value \$100.
- No. 6 A cut, the mouth of which bears N. 35° 16' E., 590 ft. from Cor. No. 2 Cincas Vistas lode, 4 ft. wide, 10 ft. face, running S. 45° W., 10 ft. to face; at the face is a tunnel 4 x 5 ft. in size, running South 25 ft. to breast.
Value cut and tunnel \$350.
- No. 7 An L shaped trench, the SW. corner of which bears N. 31° 26' E., 488 ft. from Cor. No. 2 Cincas Vistas lode, 6 ft. wide, 3 ft. deep, running East 15 ft. to SE. cor. of trench; thence North 15 ft. to the NE. cor.
Value \$50.
- No. 8 A shaft, the center of which bears N. 22° 18' E., 310 ft. from Cor. No. 2 Cincas Vistas lode, 7 x 7 ft., 5 ft. deep (caved).
Value \$60.
- No. 9 A cut, the mouth of which bears N. 19° 46' E., 410 ft. from Cor. No. 2 Cincas Vistas lode, 5 ft. wide, 4 ft. face, running N. 15° W., 10 ft. to face.
Value \$50.
- No. 10 A cut, the mouth of which bears N. 16° 46' E., 392 ft. from Cor. No. 2 Cincas Vistas lode, 5 ft. wide, 4 ft. face, running N. 15° W., 12 ft. to face.
Value \$50.
- No. 11 A cut, the mouth of which bears N. 14° 01' E., 382 ft. from Cor. No. 2 Cincas Vistas lode, 5 ft. wide, 4 ft. face, running N. 15° W., 10 ft. to face.
Value \$50.

checkbox. The alignment of the structure was as follows:

- No. 1. The discovery shaft of the Cinnos Vistas hole, the SW cor. of which is on the face line 250 ft. from the center of line 1-2, 12 x 20 ft. Value \$100.
- No. 2. A shaft, the center of which bears N. 37° E. 100 ft. from Cor. No. 1. Cinnos Vistas hole, 5 ft. wide, 2 ft. deep. Value \$100.
- No. 3. A cut, the mouth of which bears N. 37° E. 100 ft. from Cor. No. 1. Cinnos Vistas hole, 5 ft. wide, 10 ft. deep, running down 10 ft. to face. Value \$100.
- No. 4. A cut, the mouth of which bears N. 37° E. 100 ft. from Cor. No. 1. Cinnos Vistas hole, 5 ft. wide, 5 ft. deep, running down 20 ft. to face. Value \$100.
- No. 5. A shaft, the center of which bears N. 37° E. 100 ft. from Cor. No. 1. Cinnos Vistas hole, 5 x 6 ft., 7 ft. deep. Value \$100.
- No. 6. A cut, the mouth of which bears N. 37° E. 100 ft. from Cor. No. 1. Cinnos Vistas hole, 5 ft. wide, 10 ft. deep, running 2 ft. W. 10 ft. to face; the face is a tunnel 4 x 5 ft. in size, running south 2 ft. to breast. Value cut and tunnel \$300.
- No. 7. A shaft, the SW corner of which bears N. 37° E. 100 ft. from Cor. No. 1. Cinnos Vistas hole, 5 ft. wide, 3 ft. deep, running east 12 ft. to SE cor. of trench; thence down 1 ft. to the SE cor. Value \$100.
- No. 8. A shaft, the center of which bears N. 37° E. 100 ft. from Cor. No. 1. Cinnos Vistas hole, 7 x 7 ft., 2 ft. deep (covered). Value \$100.
- No. 9. A cut, the mouth of which bears N. 37° E. 100 ft. from Cor. No. 1. Cinnos Vistas hole, 5 ft. wide, 1 ft. deep, running N. 37° W. 10 ft. to face. Value \$50.
- No. 10. A cut, the mouth of which bears N. 37° E. 100 ft. from Cor. No. 1. Cinnos Vistas hole, 5 ft. wide, 1 ft. deep, running N. 37° W. 12 ft. to face. Value \$50.
- No. 11. A cut, the mouth of which bears N. 37° E. 100 ft. from Cor. No. 1. Cinnos Vistas hole, 5 ft. wide, 1 ft. deep, running N. 37° W. 12 ft. to face. Value \$50.
- No. 12. A cut, the mouth of which bears N. 37° E. 100 ft. from Cor. No. 1. Cinnos Vistas hole, 5 ft. wide, 1 ft. deep, running N. 37° W. 12 ft. to face. Value \$50.

Survey No. 4397

- No. 13 A shaft, the center of which bears N. $14^{\circ} 01'$ E., 363 ft., from Cor. No. 2 Cincas Vistas lode, 4 x 6 ft., about 40 ft. deep with concrete collar (inaccessible on account of water).
Value \$500.
- No. 14 A trench, the SE. cor. of which bears N. $24^{\circ} 51'$ E., 670 ft. from Cor. No. 2 Cincas Vistas lode, 7 ft. wide, 4 ft. deep, running N. 45° E., 15 ft.
Value \$200.
- No. 15 A shaft, the center of which bears N. $23^{\circ} 43'$ E., 678 ft. from Cor. No. 2 Cincas Vistas lode, 7 x 7 ft., 3 ft. deep (caved).
Value \$50.
- No. 16 A shaft, the center of which bears N. $26^{\circ} 11'$ E., 530 ft. from Cor. No. 2, Cincas Vistas lode, 6 x 10 ft., 3 ft. deep.
Value \$50.
- No. 17 A shaft, the center of which bears/ N. $4^{\circ} 36'$ E., 278 ft. from Cor. No. 2 Cincas Vistas lode, 4 x 6 ft., 3 ft. deep.
Value \$40.

OTHER IMPROVEMENTS

None

OTHER CORNER DESCRIPTIONS

The corner of Secs. 24 and 25, T. 19 S., R. 15 E., is monumented with an iron post, 2 ins. diam., showing 10 ins. above ground, marked and witnessed as described in the official record.

Field Assistants

Name	Capacity
E. H. Jenkins	Chainman
J. J. Walden	Chainman

No. 14. A small, thin center of which bears a...
 No. 15. A small, thin center of which bears a...
 No. 16. A small, thin center of which bears a...
 No. 17. A small, thin center of which bears a...

OF THE PROCEEDINGS

Name

OF THE GENERAL INVESTIGATION

The other... and... is...
 with an... showing...
 worked and witnessed as described in the... record.

Field Assistant

Name

Special
 Chairman
 Chairman

Chairman
 Chairman

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

CERTIFICATE OF SURVEYOR

June 1, 1955

I, T.N. Stevens,
Mineral Surveyor, hereby certify upon honor that in pursuance of an order received from the
Office Cadastral Engineer, at Phoenix, Arizona
dated April 15, 1955, I have faithfully and correctly executed the survey of
the mining claim of Arnulfo Pena
known as the Cincas Vistas Lode
(Lode, placer, or mill site)
situate in Sections 24 and 25 Greaterville Mining District, Pima County, Ariz,
T. 19 S., R. 15 E., G. & S.R.M. Meridian, Arizona, and
(State)
designated as Survey No. 4397, which is represented in the foregoing field notes as having been
executed by me and under my direction, and that said survey has been made in strict conformity with said order,
the Manual of Instructions for the Survey of the Public Lands of the United States, and in the specific manner
described in the foregoing field notes, and I do further certify that the labor expended and improvements made
upon or for the benefit of the lode
(Lode or placer) location(s) embraced in the said mining claim by
claimant(s) or his grantors are fully stated in my report therein, and that the character,
extent, location, and itemized value thereof are specified therein with particularity and full detail, and that no
portion of, or interest in, said labor and improvements so credited to this claim has been included in the estimate
of expenditures upon any other claim.

Tucson, Arizona
(Place)

T.N. Stevens
(Mineral Surveyor)

CERTIFICATE OF APPROVAL

Survey Office
(Office)
Phoenix, Arizona August 3, 19 55
(Place) (Date)

The foregoing field notes of mineral survey No. 4397, in
Sections 24 and 25, T. 19 S., R. 15 E., G. & S.R.B. and Meridian,
Arizona, executed by T. N. Stevens, Mineral Surveyor,
(State)
under order dated April 15, 1955, having been critically examined and the necessary
corrections made prior to their certification by the surveyor, the field notes and the survey therein described
are hereby approved.

Everett H. Kimmell
Everett H. Kimmell

Office Cadastral Engineer
(Title)

April 10, 1922

Dear Sir:

Enclosed please find

the report of the

committee on the

subject of the proposed

amendment to the

constitution of the

association, which

was adopted by the

annual meeting of

CERTIFICATE OF APPROVAL

James W. [Name]

Secretary

The foregoing is a true and correct copy of the

report of the committee on the

subject of the proposed

amendment to the

constitution of the

association, which

was adopted by the

annual meeting of

the association, held

CERTIFICATE OF TRANSMISSION

I hereby certify that the foregoing is a true and correct copy of the

report of the committee on the subject of the proposed

amendment to the constitution of the association,

which was adopted by the annual meeting of the association,

UNITED STATES DEPARTMENT OF THE INTERIOR 9605 (956)
BUREAU OF LAND MANAGEMENT M.S. 4397
ARIZONA STATE OFFICE

NOTICE OF CANCELLATION OF MINERAL SURVEY

The CINCAS VISTAS lode, Mineral Survey No. 4397, located in sections 24 and 25, Township 19 South, Range 15 East, Gila and Salt River Meridian, Arizona, is hereby canceled.


This claim has not been filed with the Arizona State Office, Bureau of Land Management, in accordance with Section 314, 90 STAT. 2769, (43 U.S.C. 1744).

This cancellation was necessitated to clear the record.

The Mineral Survey Plat should be noted as follows:

"CINCAS VISTAS lode, M.S. 4397 was canceled July 12, 2012, by memo 9605 (956) M.S. 4397, which is now a part of the original field notes."

July 12, 2012
Date



Chief Cadastral Surveyor of Arizona

