

Form 4-683
(January 1963)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Mineral Survey number	4611
State	Arizona
Land District	Arizona

FIELD NOTES

Of the Survey of the Mining Claim of *(name and address of Claimant)*

U. S. Marble Products Company
2865 Colorado Boulevard
Los Angeles 41, California

Known as the *(name of group, if any)*

U. S. Marble Mill Site Group

CONSISTING OF LOCATIONS NAMED AND LOCATED AS FOLLOWS

NAME OF LOCATION	DATE	
	LOCATED	AMENDED
U. S. Marble Mill Site #1	4/ 3/61	6/11/63
U. S. Marble Mill Site #2	12/12/61	6/11/63
U. S. Marble Mill Site #3	4/ 3/61	6/11/63
U. S. Marble Mill Site #4	6/11/63	

Mining district			County	
Harcuvar			Yuma	
Section	Township	Range	Meridian	Survey under order dated
24	6 N.	12 W.	G&SR	Sept. 30, 1963
Survey commenced		Survey completed	Name of Mineral Surveyor	
Nov. 1, 1963		Nov. 2, 1963	Olaf Hondrum	

SURVEY NO. 4611

1.

FEET

This survey was made with a K & E transit, No. 129403, with horizontal limb 6.2 inches diameter, having two double opposite verniers, and full vertical circle 5 inches in diameter, having one double vernier; the verniers read to one minute of arc; the eye piece is equipped with a colored glass for making direct observations on the sun. The instrument was in good condition at the time of the survey and all adjustments were in good order.

All azimuths in this record were determined by the method of deflection angles referred to the meridian established by direct observation on the sun November 2, 1963, at Corner No. 1 of U. S. Marble Mill Site #3, latitude 33°50'30" N., longitude 113°27'25" W., turning from a reference point in a N. W. direction clockwise to the sun in the S.E. direction.

True bearing of reference point N. 22° - 36' W.

The lines were measured with a Lufkin steel tape 300 ft. in length, graduated every foot, with the first and last foot graduated to hundredths of a foot. The tape was compared with a standard and found correct. All lines of this survey were run by direct methods.

The magnetic declination observed at each corner of the survey gave a uniform value of 15°30' E.

U. S. MARBLE MILL SITE #1

At Cor. No. 1 of U.S. Marble Mill Site #1, identical with Cor. No. 1 of U. S. Marble Mill Site #2 of this survey, on the south R/W line of U.S. Highway 60 and 70.

Set an iron post, 20 ins. long, 2 ins. diam., 20 ins. in the ground, with aluminum cap mkd. 1-1-2-1 U.S.M.M.S.-4611; from which

the S.E. Cor. of sec. 24, T. 6 N., R. 12 W., G&SRM, bears S. 38°51' E., 2581.1 ft. dist., a 6 x 8 in. wooden post, 6 ft. high.

Thence S. 22°36' E.

660.0 Cor. No. 2, identical with Cor. No. 4 of U.S. Marble Mill Site #2, Cor. No. 2 of U.S. Marble Mill Site #3 and Cor. No. 2 of U.S. Marble Mill Site #4, all of this survey.

Set an iron post, 20 ins. long, 2 ins. diam., 20 ins. in the ground, with aluminum cap mkd. 1-2-2-4-3-2-4-2 U.S.M.M.S.-4611.

Thence S. 67°24' W.

330.0 Cor. No. 3, identical with Cor. No. 3 of U. S. Marble Mill Site #4, of this survey.

Set an iron post, 30 ins. long, 2 ins. diam., 20 ins. in the ground, with aluminum cap mkd. 1-3-4-3 U.S.M.M.S.-4611.

Thence N. 22°36' W.

660.0 Cor. No. 4, on the south R/W line of U.S. Highway 60 and 70.

Set an iron post, 30 ins. long, 2 ins. diam., 20 ins. in the ground, with aluminum cap mkd. 1-4 U.S.M.M.S.-4611.

3

FEET	
	Thence N. 67°24' E.
48	Road, bears NW. and SE.
248	Power line, bears NW. and SE.
330.0	Cor. No. 1, and place of beginning.
	U. S. Marble Mill Site #2
	Beginning at Cor. No. 1 of U. S. Marble Mill Site #2, identical with Cor. No. 1 of U. S. Marble Mill Site #1 of this survey, previously described.
	Thence N. 67°24' E.
330.0	Cor. No. 2, on the south R/W line of U. S. Highway 60 and 70. This corner falls in mud-filled ditch and was not set.
	Thence S. 22°36' E.
25.0	Witness for Cor. No. 2 Set an iron post, 30 ins. long, 2 ins. diam., 20 ins. in the ground, with aluminum cap mkd. W.C. 2-2 U.S.M.M.S.-4611.
660.0	Cor. No. 3, identical with Cor. No. 3 of U.S. Marble Mill Site #3 of this survey. Set an iron post, 30 ins. long, 2 ins. diam., 20 ins. in the ground, with aluminum cap mkd. 2-3-3-3 U.S.M.M.S. -4611.
	Thence S. 67°24' W.
330.0	Cor. No. 4, identical with Cor. No. 2 of U. S. Marble Mill Sites #s 1, 3 and 4, previously described.
	Thence N. 22°36' W.
660.0	Cor. No. 1, and place of beginning.
	U. S. Marble Mill Site #3
	At Cor. No. 1 of U. S. Marble Mill Site #3, identical with Cor. No. 1 of U. S. Marble Mill Site #4 of this survey. Set an iron post, 30 ins. long, 2 ins. diam., 20 ins. in the ground, with aluminum cap mkd. 3-1-4-1 U.S.M.M.S.-4611; from which The SE. Cor. Sec. 24, T. 6 N., R. 12 W., G&SRM, bears S. 54°33' E., 1364.7 ft. dist., previously described.
	Thence N. 22°36' W.
660.0	Cor. No. 2, identical with Cor. No. 2 of U.S. Marble Mill Site #s 1 and 4, and Cor. No. 4 of U.S. Marble Mill Site #2, all of this survey, previously described.
	Thence N. 67°24' E.
330.0	Cor. No. 3, identical with Cor. No. 3 of U.S. Marble Mill Site

SURVEY NO. 4611

3.

FEET	
	#2 of this survey, previously described. Thence S. 22°36' E.
660.0	Cor. No. 4 Set an iron post, 30 ins. long, 2 ins. diam., 20 ins. in the ground, with aluminum cap mkd. 3-4 U.S.M.M.S.-4611. Thence S. 67°24' W.
205	Road, bears N. 40° W. and S. 40° E.
330.0	Cor. No. 1 and place of beginning.
<hr/>	
U. S. Marble Mill Site #4	
	Beginning at Cor. No. 1 of U. S. Marble Mill Site #4, identical with Cor. No. 1 of U. S. Marble Mill Site #3 of this survey, previously described. Thence N. 22°36' W.
660.0	Cor. No. 2, identical with Cor. No. 2 of U. S. Marble Mill Site #s 1 and 3, and Cor. No. 4 of U. S. Marble Mill Site #2, all of this survey, previously described. Thence S. 67°24' W.
330.0	Cor. No. 3, identical with Cor. No. 3 of U. S. Marble Mill Site #1 of this survey, previously described. Thence S. 22°36' E.
660.0	Cor. No. 4. Set an iron post, 30 ins. long, 2 ins. diam., 20 ins. in the ground, with aluminum cap mkd. 4-4 U.S.M.M.S.-4611. Thence N. 67°24' E.
330.0	Cor. No. 1, and place of beginning.
<hr/>	
SURVEY NO. 4611	
A R E A S	
	<u>Acres</u>
Total area, U.S. Marble Mill Site #1	5.000
Total area, U.S. Marble Mill Site #2	5.000
Total area, U.S. Marble Mill Site #3	5.000
Total area, U.S. Marble Mill Site #4	5.000
L O C A T I O N	
This survey is located in the SE $\frac{1}{4}$ Sec. 24, T. 6 N., R. 12 W., G&SRM.	
The survey of the U. S. Marble Mill Sites #1, #2, #3, and #4 is identical with the respective or amended locations as marked on the ground.	

FEET

I M P R O V E M E N T S

The improvements made upon or for the benefit of each of the locations embraced in said Mill Sites by the claimant or its grantors are as follows:

From Cor. No. 4, U. S. Marble Mill Site #2 --

1. A steel bin, 9 x 9 ft., 14 ft. deep, the South corner of which bears N. 16° E., 80 ft. dist.; West side bears N. 38° W.
2. A crusher, 3 x 3 ft. bears N. 10° E., 84 ft. dist.
3. A conveyor belt, 30 ins. wide, bears North 115 ft. dist.; lengthwise bears N. 38° W. - S. 38° E.
4. A crusher, 4 x 20 ft., the South end of which bears N. 8°30' W., 141 ft. dist.; lengthwise, bears N. 38° W.
5. A steel elevator 3 x 3 ft., 24 ft. high, the West corner of which bears N. 12°30' W., 162 ft. dist.
6. A steel bin, 14 x 14 ft., 14 ft. high, the East corner of which bears N. 1°45' W., 171 ft. dist.; East side bears N. 36° W.
7. A sheet metal building, 20 x 28 ft., South corner of which bears N. 15°30' W., 205 ft. dist.; West side bears N. 36° W. 28 ft. Inside is a steel bin, 10 x 10 ft.

From Corner No. 3, U. S. Marble Mill Site #2 --

8. A steel trommel, 3 ft. diam., 20 ft. long, South end of which bears N. 80°30' W., 317 ft. dist.; lengthwise, bears N. 36° W.
9. A steel tumbler, 4 ft. diam., 18 ft. long, the South end of which bears N. 77° W. 338 ft. dist., lengthwise, bears N. 35° W.
10. A 4-in. well, 640 ft. deep, bears N. 71°50' W., 256 ft. dist.

From Corner No. 1, U. S. Marble Mill Site #2 --

11. A frame building, 30 x 40 ft., the Northwest corner of which bears due East, 150 ft. dist.; the West side bears S. 22°36' E., 40 ft.

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

CERTIFICATE OF SURVEYOR

Name of Mineral Surveyor <p style="text-align: center;">Olaf Hondrum</p>	Date <p style="text-align: center;">November 18, 1963</p>
---	--

I HEREBY CERTIFY That in pursuance of an order received from the Bureau of Land Management, at Phoenix, Arizona, dated September 30, 1963, I have carefully executed the survey of the claim of U. S. Marble Products Company, known as the (lode, placer, or mill site) U. S. Marble Mill Site #s 1, 2, 3 and 4, situated in Section 24, Township 6 N., Range 12 W., Gila & Salt River Meridian, in the State of Arizona.

This survey, designated as number 4611, has been executed by me and under my direction and has been made in strict conformity with said order, the Manual of Instructions for the Survey of Public Lands of the United States, and in the specific manner described in the foregoing field notes.

I FURTHER CERTIFY That the labor expended and improvements made upon and for the benefit of the (lode or placer) U. S. Marble Mill Site #s 1, 2, 3 and 4 location(s) embraced in the said mining claim by claimant(s) or grantors are fully stated in my report. The character, extent, location, and itemized value are specified in full detail. No portion of, or interest in, said labor and improvements so credited to this claim has been included in the estimate of expenditures upon any other claim.

10901 Connecticut Avenue
Sun City, Arizona

(Location)

Olaf Hondrum

(Signature of Mineral Surveyor)

CERTIFICATE OF APPROVAL

Office Bureau of Land Management, State Office
Location Phoenix, Arizona
Date December 5, 1963

The foregoing field notes of mineral survey number 4611, in Township 6 N., Range 12 W., G. & S. R. Meridian, in the State of Arizona, executed by Olaf Hondrum, Mineral Surveyor, under order dated Sept. 30, 1963, having been critically examined and the necessary corrections made prior to their certification by the surveyor, the field notes and the survey therein described are hereby approved.

Raymond C. Cleghorn

(Authorized Signature)

Acting State Director

(Title)

CERTIFICATE OF TRANSCRIPT

I CERTIFY That the foregoing transcript of field notes of the above described mineral survey number is a true copy of the original field notes.

(Authorized Signature)

(Title)

Title 18, U. S. C. section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious, or fraudulent statements or representations as to any matter within its jurisdiction.

MEMORANDUM FOR THE RECORD

DATE: 10/15/54

TO: SAC, NEW YORK

FROM: SA [Name], NEW YORK

SUBJECT: [Subject]

[Detailed body text]

[Detailed body text]

[Detailed body text]

[Detailed body text]

[Detailed body text]

[Detailed body text]

[Detailed body text]

[Detailed body text]

UNITED STATES DEPARTMENT OF THE INTERIOR 9605 (956)
BUREAU OF LAND MANAGEMENT M.S. 4611
ARIZONA STATE OFFICE

NOTICE OF CANCELLATION OF MINERAL SURVEY

The U. S. Marble Mill Site #1, U. S. Marble Mill Site #2, U. S. Marble Mill Site #3 and U. S. Marble Mill Site #4, Mineral Survey No. 4611, located in section 24, Township 6 North, Range 12 West, Gila and Salt River Meridian, Arizona, are hereby canceled.


These claims have not been filed with the Arizona State Office, Bureau of Land Management, in accordance with Section 314, 90 STAT. 2769, (43 U.S.C. 1744).

This cancellation was necessitated to clear the record.

The Mineral Survey Plat should be noted as follows:

"U. S. Marble Mill Site #1, U. S. Marble Mill Site #2, U. S. Marble Mill Site #3 and U. S. Marble Mill Site #4, M.S. 4611, were canceled March 25, 2002, by memo 9605 (956) M.S. 4611, which is now a part of the original field notes."

March 25, 2002
Date



Chief Cadastral Surveyor of Arizona

