UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FIELD NOTES

of the

.Dependent Resurvey of	a Portion of Su	bdivision	
a	nd		
Survey of Subdivisional	Lines of Section	ns 27 and 28	
	of		
Township 14 S	outh, Range 13 E	as t	
·			
Gila & St	alt Riven	W - = 2	
Of the Gila & Sa			
In the State of Arizo	ла		
EXEC	JTED BY		
Clarence E. Bilbray,	(Cartographer	Cadastral)	
<u></u>		·	
Under special instructions dated	November 19	, 19.52., which pro	vided
for the surveys included under Group No	. 286 ,	approved November 26,	1952
and assignment instructions dated	December 1	, 19.52	•
Survey commenced	December 15	, 19.52	
Survey completed	December 31	. <i>19</i> 52	

U. S. GOVERNMENT PRINTING OFFICE 16-56770-1

BCOK 4449

INDEX DIAGRAM

Townshi	pll. Sou	th	., Range	13 East	
6	5	4	8	2	1
7	8	9	10	11	12
18	17	16	15	14	13
19	20	21	22	23	24
30	29	7 10 11 10 6 9 11	5 8 9 2 9 4 3 8 4 3 2	2 26 1	25
81	32	88	84	85	86

T. 14 S., R. 13 E.

The township boundaries and subdivisional lines were originally surveyed by S. W. Foreman in 1871. The south boundary was retraced by C. M. Leedy in 1915. The west 3-1/2 miles of this boundary were retraced by W. E. Heister in 1931 and the quarter section corner of sections 3 and 34 and the corner of sections 5, 6, 31 and 32, were reestablished and monumented. The west boundary of the township was resurveyed and a double set of corners established by W. H. Thorn in 1925. Sections 9, 10, 15 and 16 were resurveyed with partial subdivisions by B. J. Kinsey in 1942.

The survey was executed with a light mountain solar transit made by W. and L. E. Gurley, Serial No. 371540, constructed in accordance with the standard instrumental specifications of the Bureau of Land Management. The instrument was in good condition and having been placed in satisfactory adjustment prior to the beginning of the survey, was tested and found free from appreciable error.

The measurements were made with a narrow steel tape, 5 chains in length, graduated to tenths of a link for the first ten links, every link for the remainder of the first 100 links, and at each 10 link interval for the remaining 400 links. The tape was tested by comparison with a standard 1 chain steel tape and found correct. The measurements were made on the slope, and the vertical angle of each interval was ascertained by a clinometer in good adjustment; the horizontal equivalents are entered in the field note record.

The directions of all lines were determined by transit method, with azimuth obtained from U. S. Coast and Geodetic Survey triangulation station "Cat Mountain" which is located in the $\mathbb{N}^{\frac{1}{4}}$ of section 30, T. 14 S., R. 13 E. All bearings were adjusted for differences in longitude between stations.

The geographic position of the southeast corner of section 27, T. 14 S., R. 13 E., as computed through the tie made to triangulation station Warner, is:

Latitude 32° 10' 39.9" N.

Longitude 110° 59' 38.3" W.

Chains

Dependent Resurvey of a Portion of Subdivision of T. 14 S., R. 13 E.

(Reestablishment of Survey Executed by S. W. Foreman in 1871)

Beginning at the corner of secs. 26, 27, 34, and 35, T. 14 S., R. 13 E., marked by a nail in pavement on center line of Ajo Highway, this point is used by local engineers and accepted by property owners. (True point not remonumented.)

from which

An iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., set 24 ins. in the ground, for a reference monument, bears S. 45° E., 60 lks. dist., with brass cap mkd. Tl4S R13E S35 RM 1952 and an arrow pointing to the true corner.

An iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., set 24 ins. in the ground, for a reference monument, bears S. 45° W., 60 lks. dist., with brass cap mkd. T14S R13E S34 RM 1952 and an arrow pointing to the true corner.

N. 0° 13' W., bet. secs. 26 and 27...

Over nearly level land, through cultivated field.

19.70

Road, bears E. and W.

38.80

Leave field and enter undergrowth, bears E. and W.

39.785

The $\frac{1}{4}$ sec. cor. of secs. 26 and 27, which is marked by an iron pipe, 2 ins. diam., 6 ins. above ground, at corner of fences which bear

Dependent Resurvey of a Portion of Subdivision of T. 14 S., R. 13 E.

Chains

N., E. and W., this point is used by local engineers and accepted by property owners

At the corner point

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.

from which

A mesquite, 6 ins. diam., bears S. $49\frac{1}{2}^{\circ}$ E., 12 lks. dist., mkd. $\frac{1}{4}$ S26 BT.

A mesquite, 8 ins. diam., bears N. $59\frac{1}{4}^{\circ}$ W., 23 lks. dist., mkd. $\frac{1}{4}$ S27 BT.

Bury the old iron pipe alongside the iron post.

N. 0° 34' W., Beginning new measurement.

1.00 | Thence along E. side of cultivated field, bears N. and W.

30.00 Leave field, bears S. and W.

31.00 Thence along W. side of field, bears N. and E.

The corner of secs. 22, 23, 26, and 27, marked by an iron pipe, 2 ins. diam., 6 ins. above ground, at corner of fences which bear N., S., E., and W., marked for secs. 22, 23, 26, and 27, this point used by local engineers and accepted by property owners.

At the corner point

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 2μ ins. in the ground, with brass cap mkd.

T14 S R13E						
S22	S23					
S27	S 26					

1952

from which

U. S. Coast and Geodetic Survey triangulation station "Warner", bears N. 6° 37' E., 99.753 chs. dist. (by triangulation)

Bury the old iron pipe alongside the iron post.

Land, nearly level.
Soil, sandy loam.
Undergrowth, mesquite...

From the corner of secs. 26, 27, 34 and 35.

N. 89° 56' W., bet. secs. 27 and 34.

Over nearly level land, along center line of Ajo Highway.

Dependent Resurvey of a Portion of Subdivision of T. 14 S., R. 13 E.

Chains

The $\frac{1}{4}$ sec. cor. of secs. 27 and 34, which is marked by a nail in pavement on center line of Ajo Highway, this point is used by local engineers and accepted by property owners in this vicinity, accepted as the best existing evidence of position of original corner (not remonumented)

from which

An iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., set 26 ins. in the ground, for a reference monument, bears N. 45° E., 60 lks. dist., with brass cap mkd. $\frac{1}{4}$ S27 RM 1952 and an arrow pointing to the true corner.

An iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., set 26 ins. in the ground, for a reference monument, bears S. 45° E., 60 lks. dist., with brass cap mkd. $\frac{1}{4}$ S34 RM 1952 and an arrow pointing to the true corner.

N. 89° 56' W., beginning new measurement.

0.81 Intersection of Ajo Highway and Mission Road.

20.00 Point for the W 1/16 sec. cor. of secs. 27 and 34, near S. edge of pavement of Ajo Highway.

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 30 ins. in the ground, with brass cap mkd.

1952

from which

An iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., set 24 ins. in the ground, for a reference monument, bears N. 45° E., 90 lks. dist., with brass cap mkd. W 1/16 S27 RM 1952 and an arrow pointing to the true corner.

An iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., set 24 ins. in the ground, for a reference monument, bears S. 45° W., 90 lks. dist., with brass cap mkd. W 1/16 S34 RM 1952 and an arrow pointing to the true corner.

40.00

The corner of secs. 27, 28, 33, and 34, which is marked by an iron pipe, $2\frac{1}{2}$ ins. diam., set flush with the ground, with cap mkd. for secs. 27, 28, 33, and 34, (Set by County in 1933) used by local engineers and accepted by property owners, accepted as the best existing evidence of position of original corner.

At the corner point

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 30 ins. in the ground; with brass cap mkd.

1952

from which

An iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., set 2μ ins. in the ground, for a reference monument, bears N. 45° E., 80 lks. dist., with brass cap mkd. Tl4S R13E S27 RM 1952 and an arrow pointing to the true corner.

Dependent Resurvey of a Portion of Subo	odivision of T. 14 S.	, R. 13 E.
---	-----------------------	------------

• • •	Dependent Resurvey of a Portion of Subdivision of T. 14 S., R. 13 E.
Chains	An iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., set 24 ins. in the ground, for a reference monument, bears S. 45° W., 80 lks. dist., with brass cap mkd. Tl4S R13E S33 RM 1952 and an arrow pointing to the true corner.
	Bury the old iron pipe alongside the iron post.
	Land, nearly level. Soil, sandy loam and rocky. Undergrowth, greasewood and mesquite.
	N. 0° 32' W., bet. secs. 27 and 28.
•	Over gently rolling land, through undergrowth.
0.20	Center line of Ajo Highway, bears E. and SW.
19.00	Wash, drains ESE.
19.853	Point for the S 1/16 sec. cor. of secs. 27 and 28.
	Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 2μ ins. in the ground, with brass cap mkd.
	s 1/16
	S28 S27
	1952
	raise a mound of stone, 3 ft. base, 2 ft. high, W. of cor.
21.00	Old road, bears NW. and SE.
39.706	Point for the $\frac{1}{4}$ sec. cor. of secs. 27 and 28, at proportionate distance, there is no remaining evidence of the original corner.
•	Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 2μ ins. in the ground, with brass cap mkd.
	1952
•	raise a mound of stone, 3 ft. base, 2 ft. high, W. of cor.
52.60	Wash, 50 lks. wide, 6 ft. deep, drains E.
74.40	Old road, bears NW. and SE.
79.412	The corner of secs. 21, 22, 27, and 28, falls on center line of a newly constructed road, reference by an iron pin, N. 22.7 lks. dist., and an iron pin, S. 22.7 lks. dist., and an old iron pipe lying loose on ground, this point used by local engineers and property owners, accepted as the best existing evidence of position of original corner
	At the corner point
	Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 30 ins. in the ground, with brass cap mkd.
	T14SR13E S21 \ S22
	. 528 S27
	1952

•	•	Dependent Resurvey of a Portion of Subdivision of T. 14 S., R. 13 E.
	Chains	from which
		An iron pin, $\frac{1}{2}$ in. diam., 6 ins. above ground, bears N. 22.7 lks. dist. (Set by local engineers)
		An iron pin, $\frac{1}{2}$ in. diam., 6 ins. above ground, bears S. 22.7 lks. dist. (Set by local engineers)
		From this corner U. S. Coast and Geodetic Survey triangulation station, bears N. 42° 43' E., 135.15 chs. dist.
	•	Land, rolling. Soil, sandy loam and rocky. Undergrowth, greasewood, mesquite and paloverde.
		From the corner of secs. 22, 23, 26, and 27.
		S. 89° 39' W., bet. secs. 22 and 27.
		Over gently rolling land.
·	20.50	Center line of Mission Road, bears NE. and S.
	36.10	Wash, drains ENE.
	40.05	The $\frac{1}{4}$ sec. cor. of secs. 22 and 27, marked by an iron pipe, 1 in. diam., 12 ins. above ground, this point used by local engineers and accepted by property owners, accepted as the best existing
	•	evidence of position of original corner. At the corner point
		Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., $2h$ ins, in the ground,
		with brass cap mkd.
		S 22 4 S 27
		1952
		raise a mound of stone, 3 ft. base, 2 ft. high, N. of cor., and bury the old iron pipe alongside the iron post.
		N. 89° 57' W., beginning new measurement.
	10.45	Bladed road, bears ENE. and W. Thence along road.
	18,00	Same road, bears E. and WSW.
	40.14	The corner of secs. 21, 22, 27, and 28.
		Land, gently rolling. Soil, sandy and rocky. Undergrowth, greasewood, mesquite and paloverde.
		From the corner of secs. 27, 28, 33, and 34.
		S. 89° 30' W., bet. secs. 28 and 33.
Φ,		over rolling land, through undergrowth.
	5.00	Center line of Ajo Highway, bears E. and curving WSW.
	20.01	Point for the E 1/16 sec. cor. of secs. 28 and 33.
		Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.

	Dependent Resurvey of a Portion of Subdivision of T. 14 S., R. 13 E.
Chains	E 1/16 S 28 S 33
	1952
	raise a mound of stone, 3 ft. base, 2 ft. high, N. of cor.
23.10	Wash, 6 ft. deep, 10 lks. wide, drains SSE.
30.00	Power line, bears N. and SW.
34.00	Wash, 8 ft. deep, 20 lks. wide, drains SSE.
40.02	The $\frac{1}{4}$ sec. cor. of secs. 28 and 33, marked by an iron pipe, 1 in. diam., 12 ins. above ground, this point used by local engineers and accepted by property owners, accepted as the best existing evidence of position of original corner.
	At the corner point
	Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.
	s 28 4 s 33
•	1952
	raise a mound of stone, 3 ft. base, 2 ft. high, N. of cor., and bury the old iron pipe alongside the iron post.
	S. 89° 30' W., beginning new measurement
3.80	Wash, 6 ft. deep, 10 lks. wide, drains SSE.
29.60	Bottom of draw, drains S.
40.01	The corner of secs. 28, 29, 32, and 33, marked by an iron pipe, $2\frac{1}{2}$ ins. diam., 12 ins. above ground, with cap mkd. for secs. 28, 29, 32 and 33, this point used by local engineers and accepted by property owners, accepted as the best existing evidence of position of original corner.
	At the corner point
	Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.
	T14sr13E s29 s28 s32 s33
	1952 ·
	raise a mound of stone, 3 ft. base, 2 ft. high, W. of cor.
	Land, rolling and hilly. Soil, rocky.
-	Undergrowth, greasewood, mesquite and palowerde.
	From the corner of secs. 28, 29, 32, and 33.
	N. 1° 01' W., bet. secs. 28 and 29.
	Ascend 215 ft. over rocky S. slope, through undergrowth.
18.10	Top of ascent; descend 210 ft. over rocky N. slope.

<u>.</u>	•	Dependent Resurvey of a Portion of Subdivision of T. 14 S., R. 13 E.
	Chains 32.10	Power line, bears E. and W
	34.30	Wash, drains E.
	40.31	Point for the $\frac{1}{4}$ sec. cor. of secs. 28 and 29, at proportionate distance, there is no remaining evidence of original corner.
		Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 4 ins. in the ground to bedrock, and in a mound of stone to top, with brass cap mkd.
		1/4
		. S29 S28
		1952
		Thence over rolling land.
	46.50	Top of ridge, bears E. and W.
	51.30	Bottom of draw, drains E.
	58 . 55	Top of ridge, bears E. and W.
	65.50	Bladed road, bears E. and W.
	70.60	Shallow wash, drains SE.
	80.62	The corner of secs. 20, 21, 28, and 29, which is monumented with an iron post, 2 ins. diam., 10 ins. above ground, set and marked as described in the official record.
!		Land, rolling and mountainous. Soil, rocky. Undergrowth, greasewood, mesquite, paloverde and cacti.
		From the corner of secs. 21, 22, 27, and 28.
		N. 89° 26' W., bet. secs. 21 and 28.
		Over rolling and broken land, through undergrowth.
	20.00	Power line, bears N. and S.
	23.80	Wash, 4 ft. deep, 15 lks. wide, drains NE.
•	35 . 60	Wash, 3 ft. deep, 10 lks. wide, drains SE.
	40.32	The $\frac{1}{4}$ sec. cor. of secs. 21 and 28, marked by an iron pipe, 2 ins. diam., 6 ins. above ground, mkd. $\frac{1}{4}$ for secs. 21 and 28, used by local engineers and accepted by property owners, accepted as the best existing evidence of position of original corner.
		At the corner point
		Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.
		1 S 21 4 S 28
		1952
		raise a mound of stone, 3 ft. base, 2 ft. high, N. of cor., and bury the old iron pipe alongside the iron post.
		N. 89° 45' W., beginning new measurement.

•	Dependent Resurvey of a Portion of Subdivision of Tl4 S., R. 13 E.
Chains 0.40	Power line, bears N. and S.
10.10	Ravine, drains N.
15.25	Top of low ridge, bears N. and S.
32.70	Wash, 4 ft. deep, 10 lks. wide, drains S.
40.36	The corner of secs. 20, 21, 28, and 29.
	Land, rolling and broken. Soil, sandy and rocky. Undergrowth, greasewood, mesquite, paloverde and cacti.
	Subdivision of Section 27, T. 14 S., R. 13 E.
	From the $\frac{1}{4}$ sec. cor. of secs. 27 and 34.
	N. 0° 25' W., on the N. and S. center line of sec. 27.
	Over nearly level land.
19.845	Point for the C-S 1/16 sec. cor. of sec. 27, falls on driveway pavement.
	Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 30 ins. in the ground, with brass cap mkd.
	c s 1/16 s27
	c
	1952
	from which
·	The northwest cor. of house, bears N. 46° 40' E., 1.38 chs. dist.
	The northwest cor. of house, bears S. 58° 18' E., 1.455 chs. dist.
35.00	Center line of Mission Road, bears NNE. and S.
39.69	The C $\frac{1}{4}$ sec. cor. of sec. 27, marked by an iron pipe, $l\frac{1}{2}$ ins. diam., 2 ins. above ground, with cap mkd. C $\frac{1}{4}$ S 27, this point was established by local engineers and used in making subdivisional surveys in this wicinity, and accepted by adjoining property owners.
	At the corner point
	Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.
	C ¼ 827
	1952
46.05	Wash, 6 ft. deep, 50 lks. wide, drains E.
64.55	Wash, 2 ft. deep, 15 lks. wide, drains E.
79.425	The $\frac{1}{4}$ sec. cor. of secs. 22 and 27.
	Land, gently rolling. Soil, sandy loam.
	Undergrowth, greasewood, mesquite, paloverde and cacti.
1	5

	Subdivision of Section 27, T. 14 S., R. 13 E.
Chains	From the $\frac{1}{4}$ sec. cor. of secs. 26 and 27.
	S. 89° 52' W., on the E. and W. center line of sec. 27.
	Over nearly level land, through undergrowth.
38.70	Center line of Mission Road, bears N. and S.
40.15	The C $\frac{1}{4}$ sec. cor. of sec. 27.
	N. 89° 56' W., beginning new measurement. ($W_{\Xi}^{\frac{1}{2}}$ of E. and W. center line of sec. 27)
20.036	Point for the C-W 1/16 sec. cor. of sec. 27.
•	Set am iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 25 ins. in the ground, with brass cap mkd.
	C W 1/16 S 27 C
	1952
40.072	The $\frac{1}{4}$ sec. cor. of secs. 27 and 28.
	Land, gently rolling.
	Soil, sandy. Undergrowth, greasewood, mesquite, paloverde and cacti.
	Subdivision of the SW_{4}^{\perp} of Sec. 27.
	From the W 1/16 sec. cor. of secs. 27 and 34.
0.15	N. 0° 30' W., on the N. and S. center line of the $SW_{\frac{1}{4}}$ of sec. 27. Center line of Ajo Highway, bears E. and W.
19.85	Point for the SW 1/16 sec. cor. of sec. 27, at the intersection of
19.00	the E. and W. center line of the $SW_{\frac{1}{4}}$ of sec. 27.
,	Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 2μ ins. in the ground, with brass cap mkd.
	SW 1/16 S27
	1952
39.698	The C-W 1/16 sec. cor. of sec. 27.
	From the C-S 1/16 sec. cor. of sec. 27.
	N. 89° 56' W., on the E. and W. center line of the $SW_{\frac{1}{4}}$ of sec. 27.
0.15	Power line, bears N. and S.
0.40	Center line of Mission Road, bears N. and S.
20.009	The SW 1/16 sec. cor. of sec. 27.
40.021	The S 1/16 sec. cor. of secs. 27 and 28.
	Subdivision of Section 28, T. 14 S., R. 13 E.
	From the $\frac{1}{4}$ sec. cor. of secs. 28 and 33.
1	ı

	Subdivision of Section 28, T. 14 S., R. 13 E.	
Chains	N. 0° 46' W., on the N. and S. center line of sec. 28.	
	Over rolling land, through undergrowth	
. • €	n Name Alma ed 7 jeulim ammy, bosem al. emeck.	
3.00	Ascend 175 ft. over rocky S, slope.	
14.20	Top of spur, slopes E. Thence descend 100 ft. over rocky N. slope.	
18.80	Wash, 3 ft. deep, 10 lks. wide, drains E., ascend 85 ft. over S. slope.	,
20.025	Point for the C-S 1/16 sec. cor. of sec. 28.	
	Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 4 ins. in the ground, to bedrock, and in a mound of stone to top, with brass cap mkd.	
	C .	
	s 1/16 s 28	
	1952	
23.80	Top of spur, slopes E., descend 150 ft. over N. slope.	
35.40	Wash, 2 ft. deep, 10 lks. wide, drains E. Thence over rolling and broken land.	-0
37.10	Power line, bears NW. and SSE.	∿
40.05	Point for the C \frac{1}{4} sec. cor. of sec. 28, at the intersection of the E. and W. center line of sec. 28.	
	Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.	
	C ½ S 28	
	1952	
	raise a mound of stone, 3 ft. base, 2 ft. high, W. of cor.	
49.10	Wash, 6 ft. deep, 40 lks. wide, drains SE.	
56.10	Bladed road, bears ENE. and WSW.	
72.40	Wash, 3 ft. deep, 20 lks. wide, drains NE.	
80.18	The $\frac{1}{4}$ sec. cor. of secs. 21 and 28.	
	Land, hilly and broken. Soil sandy and rocky. undergrowth, greasewood, mesquite, paloverde and cacti.	
	From the $\frac{1}{4}$ sec. cor. of secs. 27 and 28.	
	S. 89° 58' W., on the E. and W. center line of sec. 28.	
	Over rolling broken land, through undergrowth.	
20.074	Point for the C-E 1/16 sec. cor. of sec. 28.	
	Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 12 ins. in the ground to bedrock, and in a mound of stone to top, with brass cap mkd.	

BOOK 4449

Subdivision	\mathbf{of}	Section	28,	T.	14	S.,	R_{ullet}	13	Ε.

Subdivision of Section 28, T. 14 S., R. 13 E.			
Chains .	c E 1/16 s 28		
	1952		
40.148	The C $\frac{1}{4}$ sec. cor. of sec. 28.		
	Thence over hilly and broken land.		
41.35	Power line, bears N. and S.		
69.10	Wash, 8 ft. deep, 40 lks. wide, drains NE,		
80.318	The $\frac{1}{4}$ sec. cor. of secs. 28 and 29.		
	Land, hilly and broken. Soil, sandy and rocky. undergrowth, greasewood, mesquite, paloverde and cacti.		
	Subdivision of the SE14.of Sec. 28.		
	From the E 1/16 sec. cor. of secs. 28 and 33.		
	N. 0° 41' W., on the N. and S. center line of the $SE_{\frac{1}{4}}$ of sec. 28.		
19.947	Point for the SE 1/16 sec. cor. of sec. 28, at the intersection of the E. and W. center line of the $SE^{\frac{1}{4}}$ of sec. 28.		
	Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.		
	SE 1/16 S28		
	1952		
21.25	Wash, 6 ft. deep, 15 lks. wide, drains E.		
39.877	The CE 1/16 sec. cor. of sec. 28.		
	From the S 1/16 sec. cor. of secs. 27 and 28.		
	S. 89° μ W., on the E. and W. center line of the $SE_{\frac{1}{4}}^{\frac{1}{2}}$ of sec. 28.		
14.55	Power line, bears N. and S.		
20.035	The SE 1/16 sec. cor. of sec. 28.		
40.075	The C-S 1/16 sec. cor. of sec. 28.		
	General Description		
	The surface of the east-half of section 27 is nearly level, the west-half of this section and the greater portion of the east-half of section 28 is gently rolling. The west-half of section 28 is hilly and broken. The general drainage is to the east through a number of washes. The eastern portion of section 27 is under cultivation. The sections are covered with an undergrowth of greasewood, mesquite, paloverde and cacti. The soil is a sandy loam except for the western portion of section 28, which is very rocky. The Freedom Homes Subdivision is located in the southeast quarter of section 27. The Ajo Highway traverses along the south boundary of section 27 and leaves the south boundary of section 28		
	approximately 5 chains west of the corner of sections 27, 28, 33 and 34. Mission Road traverses through section 27 in a north-easterly direction, entering section 27 near the quarter corner of		

BOOK 4449

·· Subdivision of Section 28, T. 14 S., R. 13 E.
27 and 34 and leaving on the north boundary of the section

sections 27 and 34 and leaving on the north boundary of the section 20 chains west of the corner of sections 22, 23, 26 and 27.

4-680 (Feb., 1950)

UNITED STATES COK 4449 DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FIELD ASSISTANTS

NAMES	CAPACITY	
Charles C. Doak W. Bustos	Cartographic Survey Aid	
P. Martinez	Surveying and Cartographic Aid	
D, Williams	11 11	
·		
	·	
·		
	•	
	in the second se	

16--53565-

CERTIFICATE OF CADASTRAL ENGINEER

I, Clarence E. Bilbray	, HEREBY CERTIFY upon honor that, in
pursuance of special instructions bearing date of the	19th day of November ,1952,
I have surveyed a dependently resurveyed a po	rtion of the subdivision and surveyed
the subdivisional lines of sections 27 an	
tima tek	
of the Gila & Salt River Meridian, in the State of	, which are
represented in the foregoing field notes as having be	en executed by me and under my direction; and that
said survey has been made in strict conformity with	said instructions, the Manual of Instructions for the
Survey of the Public Lands of the United States, an	d in the specific manner described in the foregoing
field notes.	10 - 3
Denver, Colorado	Claruse E. Bilbray
January 18, 1955	Cartographer (Cadastral)
CERTIFICATE	OF APPROVAL
	BUREAU OF LAND MANAGEMENT,
	Washington, D. C., AUG 3 0 1955 , 19
The foregoing field notes of the successor depen	dent resurvey of a portion of the
subdivision and survey of the subdivision	al lines of sections 27 and 28, in
Township 14 South, Range 13 East of the G	ila and Salt River Meridian, Arizona
executed byClarence E. Bilbray	
having been critically examined and found correct,	are hereby approved.
en de la companya de La companya de la companya del companya de la companya del companya de la c	Chief, Division of Cadadal Engineering. Cadastral Engineering (Staff Officer
· · · · · · · · · · · · · · · · · · ·	7
- CERTIFICATE (OF TRANSCRIPT
I century that the foregoing transcript of the	ield notes of the above described surveys in
	original field notes
	Chief. Division of Cadastral Engineering.