

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Original

FIELD NOTES

of the

Dependent Resurvey

of the

South Boundary

and a

Portion of the Subdivision

of

Township 8 South, Range 27 East

Of the Gila and Salt River *Meridian,*

In the State of Arizona

EXECUTED BY

Donald E. Harding, Cadastral Surveyor

Under special instructions dated February 6, 1957, *which provided*
for the surveys included under Group No. 313, *approved* February 6, 1957
and assignment instructions dated February 6, 1957

Survey commenced February 20, 1957

Survey completed March 8, 1957

26
11

BOOK 4546
INDEX DIAGRAM

Township 8 South, Range 27 East

6 14 13	5 9 13	4 7 9	3 6 10	2 11	1 12
7 11	12 8 11	8 9 7	10 15	11 14	12 13
18 10	17 20	16 21	15 22	14 23	13 24
19	20	21	22	23	24
30	29	28	27	26	25
31 5	32 4	33 3	34 3	35 2	36 1

Township 8 South, Range 27 East

Chains

The four boundaries of this township were surveyed by T. F. White in 1874 and 1875; the subdivisional lines were surveyed by T. F. White in 1875, as represented on the plat approved March 31, 1875. The east boundary was resurveyed by W. B. Kimmel in 1914, as represented on the plat of T. 8 S., R. 28 E., approved June 19, 1915.

The resurvey of the north boundary is provided for in the notes of T. 7 S., R. 27 E. of this group. The resurvey of the west boundary is provided for in the resurvey of T. 8 S., R. 26 E. of group 299.

For the test of the instruments and methods used, see the notes for T. 7 S., R. 27 E. of this group.

The following transcribed field notes are those of the resurvey of the south boundary and a portion of the subdivision. The geographic position of the southeast corner of the township is latitude $32^{\circ} 41' 11.177''$ N., and longitude $109^{\circ} 31' 39.659''$ W. The mean magnetic declination is $13\frac{1}{2}^{\circ}$ E.

Dependent Resurvey of the South Boundary of T. 8 S., R. 27 E.

Reestablishment of the survey executed by T. F. White in 1874 and 1875.

No original corners were found for the six miles of this boundary, therefore, the corners are set at proportionate distance from the corner of Ts. 8 and 9 S., Rs. 27 and 28 E., which is monumented with an iron post set, marked, and witnessed as described in the official record.

N. $89^{\circ} 58'$ W., bet. secs. 1 and 36.

Over nearly level land, through scattered undergrowth.

39.89 Point for the $\frac{1}{4}$ sec. cor. for secs. 1 and 36, at proportionate distance.

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.

T8S R27E
 $\frac{1}{4}$ $\frac{S36}{S1}$
 T9S
 1957

Raise a mound of stone, 2 ft. base, $1\frac{1}{2}$ ft. high, N. of cor.

79.30 Wash, 80 lks. wide, 9 ft. deep, drains N.

79.78 Point for the cor. of secs. 1, 2, 35 and 36, at proportionate distance, falls in wash. Not safe to monument.

Land, nearly level.

Soil, sandy clay.

Timber, none; undergrowth, scattered greasewood, mesquite, cacti and sparse grass.

Dependent Resurvey
S. Bdy., Township 8 South, Range 27 East

Chains

N. 89° 58' W., bet. secs. 2 and 35.

Over level land, through scattered undergrowth.

0.35 Point selected for the witness cor. of secs. 1, 2, 35 and 36.

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

T8S R27E
S35 | S36 W
S2 | S1 C
T9S
1957

4.00 Wash, 60 lks. wide, 7 ft. deep, drains N.

9.20 Small wash, drains NW.

11.20 Small wash, drains N.

19.60 East bank of San Simon River.

20.50 Main channel of San Simon River, 50 lks. wide, 1 ft. deep, drains NNW.

24.60 West bank of San Simon River.

33.30 Southern Pacific Railroad (branch line), bears S. and NW.

33.90 Telephone line, bears S. and NW.

39.89 Point for the ¼ sec. cor. of secs. 2 and 35, at proportionate distance.

Set an iron post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.

T8S R27E
¼ S35
S 2
T9S
1957

Deposit broken glass at the base of the post for witness.

66.20 Small wash, drains NE.

79.78 Point for the cor. of secs. 2, 3, 34 and 35, at proportionate distance.

Set an iron post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.

T8S R27E
S34 | S35
S3 | S2
T9S
1957

Land, nearly level.

Soil, sandy clay.

Timber, none; undergrowth, scattered greasewood, mesquite, cacti, and sparse grass.

Dependent Resurvey
S. Bdy., Township 8 South, Range 27 East

Chains	
	N. 89° 58' W., between secs. 3 and 34. Over level land, through scattered undergrowth.
39.89	Point for the $\frac{1}{4}$ sec. cor. of secs. 3 and 34. Set an iron post, 28 ins. long, 2 $\frac{1}{2}$ ins. diam., 22 ins. in the ground, with brass cap mkd. <div style="text-align: center;">T8S R27E $\frac{1}{4}$ $\frac{S34}{S3}$ T9S 1957</div>
	Raise a small mound of stone N. of cor.
61.40	Old road, bears NW. and S.
72.00	Small wash, drains NE.
79.78	Point for the cor. of secs. 3, 4, 33, and 34, at proportionate distance. Set an iron post, 28 ins. long, 2 $\frac{1}{2}$ ins. diam., 22 ins. in the ground, with brass cap mkd. <div style="text-align: center;">T8S R27E $\frac{S33}{S4}$ $\frac{S34}{S3}$ T9S 1957</div>
	Raise a mound of stone, 2 ft. base, 1 $\frac{1}{2}$ ft. high, W. of cor. Land, nearly level. Soil, sandy clay. Timber, none; undergrowth, scattered greasewood, mesquite, cacti, and sparse grass.
	N. 89° 58' W., between secs. 4 and 33. Over nearly level land, through scattered undergrowth.
30.10	Small wash, drains NE.
39.89	Point for the $\frac{1}{4}$ sec. cor. of secs. 4 and 33, at proportionate distance. Set an iron post, 28 ins. long, 2 $\frac{1}{2}$ ins. diam., 22 ins. in the ground, with brass cap marked. <div style="text-align: center;">T8S R27E $\frac{1}{4}$ $\frac{S33}{S4}$ T9S 1957</div>
	Deposit broken glass at base of the post for witness.
63.00	Low flat ridge, bears NE. and SW.

Dependent Resurvey
S. Bdy., Township 8 South, Range 27 East

Chains

79.78 Point for the cor. of secs. 4, 5, 32, and 33, at proportionate distance.

Set an iron post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.

T8S R27E
S32|S33
S5|S4
T9S
1957

Land, nearly level.
Soil, sandy clay.
Timber, none; undergrowth, scattered greasewood, mesquite, cacti, and sparse grass.

N. 89° 58' W., between secs. 5 and 32,

Over nearly level land, through scattered undergrowth.

39.89 Point for the ¼ sec. cor. of secs. 5 and 32, at proportionate distance.

Set an iron post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.

T8S R27E
¼ S32
S5
T9S
1957

Raise a mound of earth, 3 ft. base, 1½ ft. high, N. of cor.

79.00 Track road, bears N. and S.

79.79 Point for the cor. of secs. 5, 6, 31, and 32, at proportionate distance.

Set an iron post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.

T8S R27E
S31|S32
S6|S5
T9S
1957

Deposit charcoal in the hole with the post for witness.

Land, nearly level.
Soil, sandy clay.
Timber, none; undergrowth, scattered greasewood, mesquite, cacti, and sparse grass.

Dependent Resurvey
S. Bdy., Township 8 South, Range 27 East

Chains	
	N. 89° 58' W., between secs. 6 and 31.
	Over nearly level land, through scattered undergrowth.
1.40	Fence, bears N. 30° E. and S. 30° W.
11.80	Fence, bears N. 60° W. and S. 60° E.
18.80	Dirt reservoir, bears N. 3 chs. dist.
39.89	Point for the $\frac{1}{4}$ sec. cor. of secs. 6 and 31, at proportionate distance.
	Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 22 ins. in the ground with brass cap mkd.
	T8S R27E $\frac{1}{4}$ $\frac{S31}{S6}$ T9S 1957
45.10	Small wash, drains N. 15° E.
70.50	Old road, bears NE. and SW.
78.10	Wash, drains N.
78.82	Fence, bears N. and S.
78.85	The cor. of Ts. 8 and 9 S., Rs. 26 and 27 E., monumented with a partially rotted stake, firmly set in a mound of earth.
	At the cor. point
	Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.
	T8S R26E R27E $\frac{S36}{S1} \frac{S31}{S6}$ T9S 1957
	Deposit a sandstone, 4 X 4 X 3, marked with a cross (X) at the base of the post for witness.
	From above cor. point, cor. of fences N., S., and W., bears E. 3 lks. dist.
	Land, nearly level. Soil, sandy clay. Timber, none; undergrowth, scattered greasewood, mesquite, cacti, and sparse grass.

Dependent Resurvey
Township 8 South, Range 27 East

Chains

Dependent Resurvey
of a Portion of the Subdivision of T. 8 S., R. 27 E.

Reestablishment of the Survey executed by T. F. White in 1875
The cor. of secs. 9, 10, 15, and 16, which is monumented with a
rotted post in a mound of earth

from which

A mesquite stump bears N. $47\frac{1}{2}^{\circ}$ E., 36 lks. dist., marked BT only.

A mesquite stump bears N. 75° E., 91 lks. dist., marked BT only.

A mesquite stump bears S. 68° W., 1.59 lks. dist.

At the cor. point

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 22 ins. in the
ground, with brass cap mkd.

T8S R27E
S9 | S10
S16 | S15
1957

Deposit broken glass at base of post for witness.

N. $0^{\circ} 23'$ E., between secs. 9 and 10.

Over nearly level land, through scattered undergrowth.

23.20 South bank of San Simon River, bears NW. and SE.

27.90 Main channel of San Simon River, 120 lks wide, 1 ft. deep, drains NW.

32.50 North bank of San Simon River, bears NW. and SE.

39.78 Point for the $\frac{1}{4}$ sec. cor. of secs. 9 and 10, at proportionate
distance. No remaining evidence of the original corner.

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 22 ins. in the
ground, with brass cap mkd.

T8S R27E
 $\frac{1}{4}$
S9 | S10
1957

Deposit a sandstone 4 X 3 X 2, marked with a cross (X), at base of
the post for witness.

44.30 Fence, bears SE. and NW.

73.20 Track road, bears ESE. and NW.

76.90 Small wash, drains NW.

79.20 Track road, bears E. and W.

79.56 The cor. of secs. 3, 4, 9, and 10, monumented with a dimly marked
sandstone 10 X 8 X 6 ins., in a mound of stones and earth.

Dependent Resurvey
Township 8 South, Range 27 East

Chains	<p>At the corner point</p> <p>Set an iron post, 28 ins. long, 2½ ins. diam., 20 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;">T8S R27E • S4 S3 • S9 S10 1957</p> <p>Raise a mound of stone, 2 ft. base, 1½ ft. high, W. of cor.</p> <p>Land, nearly level. Soil, sandy clay. Timber, none; undergrowth, scattered mesquite, rabbit brush, greasewood, and sparse grass.</p>
2.80 10.00 15.30 39.58	<p>N. 0° 16' W., between secs. 3 and 4.</p> <p>Over nearly level land, through scattered undergrowth.</p> <p>Small wash, drains W.</p> <p>Dirt reservoir, bears E. 3 chs. dist.</p> <p>Small wash, drains W.</p> <p>Point for the ¼ sec. cor. of secs. 3 and 4, at proportionate distance. No remaining evidence of original cor.</p> <p>Set an iron post, 28 ins. long, 2½ ins. diam., 20 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;">T8S R27E ¼ S4 S3 1957</p>
79.21	<p>Raise a mound of stone, 2 ft. base, 1½ ft. high, W. of cor.</p> <p>The cor. of secs. 3, 4, 33, and 34, on the N. boundary of the township, which is monumented with an iron post, set, marked, and witnessed as described in the notes of T. 7 S., R. 27 E.</p> <p>Land, nearly level. Soil, sandy clay. Timber, none; undergrowth, scattered mesquite, rabbit brush, greasewood, and sparse grass.</p>
37.25 37.85 40.03	<p>From the cor. of secs. 9, 10, 15, and 16.</p> <p>S. 89° 52' W., between secs. 9 and 16.</p> <p>Over nearly level land, through scattered undergrowth.</p> <p>Southern Pacific Railroad (branch line), bears NW. and SE.</p> <p>Telephone line, bears NW. and SE.</p> <p>Point for the ¼ sec. cor. of secs. 9 and 16, at proportionate distance. No remaining evidence of the original cor.</p> <p>Set an iron post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;">T8S R27E ¼ S9 S16 1957</p>
44.95 60.35 72.35 73.90	<p>Deposit broken glass at base of the post for witness.</p> <p>Wash, 40 lks. wide, 6 ft. deep, drains NE.</p> <p>Wash, 20 lks. wide, 10 ft. deep, drains NE.</p> <p>Track road, bears SSE. and WNW.</p> <p>Wash, 1 ch. wide, 4 ft. deep, drains NE.</p>

Dependent Resurvey
Township 8 South, Range 27 East

Chains
80.06

The cor. of secs. 8, 9, 16, and 17, which is monumented with a partially rotted post in a mound of earth,
from which

A mesquite stump bears N. 30° W. 99 lks. dist., marked BT only.

A mesquite stump bears N. 85¼° W. 78 lks. dist., marked BT only.

At the cor. point

Set an iron post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.

T8S R27E
S8|S9
S17|S16
1957

Deposit a sandstone 4 X 4 X 3, marked with a cross (X), at base of the post for witness.

N. 0° 29' E., between secs. 8 and 9.

Over nearly level land, through scattered undergrowth.

4.60 Track road, bears ESE. and W.

35.80 Wash, 20 lks. wide, 6 ins. deep, drains NE.

39.00 Wash, 40 lks. wide, 6 ins. deep, drains ENE.

39.82 Point for the ¼ sec. cor. for secs. 8 and 9, at proportionate distance. No remaining evidence of the original cor.

Set an iron post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.

T8S R27E
¼
S8|S9
1957

Deposit broken glass at base of the post for witness.

from which

A mesquite, 4 ins. diam., bears S. 63½° E., 36 lks. dist., marked ¼S9BT.

52.40 Wash, 50 lks. wide, 1 ft. deep, drains NE.

55.60 Track road, bears NNW. and SE.

63.80 Telephone line, bears NNW. and SSE.

64.70 Southern Pacific Railroad (branch line) bears NNW. and SSE.

68.30 Small wash, drains NNW.

79.64 Point for the cor. of secs. 4, 5, 8, and 9, at proportionate distance. No remaining evidence of the original cor.

Set an iron post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.

T8S R27E
S5|S4
S8|S9
1957

Deposit broken glass at base of the post for witness.

Land, nearly level.

Soil, sandy clay.

Timber, none; undergrowth, scattered mesquite, rabbit brush, greasewood, and sparse grass.

Dependent Resurvey
Township 8 South, Range 27 East

Chains	
	From cor. of secs. 3, 4, 9, and 10.
	S. 89° 50' W., between secs. 4 and 9.
	Over nearly level land, through scattered undergrowth.
6.00	Wash, 20 lks. wide, 1 ft. deep, drains NW.
11.80	Track road, bears NW. and SE.
25.50	Wash, 75 lks. wide, 2 ft. deep, drains NW.
39.94	Point for the $\frac{1}{4}$ sec. cor. of secs. 4 and 9, at proportionate distance. No remaining evidence of the original cor.
	Set an iron post, 28 ins. long, 2 $\frac{1}{2}$ ins. diam., 22 ins. in the ground, with brass cap mkd.
	T8S R27E $\frac{1}{4}$ $\frac{S4}{S9}$ 1957
	Deposit broken glass at base of the post for witness.
46.70	Small wash, drains NW.
48.30	East bank of the San Simon River, bears NW. and SE.
68.20	Main channel of the San Simon River, 2 chs. wide, 2 ft. deep, drains NW.
70.20	West bank of the San Simon River, bears NW. and SE.
79.88	The cor. of secs. 4, 5, 8, and 9.
	Land, nearly level. Soil, sandy clay. Timber, none; undergrowth, scattered mesquite, rabbit brush, greasewood, and sparse grass.
	N. 0° 19' W., between secs. 4 and 5.
	Over nearly level land, through scattered undergrowth.
15.70	Wash 20 lks. wide, 2 ft. deep, drains NW.
23.30	South bank of the San Simon River, bears NW. and SE.
26.50	Main channel of the San Simon River, 3 chs. wide, 2 ft. deep, drains NW.
32.10	North bank of the San Simon River, bears NW and SE.
38.00	Wash, 15 lks. wide, 2 ft. deep, drains W.
39.82	Point for the $\frac{1}{4}$ sec. cor. of secs. 4 and 5, at proportionate distance. No remaining evidence of the original cor.
	Set an iron post, 28 ins. long, 2 $\frac{1}{2}$ ins. diam., 22 ins. in the ground, with brass cap mkd.

Dependent Resurvey
Township 8 South, Range 27 East

Chains	
	T8S $\frac{1}{2}$ R27E S5 S4 1957
	Deposit broken glass at base of the post for witness.
75.50	Track road, bears NW. and SE.
79.53	The cor. of secs. 4, 5, 32, and 33 on the N. boundary of the township, which is monumented with an iron post, set, marked, and witnessed as described in the notes for T. 7 S., R. 27 E.
	Land, nearly level. Soil, sandy clay. Timber, none; undergrowth, scattered mesquite, rabbit brush, greasewood, and sparse grass.
	The $\frac{1}{4}$ sec. cor. of secs. 17 and 18, which is monumented with a rotted stake in a mound of earth, witnessed by pits N. and S.
	At the cor. point
	Set an iron post, 28 ins. long, 2 $\frac{1}{2}$ ins. diam., 22 ins. in the ground, with brass cap mkd.
	T8S R27E $\frac{1}{4}$ S18 S17 1957
	Deposit a sandstone 3 X 3 X 2, marked with a cross (X) at base of the post for witness.

	N. 0° 43' W., between secs. 17 and 18.
	Over nearly level land, through scattered undergrowth.
6.00	Track road, bears ENE. and WSW.
6.30	Fence, bears ENE. and WSW.
39.86	Point for the cor. of secs. 7, 8, 17, and 18, at proportionate distance. No remaining evidence of the original cor.
	Set an iron post, 28 ins. long, 2 $\frac{1}{2}$ ins. diam., 22 ins. in the ground, with brass cap mkd.
	T8S R27E S7 S8 S18 S17 1957
	Deposit broken glass at base of the post for witness.
	Set an oak post 6 ft. long, 8 ins. sq., 2 ft. in the ground, 3 lks. W. of the cor.
	Land, nearly level. Soil, sandy clay. Timber, none; undergrowth, scattered mesquite, rabbit brush, greasewood, and sparse grass.

Dependent Resurvey
Township 8 South, Range 27 East

Chains

From the cor. of secs. 8, 9, 16 and 17.

S. 89° 56' W., bet. secs. 8 and 17.

Over nearly level land, through scattered undergrowth.

7.60 Track road, bears NE. and SW.

24.00 Wash, 50 lks. wide, 6 ins. deep, drains NE.

32.00 Windmill, steel storage tank, and small drinking tank, with cattle corral N., bears N. 8 chs. dist.

38.50 Track road, bears NE. and SW.

39.93 The $\frac{1}{4}$ sec. cor. of secs. 8 and 17, as reestablished from the remains of two bearing trees.

A mesquite stump, bears S. 1° E., 90 lks. dist.

A partially dead mesquite, bears N. 22° E., 1 ch. dist.

At the cor. point

Set an iron post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.

T8S R27E
 $\frac{1}{4}$ $\frac{S\ 8}{S17}$
1957

Raise a mound of stone, 2½ ft. base, 2 ft. high, N. of cor.

S. 89° 40' W., beginning new measurement.

15.70 Fence, bears N. and S.

39.74 The cor. of secs. 7, 8, 17 and 18.

Land, nearly level.

Soil, sandy clay.

Timber, none; undergrowth, scattered mesquite, rabbit brush, greasewood, and sparse grass.

N. 89° 50' W., bet. secs. 7 and 18.

Over nearly level land, through scattered undergrowth..

16.10 Dirt reservoir, bears N. 6 chs. dist.

27.60 Wash, 10 lks. wide, 1 ft. deep, drains NE.

39.76 Point for the $\frac{1}{4}$ sec. cor. of secs. 7 and 18, at proportionate distance; no remaining evidence of the original cor.

Set an iron post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.

Dependent Resurvey
Township 8 South, Range 27 East

Chains

T8S R27E

$$\frac{1}{4} \frac{S7}{S18}$$
 1957

Deposit broken glass at base of the post for witness.

78.40 Road, bladed, bears N. and S.

78.50 Fence, bears N. and S.

78.62 The cor. of secs. 7, 12, 13 and 18, on the W. boundary of the township, which is monumented with an iron post, set, marked and witnessed as described in the notes of T. 8 S., R. 26 E.

From above corner USSES triangulation station (Jones), bears N. 52° 14' 10" E., 29.61 chs. dist.

Land, nearly level.

Soil, sandy clay.

Timber, none; undergrowth, scattered mesquite, rabbit brush, greasewood and sparse grass.

From the cor. of secs. 7, 8, 17 and 18.

N. 0° 16' E., bet. secs. 7 and 8.

Over nearly level land, through scattered undergrowth.

30.30 Small wash, drains NE.

39.86 Point for the $\frac{1}{4}$ sec. cor. of secs. 7 and 8, at proportionate distance. No remaining evidence of the original cor.

Set an iron post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.

T8S R27E

$$\frac{1}{4} \frac{S7|S8}{S7|S8}$$
 1957

Deposit broken glass at base of the post for witness.

40.90 Fence corner, with fences bearing E. and NNW.

71.80 Windmill, dirt stock tank, loading pens and chutes, and old rock house, bears W. 10 chs. dist.

79.72 Point for the cor. of secs. 5, 6, 7 and 8, at proportionate distance. No remaining evidence of the original cor.

Set an iron post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.

T8S R27E

$$\frac{S6|S5}{S7|S8}$$
 1957

Deposit broken glass at base of the post for witness.

Dependent Resurvey
Township 8 South, Range 27 East

Chains	
	<p>Set an oak post, 4 ins. sq., 7 ft. long, 2 ft. in the ground, 3 lks. W. of the cor.</p> <p>Land, nearly level. Soil, sandy clay. Timber, none; undergrowth, scattered mesquite, rabbit brush, greasewood and sparse grass.</p>
	<p>From the cor. of secs. 4, 5, 8 and 9.</p> <p>S. 89° 57' W., bet. secs. 5 and 8.</p> <p>Over nearly level land, through scattered undergrowth.</p>
12.90	Southern Pacific Railroad (branch line) bears NW. and SE.
13.50	Telephone line, bears NW. and SE.
40.01	<p>Point for the $\frac{1}{4}$ sec. cor. of secs. 5 and 8, at proportionate distance. No remaining evidence of the original cor.</p> <p>Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 22 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;">T8S R27E $\frac{1}{4}$ $\frac{S5}{S8}$ 1957</p> <p>Deposit broken glass at base of the post for witness.</p> <p>Set an oak post, 6 ins. sq., 6 ft. long, 2 ft. in the ground, 3 lks. N. of cor.</p>
41.00	Wash, 30 lks. wide, 3 ft. deep, drains NE.
42.70	Wash, 15 lks. wide, 2 ft. deep, drains NE.
48.40	Fence, bears S. and N., 4 chs. to cor., thence westerly.
67.40	Small wash, drains NE.
76.90	Track road, bears NW. and SE.
80.02	<p>The cor. of secs. 5, 6, 7 and 8.</p> <p>Land, nearly level. Soil, sandy clay. Timber, none; undergrowth, scattered mesquite, rabbit brush, greasewood and sparse grass.</p>
	<p>N. 89° 57' W., bet. secs. 6 and 7.</p> <p>Over nearly level land, through scattered undergrowth.</p>
7.75	Fence, bears N. and S.
10.00	Windmill, dirt stock tank, loading pens and chutes and old rock house, bears S. 8 chs. dist.

Dependent Resurvey
Township 8 South, Range 27 East

Chains	
16.00	Road, bears ESE. and WNW; dirt reservoir, bears N. 5 chs. dist.
19.80	Small wash, drains NE.
34.00	Track road, bears N. and S.
39.95	Point for the $\frac{1}{4}$ sec. cor. of secs. 6 and 7, at proportionate distance. No remaining evidence of the original cor.
	Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 22 ins. in the ground, with brass cap mkd.
	<p style="text-align: center;">T8S R27E $\frac{1}{4}$ $\frac{S6}{S7}$ 1957</p>
	Deposit broken glass at base of the post for witness.
50.50	Road, bears SE. and NW.
73.15	Road, bladed, bears N. and S.
79.05	The cor. of secs. 1, 6, 7 and 12, on the W. boundary of the township, which is monumented with an iron post, set, marked, and witnessed as described in the notes for T. 8 S., R. 26 E.
	<p>Land, nearly level. Soil, sandy clay. Timber, none; undergrowth, scattered mesquite, rabbit brush, greasewood, and sparse grass.</p>
	From the cor. of secs. 5, 6, 7 and 8.
	N. $0^{\circ} 10'$ W., bet. secs. 5 and 6.
	Over nearly level land, through scattered undergrowth.
0.80	Road, bears ENE. and W.
7.60	Dirt reservoir, bears W., 8 chs. dist.
7.70	Fence, bears E. and W.
39.86	Point for the $\frac{1}{4}$ sec. cor. of secs. 5 and 6, at proportionate distance. No remaining evidence of the original cor.
	Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 22 ins. in the ground, with brass cap mkd.
	<p style="text-align: center;">T8S R27E $\frac{1}{4}$ S6 S5 1957</p>
	Deposit broken glass at base of the post for witness.
44.70	Wash, 50 lks. wide, 10 ft. deep, drains NE.
64.10	Wash, 15 lks. wide, 1 ft. deep, drains NE.

Dependent Resurvey
Township 8 South, Range 27 East

Chains	
71.90	Small wash, drains ENE.
79.64	<p>The cor. of secs. 5, 6, 31, and 32, on the N. boundary of the township, which is monumented with an iron post, set, marked, and witnessed as described in the notes for T. 7 S., R. 27 E.</p> <p>Land, nearly level. Soil, sandy clay. Timber, none; undergrowth, scattered mesquite, rabbit brush, greasewood, and sparse grass.</p>
	<p>The portion of T. 8 S., R. 27 E., which was resurveyed is nearly level land with scattered undergrowth and fair grass. Stock water is available through drilled wells and manmade dirt tanks.</p> <p>There is no farming or other related activities in this township. The only revenue derived is from grazing.</p> <p>A branch line of the Southern Pacific Railroad bisects the township from the NW. cor. to the SE. cor. The township is also bisected by the San Simon River, which ordinarily is dry.</p> <p>The average elevation is 3,000 ft. There is no one living within the area surveyed.</p>

4-680
(Feb., 1960)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FIELD ASSISTANTS

NAMES	CAPACITY
Jack McCulley	Instrument Man
Paul Bauer	Note Keeper
Wade Betenson	Chainman
Wayne DeLange	Flagman
Max Ricketts	Truck Driver and Foreman

CERTIFICATE OF CADASTRAL ENGINEER

I, Donald E. Harding, HEREBY CERTIFY upon honor that, in pursuance of special instructions bearing date of the 6th day of February, 1957 I have ~~surveyed~~ ^{resurveyed} ~~independently~~ ^{dependently} resurveyed the south boundary and a portion of the subdivision of Township 8 South, Range 27 East

of the Gila & Salt River Meridian, in the State of Arizona, which are represented in the foregoing field notes as having been executed by me and under my direction; and that said survey has been made in strict conformity with said instructions, the Manual of Instructions for the Survey of the Public Lands of the United States, and in the specific manner described in the foregoing field notes.

Salt Lake City, Utah
August 16, 1957

Donald E. Harding
Donald E. Harding
Cadastral Surveyor

CERTIFICATE OF APPROVAL

BUREAU OF LAND MANAGEMENT,
Washington, D. C., JAN 21 1958, 19

The foregoing field notes of the ~~survey of~~ ^{survey of dependent} resurvey of the south boundary and a portion of the subdivision of Township 8 South, Range 27 East of the Gila and Salt River Meridian, in the State of Arizona.

executed by Donald E. Harding having been critically examined and found correct, are hereby approved.

Earl G. Hartman
Earl G. Hartman
Cadastral Engineering Staff Officer.

CERTIFICATE OF TRANSCRIPT

I CERTIFY that the foregoing transcript of the field notes of the above-described surveys in _____, is a true copy of the original field notes.

Cadastral Engineering Staff Officer.