Form 4-679 (January 1963)

BOOK 4700 UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FIELD NOTES

	DEPENDEN'	T RESURVEY	7	
	of	the		
S	outh, East and	d West Boun	daries	
		J		
	and	d the		***************************************
	Subdivis	ional Lines		,,, <u>, , , , , , , , , , , , , , , , , </u>
То	wnship 12 Sout	th, Range 2	9 East	+ + t
	744444444444444444444444444444444444444			
			MATERIO SALIDA DE LA CALLA CAL	
	C:1 1	Calle Discour		
				Meridian,
In the State of	ALI	120118		•
	EXE	CUTED B	Υ	
Pau	l G. Bauer, Sı	urveying Te	chnician	
Under special instructions dat	edJune 2	26	, 19 <u>62</u> , which pro	ovided for the surveys
included under Group Number.	378	, approved	June 26, 196	,
and assignment instructions dat	ed January I	16	., 19 <u>63</u> .	
Survey	commencedJ	January 15	, 19 <u>63</u>	

Survey completed _____February 7 ____, 19 63

	T	ownsh	12 <u>12</u>	Sou	th		, Range	29	East		,	
13	6	44	5	36	4	31	8	25	2	20	1	9
	43		43		36		30		25		19	
13	7	42	8	35	9	30	10	24	11	18	12	9
	42		41		35		29		24		18	
	18	41	17	34	16	29	15	23	14	17	13	8
	40		40		34		28		23		17	
	19	39	20	33	21	28	22	22	28	16	24	7
	39		39		33		27		22		16	
10	30	38	29	32	28	27	27	21	26	15	25	7
	37		37		32		26		21		15	
10	81	36	82	31	88	26	84	20	85	14	36	6
	5		4		4		3		3		2	

Township 12 South, Range 29 East, G&SRM, Arizona

CHAINS

The north boundary was surveyed in 1884 by L. Wolfley and dependently resurveyed in 1952 by C. E. Bilbray.

The south boundary was surveyed in 1883 by R. C. Powers, and dependent resurveyed in 1884 by L. Wolfley.

The east and west boundaries were surveyed in 1884 by L. Wolfley. The subdivisional lines were surveyed in 1885 by J. C. Smith.

This survey was executed in accordance with the specifications as set forth in the Manual of Surveying Instructions, 1947, and the Special Instructions dated June 26, 1962.

Only the true line bearings and horizontal distances for the surveyed lines are given in these notes. Unless described, each corner was monumented with a standard iron post, 30 inches long, $2\frac{1}{2}$ inches in diameter, flanged at the base and with a brass cap riveted to the top. The original corner monuments were deposited alongside the new monuments, unless described otherwise. All guard posts were fir posts, 4 inches square, 5 feet in length.

The geographic position of the southeast corner of the township is: Latitude, $32^{\circ}20'35.04"$ North and Longitude, $109^{\circ}19'47.52"$ West.

The magnetic declination was found to be 13°30' East.

Dependent Resurvey South Boundary, T12S, R29E, Arizona

Reestablishment of the Survey in 1883 by R. C. Powers

From the cor. of secs. 1, 6, 31 and 36, Ts12&13S, Rs29&30E, determined by proportionate measurement.

Set the iron post 18 ins. in the ground, cap mkd.

T12S R29E R30E S36 S31 S1 S6 T13S 1963

deposit glass and set a guard post.

from which

The cor. of secs. 4, 5, 32 and 33, Ts12&13S, R30E, monumented by a 3"x 4" pine post loosely set and plainly mkd., bears N. $89^{\circ}47'$ E., 158.52 chs. dist.

At the corner point

Set the iron post 24 ins. in the ground, cap mkd.

T	CHAINS	
-	1	T12S_R30E
	• .	S32 S33
		S 5 S 4 T 13S
		1963
		The cor. of secs. 13, 18, 19 and 24, T13S, Rs29&30E, monumented by a 4"x 4"x 30" precast
		cement post used by local surveyors and adjacent
		land owners, bears S. 0°22'30" W., 246.33 chs.
		dist., and is the best remaining evidence of the
		original corner.
		At the corner point
		Set the iron post 24 ins. in the ground, cap mkd.
		T13S
		R29E R30E
		<u>S13 S18</u> S24 S19
		1963
		deposit glass and set guard post.
		Thence
		N. 88°57' W., bet. secs. 1 and 36.
		Over nearly level land, through scattered creosote and grass.
	34.84	Small dam, bears NW. for 1.50 chs. and SE. for 2.00 chs.
	40.00	Point for the ½ sec. cor. of secs. 1 and 36, at proportionate distance; there is no remaining evidence of the original corner.
		Set the iron post 22 ins. in the ground, cap mkd.
		T12S R29E
		$\frac{1}{4} \frac{S \ 36}{S \ 1}$
		4 S 1 T13S
		1133
	74.16	Small wash, drains NE.
	22 01	D C the same of same 1 2 35 and 36 at pro-
	80.01	Point for the cor. of secs. 1, 2, 35 and 36, at proportionate distance; there is no remaining evidence of the original corner.
		Set the iron post 22 ins. in the ground, cap mkd.
		T12S R29E
		<u>\$35</u> \$36
		S 2 S 1 T13S
		1963
		set guard post.
		Land, nearly level.
		Soil, sandy loam.
		Timber, none; undergrowth, scattered creosote brush and grass.
T	-	

BOOK_4700

	C11 A 1217	Dependent Resurvey, S. Bdy., T12S, R29E, Arizona 3
	CHAINS	N. 88°57' W., bet. secs. 2 and 35.
		Over nearly level land, through medium dense creosote brush.
	3.94	Barbed wire fence, bears N. and S.
	40.00	Point for the $\frac{1}{4}$ sec. cor. of secs. 2 and 35, at proportionate distance; there is no remaining evidence of the original corner.
		Set the iron post 22 ins. in the ground, cap mkd.
		T12S R29E 2 S 35 S 2 T13S 1963
	80.01	Point for the corner of secs. 2, 3, 34 and 35, at proportionate distance; there is no remaining evidence of the original corner.
		Set the iron post 22 ins. in the ground, with a fir guard post alongside, cap mkd.
		T12S R29E S34 S35 S3 S2 T13S 1963
		from which
		New well, not in usable condition, bears N. 28°13' E., 7.82 chs. dist.
		Land, nearly level. Soil, sandy loam. Timber, none; undergrowth, medium dense creosote.
		N. 88°57' W., bet. secs. 3 and 34.
		Over nearly level land, through medium dense creosote brush, mesquite and grass.
	2.84	Old bladed road, bears N. and S.
	40.00	Point for the $\frac{1}{4}$ sec. cor. of secs. 3 and 34 at proportionate distance; there is no remaining evidence of the original corner.
		Set the iron post 22 ins. in the ground, cap mkd.
		T12S R29E
		T13S 1963
		deposit glass.
	80.01	Point for the cor. of secs. 3, 4, 33 and 34, at proportionate distance; there is no remaining evidence of the original corner.
1	- -	

Dependent	Resurvey.	. S.	Bdy.	T12S.	R29E.	Arizona

CHAINS	1
	Set the iron post 22 ins. in the ground, cap mkd.
	T12S R29E S33 S34 S4 S3 T13S R29E 1963
	set guard post.
	Land, nearly level. Soil, sandy. Timber, none; undergrowth, medium dense creosote brush, grass and weeds.
	N. 88°57' W., bet. secs. 4 and 33.
	Over nearly level land, through medium dense mesquite and creosote brush.
28.43	Dirt road, bears S. 10° E. and N. 10° W. for 1.00 chain, thence W.
40.00	Point for the ½ sec. cor. of secs. 4 and 33, at proportionate distance; there is no remaining evidence of the original corner.
	Set the iron post 24 ins. in the ground, cap mkd.
	T12S R29E 1/4 S 33 S 4 T13S 1963
46.14	Cor. of fences bearing S. and N. 88°57' W. bears S., 2.234 chs. dist.
79.35	Cor. of fences bearing N. and S. 88°57' W. bears S., 2.232 chs. dist.
80.01	Point for the cor. of secs. 4, 5, 32 and 33, at proportionate distance; there is no remaining evidence of the original corner.
	Set the iron post 22 ins. in the ground, cap mkd.
	T12S R29E S32 S33 S 5 S 4 T13S 1963
	deposit glass and set guard post.
	Land, nearly level. Soil, sandy. Timber, none; undergrowth, medium dense mesquite and creosote brush.
	N. 88°57' W., bet. secs. 5 and 32.
	Over nearly level land, through medium dense mesquite.
_	

	•	BOOK 4100
		Dependent Resurvey, S. Bdy., T12S, R29E, Arizona
	CHAINS	
	40.00	Point for the $\frac{1}{4}$ sec. cor. of secs. 5 and 32, at proportionate distance; there is no remaining evidence of the original corner.
		Set the iron post 22 ins. in the ground, cap mkd.
		T12S R29E
		½ S 32 S 5
		T13S
		1963
		Set a rock 5x6x10 inches alongside of corner.
-	80.01	Point for the cor. of secs. 5, 6, 31 and 32, at proportionate distance; there is no remaining evidence of the original corner.
		Set the iron post 22 ins. in the ground, cap mkd.
		TIOC DOOR
		T12S R29E S31 S32
		S 6 S 5
		T13S
		1963
		set guard post.
		Land, nearly level.
		Soil, sandy.
		Timber, medium dense mesquite.
		N. 88°57' W., bet. secs. 6 and 31.
		Over nearly level land, through medium dense mesquite.
	40.00	Point for the ½ sec. cor. of secs. 6 and 31, at proportionate distance; there is no remaining evidence of the original corner.
		Set the iron post 22 ins. in the ground, cap mkd.
		T12S R29E
		$\frac{1}{4} \frac{\text{S } 31}{\text{S } 6}$
		T13S
		1963
		deposit glass.
	78.01	The cor. of secs. 1, 6, 31 and 36, Ts12&13S, Rs28&29E, monumented by an iron pipe 2 ins. diam., projecting 4 ft. out of the ground, with pieces of the original corner alongside. This point is used locally and is accepted as the best remaining evidence of the original corner.
		At the corner point
	·	Set the iron post 26 ins. in the ground, cap mkd.
	•	1

		BOOK 4700
6		Dependent Resurvey, S. Bdy., T12S, R29E, Arizona 6
	CHAINS	T12S R28E R29E S36 S31 S 1 S 6 T13S 1963
		deposit glass and set guard post. Land, nearly level. Soil, sandy. Timber, none; undergrowth, creosote brush.
		Dependent Resurvey East Boundary, T12S, R29E, Arizona
		Reestablishment of the Survey in 1884 by L. Wolfly
		From the cor. of secs. 1, 6, 31 and 36, Ts12&13S, Rs29&30E.
		N. 0°02' W., bet. secs. 31 and 36.
		Over nearly level land, through scattered mesquite.
	7.40	Dirt roadway across dry bed of pond, bears E. and W.
	31.20	Evidence of old fence line, bears SE. and NW.
	41.05	Point for the ½ sec. cor. of secs. 31 and 36, at proportionate distance; there is no remaining evidence of the original corner.
		Set the iron post 22 ins. in the ground, cap mkd.
		T12S R29E R30E ¹ 4 S36 S31 1963
	79.06	Barbed wire fence, bears E. and W.
	82.10	Point for the cor. of secs. 25, 30, 31 and 36, at proportionate distance; there is no evidence of the original corner.
		Set the iron post 22 ins. in the ground, cap mkd.
		T12S R29E R30E S25 S30 S36 S31 1963
		from which
		West well, bears N. 71°16' W., 22.25 chs. dist.
		set guard post.

,		Dependent Resurvey, E. Bdy., T12S, R29E, Arizona 7
	CHAINS	(1) (1) (1) (1) (1) (1) (1) (1) (1) (1)
•		Land, nearly level. Soil, sandy. Timber, none; undergrowth, scattered mesquite, shadscale and cacti.
		N. 0°02' W., bet. secs. 25 and 30.
		Over nearly level land, through medium dense mesquite.
	7.00	Dirt road, bears S. 85° W. and N. 85° E.
	41.05	Point for the ½ sec. cor. of secs. 25 and 30, at proportionate distance; there is no remaining evidence of the original corner.
		Set the iron post 20 ins. in the ground, cap mkd.
		T12S R29E_R30E
		S25 S30 1963
	82.10	The cor. of secs. 19, 24, 25 and 30, monumented by a pine post 3 ft. long, 3"x 4", plainly mkd. and loosely set.
		At the corner point
		Set the iron post 22 ins. in the ground, cap mkd.
		T12S R29E R30E S24 S19 S25 S30 1963
		set guard post.
		Land, nearly level. Soil, sandy. Timber, none; undergrowth, medium dense mesquite and scattered creosote brush and shadscale.
		N. 0°37' E., bet. secs. 19 and 24.
		Over nearly level land, through scattered creosote brush and mesquite.
•	27.32	Barbed wire fence, bears E. and W.
	39.77	Point for the ½ sec. cor. of secs. 19 and 24 at proportionate distance; there is no remaining evidence of the original corner.
		Set the iron post 22 ins. in ground, cap mkd.
		T12S R29E R30E
		S24 S 19 1963
	-	

GYLATIVE	
79.54	Point for the cor. of secs. 13, 18, 19 and 24, at proportionate distance; there is no remaining evidence of the original corner.
	Set the iron post 22 ins. in ground, cap mkd.
	T12S R29E R30E S13 S18 S24 S19 1963
	set guard post.
	Land, nearly level. Soil, sandy. Timber, none; undergrowth, scattered creosote brush and medium dense mesquite and shadscale.
	N. 0°37' E., bet. secs. 13 and 18.
	Over nearly level land, through medium dense mesquite and shadscale.
23.68	Left bank of San Simon Creek, bears N. 44° W. and S. 44° E.
26.58	Right bank of San Simon Creek, bears N. 44° W. and S. 44° E.
39.77	Point for the $\frac{1}{4}$ sec. cor. of secs. 13 and 18, at proportionate distance; there is no remaining evidence of the original corner.
	Set the iron post 22 ins. in the ground, cap mkd.
	T12S R29E R30E \$13 S18 1963
53.68	Dirt road, bears S. 50° E. and N. 50° W.
79.54	Point for the cor. of secs. 7, 12, 13 and 18, at proportionate distance; there is no remaining evidence of the original corner.
	Set the iron post 22 ins. in ground, cap mkd.
	T12S R29E R30E S12 S 7 S13 S18 1963
	from which
	The most northerly one of the two Coyote Wells bears N. 56°17' W., 57.66 chs. dist. Note: Not usable.
	set guard post.

	Dependent Resurvey, E. Bdy., T12S, R29E, Arizona
CHAINS	
	Land, nearly level, with some sand dunes. Soil, sandy. Timber, none; undergrowth, medium dense mesquite and creosote brush.
	N. 0°37' E., bet. secs. 7 and 12.
	Over nearly level land through bunch grass.
39.77	Point for the ½ sec. cor. of secs. 7 and 12, at proportionate distance; there is no remaining evidence of the original corner.
	Set the iron post 22 ins. in the ground, cap mkd.
	T12S R29E_R30E
	S 12 S 7 1963
79.54	The cor. of secs. 1, 6, 7 and 12, monumented by an iron post $2\frac{1}{2}$ ins. diam., mkd. and witnessed as described in the official record.
	The cor. is located at cor. of fences bearing E., W. and N.
	Land, nearly level. Soil, sandy. Timber, none; undergrowth, bunch grass.
	N. 0°40' W., bet. secs. 1 and 6.
	Over nearly level land, covered with bunch grass.
34.14	Wash, 1 ft. deep, 50 lks. wide, drains NW. into San Simon Creek.
40.42	Point for the ½ sec. cor. of secs. 1 and 6, at proportionate distance; there is no remaining evidence of the original corner.
	Set the iron post 22 ins. in ground, cap mkd.
	T12S R29E R30E
	S 1 S 6
	1963
	deposit glass.
80.84	The cor. of secs. 1, 6, 31 and 36, Ts. 11 and 12 S., Rs. 29 and 30 E., monumented by an iron post, $2\frac{1}{2}$ ins. diam., mkd. and witnessed as described in the official record.
	from which
	A dyke on the NE edge of a catch pond bears S. 53° W., 4.10 chs. dist.
1	

		Dependent Resurvey, w. bdy., 1125, R29E, Arizona	10
•	CHAINS	Land, nearly level. Soil, sandy. Timber, none; undergrowth, bunch grass.	
		Dependent Resurvey West Boundary, T12S, R29E, Arizona	
		Reestablishment of the Survey in 1884 by L. Wolfly	
		From the cor. of secs. 1, 6, 31 and 36, Ts12&13S, Rs28&29E	
		N. 0°11' E., bet. secs. 31 and 36.	
		Over nearly level land, through medium dense mesquite, grass and scattered yucca.	
	40.41	Point for the ½ sec. cor. of secs. 31 and 36, at proportionate distance; there is no remaining evidence of the original corner.	
		Set the iron post 22 ins. in the ground, cap mkd.	
		T12S R28E R 29E	
		\$36 S31	
		1963	
	79.30	Fence, barbed wire, bears W. and 0.284 chs. E. to cor. of fences bearing E., W. and N.	
	80.82	Point for the cor. of secs. 25, 30, 31 and 36, at proportional distance; there is no remaining evidence of the original corner.	
		Set the iron post 24 ins. in the ground, cap mkd.	
		T12S R28E R29E	
		S25 S30	
		S36 S31 1963	
		set guard post.	
		Land, nearly level. Soil, sandy. Timber, none; undergrowth, mesquite, scattered creosote brush, yucca and grass.	
		N. 0°11' E., bet. secs. 25 and 30.	
		Over nearly level land, through medium dense creosote brush.	
	.88	Dirt roadway bears W. and N.	
	2.18	Dry canal bears E. and W.	
	2.68	Cor. of cultivated field, bears W. and N.	
\dashv			

		Dependent Resurvey, W. Bdy., T12S, R29E, Arizona 11.
	40.41	Point for the ½ sec. cor. of secs. 25 and 30, at proportionate distance; there is no remaining evidence of the original corner.
		Set the iron post 28 ins. in the ground, cap mkd.
		T12S R28E R29E
		\$25 \$30 1963
		from which
		A N. and S. fence line bears 14.5 lks. E.
		set a guard stake.
	80.32	Corner of barbed wire fences bearing S. and W.
	80.82	The cor. of secs. 19,24, 25 and 30, monumented by a 4"x 4"x 30" precast cement post with pieces of old original corner alongside. This corner used by local surveyors and adjacent land owners, and is the best remaining evidence of the original corner.
		At the corner point
		Set the iron post 22 ins. in the ground, cap mkd.
		T12S R28E R29E S24 S19 S25 S30 1963
		bury the 4"x 4" cement alongside the iron post and set guard stake.
		Land, nearly level. Soil, sandy loam. Timber, none; undergrowth, medium dense creosote brush.
		N. 0°25' E., bet. secs. 19 and 24.
		Over nearly level land, through medium dense creosote brush and mesquite.
	34.90	Dirt road, bears N. 25° W. and S. 30° E.
	40.35	Point for the ½ sec. cor. of secs. 19 and 24, at proportionate distance; there is no remaining evidence of the original corner.
		Set the iron post 22 ins. in the ground, cap mkd.
		T12S R28E R29E
		S24 S 19 1963
		deposit glass at base of iron post.
•		
~	1	

1963

CHAINS	Dependent Resurvey, W. Bdy., T12S, R29E, Arizona	T	
	Successible to		
	from which	1	
	A N. and S. fence bears E., 1.17 chs. dist.		
	set guard post.		
	Land, nearly level. Soil, sandy and sandy loam. Timber, none; undergrowth, mesquite, creosote brush and scattered yucca and cacti.		
	7 and 12		
	N. 0°25' E., bet. secs. 7 and 12.		
	Over nearly level land, through medium dense mesquite and grass.		
19.86	Fence, barbed wire, bears E. and W.		
40.35	Point for the $\frac{1}{4}$ sec. cor. of secs. 7 and 12, at proportionate distance; there is no remaining evidence of the original corner.		
	Set the iron post 22 ins. in the ground, cap mkd.		
	T12S		
	R28E R29E		
	S12 S7 1963		
	from which		
	A N. and S. fence line bears E., 1.11 chs. dist.		
80.70	Point for the cor. of secs. 1, 6, 7 and 12, at proportionate distance; there is no remaining evidence of the original corner.		
	Set the iron post 22 ins. in the ground, cap mkd.		
	T12S R28E R29E S1 S6 S12 S7 1963		
	set guard post.		
	Land, level. Soil, sandy. Timber, none; undergrowth, mesquite and scattered creosote brush and yucca.		
	N. 0°25' E., bet. secs. 1 and 6.		
	Over nearly level land, through medium dense creosote brush and mesquite.		
40.35	Point for the ½ sec. cor. of secs. 1 and 6, at proportionate distance; there is no remaining evidence		

		Dependent Resurvey, W. Bdy., T12S, R29E, Arizona
	CHAINS	
	,	Set the iron post 22 ins. in the ground, cap mkd.
l		T12S R28E R29E
		· · · · · · · · · · · · · · · · · · ·
		S 1 S 6 1963
		from which
		A N. and S. fence line bears W., 0:02 chs. dist.
		deposit glass and set guard post.
	80.70	The cor. of secs. 1, 6, 31 and 36, Ts. 11 and 12 S., Rs. 28 and 29 E., monumented by an iron pipe $2\frac{1}{2}$ ins. diam., set, mkd. and witnessed as described in the official record.
l		Land, nearly level.
		Soil, sandy. Timber, none; undergrowth, mesquite and medium dense creosote brush.
		Dependent Resurvey of the Subdivisions Township 12 South, Range 29 East, Arizona
		Reestablishment of the Survey in 1885 by J. C. Smith
		Beginning at the cor. of secs. 1, 2, 35 and 36, on the S. bdy. of the township.
		N. 0°08' W., bet. secs. 35 and 36.
		Over nearly level land, through scattered mesquite and grass.
	40.31	Point for the $\frac{1}{4}$ sec. cor. of secs. 35 and 36, at proportionate distance; there is no remaining evidence of the original corner.
		Set the iron post 22 ins. in ground, cap mkd.
		T12S, R29E
		s35 s36 1963
		deposit glass.
	55.20	Barbed wire fence, bears N. 80° E. and S. 80° W.
	80.62	Point for the cor. of secs. 25, 26, 35 and 36, at proportionate distance; there is no remaining evidence of the original corner.
		Set the iron post 24 ins. in the ground, cap mkd.
	-	T12S R29E <u>S26 S25</u> S35 S36 1963

set guard post.

Dependent	Resurvey.	Subdivisions,	T12S.	R29E.	Arizona

		Dependent Resurvey, Subdivisions, T12S, R29E, Arizona	15.
•	CHAINS	Land, nearly level. Soil, sandy. Timber, none; undergrowth, mesquite and yucca.	
		From the cor. of secs. 25, 30, 31 and 36, on the E. bdy. of the township.	
		S. 89°59' W., bet. secs. 25 and 36.	
		Over nearly level land, through scattered creosote brush.	
	14.90	Fence (E. side of corral), bears N. 02° W. and S. 02° E.	
·	19.70	Fence, barbed wire, bears N. and S.	
	20.80	Fence, net and barbed wire, bears N. 15° W. and S. 15° E.	
	22.00	Fence, net and barbed wire, bears N. and S. (W. side of corral)	
	35.65	Dry creek bed, 15 lks. wide, 2 ft. deep, drains N. 10° E. for 2.60 chs., then NE.	
	40.07	Point for the ½ sec. cor. of secs. 25 and 36, at proportionate distance; there is no remaining evidence of the original corner.	
		Set the iron post 22 ins. in the ground, cap mkd.	
		T12S R29E 1/4 S 25 1/5 36 1963	
	80.13	The cor. of secs. 25, 26, 35 and 36.	
		Land, nearly level. Soil, sandy. Timber, none; undergrowth, medium dense creosote brush.	
· · · · · · · · · · · · · · · · · · ·		N. 0°05' E., bet. secs. 25 and 26.	
•		Over nearly level land, through medium dense creosote brush.	
	40.31	Point for the $\frac{1}{4}$ sec. cor. of secs. 25 and 26, at proportionate distance; there is no remaining evidence of the original corner.	
		Set the iron post 22 ins. in the ground, cap mkd.	
		T12S R29E	
		S26 (S25 1963	
	48.88	Dirt road, bears N. 51° W. and S. 51° E.	
_	80.62	Point for the cor. of secs. 23, 24, 25 and 26, at proportionate distance; there is no remaining evidence of the original corner.	

		BOOK 4700
6		Dependent Resurvey, Subdivisions, T12S, R29E, Arizona 16.
	CHAINS	Set the iron post 22 ins. in the ground, cap mkd.
		T12S R29E S23 S24 S26 S25 1963
		set guard post.
		Land, nearly level. Soil, sandy. Timber, none; undergrowth, medium dense creosote half way and scattered creosote half way.
		From the cor. of secs. 19, 24, 25 and 30, on the E. bdy. of the township.
		S. 88°56' W., bet. secs. 24 and 25.
		Over nearly level land, through mesquite and creosote brush.
	24.20	Gully, 8 ft. deep, 1 chain wide, drains N. 45° E.
	40.00	Point for the ½ sec. cor. of secs. 24 and 25, at proportionate distance; there is no remaining evidence of the original corner.
		Set the iron post 22 ins. in the ground, cap mkd.
		T12S R29E 2 S 24 S 25 1963
	80.00	The cor. of secs. 23, 24, 25 and 26.
		Land, nearly level. Soil, sandy, sandy loam. Timber, none; undergrowth, creosote brush, scrub mesquite and weeds.
		N. 0°33' E., bet. secs. 23 and 24.
	1	Over a seel a lovel land, through controred crossets

Over nearly level land, through scattered creosote brush and grass.

23.66 Fence, barbed wire, bears E. and W.

Point for the ½ sec. cor. of secs. 23 and 24, at proportionate distance; there is no remaining evidence of the original corner.

Set the iron post 22 ins. in the ground, cap mkd.

T12S R29E

\$23 | S24

1963

75.96 | Remains of old fence, bears E. and W.

80.62

Point for the cor. of secs. 13, 14, 23 and 24, at proportionate distance; there is no remaining evidence of the original corner.

CHAINS	Dependent Resurvey, Subdivisions, T12S, R29E, Arizona
	Set the iron post 22 ins. in the ground, cap mkd.
	T12S R29E <u>\$14 \$13</u> \$23 \$24 1963
	set guard post.
·	Land, nearly level. Soil, sandy. Timber, none; undergrowth, medium dense creosote brush and grass.
	From the cor. of secs. 13, 18, 19 and 24, on the E. bdy. of the township.
	N. 89°44' W., bet. secs. 13 and 24.
	Over nearly level land, through scattered mesquite and creosote brush, also grass.
35.90	Gully, 6 ft. deep, 70 lks. wide, drains N. 15° E.
40.02	Point for the ½ sec. cor. of secs. 13 and 24, at proportionate distance; there is no remaining evidence of the original corner.
	Set the iron post 22 ins. in the ground, cap mkd.
	T12S R29E 2 S 13 S 24 1963
64.40	Dike, bears N. 10° W. and S. 10° E.
80.03	The cor. of secs. 13, 14, 23 and 24.
	Land, nearly level. Soil, sandy. Timber, scattered mesquite; undergrowth, creosote brush.
	N. 0°40' E., bet. secs. 13 and 14.
	Over nearly level land, through medium dense creosote brush.
7.84	Dim dirt road, bears S. 65° W., and N. 65° E.
40.31	Point for the ½ sec. cor. of secs. 13 and 14, at proportionate distance; there is no remaining evidence of the original corner.
	Set the iron post 22 ins. in the ground, cap mkd.
	T12S_R29E
	S14 S13 1963
40.34	Wash, 1 ft. deep, 10 lks. wide, drains N. 80° E.
1	Point for the cor. of secs. 11, 12, 13 and 14, at

		≥ BOOK4700				
		Dependent Resurvey, Subdivisions, T12S, R29E, Arizona 18.				
	CHAINS	Set the iron post 22 ins. in the ground, cap mkd.				
		T12S R29E <u>\$11 \$12</u> <u>\$14 \$13</u> 1963				
		from which				
		The most southerly of the two Coyote Wells bears N. 49º20' E., 21.87 chs. dist. This well is not being used.				
		set guard post.				
		Land, nearly level. Soil, sandy. Timber, none; undergrowth, medium dense creosote brush.				
		From the cor. of secs. 7, 12, 13 and 18, on the E. bdy. of the township.				
		N. 89°28' W., bet. sec. 12 and 13.				
		Over nearly level land, through scattered creosote, scrub mesquite, and salt cedar.				
	23.42	Road, bears S. 30° E. and N. 35° W.				
	31.15	Wash, 20 1ks. wide, 1 ft. deep, drains N. 45° W., from S. 20° E.				
	40.00	Point for the ½ sec. cor. of secs. 12 and 13, at proportionate distance; there is no remaining evidence of the original corner.				
		Set the iron post 22 ins. in the ground, cap mkd.				
		T12S R29E 1/4 S 12 S 13 1963				
l	42.25	Wash, 1 ft. deep, 15 lks. wide, drains N. 30° W.				
	48.20	San Simon Creek, 1.00 chain wide, 3 ft. deep, drains N. 45° W. from S. 20° E.				
	80.00	The cor. of secs. 11, 12, 13 and 14.				
		Land, nearly level. Soil, sandy. Timber, medium dense salt cedar; undergrowth, creosote brush and scrub mesquite.				
		N. 0°29' E., bet. secs. 11 and 12.				
		Over nearly level land, through scattered mesquite and creosote brush, ground covered with grass.				
	18.62	Wash, 50 lks. wide, 1 ft. deep, drains N. 80° E. into San Simon Creek.				
+	40.31	Point for the ½ sec. cor. of secs. 11 and 12, at proportionate distance; there is no remaining evidence of the original corner.				

Dependent	Resurvey,	Subdivisions,	T12S,	R29E,	Arizona	19

		Dependent Resulter, Bushivisions, 1123, 1121, 1121
	CHAINS	
		Set the iron post 22 ins. in the ground, cap mkd.
		T12S_S29E
		S11 S12
		1963
	75.40	About the center of San Simon Creek. Note: Right and left banks cannot be determined.
	80.62	Point for the cor. of secs. 1, 2, 11 and 12, at proportionate distance; there is no remaining evidence of the original corner.
		Set the iron post 22 ins. in the ground, cap mkd.
		T12S R29E S2 S1 S11 S12 1963
		set guard stake.
		Land, nearly level. Soil, sandy and sandy loam. Timber, none; undergrowth, mesquite, scattered creosote brush and grass cover.
		From the cor. of secs. 1, 6, 7 and 12, on the E. bdy. of the township.
		N. 88°41' W., bet. secs. 1 and 12.
		Over nearly level land, through medium grass.
	3.00	Fence, barbed wire, bears N. 87° W., and E.
	13.20	Bladed road, bears irregularly E. and W. (Road meanders along line for next 27 chs.)
	39.10	Same bladed road, bears easterly and S. 45° W.
	40.08	Point for the ½ sec. cor. of secs. 1 and 12, at proportionate distance; there is no remaining evidence of the original corner.
		Set the iron post 22 ins. in the ground, cap mkd.
		T12S R29E
		½ S 1 S 12
	·	1963
	65.65	Wash, 15 lks. wide, 1 ft. deep, drains S. 60° W.
	69.50	Bladed road, bears S. 17° E. and N. 17° W. for 2 chs. to gate, then N.
	80.16	The cor. of secs. 1, 2, 11 and 12.
		Land, nearly level. Soil, sandy. Timber, scattered salt cedar; undergrowth, scrub mesquite and grass.
-	_	
		1

Dependent	Resurvey,	Subdivisions,	T12S.	R29E.	Arizona	20.

	CHAINS						
•		N. 0°35' W., bet. secs. 1 and 2.					
		Over nearly level land, through scattered salt cedar.					
	2.10	Fence, barbed wire, bears S. 88° E., and N. 88° W.					
	20.70	Dirt road, bears E. and W.					
	40.31	Point for the $\frac{1}{4}$ sec. cor. of secs. 1 and 2, at proportionate distance; there is no remaining evidence of the original corner.					
		Set the iron post 22 ins. in the ground, cap mkd.					
		T12S ₁ R29E					
		S 2 S 1 1963					
	56.20	Enter medium dense growth of mesquite.					
	80.55	The cor. of secs. 1, 2, 35 and 36, on the N. bdy. of the township, monumented by an iron post $2\frac{1}{2}$ ins. diam., set, mkd. and witnessed as described in the official record.					
		Land, nearly level. Soil, sandy. Timber, scattered cedar; undergrowth, scrub mesquite.					
		From the cor. of secs. 2, 3, 34 and 35, on the S. bdy. of the township.					
		0°12' W., bet. secs. 34 and 35.					
		Over nearly level land, through medium growth of creosote brush.					
	40.32	Point for the $\frac{1}{4}$ sec. cor. of secs. 34 and 35, at proportionate distance; there is no remaining evidence of the original corner.					
ĺ		Set the iron post 22 ins. in the ground, cap mkd.					
		T12S R29E					
		\$34 S35 1963					
		deposit glass.					
	80.64	Point for the cor. of secs. 26, 27, 34 and 35, at proportionate distance; there is no remaining evidence of the original corner.					
		Set the iron post 22 ins. in the ground, cap mkd.					
		T12S R29E <u>S27 S26</u> S34 S35 1963					
		set guard post.					

Dependent Resurvey	, Subdivisions,	T12S,	R29E,	Arizona	21
--------------------	-----------------	-------	-------	---------	----

CHAINS	Land, nearly level. Soil, sandy. Timber, none; undergrowth, creosote brush.
	Timber, mone, andergrowth, ordered brands
	From the cor. of secs. 25, 26, 35 and 36.
	N. 88°55' W., bet. secs. 26 and 35.
	Over nearly level land, through medium dense creosote brush.
40.03	Point for the ½ sec. cor. of secs. 26 and 35, at proportionate distance; there is no remaining evidence of the original corner.
	Set the iron post 22 ins. in the ground, cap mkd.
	T12S R29E 1/4 S 26 S 35
	1963
80.07	The cor. of secs. 26, 27, 34 and 35.
	Land, nearly level. Soil, sandy loam.
	Timber, none; undergrowth, scattered creosote brush and grass.
	N 00101 F hat goes 26 and 27
	N. 0°10' E., bet. secs. 26 and 27.
	Over nearly level land, through scattered creosote brush.
40.32	Point for the ½ sec. cor. of secs. 26 and 27, at proportionate distance; there is no remaining evidence of the original corner.
	Set the iron post 22 ins. in the ground, cap mkd.
	T12S R29E
	S27 ∫S26 1963
80.64	Point for the cor. of secs. 22, 23, 26 and 27, at proportionate distance; there is no remaining evidence of the original corner.
	Set the iron post 22 ins. in the ground, cap mkd.
	T12S R29E S22 S23
	S27 S26 1963
	set guard post.
	Land, nearly level.
	Soil, sandy. Timber, none; undergrowth, scattered creosote brush.
ī	I

Dependent R	Resurvey,	Subdivisions,	T12S,	R29E,	Arizona	22.
-------------	-----------	---------------	-------	-------	---------	-----

-		i i i i i i i i i i i i i i i i i i i
	CHAINS	From the cor. of secs. 23, 24, 25 and 26.
		N. 88°55' W., bet. secs. 23 and 26.
		Over nearly level land, covered with grass, with scattered creosote brush.
	39.96	Point for the ½ sec. cor. of secs. 23 and 26, at proportionate distance; there is no remaining evidence of the original corner.
		Set the iron post 22 ins. in the ground, cap mkd.
		T12S R29E \[\frac{1}{4} \frac{\text{S 23}}{\text{S 26}} \\
	51.32	Track road, bears S. 58° E. and N. 58° W.
	79.92	The cor. of secs. 22, 23, 26 and 27.
		Land, nearly level. Soil, sandy loam. Timber, none; undergrowth of grasses and scattered creosote brush.
		N. 0°30' E., bet. secs. 22 and 23.
		Over nearly level land, through scattered creosote brush.
	22.00	Fence, barbed wire, bears E. and W.
	22.30	Junction of roads bearing N. 0°35' E., S. 58°30' E., S. 0°35' W. and N. 58°30' W.
	40.32	Point for the $\frac{1}{2}$ sec. cor. of secs. 22 and 23, at proportionate distance; there is no remaining evidence of the original corner.
		Set the iron post 22 ins. in the ground, cap mkd.
		T12S R29E
	**	\$22 \(\frac{1}{5} \) \$23 1963
	80.64	Point for the cor. of secs. 14, 15, 22 and 23, at proportionate distance; there is no remaining evidence of the original corner.
		Set the iron post 22 ins. in the ground, cap mkd.
		T12S R29E <u>S15 S14</u> S22 S23 1963
		set guard post.
		Land, nearly level. Soil, sandy and sandy loam. Timber, none; undergrowth, mesquite and scattered creosote brush, also grass.
Γ		

1 00040000	Dependent Resurvey, Subdivisions, T12S, R29E, Arizona
CHAINS	From the cor. of secs. 13, 14, 23 and 24.
	N. 88°54' W., bet. secs. 14 and 23.
	Over nearly level land, through medium dense creosote brush.
39.98	Point for the $\frac{1}{4}$ sec. cor. of secs. 14 and 23, at proportionate distance; there is no remaining evidence of the original corner.
	Set the iron post 22 ins. in the ground, cap mkd.
	T12S_R29E
	$\frac{1}{4} \frac{S}{S} \frac{14}{23}$ 1963
69.43	Dirt road, bears N. 74°20' E. and S. 24°20' W.
79.03	Dirt road, bears N. and S.
79.96	The cor. of secs. 14, 15, 22 and 23.
	Land, nearly level. Soil, sandy and sandy loam. Timber, scattered mesquite; undergrowth, grass and creosote brush.
	N. 0°42' E., bet. secs. 14 and 15.
	Over nearly level land, through medium dense creosote brush, scattered mesquite and grass.
40.32	Point for the ½ sec. cor. of secs. 14 and 15, at proportionate distance; there is no remaining evidence of the original corner.
	Set the iron post 22 ins. in the ground, cap mkd.
	T12S R29E
	S15 S14 1963
49.04	Drift fence, bears E. and W.
52.74	Drift fence, bears SW. and NE.
80.64	Point for the cor. of secs. 10, 11, 14 and 15, at proportionate distance; there is no remaining evidence of the original corner.
	Set the iron post 22 ins. in the ground, cap mkd.
	T12S R29E S10 S11 S15 S14 1963
	set guard post.
	Land, nearly level. Soil, sandy. Timber, none; undergrowth, mesquite and scattered

	Dependent Resurvey, Subdivisions, T12S, R29E, Arizona	24.
S	From the cor. of secs. 11, 12, 13 and 14.	
	N 00050 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	

· 	bependent Resulvey, Subdivisions, 1125, R29E, Alizona
CHAINS	From the cor. of secs. 11, 12, 13 and 14.
	N. 88°53' W., bet. secs. 11 and 14.
	Over nearly level land, through medium dense creosote brush and grass.
8.39	Gully, 1.10 chs. wide, with 15 ft. banks, drains N. 30° E.
39.94	Point for the ½ sec. cor. of secs. 11 and 14, at proportionate distance; there is no remaining evidence of the original corner.
	Set the iron post 22 ins. in the ground, cap mkd.
	T12S R29E \[\frac{1}{4} \frac{S}{S} \frac{11}{14} \\ 1963
43.74	Head of gully, 1.00 chain wide, 10 ft. deep, drains NE.
78.40	Road, bears N. and S.
79.89	The cor. of secs. 10, 11, 14 and 15.
	Land, nearly level. Soil, sandy. Timber, none; undergrowth creosote brush and grass.
	N. 0°18' E., bet. secs. 10 and 11.
	Over nearly level land, through medium dense creosote brush.
40.32	Point for the ½ sec. cor. of secs. 10 and 11, at proportionate distance; there is no remaining evidence of the original corner.
	Set the iron post 22 ins. in the ground, cap mkd.
	T12S R29E
	\$10 \$11 1963
46.00	Dirt road bears E. and W.
61.40	Dirt road bears E. and W.
72.20	Small wash, 1 ft. deep, .05 lks. wide, drains N. 60° E.
80.64 .	Point for the cor. of secs. 2, 3, 10 and 11, at proportionate distance; there is no remaining evidence of the original corner.
	Set the iron post 22 ins. in the ground, cap mkd.
	T12S R29E S3 S2 S10 S11 1963
	set guard post.

BOOK_4700

 CHAINS	Dependent Resurvey, Subdivisions, T12S, R29E, Arizona 25.
CHAINS	Land, nearly level.
	Soil, sandy.
	Timber, none; undergrowth, medium dense creosote brush.
	From the cor. of secs. 1, 2, 11 and 12.
	N. 88°54' W., bet. secs. 2 and 11.
	Over San Simon Wash bottom, through medium salt cedar and creosote brush.
20.80	Water sump, 20 1ks. wide, 5 ft. deep, dug on a N. 30° E. and S. 30° W. axis.
40.04	Point for the ½ sec. cor. of secs. 2 and 11, at proportionate distance; there is no remaining evidence of the original corner.
	Set the iron post 22 ins. in the ground, cap mkd.
	T12S R29E
	$\frac{1}{4}$ $\frac{S}{S}$ $\frac{2}{11}$
	1963
	from which
	A cor. of fences bearing E. and N. 65° W. bears N., 1.42 chs. dist.
46.60	Wash, 15 1ks. wide, 1 ft. deep, drains NE.
64.89	Wash, 15 lks. wide, 1 ft. deep, drains NE.
72.69	Gully, 25 lks. wide, 5 ft. deep, drains NE., and bladed road bears E. and W.
79.22	Graveled road, bears S. 02° E. and N. 02° W.
80.09	The cor. of secs. 2, 3, 10 and 11.
	Land, nearly level.
	Soil, sandy. Timber, salt cedar; undergrowth, creosote, scrub
	mesquite and grass.
	N. 0°34' W., bet. secs. 2 and 3.
	Over nearly level land, through medium dense creosote.
14.87	Dirt road, bears E. and W.
20.37	Gully, 25 lks. wide, with 9 ft. banks, drains N. 45° E.
21.87	Dirt road, bears N. S. and S. 80° W.
40.32	Point for the 4 sec. cor. of secs. 2 and 3, at pro-
	portionate distance; there is no remaining evidence of the original corner.
	Set the iron post 22 ins. in the ground, cap mkd.
	T12S_R29E
+	S 3 S 2
ł	1963

Dependent	Resurvey	Subdivisions,	T12S	R29E	Arizona	26
Dependent	Resurvey,	Subulvisions,	1120,	NZJE,	ALIZONA	20.

CHAINS	
79.40	Bladed road, bears E. and W.
80.22	Fence, barbed wire, bears E. and W.
80.68	The cor. of secs. 2, 3, 34 and 35, on the N. bdy. of the township, monumented by an iron post $2\frac{1}{2}$ ins. diam., set, mkd. and witnessed as described in the official record.
	From the cor. of secs. 3, 4, 33 and 34, on the S. bdy. of the township.
	N. 0°12' W., bet. secs. 33 and 34.
	Over nearly level land, through scattered mesquite and creosote brush.
40.31	Point for the ½ sec. cor. of secs. 33 and 34, at proportionate distance; there is no remaining evidence of the original corner.
	Set the iron post 22 ins. in the ground, cap mkd.
	T12S_R29E
	\$33 \big \$34 1963
80.63	Point for the cor. of secs. 27, 28, 33 and 34, at proportionate distance; there is no remaining evidence of the original corner.
	Set the iron post 22 ins. in the ground, cap mkd.
	T12S R29E <u>S28 S27</u> <u>S33 S34</u> 1963
	set guard post.
	Land, nearly level. Soil, sandy. Timber, none; undergrowth, mesquite and creosote brush.
	From the cor. of secs. 26, 27, 34 and 35.
	N. 89°00' W., bet. secs. 27 and 34.
	Over nearly level land covered with grasses and weeds.
1.11	Gravel road, bears N. 02° E. and S. 02°30' W.
39.99	Point for the ½ sec. cor. of secs. 27 and 34, at proportionate distance; there is no remaining evidence of the original corner.
	Set the iron post 22 ins. in the ground, cap mkd.
	T12S R29E 2 S 27 S 34 1963
<u> </u>	I

	BOOK 4700
	Dependent Resurvey, Subdivisions, T12S, R29E, Arizona 27.
CHAIN	S
79.98	The cor. of secs. 27, 28, 33 and 34.
	Land, nearly level.
	Soil, sandy loam. Timber, none; undergrowth, medium dense creosote
	brush.
	N. 0°16' E., bet. secs. 27 and 28.
	Over nearly level land, through medium dense creosote brush.
40.31	Point for the 1/4 sec. cor. of secs. 27 and 28, at proportionate distance; there is no remaining evidence of the original corner.
	Set the iron post 22 ins. in the ground, cap mkd.
	T12S R29E
	\$28 \$27 1963
	1963
80.63	Point for the cor. of secs. 21, 22,27 and 28, at proportionate distance; there is no remaining evidence of the original corner.
	Set the iron post 22 ins. in the ground, cap mkd.
	T12S_R29E
	<u>S21 S22</u> S28 S27
	1963
	set guard post.
	Land, nearly level.
	Soil, sandy. Timber, none; undergrowth, medium dense creosote
	brush.
	From the cor. of secs. 22, 23, 26 and 27.
	N. 89°00' W., bet. secs. 22 and 27.
	Over nearly level land, through scattered creosote brush and grass cover.
0.3	Track road, bears N. 02°30' E. and S. 02°30' W.
39.93	Point for the ½ sec. cor. of secs. 22 and 27, at proportionate distance; there is no remaining evidence of the original corner.
	Set the iron post 22 ins. in the ground, cap mkd.
	T12S R29E
	$\frac{1}{4} \frac{S}{S} \frac{22}{27}$
	1963
79.80	The cor. of secs. 21, 22, 27 and 28.
/9.00	Inc cor. or sees. 21, 22, 2. and 201
I	

			*	
Dependent Resurvey,	Subdivisions,	T12S,	R29E, Arizona	28.

	Dependent Resurvey, Subdivisions, 1125, R29E, Arizona 20	٥.					
CHAINS	Land, nearly level. Soil, sandy. Timber, none; undergrowth, medium dense creosote brush.						
:	N. 0°29' E., bet. secs. 21 and 22.						
	Over nearly level land, through medium dense creosote brush.						
20.24	Fence, barbed wire, bears N. 79°30' W., and S. 79°30' E.						
40.32	Point for the ½ sec. cor. of secs. 21 and 22, at proportionate distance; there is no remaining evidence of the original corner.						
	Set the iron post 22 ins. in the ground, cap mkd.						
	T12S R29E						
	S21 S22 1963						
72.42	Dirt road bears S. 57°30' E. and N. 57°30' W.						
77.82	Wash, 10 lks. wide, 3 ft. deep, drains irregularly E.						
80.63	Point for the cor. of secs. 15, 16, 21 and 22, at proportionate distance; there is no remaining evidence of the original corner.						
	Set the iron post 22 ins. in the ground, cap mkd.						
	T12S R29E S16 S15 S21 S22 1963						
	set guard post.						
	Land, nearly level. Soil, sandy loam. Timber, none; undergrowth, medium dense creosote brush.						
	From the cor. of secs. 14, 15, 22 and 23.						
	N. 89°02' W., bet. secs. 15 and 22.						
	Over nearly level land, through medium dense creosote brush and scattered mesquite.						
39.94	Point for the ½ sec. cor. of secs. 15 and 22, at proportionate distance; there is no remaining evidence of the original corner.						
	Set the iron post 22 ins. in the ground, cap mkd.						
	T12S R29E $ \frac{1}{4} = \frac{S}{S} = \frac{15}{1963} $ 1963						
71.40	Wash, 10 1ks. wide, 1 ft. deep, drains N. 45° E.						
_ 79.88	The cor. of secs. 15, 16, 21 and 22.						

Dependent	Resurvey,	Subdivisions,	T12S,	R29E,	Arizona	29

	CHAINS	Land, nearly level. Soil, sandy loam. Timber, scattered mesquite; undergrowth, creosote brush and grass.					
		N. 0°29' E., bet. secs. 15 and 16.					
		Over nearly level land, through medium dense creosote.					
	40.31	Point for the $\frac{1}{4}$ sec. cor. of secs. 15 and 16, at proportionate distance; there is no remaining evidence of the original corner.					
		Set the iron post 22 ins. in the ground, cap mkd.					
		T12S R29E					
		S 16 S 15 1963					
	80.63	Point for the cor. of secs. 9, 10, 15 and 16, at proportionate distance; there is no remaining evidence of the original corner.					
		Set the iron post 22 ins. in the ground, cap mkd.					
		T12S R29E					
		S 9 S 10 S 16 S 15					
		1963					
		set guard post.					
		Land, nearly level. Soil, sandy. Timber, none; undergrowth, medium dense creosote brush and mesquite.					
		From the cor. of secs. 10, 11, 14 and 15.					
		N. 89°02' W., bet. secs. 10 and 15.					
		Over nearly level land, through medium dense creosote brush.					
	40.09	Point for the ½ sec. cor. of secs. 10 and 15, at proportionate distance; there is no remaining evidence of the original corner.					
		Set the iron post 22 ins. in the ground, cap mkd.					
		T12S R29E					
		½ <u>S 10</u> S 15					
		1963					
	80.19	The cor. of secs. 9, 10, 15 and 16.					
		Land, nearly level.					
		Soil, sandy. Timber, none; undergrowth, medium creosote brush.					
+	-						

Dependent	Resurvey,	Subdivisions,	T12S,	R29E,	Arizona	
-----------	-----------	---------------	-------	-------	---------	--

30.

3U		Dependent Regulvey, Bubalvisions, 1125, 1223, 11126114
•	CHAINS	N. 0°11' E., bet. secs. 9 and 10.
		Over nearly level land, through medium dense creosote brush.
	32.37	Wash, 10 lks. wide, 1 ft. deep, drains N. 70° E.
	40.31	Point for the ½ sec. cor. of secs. 9 and 10, at proportionate distance; there is no remaining evidence of the original corner.
		Set the iron post 22 ins. in the ground, cap mkd.
		T12S R29E ^½ S 9 S10 1963
	80.63	Point for the cor. of secs. 3, 4, 9 and 10, at proportionate distance; there is no remaining evidence of the original corner.
-		Set the iron post 22 ins. in the ground, cap mkd.
		T12S R29E S4 S3 S9 S10 1963
		set guard post.
		Land, nearly level. Soil, sandy and sandy loam. Timber, none; undergrowth, medium dense creosote brush.
•		From the cor. of secs. 2, 3, 10 and 11.
		N. 88°59' W., bet. secs. 3 and 10.
		Over nearly level land, through medium creosote brush and grass.
	28.41	Wash, 15 1ks. wide, 1 ft. deep, drains NE.
	40.18	Point for the ½ sec. cor. of secs. 3 and 10, at proportionate distance; there is no remaining evidence of the original corner.
		Set the iron post 22 ins. in the ground, cap mkd.
		T12S R29E \[\frac{1}{4} \frac{S}{S} \frac{3}{10} \\ 1963
	80.35	The cor. of secs. 3, 4, 9 and 10.
		Land, nearly level. Soil, sandy loam. Timber, none; undergrowth, medium dense creosote and grass.

CHAIN	,
	N. 0°15' W., bet. secs. 3 and 4.
	Over nearly level land, through medium dense creosote and scattered mesquite.
40.31	Point for the ½ sec. cor. of secs. 3 and 4, at proportionate distance; there is no remaining evidence of the original corner.
	Set the iron post 22 ins. in the ground, cap mkd.
	T12S ₁ R29E
	S 4 S 3 1963
80.73	The cor. of secs. 3, 4, 33 and 34, on the N. bdy. of the township, monumented by an iron post $2\frac{1}{2}$ ins. diamset, marked and witnessed as described in the official record.
	Land, nearly level.
	Soil, sandy. Timber, none; undergrowth, scattered creosote brush.
	From the cor. of secs. 4, 5, 32 and 33, on the S. bdy. of the township.
	N. 0°19' W., bet. secs. 32 and 33.
	Over nearly level land, through medium dense creosote brush and scattered mesquite.
.65	Dirt road along telephone line bears N. 89°40' W. and SE.
1.00	Telephone line bears N. 89°40' W. and SE.
40.62	Point for the ½ sec. cor. of secs. 32 and 33, at proportionate distance; there is no remaining evidence of the original corner.
	Set the iron post 22 ins. in the ground, cap mkd.
	T12S_R29E
	\$32 \$33 1963
61.15	Fence, barbed wire, bears S. 0°22' E. and N. 0°22' W.
79.65	Cor. of fences bearing S. 0°22° E. and westerly bears E. 0.47 chs. dist.
81.25	The cor. of secs. 28, 29, 32 and 33, monumented by a wood post, 2 inches square and plainly marked.
	At the corner point
	Set the iron post 20 ins. in the ground, cap mkd.
	T12S R29E S29 S28 S32 S33
	1963

	CHAINS						
	Chain	Land, nearly level. Soil, sandy.					
		Timber, none; undergrowth, mesquite and creosote brush.					
		From the cor. of secs. 27, 28, 33 and 34.					
		N. 88°30' W., bet. secs. 28 and 33.					
		Over nearly level land, through medium dense creosote brush.					
	40.07	Point for the $\frac{1}{4}$ sec. cor. of secs. 28 and 33, at proportionate distance; there is no remaining evidence of the original corner.					
		Set the iron post 22 ins. in the ground, cap mkd.					
١		T12S R29E					
-							
		1/4 S 28 S 33 1963					
	80.14	The cor. of secs. 28, 29, 32 and 33.					
		Land, nearly level.					
۱		Soil, sandy loam.					
	•	Timber, none; undergrowth, medium dense creosote					
Į		brush.					
		N. 0°33' E., bet. secs. 28 and 29.					
		Over nearly level land, through medium dense creosote brush.					
	40.27	Point for the ½ sec. cor. of secs. 28 and 29, at proportionate distance; there is no remaining evidence of the original corner.					
		Set the iron post 22 ins. in the ground, cap mkd.					
		T12S R29E					
		S29 S28 1963					
	80.54	Point for the cor. of secs. 20, 21, 28 and 29, at proportionate distance; there is no remaining evidence of the original corner.					
		Set the iron post 22 ins. in the ground, cap mkd.					
		T12S R29E					
ı		S20 S21					
		S29 S28					
		1963					
		set guard post.					
		Tand magnitudes					
		Land, nearly level. Soil, sandy. Timber, none; undergrowth, medium dense creosote brush.					
	_						

1	Dependent Resurvey, Subdivisions, T12S, R29E, Arizona	33.	<u> </u>
CHAINS	From the cor. of secs. 21, 22, 27 and 28.		
	N. 88°34' W., bet. secs. 21 and 28.		
	Over nearly level land, through scattered creosote		
	brush.		
39.90	Point for the ½ sec. cor. of secs. 21 and 28, at proportionate distance; there is no remaining evidence of the original corner.		
	Set the iron post 22 ins. in the ground, cap mkd.		
	T12S R29E		
	$\frac{1}{4} \frac{\text{S } 21}{\text{S } 28}$ 1963		
70.01			
79.81	The cor. of secs. 20, 21, 28 and 29.		
	Land, nearly level. Soil, sandy. Timber, scattered catclaw; undergrowth, scrub mesquite and creosote brush.		
	and Creosote Didsn.	.	
	N. 0°25' E., bet. secs. 20 and 21. Over nearly level land, through medium dense mesquite and scattered creosote brush.		
17.56	Fence, barbed wire, bears E. and W.		
40.27	Point for the ½ sec. cor. of secs. 20 and 21, at proportionate distance; there is no remaining evidence of the original corner.		
	Set the iron post 22 ins. in the ground, cap mkd.		
	T12S_R29E		
	\$20 \sqrt{\$21} 1963		
00.54			
80.54	Point for the cor. of secs. 16, 17, 20 and 21, at proportionate distance; there is no remaining evidence of the original corner.		
	Set the iron post 22 ins. in the ground, cap mkd.		
	T12S R29E S17 S16		
,	\$20 \$21 1963		
	set guard post.		
	Land, nearly level. Soil, sandy. Timber, mesquite; undergrowth, creosote brush.		
	From the cor. of secs. 15, 16, 21 and 22.	•	
	N. 88°38' W., bet. secs. 16 and 21.		
 _	Over nearly level land, through medium dense creosote brush and scattered mesquite.		
1		ı	

	DQO1X 4100						
	Dependent Resurvey, Subdivisions, T12S, R29E, Arizona	34.					
 CHAINS							
15.72	Dirt road to RICO triangulation station bears S. 58° E. and N. 58° W.						
39.92	Point for the ½ sec. cor. of secs. 16 and 21, at proportionate distance; there is no remaining evidence of the original corner.						
	Set the iron post 22 ins. in the ground, cap mkd.						
	T12S R29E						
	\frac{S \ 16}{S \ 21}						
	1963						
79.85	The cor. of secs. 16, 17, 20 and 21.						
'	Land, nearly level.						
	Soil, sandy and sandy loam. Timber, none; undergrowth, scattered mesquite and						
	creosote brush.						
	N. 0°20' E., bet. secs. 16 and 17.						
	Over nearly level land, through scattered mesquite, creosote brush and yucca.						
24.12	Dirt road bears N. 70° E. and S. 70° W.						
39.32	Cattle chute, bears E. and W.						
40.27	Point for the ½ sec. cor. of secs. 16 and 17, at proportionate distance; there is no remaining evidence of the original corner.						
7	Set the iron post 22 ins. in the ground, cap mkd.						
T12S R29E							
\$ 17 S 16							
S17 S16 1963							
**	from which						
	Triangulation Station RICO, a brass tablet set in concrete, bears S. 41°34' E., 3.033 chs. dist., mkd. RICO 1945.						
	Antelope Well windmill bears N. 70°31' E., 0.816 chs. dist.						
	set guard post.						
41.59	Fence, barbed wire, bears E. and W.						
80.54	Point for the cor. of secs. 8, 9, 16 and 17, at proportionate distance; there is no remaining evidence of the original corner.						
	Set the iron post 22 ins. in the ground, cap mkd.						
	T12S R29E <u>S 8 S 9</u> S17 S 16 1963						
		1					

set guard post.

Dependent Resurvey, Subdivisions, T12S, R29E, Arizona 35	Dependent	Resurvey.	Subdivisions,	T12S,	R29E,	Arizona	35.
--	-----------	-----------	---------------	-------	-------	---------	-----

CHAINS	
	Land, nearly level. Soil, sandy and sandy loam. Timber, scattered mesquite; undergrowth, scattered creosote brush and yucca.
	From the cor. of secs. 9, 10, 15 and 16.
	N. 88°40' W., bet. secs. 9 and 16.
	Over nearly level land, through medium creosote brush.
40.03	Point for the ½ sec. cor. of secs. 9 and 16, at proportionate distance; there is no remaining evidence of the original corner.
	Set the iron post 22 ins. in the ground, cap mkd.
	T12S R29E 2 S 9 S 16 1963
80.07	The cor. of secs. 8, 9, 16 and 17.
	Land, nearly level. Soil, sandy loam. Timber, none; undergrowth, scrub mesquite, creosote brush and catclaw.
	N. 0°11' E., bet. secs. 8 and 9.
	Over nearly level land, through medium dense creosote brush and scattered mesquite.
40.27	Point for the $\frac{1}{4}$ sec. cor. of secs. 8 and 9, at proportionate distance; there is no remaining evidence of the original corner.
	Set the iron post 22 ins. in the ground, cap mkd.
	T12S R29E
	S 8 S 9 1963
80.54	Point for the cor. of secs. 4, 5, 8 and 9, at proportionate distance; there is no remaining evidence of the original corner.
	Set the iron post 22 ins. in the ground, cap mkd.
	T12S R29E S 5 S 4 S 8 S 9 1963
	set guard post.
	Land, nearly level. Soil, sandy loam. Timber, none; undergrowth, scattered mesquite and medium dense creosote brush.

Dependent	Resurvey,	Subdivisions,	T12S,	R29E,	Arizona	36.
-----------	-----------	---------------	-------	-------	---------	-----

6		Dependent Resurvey, Subdivisions, T12S, R29E, Arizona 36.
	CHAINS	
		From the cor. of secs. 3, 4, 9 and 10.
	5	N. 88°45' W., bet. secs. 4 and 9.
		Over nearly level land, through medium creosote brush and grass.
	40.04	Point for the ½ sec. cor. of secs. 4 and 9, at proportionate distance; there is no remaining evidence of the original corner.
		Set the iron post 22 ins. in the ground, cap mkd.
		T12S R29E $\frac{1}{4} = \frac{S}{S} = \frac{4}{S}$ 1963
	80.09	The cor. of secs. 4, 5, 8 and 9.
		Land, nearly level. Soil, sandy loam. Timber, none; undergrowth, scattered catclaw, creosote brush and grass.
	:	N. 0°10' W., bet. secs. 4 and 5.
	·	Over nearly level land, through medium dense creosote and scattered mesquite.
	40.27	Point for the ½ sec. cor. of secs. 4 and 5, at proportionate distance; there is no evidence of the original corner.
		Set the iron post 22 ins. in the ground, cap mkd.
	,	T12S R29E
		S 5 S 4 1963
	80.62	The cor. of secs. 4, 5, 32 and 33, on the N. bdy. of the township, monumented by an iron post $2\frac{1}{2}$ ins. diam., set, mkd. and witnessed as described in the official record.
		Land, nearly level. Soil, sandy. Timber, none; undergrowth, creosote brush and grass.
		From the cor. of secs. 5, 6, 31 and 32, on the S. bdy. of the township.
		N. 0°05' E., bet. secs. 31 and 32.
		Over nearly level land, through medium dense mesquite and scattered yucca.
	.60	Dirt road, bears S. 89°40' E. and N. 89°4' W.
	.90	Telephone line, bears S. 89°40' E. and N. 89°40' W.
_	_	

· · · · · · · · · · · · · · · · · · ·	Dependent Resurvey, Subdivisions, T12S, R29E, Arizona
40.10	Point for the ½ sec. cor. of secs. 31 and 32, at proportionate distance; there is no remaining evidence of the original corner.
	Set the iron post 22 ins. in the ground, cap mkd.
	T12S_R29E
	S31 S32 1963
79.25	Fence, barbed wire, bears E. and W.
80.21	Point for the cor. of secs. 29, 30, 31 and 32, at proportionate distance; there is no remaining evidence of the original corner.
	Set the iron post 22 ins. in the ground, cap mkd.
	T12S R29E <u>S30 S29</u> <u>S31 S32</u> 1963
	set guard post.
	Land, nearly level. Soil, sandy. Timber, none; undergrowth, mesquite and scattered yucca.
	From the cor. of secs. 28, 29, 32 and 33.
	N. 89°43' W., bet. secs. 29 and 32.
	Over nearly level land, through medium dense creosote brush.
38.90	Fence, barbed wire, bears N. and S.
39.69	Point for the $\frac{1}{4}$ sec. cor. of secs. 29 and 32, at proportionate distance; there is no remaining evidence of the original corner.
	Set the iron post 22 ins. in the ground, cap mkd.
	T12S R29E 1/2 S 29 1/3 S 32 1963
58.90	Fence, barbed wire, bears N. and S.
78.90	Fence, barbed wire, bears N. and S.
79.37	The cor. of secs. 29, 30, 31 and 32.
	Land, nearly level. Soil, sandy.

Dependent	Resurvey,	Subdivisions,	T12S,	R29E,	Arizona	3 8

		Dependent Resurvey, Subdivisions, T12S, R29E, Arizona
	CHAINS	N. 88°28' W., bet. secs. 30 and 31.
		Over nearly level land, through medium dense mesquite and catclaw.
	39.71	Point for the $\frac{1}{4}$ sec. cor. of secs. 30 and 31, at proportionate distance; there is no remaining evidence of the original corner.
		Set the iron post 22 ins. in the ground, cap mkd.
		T12S R29E 1/4 S 30 S 31 1963
	77.54	Fence, barbed wire, bears N. and S.
	77.83	The cor. of secs. 25, 30, 31 and 36 on the W. bdy. of the township.
		Land, nearly level. Soil, sandy. Timber, medium dense mesquite; undergrowth, creosote brush.
		From the cor. of secs. 29, 30, 31 and 32.
		N. 0°16' E., bet. secs. 29 and 30.
		Over nearly level land, through medium dense mesquite and creosote brush, scattered yucca and cacti.
	40.10	Point for the $\frac{1}{4}$ sec. cor. of secs. 29 and 30, at proportionate distance; there is no remaining evidence of the original corner.
		Set the iron post 22 ins. in the ground, cap mkd.
		T12S R29E
		\$30 \(\frac{3}{529} \) 1963
	80.21	The cor. of secs. 19, 20, 29 and 30, monumented by a wood post 2 ins. square and plainly marked.
		At the cor. point
		Set the iron post 22 ins. in the ground, cap mkd.
		T12S R29E <u>S19 S20</u> S30 S29 1963
		from which
		A N-S fence line bears E., 0.993 chs. dist.
		set guard post.
		Land, level. Soil, sandy and sandy loam. Timber, none; undergrowth, mesquite, creosote brush, yucca and cacti.
٦	_	

		1100
		Dependent Resurvey, Subdivisions, T12S, R29E, Arizona 39.
	CHAINS	From the cor. of secs. 20, 21, 28 and 29.
		West, bet. secs. 20 and 29.
		Over nearly level land, through medium dense catclaw
	0.77	and mesquite.
	9.77	Small wash, 10 1ks. wide, 1 ft. deep, drains N. 10° E.
	39.88	Point for the ½ sec. cor. of secs. 20 and 29, at proportionate distance; there is no remaining evidence of the original corner.
		Set the iron post 22 ins. in the ground, cap mkd.
		T12S R29S 1/4 S 20 S 29 1963
	78.80	Fence, barbed wire, bears S. 0°40' E. and N. 0°40' W.
	79.75	The cor. of secs. 19, 20, 29 and 30.
		Land, nearly level. Soil, sandy loam. Timber, none; undergrowth, catclaw, mesquite and creosote brush.
		N. 88°03' W., bet. secs. 19 and 30.
		Over nearly level land, through medium dense creosote brush.
	39.99	Point for the ½ sec. cor. of secs. 29 and 30, at proportionate distance; there is no remaining evidence of the original corner.
		Set the iron post 22 ins. in the ground, cap mkd.
		T12S R29E 1/4 S 19 1963
	77.98	The cor. of secs. 19, 24, 25 and 30, on the W. bdy. of the township.
		Land, nearly level. Soil, sandy. Timber, none; undergrowth, high creosote brush.
•		From the cor. of secs. 19, 20, 29 and 30.
i		N. 0°13' E., bet. secs. 19 and 20.
	40.47	Point for the ½ sec. cor. of secs. 19 and 20, at proportionate distance; there is no remaining evidence of the original corner.
		Set the iron post 22 ins. in the ground, cap mkd.
	_	T12S_R29E 12 S19 S20
	_	\$19 \$1963
	i	

		BOOK 4700	
40		Dependent Resurvey, Subdivisions, Tl2S, R29E, Arizona 40.	
70	CHAINS		
	80.94	Point for the cor. of secs. 17, 18, 19 and 20, at proportionate distance; there is no remaining evidence of the original corner.	
		Set the iron post 22 ins. in the ground, cap mkd.	
		T12S R29E S18 S17 S19 S20	
		1963	
		set guard post.	
		Land, nearly level. Soil, sandy loam. Timber, none; undergrowth, mesquite and creosote brush.	
		From the cor. of secs. 16, 17, 20 and 21.	
		N. 88°46' W., bet. secs. 17 and 20.	
		Over nearly level land, through medium dense creosote brush and scattered mesquite.	
	39.86	Dirt road, bears NE. and W.	
	40.01	Point for the % section cor. of secs. 17 and 20, at proportionate distance; there is no remaining evidence of the original corner.	
		Set the iron post 22 ins. in the ground, cap mkd.	
		T12S R29E 1/4 S 17 S 20 1963	
	44.66	Dirt road, bears E. and NW.	٠
	65.56	Same dirt road, bears S. 60° W. and N. 60° E.	
	78.46	Fence, barbed wire, bears N. and S.	
	80.01	The cor. of secs. 17, 18, 19 and 20.	
		Land, nearly level. Soil, sandy and sandy loam. Timber, none; undergrowth, scattered mesquite, creosote brush and grass.	
		N. 88°12' W., bet. secs. 18 and 19.	
		Over nearly level land, through scattered creosote brush, mesquite and yucca.	
	40.04	Point for the ½ sec. cor. of secs. 18 and 19, at proportionate distance; there is no remaining evidence of the original corner.	
		Set the iron post 22 ins. in the ground, with a fir guard post alongside, cap mkd.	
		T12S R29E	
	+	$\frac{1}{4} \frac{S18}{S19}$	
		1963	
	1	· .	

•	CHAINS	Dependent Resurvey, Subdivisions, T12S, R29E, Arizona 41.	
	CHAINS	Cor. set in center of old dirt road.	
	77.71	The cor. of secs. 13, 18, 19 and 24, on the W. bdy. of the township.	
		Land, nearly level. Soil, sandy. Timber, none; undergrowth, scattered mesquite and yucca.	
		From the cor. of secs. 17, 18, 19 and 20.	
		N. 0°14' E., bet. secs. 17 and 18.	
		Over nearly level land, through scattered yucca, mesquite and cacti.	
	.86	Dirt road, bears S. 89° E., and N. 89° W.	
	21.46	Wash, 10 lks. wide, 1 ft. deep, drains NE.	
	40.47	Point for the ½ sec. cor. of secs. 17 and 18, at proportionate distance; there is no remaining evidence of the original corner.	
		Set the iron post 22 ins. in the ground, cap mkd.	
		T12S_R29E	
		S 18 S 17 1963	
	80.94	Point for the cor. of secs. 7, 8, 17 and 18, at proportionate distance; there is no remaining evidence of the original corner.	
		Set the iron post 22 ins. in the ground, cap mkd.	
		T12S R29E S7 S8 S18 S17 1963	
		set guard post.	
,		Land, nearly level. Soil, sandy. Timber, none; undergrowth, mesquite and scattered yucca and cacti.	
		From the cor. of secs. 8, 9, 16 and 17.	
	c	N. 89°28' W., bet. secs. 8 and 17.	
		Over nearly level land, through medium catclaw and	
	,	scattered yucca, Mormon Tea, and scrub mesquite.	
	40.06	Point for the ½ sec. cor. of secs. 8 and 17, at proportionate distance; there is no remaining evidence of the original corner.	
		Set the iron post 22 ins. in the ground, cap mkd.	
,			
-	-		
ł	i	\mathbf{I}	

Dependent	Resurvev.	Subdivisions,	T12S,	R29E,	Arizona	42.
Dependence	11050111079		,			

12	<u> </u>	Dependent Resurvey, Subdivisions, 1125, R29E, A1120Ha 4
	CHAINS	
		T12S R29E
		½ S 8 S 17
		1963
	80.12	The cor. of secs. 7, 8, 17 and 18.
		Land, nearly level.
		Soil, sandy. Timber, none; undergrowth, catclaw, yucca, mesquite and Mormon Tea.
		N. 88°22' W., bet. secs. 7 and 18.
		Over nearly level land, through medium mesquite and scattered yucca.
	40.11	Point for the ½ sec. cor. of secs. 7 and 18, at proportionate distance; there is no remaining evidence of the original corner.
		Set the iron post 18 ins. in the ground, in a small collar of stone, in an E-W fence line, cap mkd.
		T12S R29E
		¹ / ₄ S 7/ _{5 18}
		1963
	47.56	Bladed road, bears N. 18°20' E. and S. 18°20' W.
	76.26	Fence, barbed wire, bears N. and S.
	77.42	The cor. of secs. 7, 12, 13 and 18, on the W. bdy. of the township.
		Land, nearly level.
		Soil, sandy. Timber, none; undergrowth, catclaw, mesquite and grass.
		From the cor. of secs. 7, 8, 17 and 18.
		North, bet. secs. 7 and 8.
		Over nearly level land, through scattered mesquite, yucca and cacti.
	.91	Fence, barbed wire, bears E. and W.
	40.47	Point for the $\frac{1}{4}$ sec. cor. of secs. 7 and 8, at proportionate distance; there is no remaining evidence of the original corner.
		Set the iron post 22 ins. in the ground, cap mkd.
		T12S_R29E
		s 7 s 8
		1963
	62.16	Wash, 10 lks. wide, 1 ft. deep, drains N. 20° E.
_	80.94	Point for the cor. of secs. 5, 6, 7 and 8, at proportionate distance; there is no remaining evidence of the original corner.

	BOOK 4700
	Dependent Resurvey, Subdivisions, T12S, R29E, Arizona 43.
CF	Set the iron post 22 ins. in the ground, cap mkd.
	T12S R29E S6 S 5 S 7 S 8 1963
	set guard post.
	Land, nearly level. Soil, sandy. Timber, none; undergrowth, mesquite, yucca and cacti.
ĺ	From the cor. of secs. 4, 5, 8 and 9.
	N. 89°09' W., bet. secs. 5 and 8.
	Over nearly level land, through medium catclaw, creosote brush and grass.
40.	Point for the ½ sec. cor. of secs. 5 and 8, at proportionate distance; there is no remaining evidence of the original corner.
	Set the iron post 22 ins. in the ground, cap mkd.
	T12S R29E 2 S 5 S 8 1963
80.	35 The cor. of secs. 5, 6, 7 and 8.
	Land, nearly level. Soil, sandy. Timber, none; undergrowth, catclaw, yucca, mesquite, Mormon Tea, creosote brush and cacti.
	N. 88°29' W., bet. secs. 6 and 7.
	Over nearly level land, through catclaw and scrub mesquite.
8.	70 Bladed road, bears N. 39°20' E. and S. 39°20' W
9.	Fence, barbed wire, bears N. 39°20' E. and S. 39°20' W.
40.	Point for the ½ sec. cor. of secs. 6 and 7, at proportionate distance; there is no remaining evidence of the original corner.
	Set the iron post 29 ins. in the ground, cap mkd.
	T12S R29E 1/4 S 6 S 7 1963
43.	Fence, barbed wire, bears S. and N. 23° W.
76.	The cor. of secs. 1, 6, 7 and 12 on the W. bdy. of the township.

					•	
Dependent	Resurvey,	Subdivisions,	T12S,	R29E,	Arizona	44.

	Dependent Resulvey, Subarvibions, 1125, 1127, 1127						
CHAINS	Land, nearly level.						
	Soil, sandy. Timber, none; undergrowth, catclaw, yucca, mesquite, creosote brush and Mormon Tea.						
	From the cor. of secs. 5, 6, 7 and 8.						
	N. 0°04' E., bet. secs. 5 and 6.						
	Over nearly level land, through medium dense mesquite and scattered yucca and cacti.						
11.27	Bladed road, bears N. 39°30' E. and S. 39°30' W.						
12.27	Fence, barbed wire, bears N. 39°30' E., and S. 39°30' W.						
31.27	Enter medium dense growth of creosote brush.						
40.47	Point for the ½ sec. cor. of secs. 5 and 6, at proportionate distance; there is no remaining evidence of the original corner.						
	Set the iron post 22 ins. in the ground, cap mkd.						
	T12S_R29E						
	S 6 S 5 1963						
81.08	The cor. of secs. 5, 6, 31 and 32, on the N. bdy. of the township, monumented by an iron post $2\frac{1}{2}$ ins. diam. set in a N-S fence line, set, mkd. and witnessed as described in the official record.						
	Land, nearly level. Soil, sandy. Timber, none; undergrowth, catclaw, mesquite and creosote brush.						
	General Description						
	The general elevation of Township 12 South, Range 29 East is from 3420 to 3655 feet above sea level. The township is nearly level, with drainage to the northeast. The soil is shallow and sandy, with caliche underneath. There is a sparse to moderate growth of greasewood, mesquite and creosote brush, with some grass.						

Form 4-680 (January 1963)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FIELD ASSISTANTS

NAMES	CAPACITY
Wallace R. Ott	Crew Chief
Gary T. Oviatt	Transit
Alan R. Crockett	Notes
Tom D. Carter	Front Chain
Michael J. Lissy	Flagman
Gordon H. Black	Cornerman

CERTIFICATE OF SURVEY

I,	Paul G. Bauer			HEREBY C	ERTIFY upon ho	onor that,
in pursi	uance of special ins	tructions bearing da	ate of the 26	day of Jui	ne	, 1962 ,
I have	dependently r	esurveyed the s	south, east	and west	boundaries,	and
the su	ıbdivisional li	nes of Township	o 12 South,	Range 29	East	
of the	Gila and Salt	. River Meridi	an, in the State	of Ari	zona	, which
are rep	resented in the fore	going field notes as	having been ex	recuted by m	ne and under my	direction;
		een made in strict o				
		rvey of the Public				
					•	
descri	oed in the foregoing	nelu notes.	1			
				/ 6, -	2 15	
M	(Date)		Surveyi	ng (BAHASINA	Tech	nician
	, ,					
-	(0.1)			(Cadastra	1 Surveyor)	
	(Date)			Cadasiiu		
		CERTIFICA	TE OF APPRO	VAL		
The fo	oregoing field notes	of the dependen	itly resurve	eyed the s	south, east	and west
bound	aries, and the	subdivisional	lines of To	ownship 12	2 South, Ran	ge 29 East
of th	e Gila and Sal	t River Meridia	an, Arizona,			
						. •
	P1 C	Bauer, Surveyin	ag Technici:	an		
	,					
having	g been critically exa	amined and found co	rrect, are hereb	y approved.		,
	JUL 1 7 1964			1		
	(Date)			Chief, Division	on of Engineering	
				,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	/ ()	
		—— CERTIFICAT	HE OF TRANS	SKIP I		
I CER	TIFY That the fore	going transcript of t	the field notes	of the above	-described surve	eys in
			is	a true copy	of the original f	ield notes.
	(D :)			Chief Divici	on of Engineering	