Form 9180-6 (April 1965) (formerly 4-679)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FIELD NOTES

RETRACEMENT
OF A
PORTION OF THE WEST BOUNDARY
OF
TOWNSHIP 9 SOUTH, RANGE 27 EAST
DEPENDENT RESURVEY
OF THE
WEST BOUNDARY
AND A
PORTION OF THE SUBDIVISIONAL LINES
WITH
ESTABLISHMENT OF CERTAIN & SECTION
CORNERS OF MINIMUM CONTROL
ALONG THE EAST AND NORTH BOUNDARIES,
TOWNSHIP 9 SOUTH, RANGE 26 EAST
Of theGila and Salt RiverMeridian,
In the State ofArizona
•
EXECUTED BY
Louis D. Gilbert Cadastral Surveyor
Under special instructions dated February 17 , 19 69, which provided for the surveys
included under Group Number 467, approved February 17, 1969
and assignment instructions dated <u>February 18</u> , 19 <u>69</u> .
Survey commonced March 5 10 69

April 2

Survey completed _

____, 19 ____

P 0 0 K 4 9 4 7

INDEX DIAGRAM

Township 9 South, Range 26 East,										
							32 (1/4)		23 (社)	
6	59	5	4		8	31	2	22	¹ 22(装)	
58		57	46		39		31		21	5
7	56	8	46 .9	38	10	30	11	20	1222(表)	
55		54	45		37		29		19	4
							•			
18	53	17	44 16	36	15	28	14	18	1320(社)	
53		52	43		36		28		17	3
						<u>.</u>				
19	51	20	42 21	35	22	27	23	16	2418(社)	
50		49	42		34		26		14	2
30	48	29	41 28	33	27	25	26	13	2515(岩)	
48		47	40		33		25		12	1
		-								
31		32	83		84	24	35	12	36	
	6 58 7 55 18 53 19 50 30 48	6 59 58 7 56 55 18 53 53 19 51 50 30 48 48	6 59 5 58 57 7 56 8 55 54 18 53 17 53 52 19 51 20 50 49 30 48 29 48 47	6 59 5 4 58 57 46 7 56 8 46 .9 55 54 45 18 53 17 44 16 53 52 43 19 51 20 42 21 50 49 42 30 48 29 41 28 48 47 40	6 59 5 4 6 7 56 8 46 .9 38 55 54 45 36 53 52 43 35 50 49 42 21 35 48 47 40	6 59 5 4 8 39 7 56 8 46 .9 38 10 55 54 45 37 18 53 17 44 16 36 15 53 52 43 36 19 51 20 42 21 35 22 50 49 42 34 30 48 29 41 28 33 27 48 47 40 33	6 59 5 4 8 31 58 57 46 39 38 30 7 56 8 46 .9 38 10 30 55 54 45 37 37 28 53 52 43 36 18 28 53 52 43 36 22 27 50 49 42 34 34 25 48 47 40 33 27 25 48 47 40 33 33 27 25	6 59 5 4 8 31 2 58 57 46 39 31 7 56 8 46 9 38 10 30 11 55 54 45 37 29 18 53 17 44 16 36 18 28 14 53 52 43 36 28 28 19 51 20 42 21 35 22 27 28 50 49 42 34 26 30 48 29 41 28 33 27 25 26 48 47 40 33 25 25	6 59 8 4 8 31 2 22 58 57 46 39 31 20 55 54 46 38 30 11 20 55 54 45 37 29 30 11 20 18 53 17 44 16 36 18 28 14 18 53 52 43 36 28 28 16 50 49 42 31 35 22 27 28 16 50 48 29 41 28 33 27 25 26 13 48 47 40 33 25 25 25 26 13	32 (表) 23 (表) 23 (表) 25 8 59 5 4 8 31 2 22 1 22 (表) 31 2 1 22 (表) 31 2 1 21 21 22 (表) 31 21 21 21 21 22 (表) 35 54 45 37 29 19 19 18 53 17 44 16 36 18 28 14 18 1320(表) 53 52 43 36 28 17 17 19 51 20 42 21 35 22 27 28 16 2418(表) 50 49 42 34 26 14 28 14 26 14 28 14 26 14 28 14 26 14 28 14 26 14 28 14 26 14 28 14 26 14 28 14 26 14 28 14 26 14 28 14 26 14 28 14 28 14 26 14 28 14 26 14 28 14 28 14 26 14 28 14 28 14 26 14 28 14 28 14 26 14 28 14 26 14 28 14 28 14 26 14 28 14 28 14 26 14 28 14 28 14 28 14 26 14 28 14

Township 9 South, Range 26 East Gila and Salt River Meridian, Arizona

CHAINS

The east and north boundaries were surveyed in 1875 by T. F. White. The east and north boundaries were resurveyed in 1904 by P. Contzen who altered the original corners to function for the adjoining townships only. The south and west boundaries and the subdivisional lines were surveyed in 1904 by P. Contzen. The south boundary was resurveyed by W. B. Kimmel in 1917. The south boundary of Township 8 South, Range 26 East, was resurveyed by D. E. Harding in 1957 and also retraced by Louis D. Gilbert, and is described in the field notes of Township 8 South, Range 26 East executed concurrently under Group No. 470. Certain corners along the west boundary were remonumented by L. S. Mann in 1960. The west boundary of Township 9 South, Range 27 East, was resurveyed by Dell Cazier in 1961.

The following field notes are those of a retracement of a portion of the west boundary of Township 9 South, Range 27 East, and a dependent resurvey of the west boundary and a portion of the subdivisional lines, designed to restore the corners in their true original location according to the best available evidence, and the establishment of certain ½ section corners of minimum control along the east and north boundaries of Township 9 South, Range 26 East, Gila and Salt River Meridian, Arizona.

This survey was executed in accordance with the specifications as set forth in the Manual of Surveying Instructions, 1947, and the Special Instructions dated February 17, 1969. The direction of all lines were determined by solar observations and all lines refer to the true meridian.

Only the true line bearings and horizontal distances for the surveyed lines are given in these field notes. Unless described, each corner is monumented with a standard iron post 30 inches long, $2\frac{1}{2}$ inches diameter, flanged at the base and with a brass cap riveted to the top.

The geographic position of the closing corner of sections 25 and 36 on the east boundary of the township as determined by traverse from U.S.G.S. benchmark 23 RS 3635 in Sec. 30, T. 9 S., R. 27 E. is: Latitude 32°36'52.6" N. and Longitude 109°37'49.7" W.

The mean magnetic declination was found to be 13° E.

Retracement, Portion of the West Boundary T. 9 S., R. 27 E.

Retracement of a Portion of the Resurvey executed by Dell Cazier in 1961

Beginning at the cor. of secs. 30 and 31, on the W. bdy. of T. 9 S., R. 27 E., monumented by an iron post $2\frac{1}{2}$ ins. diam., projecting 4 ins. above ground, firmly set, brass cap mkd.

T9S | R27E | S 30 | S 31 1961

Retracement, Portion of the West Boundary T. 9 S., R. 27 E.

	2. 5 5., 10. 27 2.
CHAINS	
	The cor. is located 19 lks. West of a fence bearing N. and S.
•	N. 0°25' E., along the W. bdy. of sec. 30.
	Over gently rolling land, along W. side of fence.
6.80	Track road, bears N. along line and S. 85° W.
23.60	Tanque Road, bears E. and W. and track road, bears S.
38.42	The ½ sec. cor. of sec. 30, monumented by an iron post, 2½ ins. diam., projecting 18 ins. above ground, firmly set in a mound of stone, brass cap mkd.
	T9 S
`	R27E
	s 30
-	1961
	The cor. is located 9 lks. West of a fence bearing N. and S.
	N. 0°24' E., beginning new measurement.
	Over gently rolling land, along W. side of fence.
27.50	Oak Draw, 200 1ks. wide, 1 ft. deep, drains NE.
32.80.	Fence, bears W. and E., 4 lks. dist. to cor. of fences bearing N., S. and W.
41.73	The cor. of secs. 19 and 30, monumented by an iron post, $2\frac{1}{2}$ ins. diam., projecting 6 ins. above ground, firmly set in a collar of stone, brass cap mkd.
•	T9S R27E S 19 S 30
	The cor. is located 4 lks. West of a fence bearing N. and S.
	Land, gently rolling. Soil, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.
	N. 0°01' W., along the W. bdy. of sec. 19.
	Over rolling land, along W. side of fence.
8.50	Wash, 50 lks. wide, 1 ft. deep, drains irregularly NE.
39.28	The ½ sec. cor. of sec. 19, monumented by an iron post, 2½ ins. diam., projecting 6 ins. above ground, firmly set, brass cap mkd.

Retracement, Portion of the West Boundary T.~9~S.,~R.~27~E.

CHAINS	
	T9S
	R27E
	1961
٥	The cor. is located 3 lks. West of a fence bearing N. and S.
	N. 0°01' E., beginning new measurement.
	Over rolling land, along W. side of fence.
27.80	Wash, 200 lks. wide, 1 ft. deep, drains irregularly E.
39.19	The cor. of secs. 18 and 19, monumented by an iron post, $2\frac{1}{2}$ ins. diam., projecting 10 ins. above ground, firmly set in a collar of stone, brass cap mkd.
	T9S
· •	R27E S 18
	S 19
	1961
	The cor. is located 4 lks. West of a fence bearing N. and S.
	Land, rolling. Soil, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.
6	N. 0°09' E., along the W. bdy. of sec. 18.
	Over gently rolling land, along W. side of fence.
39.80	The ½ sec. cor. of sec. 18, monumented by an iron post, 2½ ins. diam., projecting 6 ins. above ground, firmly set, brass cap mkd.
	T9 S R27E
	12 18 1961
	The cor. is located 4 lks. West of a fence bearing N. and S.
	N. 0°05' E., beginning new measurement.
	Over gently rolling land, along W. side of fence.
39 . 84 。	The cor. of secs. 7 and 18, monumented by an iron post, $2\frac{1}{2}$ ins. diam., projecting 10 ins. above ground, firmly set, brass cap mkd.

4.

Retracement, Portion of the West Boundary T. 9 S., R. 27 E.

CHAINS	
	T9S
	R27E S 7
	S 18 1961
•	The cor. is located 5 lks. West of a fence bearing N. and S.
	Land, gently rolling. Soil, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.
	N. 0°11' E., along the W. bdy. of sec. 7.
	Over gently rolling land, along W. side of fence.
2.17	The closing cor. of secs. 12 and 13, T. 9 S., R. 26 E., hereinafter described.
37.30	Wash, 70 lks. wide, 1 ft. deep, drains irregularly N. 5° E.
39.62	The ½ sec. cor. of sec. 7, monumented by an iron post, 2½ ins. diam., projecting 10 ins. above ground, firmly set, brass cap mkd.
	T9S
	R27E
્	S 7 1961
	The cor. is located 4 lks. West of a fence bearing N. and S.
•	
-	N. 0°07' E., beginning new measurement.
	Over gently rolling land, along W. side of fence.
39.72	The cor. of secs. 6 and 7, monumented by an iron post, $2\frac{1}{2}$ ins. diam., projecting 8 ins. above ground, firmly set, brass cap mkd.
	T9S R27E S 6 S 7
	The cor. is located 2 lks. West of a fence bearing N. and S.
•	Land, gently rolling. Soil, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti
	and bunchgrass.

Retracement, Portion of the West Boundary . T. 9 S., R. 27 E.

-		
	CHAINS	N. 0°05' E., along the W. bdy. of sec. 6.
		Over gently rolling land, along W. side of fence.
	16.00	- '
	16.20	Wash, 20 1ks. wide, 6 ins. deep, drains irregularly NE.
	39.84	The ½ sec. cor. of sec. 6, monumented by an iron post, 2½ ins. diam., projecting 6 ins. above ground, firmly set, brass cap mkd.
		T9S R27E
		†3
		The cor. is located 2 lks. West of a fence bearing N. and S.
		N. 0°03' E., beginning new measurement.
		Over gently rolling land, along W. side of fence.
	30.70	Track road, bears N. 87° E. and S. 87° W.
	39.72	The cor. of Tps. 8 and 9 S., Rs. 26 and 27 E., monumented by an iron post, 2½ ins. diam., projecting 6 ins. above ground, firmly set, brass cap mkd.
		T8S R26E R27E S 36 S 31 S 1 S 6 T9S 1957
		The cor. is located 4 lks. West of a fence bearing N. and S.
	,	Land, gently rolling. Soil, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.
		Dependent Resurvey, West Boundary T. 9 S., R. 26 E.
		Reestablishment of the Survey executed by P. Contzen in 1904
		Beginning at the cor. of Tps. 9 and 10 S., Rs. 25 and 26 E., monumented by an iron post, 3 ins. diam., projecting 12 ins. above ground, firmly set, mound of stone W., brass cap mkd.
		T9S R25E R26E <u>S36 S31</u> S 1 S 6 T10S 1917

Dependent Resurvey, West Boundary, . T. 9 S., R. 26 E.

from which A cor. of fences, bears SW., 3 lks. dist., fences bear irregularly N. and E. N. 0°11' E., bet. secs. 31 and 36. Over rolling land. 21.20 Enter Stockton Pass Wash area, drains N. 20° E. Point for the k sec. cor. of secs. 31 and 36, at proportionate dist.; there is no remaining evidence of the orig. cor. Set the iron post 22 ins. in the ground, brass cap mkd. T9S R25E R26E \$ 36 S 31 1969 Raise a mound of stone W. of the iron post. Deposit glass at the base of the iron post. Jeep trail, bears irregularly NE. and SW. 47.40 Leave Stockton Pass Wash area, drains N. 20° E. 80.12 The cor. of secs. 25, 30, 31 and 36, monumented by an iron post, 2½ ins. diam., projecting 3 ins. above ground firmly set in a collar of stone, with brass cap mkd. T9S R25E R26E S 25 S 30 S 36 S 31 1960 The cor. is located 3 lks. East of a fence bearing N. and S. Land, rolling. Soil, rocky, sandy loam. No timber; undergrowth, creosote bush, mesquite, cactiand bunchgrass. N. 0°08 W., bet. secs. 25 and 30.		
A cor. of fences, bears SW., 3 lks. dist., fences bear irregularly N. and E. N. 0°11' E., bet. secs. 31 and 36. Over rolling land. 21.20 Enter Stockton Pass Wash area, drains N. 20° E. 40.06 Point for the ½ sec. cor. of secs. 31 and 36, at proportionate dist.; there is no remaining evidence of the orig. cor. Set the iron post 22 ins. in the ground, brass cap mkd. T9S R25E R26E \$ 36 S 31 1969 Raise a mound of stone W. of the iron post. Deposit glass at the base of the iron post. Jeep trail, bears irregularly NE. and SW. 47.40 Jeep trail, bears irregularly NE. and SW. Leave Stockton Pass Wash area, drains N. 20° E. The cor. of secs. 25, 30, 31 and 36, monumented by an iron post, 2½ ins. diam., projecting 3 ins. above ground firmly set in a collar of stone, with brass cap mkd. T9S R25E R26E \$ 25 S 30 \$ 36 S 31 1960 The cor. is located 3 lks. East of a fence bearing N. and S. Land, rolling. Soil, rocky, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.		
bear irregularly N. and E. N. 0°11' E., bet. secs. 31 and 36. Over rolling land. 21.20 Enter Stockton Pass Wash area, drains N. 20° E. 40.06 Point for the ½ sec. cor. of secs. 31 and 36, at proportionate dist.; there is no remaining evidence of the orig. cor. Set the iron post 22 ins. in the ground, brass cap mkd. T9S R25E R26E \$ 36 S 31 1969 Raise a mound of stone W. of the iron post. Deposit glass at the base of the iron post. Jeep trail, bears irregularly NE. and SW. 47.40 Jeep trail, bears Wash area, drains N. 20° E. The cor. of secs. 25, 30, 31 and 36, monumented by an iron post, 2½ ins. diam., projecting 3 ins. above ground firmly set in a collar of stone, with brass cap mkd. T9S R25E R26E S25 S 30 S 36 S 31 1960 The cor. is located 3 lks. East of a fence bearing N. and S. Land, rolling. Soil, rocky, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.	ch .	
Over rolling land. Enter Stockton Pass Wash area, drains N. 20° E. 40.06 Point for the ½ sec. cor. of secs. 31 and 36, at proportionate dist.; there is no remaining evidence of the orig. cor. Set the iron post 22 ins. in the ground, brass cap mkd. T9S R25E R26E \$ 36 S 31 1969 Raise a mound of stone W. of the iron post. Deposit glass at the base of the iron post. Jeep trail, bears irregularly NE. and SW. 47.40 Leave Stockton Pass Wash area, drains N. 20° E. 80.12 The cor. of secs. 25, 30, 31 and 36, monumented by an iron post, 2½ ins. diam., projecting 3 ins. above ground firmly set in a collar of stone, with brass cap mkd. T9S R25E R26E \$ 25 S 30 \$ 36 S 31 1960 The cor. is located 3 lks. East of a fence bearing N. and S. Land, rolling. Soil, rocky, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.		es
Enter Stockton Pass Wash area, drains N. 20° E. 40.06 Point for the ½ sec. cor. of secs. 31 and 36, at proportionate dist.; there is no remaining evidence of the orig. cor. Set the iron post 22 ins. in the ground, brass cap mkd. T9S R25E R26E \$ 36 S 31 1969 Raise a mound of stone W. of the iron post. Deposit glass at the base of the iron post. Jeep trail, bears irregularly NE. and SW. 47.40 Leave Stockton Pass Wash area, drains N. 20° E. The cor. of secs. 25, 30, 31 and 36, monumented by an iron post, 2½ ins. diam., projecting 3 ins. above ground firmly set in a collar of stone, with brass cap mkd. T9S R25E R26E S 25 S 30 S 36 S 31 1960 The cor. is located 3 lks. East of a fence bearing N. and S. Land, rolling. Soil, rocky, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.	E., bet. secs. 31 and 36.	•
Point for the ½ sec. cor. of secs. 31 and 36, at proportionate dist.; there is no remaining evidence of the orig. cor. Set the iron post 22 ins. in the ground, brass cap mkd. T9S R25E R26E \$ 36 S 31 1969 Raise a mound of stone W. of the iron post. Deposit glass at the base of the iron post. Jeep trail, bears irregularly NE. and SW. 47.50 Leave Stockton Pass Wash area, drains N. 20° E. The cor. of secs. 25, 30, 31 and 36, monumented by an iron post, 2½ ins. diam., projecting 3 ins. above ground firmly set in a collar of stone, with brass cap mkd. T9S R25E R26E \$ 25 S 30 \$ 36 S 31 1960 The cor. is located 3 lks. East of a fence bearing N. and S. Land, rolling. Soil, rocky, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.	ling land.	
tionate dist.; there is no remaining evidence of the orig. cor. Set the iron post 22 ins. in the ground, brass cap mkd. T9S R25E R26E \$ 36 \$ 31 1969 Raise a mound of stone W. of the iron post. Deposit glass at the base of the iron post. Jeep trail, bears irregularly NE. and SW. 47.40 Leave Stockton Pass Wash area, drains N. 20° E. The cor. of secs. 25, 30, 31 and 36, monumented by an iron post, 2½ ins. diam., projecting 3 ins. above ground firmly set in a collar of stone, with brass cap mkd. T9S R25E R26E \$ 25 \$ 30 \$ 36 \$ 31 1960 The cor. is located 3 lks. East of a fence bearing N. and S. Land, rolling. Soil, rocky, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.	ockton Pass Wash area, drains N. 20° E.	
T9S R25E R26E S 36 S 31 1969 Raise a mound of stone W. of the iron post. Deposit glass at the base of the iron post. Jeep trail, bears irregularly NE. and SW. 47.40 Leave Stockton Pass Wash area, drains N. 20° E. The cor. of secs. 25, 30, 31 and 36, monumented by an iron post, 2½ ins. diam., projecting 3 ins. above ground firmly set in a collar of stone, with brass cap mkd. T9S R25E R26E S 25 S 30 S 36 S 31 1960 The cor. is located 3 lks. East of a fence bearing N. and S. Land, rolling. Soil, rocky, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.	dist.; there is no remaining evidence of th	
R25E R26E S 36 S 31 1969 Raise a mound of stone W. of the iron post. Deposit glass at the base of the iron post. 47.40 Jeep trail, bears irregularly NE. and SW. 47.50 Leave Stockton Pass Wash area, drains N. 20° E. The cor. of secs. 25, 30, 31 and 36, monumented by an iron post, 2½ ins. diam., projecting 3 ins. above ground firmly set in a collar of stone, with brass cap mkd. T9S R25E R26E S 25 S 30 S 36 S 31 1960 The cor. is located 3 lks. East of a fence bearing N. and S. Land, rolling. Soil, rocky, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.	iron post 22 ins. in the ground, brass cap	kd.
Raise a mound of stone W. of the iron post. Deposit glass at the base of the iron post. 47.40 Jeep trail, bears irregularly NE. and SW. Leave Stockton Pass Wash area, drains N. 20° E. The cor. of secs. 25, 30, 31 and 36, monumented by an iron post, 2½ ins. diam., projecting 3 ins. above ground firmly set in a collar of stone, with brass cap mkd. T9S R25E R26E S 25 S 30 S 36 S 31 1960 The cor. is located 3 lks. East of a fence bearing N. and S. Land, rolling. Soil, rocky, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.	R25E R26E s 36 s 31	
Deposit glass at the base of the iron post. 47.40 Jeep trail, bears irregularly NE. and SW. Leave Stockton Pass Wash area, drains N. 20° E. The cor. of secs. 25, 30, 31 and 36, monumented by an iron post, 2½ ins. diam., projecting 3 ins. above ground firmly set in a collar of stone, with brass cap mkd. T9S R25E R26E S 25 S 30 S 36 S 31 1960 The cor. is located 3 lks. East of a fence bearing N. and S. Land, rolling. Soil, rocky, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.	• • • •	
Jeep trail, bears irregularly NE. and SW. Leave Stockton Pass Wash area, drains N. 20° E. The cor. of secs. 25, 30, 31 and 36, monumented by an iron post, 2½ ins. diam., projecting 3 ins. above ground firmly set in a collar of stone, with brass cap mkd. T9S R25E R26E S 25 S 30 S 36 S 31 1960 The cor. is located 3 lks. East of a fence bearing N. and S. Land, rolling. Soil, rocky, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.	mound of stone W. of the iron post.	
Leave Stockton Pass Wash area, drains N. 20° E. The cor. of secs. 25, 30, 31 and 36, monumented by an iron post, 2½ ins. diam., projecting 3 ins. above ground firmly set in a collar of stone, with brass cap mkd. T9S R25E R26E S 25 S 30 S 36 S 31 1960 The cor. is located 3 lks. East of a fence bearing N. and S. Land, rolling. Soil, rocky, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.	glass at the base of the iron post.	
The cor. of secs. 25, 30, 31 and 36, monumented by an iron post, 2½ ins. diam., projecting 3 ins. above ground firmly set in a collar of stone, with brass cap mkd. T9S R25E R26E S 25 S 30 S 36 S 31 1960 The cor. is located 3 lks. East of a fence bearing N. and S. Land, rolling. Soil, rocky, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.	il, bears irregularly NE. and SW.	
iron post, $2\frac{1}{2}$ ins. diam., projecting 3 ins. above ground firmly set in a collar of stone, with brass cap mkd. T9S R25E R26E S 25 S 30 S 36 S 31 1960 The cor. is located 3 lks. East of a fence bearing N. and S. Land, rolling. Soil, rocky, sandy loam. No timber; undergrowth, creosote bush, mesquite, cactiand bunchgrass.	ockton Pass Wash area, drains N. 20° E.	
R25E R26E S 25 S 30 S 36 S 31 1960 The cor. is located 3 lks. East of a fence bearing N. and S. Land, rolling. Soil, rocky, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.	t, $2\frac{1}{2}$ ins. diam., projecting 3 ins. above g	ound,
and S. Land, rolling. Soil, rocky, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.	R25E R26E S 25 S 30 S 36 S 31	
Soil, rocky, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.	is located 3 lks. East of a fence bearing	1.
N. 0°08 W., bet. secs. 25 and 30.	cky, sandy loam. r; undergrowth, creosote bush, mesquite, ca	:ti
	W., bet. secs. 25 and 30.	
Over rolling land, along E. side of fence.	ling land, along E. side of fence.	
12.50 Track road, bears SE. and NW.	ad, bears SE. and NW.	
True point for the ½ sec. cor. of secs. 25 and 30, at proportionate dist., falls in a wash in Dutch Henry Can yon, 10 lks. wide, 2 ft. deep, drains NE., impractical to monument.	onate dist., falls in a wash in Dutch Henry lks. wide, 2 ft. deep, drains NE., impracti	Can-

Dependent Resurvey, West Boundary T. 9 S., R. 26 E.

	1. 7 0., R. 20 1.
CHAINS	
44.12	The witness ½ sec. cor. of secs. 25 and 30, monumented by granite stone, 18x10x6 ins., firmly set 10 ins. in the ground, mkd. ½ on W. and WC on E. faces, with mound of stone N.
	At the corner point
	Set the iron post 16 ins. in the ground, mound of stone to top, brass cap mkd.
	T9S R25E R26E
	\mathbf{s} 25 $\int_{-\infty}^{\infty} \mathbf{s}$ 30
	W C 1969
s •	The cor. is located 3 lks. East of a fence bearing N. and S.
	Bury the orig. cor. stone alongside the iron post.
	ar 100101 IV hardwalani mary mba quanomont
	N. 0°12' W., beginning new measurement.
	Over rolling land, along E. side of fence.
34.70	Cor. of fences, bears N., N. 83° E. and S.
36.04	Point for the cor. of secs. 19, 24, 25 and 30, at proportionate dist.; there is no remaining evidence of the orig. cor.
	Set the iron post 20 ins. in the ground, brass cap mkd.
:	T9S R25E R26E S 24 S 19 S 25 S 30 1969
	The cor. is located 2 lks. West of a fence bearing N. and S.
	Set a wooden post, 3 ft. long, 3 ins. diam., alongside the iron post.
	Land, rolling. Soil, rocky, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.
	N. 0°12' W., bet. secs. 19 and 24.
	Over rolling land, along W. side of fence.
26.00	Dutch Henry Canyon, 20 lks. wide, 1 ft. deep, drains NW.
40.05	Point for the ½ sec. cor. of secs. 19 and 24, at pro-
	portionate dist.

Dependent Resurvey, West Boundary T. 9 S., R. 26 E.

	, 1. 5 b., R. 20 E.
CHAINS	
	Set the iron post 20 ins. in the ground, brass cap mkd.
	T9S R25E R26E
	S 24 S 19 1969
es.	The cor. is located 11 1ks. West of a fence bearing N. and S.
	Set a wooden post, 4 ft. long, 3 ins. diam., alongside the iron post.
41.10	Dutch Henry Canyon, 30 1ks. wide, 6 ins. deep, drains NE.
41.55	Point for the witness ½ sec. cor. of secs. 19 and 24, at proportionate dist.; there is no remaining evidence of the orig. cor.; not monumented.
59.20	Cor. of fences, bears E., 14 1ks. dist., fences bear N., E. and S.
76.20	Veach Canyon, 80 1ks. wide, 2 ft. deep, drains E.
80.10	The cor. of secs. 13, 18, 19 and 24, monumented by an iron post, $2\frac{1}{2}$ ins. diam., projecting 12 ins. above ground in a collar of stone, with brass cap mkd.
	T9S R25E R26E S 13 S 18 S 24 S 19 1960
	The cor. is located 2 lks. West of a fence bearing N. and S.
	Land, rolling. Soil, rocky, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.
	North, bet. secs. 13 and 18.
	Over rolling land, along fence bearing N. and S.
14.50	Spring Canyon, 100 lks. wide, 2 ft. deep, drains irregularly E.
23.90	Wash, 30 1ks. wide, 2 ft. deep, drains NE.
40.10	Track road, bears irregularly E. and W.
40.19	The ½ sec. cor. of secs. 13 and 18, monumented by an iron post, 2½ ins. diam., projecting 6 ins. above ground, in a collar of stone, with brass cap mkd.
	T9'S R25E R26E
•	s 13 s 18 1960
	1

.9.

Dependent Resurvey, West Boundary . T. 9 S., R. 26 E.

CHAINS	
	The cor. is located 3 lks. East of a fence bearing N. and S.
	N. 0°03' W., beginning new measurement.
	Over rolling land, along E. side of fence.
40.04	The cor. of secs. 7, 12, 13 and 18, monumented by an iron post, $2\frac{1}{2}$ ins. diam., projecting 6 ins. above ground, in a collar of stone, brass cap mkd.
	T9S R25E R26E S 12 S 7 S 13 S18 1960
	The cor. is located 3 lks. East of a fence bearing N. and S.
	Land, rolling. Soil, rocky, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.
	N 090/1 E hat one 7 and 12
	N. 0°04' E., bet. secs. 7 and 12.
0.16	Over rolling land, along E. side of fence.
0.16	Fence, bears E. and W., 3 lks. dist. to cor. of fences bearing N., E. and S.
40.10	Point for the ½ sec. cor. of secs. 7 and 12, at proportionate dist.; there is no remaining evidence of the orig. cor.
	Set the iron post 18 ins. in the ground, collar of stone to top, brass cap mkd.
	T9S R25E R26E
•	s 12 s 7 1969
ì	The cor. is located 7 lks. East of a fence bearing N. and S.
46.90	Wash, 40 1ks. wide, 2 ft. deep, drains irregularly E.
78.20	Lefthand Canyon, 40 lks. wide, 2 ft. deep, drains irregularly E.
80.20	Point for the cor. of secs. 1, 6, 7 and 12, at proportionate dist.; there is no remaining evidence of the orig. cor.

Dependent Resurvey, West Boundary . T. 9 S., R. 26 E.

	1. 9 S., R. 20 L.
CHAINS	
,	Set the iron post 14 ins. in the ground, mound of stone to top, brass cap mkd.
	T9S R25E R26E S 1 S 6 S12 S 7 1969
·	The cor. is located 13 lks. East of a fence bearing N. and S.
	Land, rolling. Soil, rocky, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.
	N. 0°04' E., bet. secs. 1 and 6.
•	Over rolling land, along E. side of fence.
4.10	Track road, bears irregularly E. and W.
16.00	Ascend steep SW. slope.
20.05	Point for the S 1/16 sec. cor. of secs. 1 and 6, at proportionate dist.
	Set the iron post 10 ins. in the ground, mound of stone to top, brass cap mkd.
	T9S R25E R26E S 1/16 S 1 S 6
	1969
	from which
·	A local cor. bear's S. 80° W., 4 lks. dist., monumented by a 2 in. brass tablet set in a concrete post, 3 ins. square, mkd. NW COR LOT 7 SEC 6 RE 1231 1950.
	The cor. is located 18 lks. East of a fence bearing N. and S.
30.50	Top of ascent; thence over flat mesa.
40.10	The ½ sec. cor. of secs. 1 and 6, monumented by an iron post, 2½ ins. diam., projecting 12 ins. above ground, in a collar of stone, brass cap mkd.
	T9S R25E R26E \$ 1 S 6
	1960

Dependent Resurvey, West Boundary T. 9 S., R. 26 E.

CHAINS	The cor. is located 6 lks. East of a fence bearing N. and S.
	N. 0°04' E., beginning new measurement.
	Over rolling land, along E. side of fence.
4.70	Descend steep N. slope.
15.40	Wash, 40 1ks. wide, 3 ft. deep, drains irregularly E.; ascend steep S. slope.
31.20	Top of ascent; thence over rolling land.
32.20	Irrigation ditch, 3 lks. wide, 6 ins. deep, flows S. 70° E. from S. 50° W.
36.11	The closing cor. of Tp. 9 S., Rs. 25 and 26 E., on the N. bdy. of the Tp., monumented by a sandstone, 14x14x5 ins., loosely set in a mound of stone, mkd. with 6 grooves and CC on S. face.
	At the corner point · · ·
-	Set the iron post 8 ins. in the ground, mound of stone to top, brass cap mkd.
•	S 36 S 1 S 6 R25E R26E T9S C C 1969 from which The cor. of Tp. 8 S., Rs. 25 and 26 E., bears N. 88°14' E., 4.64 chs. dist., monumented by an iron post, 2½ ins. diam., as described in the field notes of the retracement of the S. bdy. of T. 8 S., R. 26 E., concurrently retraced under Group 470. The ½ sec. cor. of secs. 36, T. 8 S., R. 25 E., bears S. 88°14' W., 35.38 chs. dist., monumented by an iron post, 2½ ins. diam., projecting 10 ins. above ground, in a mound of stone, brass cap mkd. T8S R25E ½ S 36 1960 A cor. of fences, bears West, 14 1ks. dist., fences bear S. and W. Land, rolling. Soil, rocky, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.

Dep. Resurvey, Portion Subdivisional Lines, T. 9 S., R. 26 E.

CHAINS	
•	Dependent Resurvey, Portion of the Subdivisional Lines, T. 9 S., R. 26 E.
	Reestablishment of the Survey executed by P. Contzen in 1904
	From the cor. of secs. 1, 2, 35 and 36, on the S. bdy. of the Tp., monumented by an iron post, 3 ins. diam., projecting 10 ins. above ground, firmly set, mound of stone W., brass cap mkd.
	T9S R26E S 35 S 36 S 2 S 1 T10S 1917
	N. 0°03' W., bet. secs. 35 and 36.
	Over rolling land.
11.60	Wash, 30 lks. wide, 1 ft. deep, drains irregularly E.
40.09	Point for the ½ sec. cor. of secs. 35 and 36, at proportionate dist.; there is no remaining evidence of the orig. cor.
	Set the iron post 16 ins. in the ground, collar of stone to top, brass cap mkd.
	T9S R26E
	s 35 s 36 1969
	Raise a mound of stone W. of the iron post.
74 . 80	Oak Draw, 40 1ks. wide, 1 ft. deep, drains irregularly
80.18	The cor. of secs. 25, 26, 35 and 36, monumented by the remains of a charred wooden post, pieces of which were found from the surface to 18 ins. in the ground, no markings legible.
	At the corner point
•	Set the iron post 22 ins. in the ground, brass cap mkd.
•	T9S R26E S 26 S 25 S 35 S 36 1969
. •	Bury the remains of the orig. cor. alongside the iron post.
	Raise a mound of stone W. of the cor.
	Land, rolling. Soil, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.
	S. 89°58' E., bet. secs. 25 and 36.

. Dep. Resurvey, Portion Subdivisional Lines, T. 9.S., R. 26 E.

	CHAINS	Over rolling land.
	9.20	Oak Draw, 50 1ks. wide, 1 ft. deep, drains NE.
	40.08	The ½ sec. cor. of secs. 25 and 36, monumented by a granite stone, 20x10x3 ins., firmly set 10 ins. in the ground, mkd. ½ on N. face, with a wooden post, 4 ft. long, 4 ins. squared, alongside.
		At the corner point
	•	Set the iron post 20 ins. in the ground, brass cap mkd.
		T9S R26E S 25 S 36 1969
		Bury the orig. cor. stone alongside the iron post.
		Set a wooden post, 4 ft. long, 4 ins. squared alongside the cor.
	•	N. 89°10' E., beginning new measurement.
		Over rolling land.
	31.60	Track road, bears NE. and SW.
	40.71	Point for the closing cor. of secs. 25 and 36, on the E. bdy. of the Tp., at proportionate dist.; there is no remaining evidence of the orig. cor.
		Set the iron post 20 ins. in the ground, brass cap mkd.
	·	T9S R26E R27E CC
,	a	from which
		The cor. of secs. 30 and 31, T. 9 S., R. 27 E., bears S. 0°25' W., 52 lks. dist., hereinbefore described.
	·	A U.S.G.S. benchmark, bears N. 0°50'20" E., 22.272 chs. dist., monumented by a standard U.S.G.S. benchmark disk set in concrete in the top of a 6 in. pipe projecting 6 ins. above ground, with disk stamped 23RS 3635 1941, Latitude, 32°37'07.105" N., Longitude, 109°37'49.481" W.
		Deposit glass at the base of the iron post.
		Land, rolling. Soil, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.
		From the cor. of secs. 25, 26, 35 and 36.
-		1

Dep. Resurvey, Portion Subdivisional Lines, T. 9.S., R. 2	odivisional Lines. I. 9 S., R. 26 E.	Dep. Resurvey, Portion
---	--------------------------------------	------------------------

CHAINS	
	N. 0°01' W., bet. secs. 25 and 26.
	Over rolling land.
5.20	Wash, 20 1ks. wide, 1 ft. deep, drains N. 80° E.
33.00	Tanque Road, bears irregularly NE. and SW.
40.05	The ½ sec. cor. of secs. 25 and 26, monumented by a granite stone, 18x10x8 ins., loosely set in the ground, mkd. ½ on a face, with a wooden post, 4 ft. long, 4 ins. squared alongside.
	At the corner point
	Set the iron post 22 ins. in the ground, brass cap mkd.
	T9S R26E
	5 26 S 25 1969
	Bury the orig. cor. stone alongside the iron post.
	Set a wooden post, 4 ft. long, 4 ins. squared, alongside the cor.
	• .
	N. 0°03' W., beginning new measurement.
c	Over rolling land.
21.90	Wash, 50 lks. wide, 1 ft. deep, drains irregularly E.
40.09	The cor. of secs. 23, 24, 25 and 26, monumented by a granite stone, 18x8x6 ins., firmly set 8 ins. in the ground, mkd. with 1 notch on E. and 2 notches on S. edges, with a wooden post, 4 ft. long, 4 ins. squared, alongside.
	At the corner point
	Set the iron post 20 ins. in the ground, brass cap mkd.
•	T9S R26E S 23 S 24 S 26 S 25 1969
•	Cor. is in a fence line bearing E. and W.
	Bury the orig. cor. stone alongside the iron post.
	Set a wooden post, 4 ft. long, 4 ins. squared, alongside the cor.
	Land, rolling. Soil, sandy loam. No timber, undergrowth, creosote bush, mesquite, cacti and bunchgrass.
	East, bet. secs. 24 and 25.
	Over rolling land, along fence line.

Den	Resurvey	Portion	Subdivisional	Lines.	Т.	.9	S.,	R.	26	Ε.
Dep.	Mesurvey,	TOLCION	Danatararonar	TITLE 5	⊥ .	٠,	υ.,	17.	20	ш•

CHAINS	
13.80	Wash, 20 1ks. wide, 1 ft. deep, drains NE.
35.00	Fence, bears SE. and W.
40.08	The ½ sec. cor. of secs. 24 and 25, monumented by a granite stone, 14x8x8 ins., firmly set 8 ins. in the ground, mkd. ½ on N. face.
	At the corner point
	Set the iron post 16 ins. in the ground, mound of stone to top, brass cap mkd.
	T9S R26E 2 S 24 S 25 1969
	Bury the orig. cor. stone alongside the iron post.
	N. 88°30' E., beginning new measurement.
	Over rolling land.
35.40	Wash, 40 lks. wide, 1 ft. deep, drains irregularly N.
41.38	Point for the closing cor. of secs. 24 and 25, on the E. bdy. of the Tp., at proportionate dist.; there is no remaining evidence of the orig. cor.
5	Set the iron post 18 ins. in the ground, collar of stone to top, brass cap mkd.
	T9S $R26E \mid R27E$ $CC = \frac{S}{S} \frac{24}{5} \mid S \mid 19$ 1969
	from which .
	The cor. of secs. 19 and 30, T. 9 S., R. 27 E., bears S. 0°01' E., 1.07 chs. dist., hereinbefore described.
	The cor. is located 4 lks. West of a fence bearing N. and S.
	Land, rolling. Soil, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.
	The point for the ½ sec. cor. of sec. 25 only, is at mid-point between the closing corners, and on the E. bdy. of the Tp.
	At the corner point
	Set the iron post 20 ins. in the ground, brass cap mkd.

Dep.	Resurvey,	Portion	Subdivisional	Lines.	Т.	9	S.,	R.	26	Ε.
F	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		Deservicer		•		.,	T/ •	-0	

	CHAINS	
		T9s
		R26E
		1969
		from which
	3	The ½ sec. cor. of sec. 30, T. 9 S., R. 27 E., bears S. 0°24' W., 2.45 chs. dist., hereinbefore described.
		The cor. is located 9 lks. West of a fence bearing N. and S.
		Deposit glass at the base of the iron post.
		From the cor. of secs. 23, 24, 25 and 26.
		N. 0°01' W., bet. secs. 23 and 24.
		Over rolling land.
	26.00	Wash, 30 1ks. wide, 1 ft. deep, drains N. 80° E.
	40.09	The ½ sec. cor. of secs. 23 and 24, monumented by a granite stone, 20x10x8 ins., firmly set 10 ins. in the ground, mkd. ½ on W. face, with a wooden post, 4 ft. long, 4 ins. squared, alongside.
		At the corner point
		Set the iron post 20 ins. in the ground, brass cap mkd.
		T9S R26E
		2 22 2 2 4
		S 23 S 24 1969
		Bury the orig. cor. stone alongside the iron post.
		Set a wooden post, 4 ft. long, 4 ins. squared, alongside the cor.
	•	
		N. 0°01' W., beginning new measurement.
	•	Over rolling land.
	18.00	Wash, 20 1ks. wide, 6 ins. deep, drains N. 85° E.
	32.20	Wash, 20 1ks. wide, 1 ft. deep, drains N. 60° E.
	40.10	The cor. of secs. 13, 14, 23 and 24, monumented by a granite stone, 18x10x8 ins., firmly set 10 ins. in the ground, mkd. with 1 notch on E. and 3 notches on S. edges, with a wooden post, 4 ft. long, 4 ins. squared, alongside.
		At the corner point
		Set the iron post 22 ins. in the ground, brass cap mkd.
		T9S R26E
		<u>s 14 s 13</u> s 23 s 24 1969
١		

Dep. Resurvey, Portion Subdivisional Lines, T. 9 S., R. 26 E.

CHAINS

Bury the orig. cor. stone alongside the iron post.

Set a wooden post, 4 ft. long, 4 ins. squared, alongside the cor.

Land, rolling.

Soil, sandy loam.

No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.

N. 89°58' E., bet. secs. 13 and 24.

Over rolling land.

Wash, 20 1ks. wide, 1 ft. deep, drains N. 20° E. 8.20

The $\frac{1}{4}$ sec. cor. of secs. 13 and 24, monumented by a 40.03 wooden post, 2 ft. long, 3 ins. squared, lying loose on the ground, remains of the post were found in the hole which the post had occupied; no markings legible.

At the corner point

Set the iron post 18 ins. in the ground, brass cap mkd.

Bury the orig. cor. post alongside the iron post.

Set a wooden post, 4 ft. long, 4 ins. squared, alongside the cor.

S. 89°54' E., beginning new measurement.

Over rolling land.

Point for the closing cor. of secs. 13 and 24, on the E. 41.49 bdy. of the Tp., at proportionate dist.; there is no remaining evidence of the orig. cor.

Set the iron post 20 ins. in the ground, brass cap mkd.

$$\begin{array}{c|c}
 & T9S \\
 & R26E & R27E \\
 & S & 13 & S & 18 \\
 & 1969 & & & \\
\end{array}$$

from which

The cor. of secs. 18 and 19, T. 9 S., R. 27 E., bears S. 0°09' W., 1.62 chs. dist., hereinbefore

The cor. is located 4 lks. West of a fence bearing N. and

Land, rolling.

Soil, sandy loam.

No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.

Dep. Resurvey, Portion Subdivisional Lines, T. 9 S., R. 26 E.

, D	ep. Resurvey, Portion Subdivisional Lines, T. 9 S., R. 26
CHAINS	
	The point for the ½ sec. cor. of sec. 24 only, is at midpoint between the closing corners and on the E. bdy. of the Tp.
	At the corner point
	Set the iron post 22 ins. in the ground, brass cap mkd.
	T9S R26E
	1969
	from which
	The ½ sec. cor. of sec. 19, T. 9 S., R. 27 E., bears S. 0°01' W., 1.30 chs. dist., hereinbefore described.
•	The cor. is located 3 lks. West of a fence bearing N. and S.
v	From the cor. of secs. 13, 14, 23 and 24.
	N. 0°02' W., bet. secs. 13 and 14.
	Over gently rolling_land.
40 . 06	The ½ sec. cor. of secs. 13 and 14, monumented by a granite stone, 18x8x6 ins., firmly set 10 ins. in the ground, mkd. ½ on W. face.
	At the corner point
	Set the iron post 20 ins. in the ground, brass cap mkd.
	T9S R26E
	s 14 s 13 1969
•	Bury the orig. cor. stone alongside the iron post.
	Set a wooden post, 4 ft. long, 4 ins. squared, alongside the cor.
	N. 0°02' W., beginning new measurement.
	Over gently rolling land.
7.90	Wash, 60 lks. wide, 1 ft. deep, drains NE.
40.04	The cor. of secs. 11, 12, 13 and 14, monumented by a granite stone, 18x10x8 ins., firmly set 10 ins. in the ground, mkd. with 1 notch on E. and 4 notches on S. edges.
	At the corner point
•	Set the iron post 20 ins. in the ground, brass cap mkd.
	T9S R26E S 11 S 12 S 14 S 13 1969

·Dep. Resurvey, Portion Subdivisional Lines, T. 9 S., R. 26 E.

CHAINS

Bury the orig. cor. stone alongside the iron post.

Set a wooden post, 4 ft. long, 4 ins. squared, alongside the cor.

Land, gently rolling.

Soil, sandy loam.

No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.

East, bet. secs. 12 and 13.

Over gently rolling land.

15.30 Wash, 20 1ks. wide, 1 ft. deep, drains NE.

The ½ sec. cor. of secs. 12 and 13, monumented by a granite stone, 16x8x8 ins., firmly set 8 ins. in the ground, mkd. ½ on N. face.

At the corner point

Set the iron post 20 ins. in the ground, brass cap mkd.

Bury the orig. cor. stone alongside the iron post.

Set a wooden post, 4 ft. long, 4 ins. square, alongside the cor.

N. 89°54' E., beginning new measurement.

Over gently rolling land.

30.40 Wash, 80 1ks. wide, 1 ft. deep, drains NE.

The closing cor. of secs. 12 and 13 on the E. bdy. of the Tp., monumented by a granite stone, 16x6x6 ins., firmly set 8 ins. in the ground, mkd. with 2 notches on N. and 4 notches on S. edges, with CC on W. face.

At the corner point

Set the iron post 24 ins. in the ground, brass cap mkd.

$$\begin{array}{c|c}
 & T9S \\
 & R26E \mid R27E \\
 \hline
 & S \mid 12 \mid S \mid 7 \\
 & 1969
\end{array}$$

from which

The cor. of secs. 7 and 18, T. 9 S., R. 27 E., bears S. 0°11' W., 2.17 chs. dist., hereinbefore described.

The cor. is located 3 lks. West of a fence bearing N. and S.

Bury the orig. cor. stone alongside the iron post.

Dep. Resurvey, Portion Subdivisional Lines, T. 9 S., R.

CHAINS

Set a wooden post, 4 ft. long, 4 ins. square, alongside the cor.

Land, gently rolling.

Soil, sandy loam.

No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.

The point for the $\frac{1}{4}$ sec. cor. of sec. 13 only, is at midpoint between the closing corners and on the E. bdy. of the Tp.

At the corner point

Set the iron post 20 ins. in the ground, brass cap mkd.

T9.S R26E 表 S 13

from which

The $\frac{1}{4}$ sec. cor. of sec. 18, T. 9 S., R. 27 E., bears S. 0°05' W., 1.915 chs. dist., hereinbefore described.

The cor. is located 5 lks. West of a fence bearing N. and S.

Set a wooden post, 4 ft. long, 4 ins. square, alongside the iron post.

From the cor. of secs. 11, 12, 13 and 14.

North, bet. secs. 11 and 12.

Over gently rolling land.

2.40 Foote Draw, 50 lks. wide, 1 ft. deep, drains irregularly

18.00 Enter Foote Draw, 110 lks. wide, 1 ft. deep, drains irregularly N. from SE.

32.00 | Leave Foote Draw, drains irregularly NE. from S.

The ½ sec. cor. of secs. 11 and 12, monumented by a granite stone, 14x10x8 ins., firmly set 8 ins. in the ground, mkd. ½ on W. face.

At the corner point

Set the iron post 18 ins. in the ground, collar of stone to top, brass cap mkd.

T9S R26E ・ え S 11 | S 12 1969

Bury the orig. cor. stone alongside the iron.post.

Dep. Resurvey, Portion Subdivisional Lines, T. 9 S., R. 26	Dep.	Resurvey,	Portion	Subdivisional	Lines,	Τ.	9 S.,	R.	26	Ε,
--	------	-----------	---------	---------------	--------	----	-------	----	----	----

	bep. Reservey, terrere
CHAINS	
•	N. 0°03' W., beginning new measurement.
	Over gently rolling land.
12.40	Wash, 70 lks. wide, 1 ft. deep, drains irregularly NE.
40.09	The cor. of secs. 1, 2, 11 and 12, monumented by a granite stone, 14x10x10 ins., firmly set 8 ins. in the ground, mkd. with 1 notch on E. and 5 notches on S. edges.
•	At the cor. point
	Set the iron post 22 ins. in the ground, brass cap mkd.
•	T9S R26E S 2 S 1 S 11 S 12 1969
	Bury the orig. cor. stone alongside the iron post.
	Set a wooden post, 4 ft. long, 3 ins. square, alongside the cor.
	Land, gently rolling. Soil, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.
•	N. 89°56' E., bet. secs. 1 and 12.
	Over gently rolling land.
14.50	Foote Draw, 100 lks. wide, 1 ft. deep, drains N. 20° W.
40.14	Point for the ½ sec. cor. of secs. 1 and 12, at proportionate dist.; there is no remaining evidence of the orig. cor.
ō	Set the iron post 20 ins. in the ground, brass cap mkd.
	T9S R26E 2 S 1 S 12 1969
	Deposit glass at the base of the iron post.
71.70 ·	Wash, 20 1ks. wide, 1 ft. deep, drains NE.
81.98	Point for the closing cor. of secs. 1 and 12, on the E. bdy. of the Tp., at proportionate dist.; there is no remaining evidence of the orig. cor.
	Set the iron post 20 ins. in the ground, brass cap mkd.
	T9S R26E R27E CC S 1 S 6 1969
	from which
	The cor. of secs. 6 and 7, T. 9 S., R. 27 E., bears S. 0°05' W., 3.01 chs. dist., hereinbefore described.

Dep. Resurvey, Portion Subdivisional Lines, T. 9 S., R. 26 E.

CHAINS

The cor. is located 2 lks. West of a fence bearing N. and S.

Deposit glass at the base of the iron post.

Land, gently rolling.

Soil, sandy loam.

No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.

The point for the $\frac{1}{4}$ sec. cor. of sec. 12 is at midpoint between the closing corners and on the E. bdy. of the Tp.

At the corner point

Set the iron post 20 ins. in the ground, brass cap mkd.

from which

The $\frac{1}{4}$ sec. cor. of sec. 7, T. 9 S., R. 27 E., bears S. 0°07' W., 2.64 chs. dist., hereinbefore described.

The cor. is located 3 lks. West of a fence bearing N. and S.

Deposit glass at the base of the iron post.

The point for the $\frac{1}{4}$ sec. cor. of sec. 1 is at proportionate dist. and on the E. bdy. of the Tp.

At the corner point

Set the iron post 20 ins. in the ground, brass cap mkd.

from which

The ½ sec. cor. of sec. 6, T. 9 S., R. 27 E., bears S. 0°03' W., 3.29 chs. dist., hereinbefore described.

The cor. is located 1 lk. West of a fence bearing N. and S.

Deposit glass at the base of the iron post.

From the cor. of secs. 1, 2, 11 and 12.

N. 0°02' W., bet. secs. 1 and 2.

Over gently rolling land.

0.78 Fence bears W. and E., 2.68 chs. dist. to cor. of fences bearing N. and W.

Dep.	Resurvey.	Portion	Subdivisional	Lines.	Т(9 S.	R.	26	Ε.
cp.	incour very	TOTETOIL	Dabatitonar			, ,,	1.	~0	

	rep. Resurvey, Tottlon Subdivisional Lines, 1. 9 3., R. 20 E.
CHAINS	
24.70	Low ridge, bears N. 55° E. and S. 55° W.
40 . 05	Point for the ½ sec. cor. of secs. 1 and 2, at proportionate dist.; there is no remaining evidence of the orig. cor.
*	Set the iron post 20 ins. in the ground, brass cap mkd.
	T9S R26E
6 5	S 2 S 1 1969
	Deposit glass at the base of the iron post.
63.80	Track road, bears N. 87° E. and S. 87° W.
76.36	Fence, bears E. and W.
76.37	Point for the closing cor. of secs. 1 and 2 on the N. bdy. of the Tp., at proportionate dist.; there is no remaining evidence of the orig. cor.
	Set the iron post 20 ins. in the ground, brass cap mkd.
,	T8S R26E S 35 S 2 S 1
	C C T9S R26E 1969
	from which
	The cor. of secs. 35 and 36, T. 8 S., R. 26 E., bears N. 89°50' E., 2.73 chs. dist., monumented by an iron post, $2\frac{1}{2}$ ins. diam., as described in the field notes of the S. bdy., T. 8 S., R. 26 E., concurrently retraced under Group 470.
	Set a wooden post, 4 ft. long, 4 ins. square, alongside the iron post.
	Land, gently rolling to nearly level. Soil, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.
٥	The point for the ½ sec. cor. of sec. 1 is at proportionate dist. and on the N. bdy. of the Tp.
	At the corner point
	Set the iron post 20 ins. in the ground, brass cap mkd.
	from which
	The ½ sec. cor. of sec. 36, T. 8 S., R. 26 E., bears N. 89°48' E., 2.30 chs. dist., monumented

Dep. Resurvey, Portion Subdivisional Lines, T. 9 S., R. 26 E.

, ,D	ep. Resurvey, Portion Subdivisional Lines, T. 9 S., R. 26 E
CHAINS	
	by an iron post, $2\frac{1}{2}$ ins. diam., as described in the field notes of the S. bdy., T. 8 S., R. 26 E., concurrently retraced under Group 470.
	The cor. is located 1 lk. North of a fence bearing E. and W.
	Raise a mound of stone S. of the iron post.
	From the cor. of secs. 2, 3, 34 and 35, on the S. bdy. of the Tp., monumented by an iron post, 3 ins. diam., projecting 14 ins. above ground, mound of stone W., with brass cap mkd.
	T9S R26E
	<u>s 34 s 35</u>
•	S 3 S 2 T10S 1917
	N. 0°01' W., bet. secs. 34 and 35.
,	Over rolling land.
4.50	Oak Draw, 150 1ks. wide, 2 ft. deep, drains N. 65° E.
40.06	The $\frac{1}{4}$ sec. cor. of secs. 34 and 35, monumented by a granite stone, $12x8x3$ ins., firmly set 6 ins. in the ground, mkd. $\frac{1}{4}$ on W. face.
	At the corner point
. •	Set the iron post 18 ins. in the ground, collar of stone to top, brass cap mkd.
ø	T9S R26E
	s 34 s 35 1969
	N. 0°01' W., beginning new measurement.
	Over rolling land.
27.00	Wash, 20 lks. wide, 1 ft. deep, drains irregularly E.
37.90	Wash, 50 lks. wide, 1 ft. deep, drains irregularly E.
40.03	The cor. of secs. 26, 27, 34 and 35, monumented by a granite stone, 20x8x6 ins., firmly set 10 ins. in the ground, mkd. with 2 notches on E. and 1 notch on S. edges.
	At the corner point
	Set the iron post 20 ins. in the ground, brass cap mkd.
	T9S R26E
	<u>s 27 s 26 3 25 3 25 3 35 3</u>
٠	S 34 S 35
·	from which
•	A U.S.G.S. benchmark, bears S. 87°47' E., 13.96 chs. dist., monumented by a standard U.S.G.S. benchmark disk set in concrete, with disk stamped 24 RS Elevation above sea 3799 1941.
	<u> </u>

·Dep.	Resurvey,	Portion	S ubdivisional	Lines,	т.	9	S.,	R.	26	Ε.	

. Dep	Resurvey, Portion Subdivisional Lines, T. 9 S., R. 26 E.
CHAINS	
	Bury the orig. cor. stone alongside the iron post.
	Raise a mound of stone W. of the cor.
	Land, gently rolling.
	Soil, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti
	and bunchgrass.
	From the cor. of secs. 25, 26, 35 and 36.
	N. 89°58' W., bet. secs. 26 and 35.
	Over rolling land.
6.90	Wash, 30 1ks. wide, 6 ins. deep, drains N. 60° E.
11.40	Same wash, 30 lks. wide, 6 ins. deep, drains SE.
19.40	Same wash, 30 lks. wide, 6 ins. deep, drains N. 20° E.
40.00	The ½ sec. cor. of secs. 26 and 35 monumented by the remains of a wooden post, badly rotted, evidence of the post was found to a depth of 18 ins. in the ground, no markings legible.
	At the corner point
	Set the iron post 20 ins. in the ground, brass cap mkd.
•	T9S R26E
	½ <u>S 26</u> 3 35
	1969
	Bury the orig. cor. post alongside the iron post.
•	West, beginning new measurement.
	Over rolling land.
26.20	Tanque Road, bears N. 60° E. and S. 60° W. curving to W. A track road bears SE. from a point 40 lks. S. 60° W.
30.70	Tanque Road, bears N. 60° W. from S. 60° E.
32.90	Wash, 50 1ks. wide, 1 ft. deep, drains N. 20° E.
40.06	The cor. of secs. 26, 27, 34 and 35.
	Land, rolling. Soil, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.
	N. 0°02' E., bet. secs. 26 and 27.
	Over rolling land.
4.80	Tanque Road, bears S. 60° E. and N. 60° W., 2.00 chs. dist., thence westerly.
21.20	Wash, 30 1ks. wide, 1 ft. deep, drains E.
i	1

Dep.	Resurvey,	Portion	S ubdivisional	Lines,	Τ.	9	S,,	R.	26	Ε.
------	-----------	---------	-----------------------	--------	----	---	-----	----	----	----

	Residence, Totalon Bubulivisional Lines, 1. 9 5., R. 20 E.
40.07	The ½ sec. cor. of secs. 26 and 27, monumented by a granite stone, 14x8x8 ins., firmly set 8 ins. in the ground, mkd. ½ on W. face.
	At the corner point
	Set the iron post 12 ins. in the ground, mound of stone to top, brass cap mkd.
	T9S R26E \$ 27 S 26
	from which
	A United States Soil Erosion Service triangulation station, bears S. 72°01'30" W., 15.47 chs. dist., monumented by a standard disk set in a 6x6 in. concrete post with disk stamped 19 YARGON 35.
	Bury the orig. cor. stone alongside the iron post.
	N. 0°02' W., beginning new measurement.
	Over rolling land.
25.10	Track road, bears irregularly N. 70° E. and S. 70° W.
39.40	Track road, bears irregularly S. 50° E. and S. 70° W.
40.08	The cor. of secs. 22, 23, 26 and 27, marked by a cor. of fences, bearing N. and E. This position is harmoniously related to existing orig. cors. and is accepted as the best available evidence of the position of the orig. cor.
	At the corner point
	Set the iron post, 22 ins. in the ground, brass cap mkd.
	T9S R26E S 22 S 23 S 27 S 26 1969
	Set a wooden post, 5 ft. long, 4 ins. square, alongside the iron post.
	Land, rolling. Soil, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.
	From the cor. of secs. 23, 24, 25 and 26.
	N. 89°57' W., bet. secs. 23 and 26.
	Over rolling land, along fence line.
32.70	Wash, 40 1ks. wide, 2 ft. deep, drains N. 30° E.
39.97	Point for the ½ sec. cor. of secs. 23 and 26, at proportionate dist.; there is no remaining evidence of the orig. cor.

Dep. Resurvey, Portion Subdivisional Lines, T. 9 S., R. 2

DE	p. Resurvey, Forcion Subdivisional Lines, 1. 9 S., R. 20 I
CHAINS	Set the iron post 22 ins. in the ground, brass cap mkd.
	T9S R26E 1 S 23 2 S 26 1969
e gre ed	The cor. is located 6 lks. North of a fence bearing E. and W.
	Set a wooden post, 4 ft. long, 3 ins. square, alongside the iron post.
79.94	The cor. of secs. 22, 23, 26 and 27.
*	Land, rolling. Soil, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.
	North, bet. secs. 22 and 23.
•	Over rolling land, along fence line.
0.20	Wash, 30 lks. wide, 1 ft. deep, drains irregularly NE.
4.70	Wash, 150 1ks. wide, 2 ft. deep, drains E.
24.20	Wash, 30 1ks. wide, 1 ft. deep, drains SE. curving E.
. 40.08 .	The $\frac{1}{2}$ sec. cor. of secs. 22 and 23, monumented by a granite stone, $15 \times 12 \times 5$ ins., firmly set 8 ins. in the ground, mkd. $\frac{1}{2}$ on W. face.
	At the corner point
	Set the iron post 20 ins. in the ground, brass cap mkd.
	T9S R26E
	s 22 s 23 1969
	Cor. is in a fence line bearing N. and S.
	Bury the orig. cor. stone alongside the iron post.
	Set a wooden post, 5 ft. long, 4 ins. squared, alongside the cor.
	North, beginning new measurement.
	Over rolling land, along fence line.
11.30	Wash, 40 lks. wide, 1 ft. deep, drains irregularly E.
39.00	Wash, 50 lks. wide, 1 ft. deep, drains N. 35° E.
40.07	Point for the cor. of secs. 14, 15, 22 and 23, at proportionate dist.
	Set the iron post 20 ins. in the ground, brass cap mkd.
	T9S R26E S 15 S 14 S 22 S 23 1969

Dep. Resurvey, Portion Subdivisional Lines, T. 9 S., R. 26 E.

_		pep. Resurvey, Fortion Subdivisional Lines, 1. 9 S., R. 26 E
	CHAINS	The cor. is located 3 lks. W. of a fence bearing N. and S.
		Set a wooden post, 4 ft. long, 3 ins. square, alongside the iron post.
		Land, rolling. Soil, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.
		From the cor. of secs. 13, 14, 23 and 24.
		N. 89°59' W., bet. secs. 14 and 23.
		Over rolling land.
	39.94	Point for the ½ sec. cor. of secs. 14 and 23, at proportionate dist.; there is no remaining evidence of the orig. cor.
		Set the iron post 20 ins. in the ground, brass cap mkd.
		T9S R26E
	e	$\frac{1}{4} \frac{\text{S. } 14}{\text{S. } 23}$
		1969
	•	from which
		A water tank and well, bears N. 0°22' E., 22.78 chs. dist.
		Set a wooden post, 2 ft. long, 3 ins. square, alongside the iron post.
	42.50	Wash, 50 lks. wide, 2 ft. deep, drains N.
	79.20	Wash, 50 lks. wide, 1 ft. deep, drains N. 35° E.
	79.88	The cor. of secs. 14, 15, 22 and 23.
		Land, rolling. Soil, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.
		North, bet. secs. 14 and 15.
ł		Over gently rolling land along fence line.
	2.00	The original witness cor. of secs. 14, 15, 22 and 23, monumented by a granite stone, 8x6x6 ins. above ground, firmly set 6 ins. in the ground, mkd. with 2 notches on E. and 3 notches on S. edges, and WC on NE. face; not remonumented. Cor. is 2 lks. E. of a fence bearing N. and S.
	11.30	Fence, bears W. and E., 2 lks. dist., to cor. of fences bearing S. and W.
	12.40	Track road, bears irregularly E. and W.
	16.50	Wash, 60 lks. wide, 2 ft. deep, drains E.

Dep. Resurvey, Portion Subdivisional Lines, T. 9 S., R. 26 E.

	ep. Resurvey, Portion Subdivisional Lines, T. 9 S., R. 26 E.
CHAINS	
40.07	The ½ sec. cor. of secs. 14 and 15, monumented by a granite stone, 14x8x6 ins., firmly set 6 ins. in the ground, mkd. ½ on W. face.
	At the corner point
	Set the iron post 12 ins. in the ground, mound of stone to top, brass cap mkd.
	T9S R26E
	S 15 S 14 1969
	Bury the orig. cor. stone alongside the iron post.
	Set a wooden post, 4 ft. long, 4 ins. square, alongside the cor.
	North, beginning new measurement.
	Over gently rolling land.
21.50	Wash, 40 lks. wide, 1 ft. deep, drains N. 75° E.
39.07	The original witness cor. of secs. 10, 11, 14 and 15, monumented by a granite stone, 10x8x8 ins. above ground firmly set, mkd. with 2 notches on E. and 4 notches on S. edges and WC on top; not remonumented.
40.07	Point for the cor. of secs. 10, 11, 14 and 15, at proportionate dist.
	Set the iron post 18 ins. in the ground, collar of stone to top, brass cap mkd.
,	T9S R26E S 10 S 11 S 15 S 14. 1969
	Land, gently rolling. Soil, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.
•	From the cor. of secs. 11, 12, 13 and 14.
	N. 89°52' W., bet. secs. 11 and 14.
	Over gently rolling land.
13.10	Foote Draw, 50 lks. wide, 1 ft. deep, drains NE. from S.
27.70	Wash, 30 lks. wide, 1 ft. deep, drains NE.
39.80	The ½ sec. cor. of secs. 11 and 14, monumented by a granite stone, 15x10x8 ins., firmly set 8 ins. in the ground, mkd. ½ on N. face.
	At the corner point
	Set the iron post 22 ins. in the ground, brass cap mkd.
I	1

Dep. Resurvey, Portion Subdivisional Lines, T. 9 S., R. 26 E.

ب .	ep. Resulvey, Toltion Babary Island Lines, 1. 3 5., 1
CHAINS	Bury the orig. cor. stone alongside the iron post.
	,
	Raise a mound of stone N. of the cor.
	West, beginning new measurement.
	Over gently rolling land.
0.60	Wash, 30 1ks. wide, 1 ft. deep, drains NE.
26.10	Wash, 100 lks. wide, 2 ft. deep, drains NE.
39.99	The cor. of secs. 10, 11, 14 and 15.
,	Land, gently rolling. Soil, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.
	North, bet. secs. 10 and 11.
	Over gently rolling land.
1.10	Wash, 30 1ks. wide, 6 ins. deep, drains NE.
40.08	The ½ sec. cor. of secs. 10 and 11, monumented by a granite stone, 18x10x8 ins., firmly set 10 ins. in the ground, mkd. ½ on W. face.
	At the corner point
	Set the iron post 20 ins. in the ground, collar of stone to top, brass cap mkd.
	T9S R26E
	s 10 s 11 1969
	Bury the orig. cor. stone alongside the iron post.
	North, beginning new measurement.
	Over gently rolling land.
2.70	Wash, 20 1ks. wide, 2 ft. deep, drains N. 75° E.
40.06	The cor. of secs. 2, 3, 10 and 11, monumented by a granite stone, 14x8x8 ins., lying loose on the ground, mkd. with 2 notches and 5 notches on adjacent edges with mound of stone W.
0	At the corner point .
	Set the iron post 8 ins. in the ground, mound of stone to top, brass cap mkd.
	T9S R26E S 3 S 2 S 10 S 11 1969
	Deposit the orig. cor. stone in the mound of stone, alongside the iron post.

·Dep. Resurvey,	Portion	Subdivisional	Lines,	T.9	S.,	R.	26	Ε.
-----------------	---------	---------------	--------	-----	-----	----	----	----

_	1	Jep. Resurvey, Portion Subdivisional Lines, 1. 9 S., R. 20 E.
	CHAINS	
		Land, gently rolling. Soil, sandy loam.
		No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.
		From the cor. of secs. 1, 2, 11 and 12.
		N. 89°58' W., bet. secs. 2 and 11.
		Over gently rolling land.
	38.50	Wash, 40 lks. wide, 2 ft. deep, drains N. 30° E.
	39.88	Point for the ½ sec. cor. of secs. 2 and 11, at proportionate dist.; there is no remaining evidence of the orig. cor.
	q	Set the iron post 10 ins. in the ground, mound of stone to top, brass cap mkd,
		T9S R26E
		\frac{1}{4} \frac{S 2}{S 11} \\ 1969
		The cor. is located 43 lks. South of a fence bearing E. and W.
	50.80	Wash, 20 1ks. wide, 1 ft. deep, drains irregularly N.
	70.60	Wash, 40 lks. wide, 1 ft. deep, drains N. 20° W.
	79.76	The cor. of secs. 2, 3, 10 and 11.
	•	Land, gently rolling. Soil, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.
	:	N. 0°02' W., bet. secs. 2 and 3.
		Over gently rolling land.
	0.07	Fence, bears E. and W.
	17.20	Fence, bears E. and W., 1.30 chs. dist., thence N.
	20.00	S. edge of stock pond, bears irregularly S. 80° E., 5.00 chs. dist., and N. 80° W., 2.00 chs. dist.
	23.70	N. edge of stock pond and dike, 10 ft. high, bears irregularly S. 80° E., 6.00 chs. dist., and N. 80° W., 1.00 chs. dist.
	36.70	Power line and maintenance road, bears N. 20° E. and S. 20° W.
	40.05	The ½ sec. cor. of secs. 2 and 3, monumented by a granite stone, 12x12x6 ins., firmly set 6 ins. in the ground, mkd. ½ on W. face.
	. •	At the corner point
		Set the iron post 22 ins. in the ground, brass cap mkd.
		T9S_R26E
		s 3 s 2
		1969
1		, · · · · · · · · · · · · · · · · · · ·

Dep. Resurvey, Portion Subdivisional Lines, T. 9 S., R. 26 E.

CH	A ·	T 8.7	c
CH	л.	м	8

Bury the orig. cor. stone alongside the iron post.

Raise a mound of stone W. of the cor.

N. 0°02! W., beginning new measurement.

Over gently rolling land.

19.70

Track road, bears E. and W.

36.02

The closing cor. of secs. 2 and 3, on the N. bdy. of the Tp., monumented by a granite stone, 12x12x8 ins., firmly set 8 ins. in the ground, mkd. with 4 notches on E. and 2 notches on W. edges, and CC on N. face.

At the corner point

Set the iron post 22 ins. in the ground, brass cap mkd.

T8S R26E
S 34
S 3 S 2
C C
T9S R26E
1969

from which

The cor. of secs. 34 and 35, T. 8 S., R. 26 E., bears S. 89°57' E., 2.66 chs. dist., monumented by an iron post, $2\frac{1}{2}$ ins. diam., as described in the field notes of the S. bdy., T. 8 S., R. 26 E., concurrently retraced under Group 470.

Bury the original corner stone alongside the iron post.

Land, gently rolling.

Soil, sandy loam.

No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.

The point for the $\frac{1}{2}$ sec. cor. of sec. 2 is at midpoint between the closing corners and on the N. bdy. of the Tp.

At the corner point

Set the iron post 20 ins. in the ground, brass cap mkd.

½ S 2 T9S R26E 1969

from which

The $\frac{1}{4}$ sec. cor. of sec. 35, T. 8 S., R. 26 E., bears N. 89°48' E., 2.69 chs. dist., monumented by an iron post, $2\frac{1}{2}$ ins. diam., as described in the field notes of the S. bdy., T. 8 S., R. 26 E., concurrently retraced under Group 470.

Dep. Resurvey, Portion Subdivisional Lines, T. 9 S., R. 26 E.

CHAINS	Deposit glass at the base of the iron post.
	From the cor. of secs. 26, 27, 34 and 35.
	N. 89°57' W., bet. secs. 27 and 34.
	Over rolling land.
4.30	Wash, 50 lks. wide, 1 ft. deep, drains S. 50° E.
10.90	Same wash, 50 lks. wide, 1 ft. deep, drains N. 70° E.
32.70	Tanque road, bears N. 55° E. and S. 55° W.
40.11	The ½ sec. cor. of secs. 27 and 34, monumented by a granite stone, 18x8x8 ins., firmly set 10 ins. in the ground, mkd. ½ on N. face.
	At the corner point
	Set the iron post 20 ins. in the ground, brass cap mkd.
• •	T9S R26E S 27 S 34 1969
	Bury the orig. cor. stone alongside the iron post.
	Raise a mound of stone N. of the cor.
	West, beginning new measurement.
	Over rolling land.
32.20	Wash, 30 1ks. wide, 1 ft. deep, drains irregularly NE.
40.06	The cor. of secs. 27, 28, 33 and 34, monumented by a granite stone, 24x10x8 ins., firmly set 16 ins. in the ground, mkd. with 3 notches on E. and 1 notch on S. edges.
	At the corner point
	Set the iron post 16 ins. in the ground, mound of stone to top, brass cap mkd.
٠	T9S R26E S 28 S 27 S 33 S 34 1969
	Deposit the orig. cor. stone in the mound of stone along- side the iron post.
	Land, rolling. Soil, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.
	N. 0°01' E., bet. secs. 27 and 28.
	Over rolling land.
5.10	Wash, 30 lks. wide, 2 ft. deep, drains irregularly E.
	1

Dep. R	Resurvey,	Portion	Subdivisional	Lines,	Τ.	9	S.,	R.	26	Ε.
--------	-----------	---------	---------------	--------	----	---	-----	----	----	----

. Де	ep. Resurvey, Portion Subdivisional Lines, T. 9 S., R. 26 E.
CHAINS	
31.40	Wash, 40 lks. wide, 1 ft. deep, drains irregularly NE.
40.07	The ½ sec. cor. of secs. 27 and 28, monumented by a sandstone, 14x8x8 ins., firmly set 8 ins. in the ground, mkd. ½ on W. face.
	At the corner point
	Set the iron post 18 ins. in the ground, collar of stone to top, brass cap mkd.
	T9S R26E
	s 28 s 27 1969
	Bury the orig. cor. stone alongside the iron post.
	N. 0°02' W., beginning new measurement.
٥	Over rolling land.
40.05	The cor. of secs. 21, 22, 27 and 28, monumented by a granite stone, 16x10x8 ins., firmly set 6 ins. in the ground, mkd. with 3 notches on E. and 2 notches on S. edges.
	At the corner point
	Set the iron post 14 ins. in the ground, mound of stone to top, brass cap mkd.
	T9S R26E S 21 S 22 S 28 S 27 1969
	Bury the orig. cor. stone alongside the iron post.
	Land, rolling. Soil, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.
	From the cor. of secs. 22, 23, 26 and 27.
	N. 89°59' W., bet. secs. 22 and 27.
	Over rolling land.
0.20	Wash, 30 lks. wide, 1 ft. deep, drains irregularly NE.
16.80	Wash, 30 lks. wide, 1 ft. deep, drains N. 75° E.
22.40	E. edge of stock pond and dike, 12 ft. high, bears N. 2.00 chs. dist., and S. 4.00 chs. dist.
24.40	W. edge of stock pond, bears N. 1.50 chs. dist., and S. 4.00 chs. dist.
40.08	Point for the ½ sec. cor. of secs. 22 and 27, at proportionate dist.; there is no remaining evidence of the orig. cor.

Dep. Resurvey, Portion Subdivisional Lines, T. 9 S., R. 26 E.

· ·	ep. kesurvey, forcion subdivisional bines, 1. 7 5., k. 20 f
CHAINS	
• .	Set the iron post 22 ins. in the ground, brass cap mkd.
	T9S R26E
	$\frac{1}{4}$ $\frac{\text{S } 22}{\text{S } 27}$
	1969
	Raise a mound of stone N. of the iron post.
52.30	Wash, 30 1ks. wide, 1 ft. deep, drains N. curving NE.
80.16	The cor. of secs. 21, 22, 27 and 28.
	Land, rolling. Soil, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.
	N. 0°01' E., bet. secs. 21 and 22.
	Over rolling land.
12.80	Wash, 20 1ks. wide, 1 ft. deep, drains N. 65° E.
31.40	Track road, bears NE. and SW.
40.06	The ½ sec. cor. of secs. 21 and 22, monumented by a granite stone, 18x10x8 ins., firmly set 10 ins. in the ground, mkd. ½ on W. face.
	At the corner point
•	Set the iron post 18 ins. in the ground, mound of stone to top, brass cap mkd.
	T9S R26E \$ 21 S 22 1969
	Deposit the orig. cor. stone in the mound of stone, along side the iron post.
ь	
	N. 0°10' E., beginning new measurement.
	Over rolling land.
27.80	Power line and maintenance road, bears N. 20° E. and S. 20° W.
37.30	Wash, 100 lks. wide, 1 ft. deep, drains N. 70° W.
40.02	The cor. of secs. 15, 16, 21 and 22, monumented by a granite stone, 16x10x8 ins., firmly set 8 ins. in the ground, mkd. with 3 notches on E. and S. edges.
٥	At the corner point
	Set the iron post 18 ins. in the ground, collar of stone to top, brass cap mkd.
	T9S R26E S 16 S 15 S 21 S 22 1969
	from which
	Cor. of fences bears N. 4°14' E., 22.15 chs. dist., fences bear S. 40° E. and N. 8° W.

Dep.	Resurvey,	Portion	Subdivisional	Lines,	T.	9	S.,	R.	26	Ε.
------	-----------	---------	---------------	--------	----	---	-----	----	----	----

, D	ep. Resurvey, Portion Subdivisional Lines, T. 9 S., R. 26 E.
CHAINS	
	Deposit the orig. cor. stone in the collar of stone.
	Raise a mound of stone W. of the cor.
	Land, rolling. Soil, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.
	From the cor. of secs. 14, 15, 22 and 23.
	N. 89°58' W., bet. secs. 15 and 22.
	Over rolling land.
0.03	Fence, bears N. and S.
29.40	Wash, 50 lks. wide, 1 ft. deep, drains N. 60° E.
39.98	The ½ sec. cor. of secs. 15 and 22, monumented by a granite stone, 14x8x8 ins., firmly set 6 ins. in the ground, mkd. ½ on N. face.
	At the corner point
	Set the iron post 16 ins. in the ground, mound of stone to top, brass cap mkd.
	T9S R26E 1 S 15 S 22 1969
	Deposit the orig. cor. stone in the mound of stone.
	S. 89°58' W., beginning new measurement.
	Over rolling land.
11.50	Wash, 30 1ks. wide, 2 ft. deep, drains NE.
20.70	Track road, bears S. 40° E. and N. 40° W.
35.60	Power line and maintenance road, bears N. 20° E. and S. 20° W.
40.05	The cor. of secs. 15, 16, 21 and 22.
	Land, rolling.
	Soil, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.
	N. 0°09' W., bet. secs. 15 and 16.
	Over gently rolling land.
32.90	Cor. of fences bears East, 1 lks. dist., fences bear N. and S. 8° E.
40.10	The ½ sec. cor. of secs. 15 and 16, monumented by a granite stone, 16x10x8 ins., lying loose on the ground, mkd. ½ on a face. The present cor. location is considered the best available evidence of the position where the corner was originally set.

Den.	Resurvey.	Portion	Subdivisional	Lines.	Т.	9	S.,	R.	26	Ε.
D'CP .	TIC GAT ACA	TOLCION	Danataronar			_	~,	T/ 0		

CHAINS	
CHAINS	At the corner point
	Set the iron post 22 ins. in the ground, brass cap mkd.
	T9S_R26E
	s 16 s 15
	1969
	The cor. is located 4 lks. West of a fence bearing N. and S.
	Bury the orig. cor. stone alongside the iron post.
	Raise a mound of stone W. of the cor.
	N. 0°03' E., beginning new measurement.
	Over gently rolling land along fence line.
15.90	Enter wash area, drains irregularly N. from S. 20° W.
23.90.	Leave wash area, drains irregularly N. 20° E.
40.00	The cor. of secs. 9, 10, 15 and 16, monumented by a granite stone, 18x8x6 ins., firmly set 10 ins. in the ground, mkd. with 3 notches on E. and 4 notches on S. edges.
	At the corner point
	Set the iron post 24 ins. in the ground, brass cap mkd.
	T9S R26E S 9 S 10 S 16 S 15 1969
N.	from which
	Cor. of fences bears West, 3 lks. dist., fences bear S. and W.
Y -	Bury the orig. cor. stone alongside the iron post.
	Land, gently rolling. Soil, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.
	From the cor. of secs. 10, 11, 14 and 15.
	S. 89°51' W., bet. secs. 10 and 15.
	Over gently rolling land.
1.60	Wash, 30 1ks. wide, 6 ins. deep, drains irregularly NE.
19.50	Wash, 40 1ks. wide, 2 ft. deep, drains irregularly N.
40.06	The ½ sec. cor. of secs. 10 and 15, monumented by a granite stone, 14x8x6 ins., firmly set 8 ins. in the ground, mkd. ½ on N. face.
	At the corner point

Dep.	Resurvey,	Portion	Subdivisional	Ļines,	Т.	9	S.,	R.	26	Ε.
------	-----------	---------	---------------	--------	----	---	-----	----	----	----

	ep. Resurvey, Portion Subdivisional Lines, T. 9 S., R. 26 E.
CHAINS	
	Set the iron post 22 ins. in the ground, brass cap mkd.
	T9S R26E
	$\frac{1}{4}$ $\frac{\text{S } 10}{\text{S } 15}$
	1969
	Bury the orig. cor. stone alongside the iron post.
·	Raise a mound of stone N. of the cor.
	N. 89°57' W., beginning new measurement.
	Over gently rolling land.
2.30	Track road, bears irregularly N. and S.
3.80	Wash, 100 1ks. wide, 2 ft. deep, drains N.
4.90	Power line and maintenance road, bears N. 20° E. and S. 20° W.
37.80	Wash, 50 1ks. wide, 2 ft. deep, drains NW. from S.
40.06	The cor. of secs. 9, 10, 15 and 16.
	Land, gently rolling.
	Soil, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.
	N. 0°08' E., bet. secs. 9 and 10.
	Over gently rolling land.
1.00	Enter wash area, drains irregularly N. from SE.
23.00	Leave wash area which terminates at a dike and stock pond, dike 8 ft. high, bears irregularly E., 1.50 chs. dist., and W. 8.00 chs. dist.
40.08	Point for the ½ sec. cor. of secs. 9 and 10, at proportionate dist.; there is no remaining evidence of the orig. cor.
	Set the iron post 20 ins. in the ground, brass cap mkd.
	T9S R26E
	in the second of
	S 9 S 10 1969
	Deposit glass at the base of the iron post.
45.90	Wash, 30 1ks. wide, 1 ft. deep, drains NW.
80.16	The cor. of secs. 3, 4, 9 and 10, determined from the remains of the orig. bearing tree:
	A mesquite stump, 12 ins. diam., bears S. 20° E., 75 lks. dist. Mks. visible, but illegible.
	·

Dep. Resurvey, Portion Subdivisional Lines, T. 9. S., R. 26 E.

· D	ep. Resurvey, Portion Subdivisional Lines, T. 9. S., R. 20
CHAINS	
	At the corner point
	Set the iron post 20 ins. in the ground, collar of stone to top, brass cap mkd.
	T9S R26E S 4 S 3 S 9 S10 1969
	Set a wooden post, 4 ft. long, 3 ins. square, alongside the iron post.
	Land, gently rolling. Soil, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.
·	From the cor. of secs. 2, 3, 10 and 11.
	S. 89°59° W., bet. secs. 3 and 10.
	Over gently rolling land.
.10	Draw, drains N.
.00	Draw, drains N.
.20	Power line and maintenance road, bears N. 20° E. and S. 20° W.
.30	Fence, bears N. 87° E. and S. 87° W.
. 92	Fence, bears N., and bears S. for 5 lks. to a cor. of fences extending N. and N. 87° E.
.985	Point for the E 1/16 sec. cor. of secs. 3 and 10 at proportionate dist.
	Set the iron post 22 ins. in the ground, brass cap mkd.
	T9S R26E
	E 1/16
	Set a wooden post, 3 ins. square, 4 ft. long, alongside the iron post.
8 . 60	Wash, 100 1ks. wide, 1 ft. deep, drains N. 30° W.
3.00	Wash, 50 1ks. wide, 2 ft. deep, drains N. 45° W.
9.97	Point for the ½ sec. cor. of secs. 3 and 10 at proportionate dist.; there is no remaining evidence of the original cor.
	Set the iron post 20 ins. in the ground, brass cap mkd.
	T9S R26E 2 S 3 S10 1969
	Set a wooden post, 4 ins. square, 3 ft. long, alongside the iron post.

Dep. Resurvey,	Portion	Subdivisional	Lines,	Τ.	9.	S.,	R.	26	Ε.
----------------	---------	---------------	--------	----	----	-----	----	----	----

	ep. Resurvey, Portion Subdivisional Lines, 1. 5, 5., K. 20 E
CHAINS	
74.20	Track road, bears irregularly SE. and NW.
79.94	The cor. of secs. 3, 4, 9 and 10.
	Land, gently rolling. Soil, sandy loam. Timber, scattered mesquite. Undergrowth, creosote bush and cacti.
,	From the cor. of secs. 27, 28, 33 and 34.
	S. 89°58' W., bet. secs. 28 and 33.
	Over rolling land.
-15.90	Power line and maintenance road, bears S. 7°30' E. and N. 7°30' W.
21.40	Cor. of R-0-W fence; fence bears N. 7°30' W. and W.
22.90	Cor. of R-O-W fence; fence bears E. and S. 7°30' E.
24.50	U.S. Highway No. 666, bears S. 7°30' E. and N. 7°30' W.
25.50	Cor. of R-0-W fence; fence bears S. 7°30' E. and W.
27.00	Cor. of R-0-W fence, fence bears E. and N. 7°30' W.
36.70	Power line, bears S. 14°30' E. and N. 14°30' W.
40.01	The ½ sec. cor. of secs. 28 and 33, monumented by a granite stone, 18x8x6 ins., firmly set 8 ins. in the ground, mkd. ½ on N. face, mound of stone N.
	At the corner point
•	Set the iron post 14 ins. in the ground, mound of stone to top, brass cap mkd.
	T9S R26E
	Deposit the orig. cor. stone in the mound of stone.
	S. 89°55' W., beginning new measurement.
	Over rolling land.
2.80	Underground pipeline and track road, bears S. 10° E. and N. 10° W.
20.70	Track road, bears irregularly N. and S.
40.01	The cor. of secs. 28, 29, 32 and 33, monumented by a granite stone, 18x10x7 ins., firmly set 10 ins. in the ground, mkd. with 4 notches on E. and 1 notch on S. edges.

Dep. Resurvey, Portion Subdivisional Lines, T. 9 S., R. 26 E.

CHAINS	At the common nation
	At the corner point
	Set the iron post 14 ins. in the ground, mound of stone to top, brass cap mkd.
	T9S R26E S 29 S 28 S 32 S 33 1969
	Bury the orig. cor. stone alongside the iron post.
	Land, rolling. Soil, rocky, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.
	N. 0°01' E., bet. secs. 28 and 29.
	Over rolling land.
,	
40.05	The ½ sec. cor. of secs. 28 and 29, monumented by a granite stone, 12x8x6 ins.; firmly set 8 ins. in the ground, mkd. ½ on W. face.
	At the corner point
	Set the iron post 22 ins. in the ground, brass cap mkd.
	T9S R26E
	s 29 s 28
	1969
	Bury the orig. cor. stone alongside the iron post.
	Raise a mound of stone W. of the cor.
•	
	N. 0°02' E., beginning new measurement.
	Over rolling land.
16.10	Wash, 20 1ks. wide, 1 ft. deep, drains irregularly NW.
40.11	The cor. of secs. 20, 21, 28 and 29, monumented by a granite stone, 16x10x8 ins., firmly set 8 ins. in the ground, mkd. with 4 notches on E. and 2 notches on S. edges.
	At the corner point
	Set the iron post 22 ins. in the ground, brass cap mkd.
	T9S R26E
	S 20 S 21 S 29 S 28
	1969
	Bury the orig. cor. stone alongside the iron post.
	·

. Dep. Resurvey, Portion Subdivisional Lines, T. 9 S., R. 26 E.

•	. DE.	p. Resurvey, Fortion Subdivisional Lines, 1. 9.5., R. 20 E.
	CHAINS	Raise a mound of stone W. of the cor.
		Land, rolling. Soil, rocky, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.
		From the cor. of secs. 21, 22, 27 and 28.
		S. 89°57' W., bet. secs. 21 and 28.
		Over rolling land.
	21.60	Track road, bears N. 30° E. and S. 30° W.
	26.30	Power line and maintenance road, bears N. 20° E. and S. 20° W., 10 lks. dist., thence S. 14°30' E.
	34.60	R-O-W fence, bears S. 17° E. and N. 17° W.
	37.70	U. S. Highway No. 666, bears S. 17° E. and N. 17° W.
	40.00	Point for the ½ sec. cor. of secs. 21 and 28, at proportionate dist.; there is no remaining evidence of the orig. cor.
		Set the iron post 20 ins. in the ground, brass cap mkd.
		T9S R26E 2 S 21 S 28 1969
		Raise a mound of stone N. of the iron post.
	40.96	R-O-W fence, bears S. 17° E. and N. 17° W.
	55.80	Power line, bears S. 14°30' E. and N. 14°30' W.
	61.40	Underground pipeline and track road, bears S. 15° E. and N. 15° W.
	74.10	Wash, 60 lks. wide, 2 ft. deep, drains NW.
	80.00	The cor. of secs. 20, 21, 28 and 29.
		Land, rolling. Soil, rocky, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.
		N. 0°01' E., bet. secs. 20 and 21.
	•	Over gently rolling land.
	3.20	Wash, 110 lks. wide, 1 ft. deep, drains irregularly NW.
	38.20	Wash, 20 1ks. wide, 6 ins. deep, drains N. 80° W.
	40.09	The ½ sec. cor. of secs. 20 and 21, monumented by a granite stone, 14x8x6 ins., firmly set 8 ins. in the ground, mkd. ½ on W. face. No evidence of the orig. bearing trees.

`Dep.	Resurvey,	Portion	Subdivisional	Lines,	T.	<u>'9</u>	S.,	R.	26	Ε.

_		ep. Resurvey, Portion Subdivisional Lines, T. 9 S., R. 26
	CHAINS	At the corner point
		Set the iron post 24 ins. in the ground, brass cap mkd.
	•	T9S R26E
		s 20 s 21 1969
		Bury the orig. cor. stone alongside the iron post.
	•	Raise a mound of stone W. of the cor.
		N. 0°03' E., beginning new measurement.
		Over gently rolling land.
	21 . 90	Underground pipeline and track road, bear S. 15° E. and N. 15° W.
	40.03	The cor. of secs. 16, 17, 20 and 21, monumented by a granite stone, 14x10x10 ins., firmly set 10 ins. in the ground, mkd. with 4 notches on E. and 3 notches on S. edges, mound of stone W.
		At the corner point
	,	Set the iron post 16 ins. in the ground, mound of stone to top, brass cap mkd.
		T9S R26E S 17 S 16 S 20 S 21 1969
		Deposit the orig. cor. stone in the mound of stone.
		Land, gently rolling. Soil, rocky, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.
		From the cor. of secs. 15, 16, 21 and 22.
		S. 89°58' W., bet. secs. 16 and 21.
		Over gently rolling land.
	2.30	Wash, 100 1ks. wide, 1 ft. deep, drains N. 50° W.
	22.10	Wash, 30 1ks. wide, 1 ft. deep, drains N. 30° W.
	40.00	The ½ sec. cor. of secs. 16 and 21, monumented by a granite stone, 18x8x6 ins., firmly set 10 ins. in the ground, mkd. ½ on N. face.
		from which an orig. bearing tree:
		A mesquite, 10 ins. diam., bears N. 24° W., 84 lks. dist., blaze overgrown. No evidence of the other orig. bearing tree.

Dep. Resurvey, Portion Subdivisional Lines, T. 9 S., R. 26 E.

. I	Dep. Resurvey, Portion Subdivisional Lines, T. 9 S., R. 26 E
CHAINS	
	At the corner point
•	Set the iron post 22 ins. in the ground, brass cap mkd.
	T9S R26E
	$\frac{1}{4} \frac{S 16}{S 21}$
	1969
	Bury the orig. cor. stone alongside the iron post.
	Raise a mound of stone N. of the cor.
	S. 89°57' W., beginning new measurement.
4	Over gently rolling land.
15.00	Wash, 30 1ks. wide, 2 ft. deep, drains N. 10° W.
18.80	Cor. of R-O-W fence; fences bear S. 16°30' E. and West, 145 lks. dist., thence N. 16°30' W.
21.90	U.S. Highway No. 666, bears S. 16°30' E. and N. 16°30' W.
23.40	Cor. of R-O-W fence; fences bear N. 16°30' W. and West, 160 lks. dist., thence S. 16°30' E.
32.10	Wash, 20 1ks. wide, 1 ft. deep, drains N. 10° W.
38.50	Power line, bears S. 14°30' E. and N. 14°30' W.
40.12	The cor. of secs. 16, 17, 20 and 21.
	Land, gently rolling. Soil, rocky, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.
	North, bet. secs. 16 and 17.
	Over gently rolling land.
5.00	Power line, bears S. 14°30' E. and N. 14°30' W.
17.60	Wash, 30 1ks. wide, I ft. deep, drains NW.
40.06	Point for the ½ sec. cor. of secs. 16 and 17, at proportionate dist.; there is no remaining evidence of the orig. cor.
	Set the iron post 15 ins. in the ground, mound of stone to top, brass cap mkd.
	T9S R26E
	s 17 s 16 1969
	1907
Į	

Dep. R	Resurvey,	Portion	Subdivisional	Lines,	Τ.	9	S.,	R.	26	Ε.
--------	-----------	---------	---------------	--------	----	---	-----	----	----	----

, De	ep. Resurvey, Fortion Subdivisional Lines, 1. 9 3., R. 20 1.
CHAINS 63.50	Track road, bears N. 65° E. and S. 65° W.
70.00	Cor. of R-O-W fence, bears West, 6 lks. dist.; fences
, 0, 00	bear S. 13° E., and S. 80° W. for 120 lks., thence N. 13° W.
76.90	U. S. Highway No. 666, bears S. 13° E. and N. 13° W.
80.12	Point for the cor. of secs. 8, 9, 16 and 17, at proportionate dist.; there is no remaining evidence of the orig. cor.
	Set the iron post 20 ins. in the ground, mound of stone to top, brass cap mkd.
	T9S R26E S 8 S 9 S 17 S 16 1969
	Land, gently rolling. Soil, rocky, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.
	From the cor. of secs. 9, 10, 15 and 16.
	S. 89°58' W., bet. secs. 9 and 16.
ė	Over gently rolling land.
0.03	Fence cor.; fences bear S. and W.
19.80	Wash, 50 lks. wide, 2 ft. deep, drains N. 20° W.
33.90	Wash, 20 lks. wide, 1 ft. deep, drains N. 5° W.
40.01	Point for the ½ sec. cor. of secs. 9 and 16, at proportionate dist.; there is no remaining evidence of the orig. cor.
•	Set the iron post 20 ins. in the ground, brass cap mkd.
	T9S R26E 1/4 S 9 S 16 1969
	The cor. is located 3 lks. N. of a fence bearing E. and W.
	Deposit glass at the base of the iron post.
61.60	Wash, 100 lks. wide, 2 ft. deep, drains irregularly N.
67.30	Fence cor.; fences bear E. and N. 70° W., 2.30 chs. dist., thence S. 70° W.
71.20	Fence cor.; fences bear W. and N. 70° E., 180 lks. dist., thence S. 70° E.
77.70	Cor. of R-O-W fence; fences bear E., W. and N. 13° W.
 79.20	Cor. of R-O-W fence; fences bear E. and S. 13° E.
80.02	The cor. of secs. 8, 9, 16 and 17.
	1

Dep. Resurvey, Portion Subdivisional Lines, T. 9 S., R. 26 E.

CHAINS	Land, gently rolling. Soil, rocky, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.
	N. 0°01' E., bet. secs. 8 and 9.
	Over gently rolling land.
10.00	R-O-W fence, bears S. 13° E. and N. 13° W.
40.06	Point for the ½ sec. cor. of secs. 8 and 9, at proportionate dist.; there is no remaining evidence of the orig. cor.
	Set the iron post 20 ins. in the ground, brass cap mkd.
	T9S R26E
	S 8 S 9 1969
c	from which
	A U.S.C.&G.S. triangulation station marker, bears N. 48°54'08" W., 7.42 chs. dist., monumented by a standard bronze station disk set in a squared concrete post projecting 4 ins. above ground, disk stamped ART 1945, Latitude: 32°39'54.982" N., Longitude: 109°42'03.904" W.
	Raise a mound of stone W. of the iron post.
60.40	Wash, 60 lks. wide, 2 ft. deep, drains irregularly N. from SE.
64.40	Wash, 60 lks. wide, 2 ft. deep, drains N. 20° E. from irregularly S.
80.12	The cor. of secs. 4, 5, 8 and 9, monumented by a granite stone, $28x12x12$ ins., firmly set 24 ins. in the ground, mkd. with 4 notches on E. and 5 notches on S. edges.
	At the corner point
	Set the iron post 24 ins. in the ground, brass cap mkd.
	T9S R26E S 5 S 4 S 8 S 9 1969
	Bury the orig. cor. stone alongside the iron post.
•	Raise a mound of stone W. of the cor.
, .	Land, gently rolling. Soil, rocky, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.
,	From the cor. of secs. 3, 4, 9 and 10.
	S. 89°55' W., bet. secs. 4 and 9.

Dep. Resurvey,	Portion	Subdivisional	Lines,	Τ.	9.5.,	ĸ.	20	c.
----------------	---------	---------------	--------	----	-------	----	----	----

	. De	p. Resurvey, Portion Subdivisional Lines, T. 9.S., R. 26 E.
	CHAINS	
		Over gently rolling land.
	2.90	Wash, 20 1ks. wide, 1 ft. deep, drains N.
	20.40	Wash, 100 1ks. wide, 1 ft. deep, drains N. 10° W.
-	38.20	Wash, 50 lks. wide, 1 ft. deep, drains irregularly N.
	40.13	The ½ sec. cor. of secs. 4 and 9, monumented by a granite stone, 12x12x6 ins., firmly set 8 ins. in the ground, mkd ½ on N. face.
	٠	At the corner point
		Set the iron post 22 ins. in the ground, brass cap mkd.
		T9S R26E 1/4 S 9 1969
		Bury the orig. cor. stone alongside the iron post.
		Set a wooden post, 4 ft. long, 4 ins. diam., alongside the cor.
		S. 89°59' W., beginning new measurement.
		Over gently rolling land.
	11.10	Wash, 30 lks. wide, 1 ft. deep, drains irregularly N.
	22.10	Track road, bears N. and S.
	38.20	Wash, 40 lks. wide, 2 ft. deep, drains N.
	40.05	The cor. of secs. 4, 5, 8 and 9.
		Land, gently rolling. Soil, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.
	^	From the cor. of secs. 28, 29, 32 and 33.
		N. 89°57' W., bet. secs. 29 and 32.
		Over rolling land.
	33.70	Enter wash area, drains irregularly N.
	39.68	The ½ sec. cor. of secs. 29 and 32, monumented by a sand stone, 18x10x6 ins., firmly set 8 ins. in the ground, mkd. ½ on N. face.
		At the corner point
		Set the iron post 20 ins. in the ground, brass cap mkd.
		T9S R26E 2 S 29 S 32 1969

Dep. Resurvey, Portion Subdivisional Lines, T. 9 S., R. 26 E.

•	De	p. Resurvey, Portion Subdivisional Lines, T. 9 S., R. 26 E.
	CHAINS	
		Bury the orig. cor. stone alongside the iron post.
		Raise a mound of stone N. of the cor.
		•
	•	N. 89°59' W., beginning new measurement.
		Over rolling land.
•	11.80	Track road, bears irregularly N. and S.
	15.80	P Ranch Canyon, 50 lks. wide, 2 ft. deep, drains N.
	16.10	Leave wash area, drains N.
	40.05	The cor. of secs. 29, 30, 31 and 32, monumented by a granite stone, projecting 8 ins. above ground, firmly set, mkd. with 5 notches on E. and 1 notch on S. edges; not remonumented.
		Land, rolling. Soil, rocky, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.
		N. 89°59' W., bet. secs. 30 and 31.
		Over rolling land.
	2.80	Wash, 10 1ks. wide, 1 ft. deep, drains NW.
	40.02	Point for the ½ sec. cor. of secs. 30 and 31, at proportionate dist.; there is no remaining evidence of the orig. cor.; not monumented. Point falls in a wash, 20 lks. wide, 6 ins. deep, draining N. from SE.
	49.90	Jeep trail, bears S. 10° E. and N. 10° W.
	54.50	Track road, bears NE. and SW.
	62.10	Track road, bears N. 80° E. and S. 80° W.
	64.00	Stockton Pass Wash, 50 1ks. wide, 2 ft. deep, drains N.
	69.00	Track road, bears irregularly N. and S.
	70.60	Wash, 50 lks. wide, 2 ft. deep, drains N.
	79.44	The cor. of secs. 25, 30, 31 and 36, on the W. bdy. of the Tp.
		Land, rolling. Soil, rocky, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.
		From the cor. of secs. 29, 30, 31 and 32.
		N. 0°20' W., bet. secs. 29 and 30.

CHAINS	Over rolling land.
40.07	Point for the ½ sec. cor. of secs. 29 and 30, at proportionate dist.; there is no remaining evidence of the orig. cor.
	Set the iron post 20 ins. in the ground, brass cap mkd.
	T9S R26E
	s 30 s 29
	1969
•	Raise a mound of stone W. of the iron post.
41.50	Track road, bears irregularly SE. and NW.
78.20	Wash, 150 lks. wide, 1 ft. deep, drains irregularly NE.
80.14	The cor. of secs. 19, 20, 29 and 30, monumented by a granite stone, 20x12x10 ins., firmly set 10 ins. in the ground, mkd. with 5 notches on E. and 2 notches on S. edges, mound of stone W.
	At the corner point .
	Set the iron post 22 ins. in the ground, brass cap mkd.
	T9S R26E S 19 S 20 S 30 S 29 1969
D	Bury the orig. cor. stone alongside the iron post.
	Raise a mound of stone W. of the cor.
	Land, rolling. Soil, rocky, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.
	From the cor. of secs. 20, 21, 28 and 29.
	N. 89°56' W., bet. secs. 20 and 29.
	Over rolling land.
36.10	Wash, 20 1ks. wide, 1 ft. deep, drains NW.
38.50	Low spur, slopes NW.
40.15	The ½ sec. cor. of secs. 20 and 29, monumented by a granite stone, 16x10x8 ins., firmly set 10 ins. in the ground, mkd. ½ on N. face.
	At the corner point
	Set the iron post 22 ins. in the ground, brass cap mkd.
	T9S R26E
	$\frac{1}{4} = \frac{s}{s} \frac{20}{29}$ 1969

Dep.	Resurvey,	Portion	S ubdivisional	Lines,	Т.	9	s.,	R.	26	Ε.
				,	- •	_	υ.,			

 • •	
CHAINS	Bury the orig. cor. stone alongside the iron post.
	Raise a mound of stone N. of the cor.
	·
•	N. 89°57' W., beginning new measurement.
	Over gently rolling land.
20.70	P Ranch Canyon, 70 lks. wide, 1 ft. deep, drains irregularly N.
39.30	Wash, 100 lks. wide, 1 ft. deep, drains N. 30° E.
40.06	The cor. of secs. 19, 20, 29 and 30.
	Land, rolling. Soil, rocky, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.
a.	N. 89°46' W., bet. secs. 19 and 30.
	Over gently rolling land.
1.0.00	Track road, bears irregularly N. and S.
18.90	Wash, 10 lks. wide, 1 ft. deep, drains irregularly N.
31.60	Wash, 10 lks. wide, 1 ft. deep, drains irregularly N.
40.08	The ½ sec. cor. of secs. 19 and 30, monumented by a granite stone, 16x10x8 ins., lying loose on the ground, mkd. ½ on a face. The present cor. location is considered the best available evidence of the position where the corner was originally set.
	At the corner point .
	Set the iron post 22 ins. in the ground, brass cap mkd.
	T9S R26E
	$\frac{1}{2}$ $\frac{\mathbf{S}}{\mathbf{S}} \frac{19}{30}$
	1969
	Bury the orig. cor. stone alongside the iron post.
	Set a steel fence post, 4 ft. long, alongside the cor.
	S. 89°51' W., beginning new measurement.
	Over gently rolling land.
6 . 20	Stockton Pass Wash, 100 lks. wide, 1 ft. deep, drains N.
16.50	Track road, bears irregularly N. and S.
 17.70	Fence, bears irregularly N. 86° E. and S. 86° W.

Dep. Resurvey, Portion Subdivisional Lines, T. 9 S., R. 26 E.

	CHAINS		
	23.10	Low spur, slopes N.	
	31.10	Dutch Henry Canyon, 20 lks. wide, 1 ft. deep, drains N. 20° W.	
	39.15	The cor. of secs. 19, 24, 25 and 30, on the W. bdy. of the Tp.	
		Land, gently rolling. Soil, rocky, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.	
	: -a -	From the cor. of secs. 19, 20, 29 and 30.	
		N. 0°02' E., bet. secs. 19 and 20.	
	•	Over gently rolling land.	
	12.10	Wash, 110 1ks. wide, 1 ft. deep, drains NE.	
	40.05	The ½ sec. cor. of secs. 19 and 20, monumented by a gran- ite stone, 10x8x6 ins., firmly set 6 ins. in the ground, mkd. ½ on W. face.	
		At the corner point	
		Set the iron post 24 ins. in the ground, brass cap mkd.	
		T9S R26E	
		s 19 s 20 1969	
		Bury the orig. cor. stone alongside the iron post.	
		Raise a mound of stone W. of the cor.	
		N. 0°01' E., beginning new measurement.	
:		Over gently rolling land.	
	14.80	Wash, 100 lks. wide, 1 ft. deep, drains NE.	
	40.03	The cor. of secs. 17, 18, 19 and 20, determined from the remaining orig. bearing trees:	
		A mesquite, 10 ins. diam., bears S. 15°30' W., 48 lks. dist. Blaze overgrown.	
		A mesquite, 6 ins. diam., bears N. 57°30' W., 20 lks. dist. Blaze overgrown. No evidence of the other orig. bearing trees.	
		At the corner point	
		Set the iron post 22 ins. in the ground, brass cap mkd.	
		T9S R26E S 18 S 17 S 19 S 20 1969	

. Dep. Resurvey, Portion of the Subdivisional Lines, T. 9 S., R. 26 E.

_		
	CHAINS	Raise a mound of stone W. of the iron post.
		•
		Land, gently rolling. Soil, rocky, sandy loam.
		No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.
		From the cor. of secs. 16, 17, 20 and 21.
		N. 89°59' W., bet. secs. 17 and 20.
		Over rolling land.
	4.70	Underground pipeline and track road, bears S. 15° E. and N. 15° W.
	27.20	Wash, 50 lks. wide, 2 ft. deep, drains N. 20° W.
	37.70	Wash, 40 lks. wide, 2 ft. deep, drains irregularly NW.
	40.12	The $\frac{1}{4}$ sec. cor. of secs. 17 and 20, monumented by a granite stone, $14x8x6$ ins., firmly set 8 ins. in the ground, mkd. $\frac{1}{4}$ on N. face.
		At the corner point
	·	Set the iron post 18 ins. in the ground, collar of stone to top, brass cap mkd.
		T9S R26E
		$\frac{1}{4} \frac{\text{S } 17}{\text{S } 20}$
		1969
		Bury the orig. cor. stone alongside the iron post.
		S. 89°56' W., beginning new measurement.
		Over rolling land.
	5.30	Wash, 100 lks. wide, 2 ft. deep, drains N. 55° W.
	26.50	Enter P Ranch Canyon wash area, drains irregularly N. 15° W.
	35.00	Leave P Ranch Canyon wash area.
	35.60	Track road, bears irregularly N. and S.
	36.40	Track road, bears irregularly N. and S.
	40.04	The cor. of secs. 17, 18, 19 and 20.
	·	Land, rolling. Soil, rocky, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.

D D	D	0.111111	~ ·	m 0	~	_	0.0	-
Dep. Resurvey,	Portion	Subdivisional	Lines,	T9	δ.,	к.	26	Ľ.

1	bep. Resurvey, Forcion Subdivisional Lines, 19 5., R. 20 L.
CHAINS	N. 89°58' W., bet. secs. 18 and 19.
	Over rolling land.
9.60	Wash, 80 1ks. wide, 2 ft. deep, drains N. 25° E.
11.20	Track road, bears irregularly N. and S.
14.80	Fence, bears N. 18° E. and S. 18° W.
31.30	Wash, 50 1ks. wide, 1 ft. deep, drains N. 35° E.
40.02	The ½ sec. cor. of secs. 18 and 19, monumented by a granite stone, 18x12x10 ins., firmly set 10 ins. in the ground, mkd. ½ on N. face.
	At the corner point
	Set the iron post 22 ins. in the ground, brass cap mkd.
	T9S R26E 1/2 S 18 S 19 1969
	Bury the orig. cor. stone alongside the iron post.
.,	Raise a mound of stone N. of the cor.
	N. 89°57' W., beginning new measurement.
13.60	Stockton Pass Wash, 80 lks. wide, 1 ft. deep, drains irregularly N.
17.20	Fence, bears N. 15° E. and S. 15° W.
18.80	Track road, bears irregularly N. and S.
27.40	Wash, in Dutch Henry Canyon, 80 lks. wide, with 6 ft. banks, drains N.
39.46	The cor. of secs. 13, 18, 19 and 24, on the W. bdy. of the Tp.
	Land, rolling. Soil, rocky, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.
	From the cor. of secs. 17, 18, 19 and 20.
	N. 0°05' W., bet. secs. 17 and 18.
	Over gently rolling land.
3.60	Track road, bears irregularly SE. and NW. Enter P. Ranch Canyon wash area, drains N. 20° W.
11.00	Track road, bears irregularly E. and W.
15.10	P Ranch Canyon, 50 lks. wide, 1 ft. deep, drains irregularly NW. Leave wash area.
22.80	Track road, bears irregularly NE. and SW.
1	

Dep. Resurvey,	Portion	Subdivisional	Lines,	T9	S.,	R.	26	Ε.

De	ep. Resurvey, Portion Subdivisional Lines, T. 9 S., R. 26 E.
CHAINS	
29.10	Fence, bears N. 55° E. and S. 55° W.
40.03	The ½ sec. cor. of secs. 17 and 18, monumented by a sandstone, 20x8x6 ins., lying loose on the ground, mkd. ½ on a face.
	At the corner point
	Set the iron post 22 ins. in the ground, brass cap mkd.
	T9S R26E
	s 18 s 17 1969
	Bury the orig. cor. stone alongside the iron post.
	Raise a mound of stone W. of the cor.
	N. 0°01' E., beginning new measurement.
	Over rolling land.
40.05	The cor. of secs. 7, 8, 17 and 18, monumented by a gran- ite stone, 18x8x7 ins., firmly set 10 ins. in the ground, mkd. with 5 notches on E. and 4 notches on S. edges, with mound of stone W.
	At the corner point
	Set the iron post 22 ins. in the ground, brass cap mkd.
	T9S R26E S 7 S 8 S 18 S 17 1969
	Bury the orig. cor. stone alongside the iron post.
``	.Raise a mound of stone W. of the cor.
	Land, gently rolling to rolling. Soil, rocky, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.
	From the cor. of secs. 8, 9, 16 and 17.
	S. 89°56' W., bet. secs. 8 and 17.
	Over gently rolling land.
0.76	U.S. Highway No. 666, bears S. 13° E. and N. 13° W.
4.00	Cor. of R-O-W fence; fences bear S. 13° E., W. and N. 13° W.
19.10	Power line, bears S. 14°30' E. and N. 14°30' W.
25.50	Underground pipeline and track road, bears S. 15° E. and N. 15° W.
37.30	Fence cor.; fences bear N., E. and W.

Dep	. Resurvey,	Portion	Subdivisional	Lines,	Τ.	9 S.	, R.	26	Ε.
-----	-------------	---------	---------------	--------	----	------	------	----	----

. De	ep. Resurvey, Portion Subdivisional Lines, T. 9 S., R. 26 E.
39.50	Wash, 50 lks. wide, 2 ft. deep, drains irregularly N.
40.08	Point for the ½ sec. cor. of secs. 8 and 17, at proportionate dist.; there is no remaining evidence of the orig. cor.
	Set the iron post 20 ins. in the ground, brass cap mkd.
	T9S R26E 2 S 8 S 17 1969
	The cor. is located 3 lks. North of a fence bearing E. and W.
	Deposit glass at the base of the iron post.
61.20	Wash, 20 lks. wide, 1 ft. deep, drains irregularly N.
63.20	Track road, bears irregularly S. and N., 1.00 chs. dist., thence E., 3.00 chs. dist., thence irregularly N.
63.40	Fence, bears S. and N., 6 lks. dist. to cor. of fences bearing E., S. and W.
80.16	The cor. of secs. 7, 8, 17 and 18.
	Land, gently rolling. Soil, rocky, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.
	N. 89°54' W., bet. secs. 7 and 18.
	Over gently rolling land, along fence line.
0.70	Power line, bears S. 20° W. and N. 20° E., 2.00 chs. dist., thence N.
8.10	Stockton Pass Wash, 70 lks. wide, 1 ft. deep, drains N.
13.50	Track road, bears irregularly S. and N. 20° E., 3.00 chs. dist., thence irregularly N.
37.70	Wash, 20 lks. wide, 1 ft. deep, drains N.
40.12	Point for the ½ sec. cor. of secs. 7 and 18, at proportionate dist.; there is no remaining evidence of the orig. cor.
,	Set the iron post 22 ins. in the ground, brass cap mkd.
,	T9S R26E 1/2 S 7 S 18 1969
	The cor. is located 8 lks. South of a fence bearing E. and W.
	Raise a mound of stone N. of the iron post.
77.80	Spring Canyon, 30 lks. wide, 1 ft. deep, drains N. from SE.
79.30	Jeep trail, bears N. and S.

Den.	Resurvey.	Portion	Subdivisional	Lines.	Τ.	9	S.,	R.	26	Ε.
Dep.	MESOT AGA	TOLCION	Danatararouar	وقاعتندند			\sim \circ	T/ 0	-0	 •

CHAINS	
79.44	The cor. of secs. 7, 12, 13 and 18, on the W. bdy. of the Tp.
	Land, gently rolling. Soil, rocky, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.
	From the cor. of secs. 7, 8, 17 and 18.
	N. 0°01' E., bet. secs. 7 and 8.
	Over gently rolling land.
0.14	Fence, bears E. and W.
0.25	Power line, bears S. 20° W. and N. 20° E. curving North.
40.14	The ½ sec. cor. of secs. 7 and 8, monumented by a granite stone, 20x12x12 ins., firmly set 12 ins. in the ground, mkd. ½ on W. face, from which the remains of an orig. bearing tree:
	A mesquite stump, 8 ins. diam., bears S. 88° E., 28 lks. dist., mkd. ½ S 8 BT. No evidence of the other orig. bearing tree.
	At the corner point
	Set the iron post 24 ins. in the ground, brass cap mkd.
	T9S_R26E
	s 7 s 8 1969
	Bury the orig. cor. stone alongside the iron post.
	Raise a mound of stone W. of the cor.
	N. 0°02' E., beginning new measurement.
	Over gently rolling land, along W. side of power line.
16.20	Track road, bears irregularly E. and W.
	The cor. of secs. 5, 6, 7 and 8, monumented by a concrete
40.12	post, 36 ins. long, 3 ins. square, firmly set 30 ins. in the ground, verified by record course and dist., from the remains of an original bearing tree:
	A mesquite stump, 18 ins. diam., bears S. 48° E., 96 lks. dist., no legible markings.
	At the corner point
·	Set the iron post 24 ins. in the ground, brass cap mkd.
	. T9S.R26E
` •	<u>s 6 s 5</u> s 7 s 8 1969
	Bury the concrete post alongside the iron post.

.Dep. Resurvey, Portion Subdivisional Lines, T. 9 S., R. 26 E.

CHAINS	
•	Cor. is in a fence line (abandoned), bearing E. and W.
	Land, rolling. Soil, sandy loam.
	No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.
	From the cor. of secs. 4, 5, 8 and 9.
	N. 89°59' W., bet. secs. 5 and 8.
•	Over gently rolling land.
17.50	R-O-W fence, bears S. 13° E. and N. 13° W.
19.20	U. S. Highway No. 666, bears S. 13° E. and N. 13° W.
20.70	R-O-W fence, bears S. 13° E. and N. 13° W.
39.20	Fence, bears N. 5° E. and S. 5° W.
40.02	The ½ sec. cor. of secs. 5 and 8, monumented by a concrete post, 3 ins. square, projecting 4 ins. above ground, firmly set, mkd. Sec. 5 Sec. 8 T9S R26E 8 RE 1231 1950. An old redwood stake was found in the ground alongside the concrete post. This is accepted as the best remaining evidence of the orig. cor. position.
t	At the corner point .
	Set the iron post 24 ins. in the ground, in a collar of stone, brass cap mkd.
	T9S R26E 1
	Bury the inverted concrete post and the old redwood stake, alongside the iron post.
	N. 89°59' W., beginning new measurement.
•	Over nearly level land.
0.70	Power line, bears S. 14°30' E. and N. 14°30' W.
5.00	Track road, bears N. 15° W. and S. 15° E. for 1.50 chs., thence bears SW.
5.30	Underground pipeline, bears S. 15° E. and N. 15° W.
6.90	Wash, 30 1ks. wide, 1 ft. deep, drains irregularly N.
11.60	Track road, bears NE. and SW.
20.05	The W 1/16 sec. cor. of secs. 5 and 8, monumented by a concrete post, 3 ins. square, firmly set, projecting 6 ins. above ground, mkd. SW COR SE\(\frac{1}{2}\)SW\(\frac{1}{2}\) SEC 5 RE 1231 1950.
	At the corner point

тер	Resulvey, Totalon Basalvisional Elmos, 1. 7 2., no 20
CHAINS	
•	Set the iron post 24 ins. in the ground, brass cap mkd.
	T9S R26E
	$W 1/16 \frac{S 5}{S 8}$
	1969
• .	Bury the inverted concrete post alongside the iron post.
	Set a wooden post, 4 ins. diam., 4 ft. long, alongside the corner.
35.00	Wash, 20 1ks. wide, 1 ft. deep, drains irregularly N.
40.00	Power line, bears N. and S.
40.10	The cor. of secs. 5, 6, 7 and 8.
	Land, gently rolling.
	Soil, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti
	and bunchgrass.
	West, bet. secs. 6 and 7.
	Over gently rolling land.
0.70	Jeep trail, bears irregularly N. and S.
20.03	Point for the E 1/16 sec. cor. of secs. 6 and 7, at proportionate dist.
	Set the iron post 24 ins. in the ground, brass cap mkd.
	T9S R26E
	E 1/16 S 7
	1969
	Raise a mound of stone N. of the iron post.
	•
26.00	Stockton Pass Wash, 50 lks. wide, 2 ft. deep, drains irregularly N.
40.06	The ½ sec. cor. of secs. 6 and 7, monumented by a concrete post, 36 ins. long, 3 ins. square, firmly set 20 ins. in the ground, mkd. ½ SEC 6 SEC 7 TWP 9 S. R. 26 E. RE 1231 1950, from which the remains of the orig. bearing trees:
	A mesquite stump, 6 ins. diam., bears S. 46° E., 57 lks. dist., no legible markings.
	A mesquite stump, 6 ins. diam., bears N. 23°45' W., 101 1ks. dist., no legible markings.
	At the corner point
	Set the iron post 22 ins. in the ground, brass cap mkd.
	T9S R26E
	S 6 5 7
]
	1969

CHAINS	Bury the concrete post alongside the iron post.
٠	
	Raise a mound of stone N. of the cor.
	N. 89°56' W., beginning new measurement.
	Over gently rolling land.
4.00	Spring Canyon, 50 lks. wide, 1 ft. deep, drains irregularly N. from SW.
18.70	Lefthand Canyon, 100 lks. wide, 1 ft. deep, drains irregularly N.
30.60	Jeep trail, bears irregularly N. and S.
3937	The cor. of secs. 1, 6, 7 and 12, on the W. bdy. of the Tp.
	Land, gently rolling. Soil, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.
	From the cor. of secs. 5, 6, 7 and 8.
	N. 0°03' E., bet. secs. 5 and 6.
	Over gently rolling land, along the W. side of a power line bearing N. and S.
13.50	Jeep trail, bears irregularly N. 10° E. and S. 10° W.
20.06	Point for the S 1/16 sec. cor. of secs. 5 and 6, at proportionate dist.
	Set the iron post 20 ins. in the ground, brass cap mkd.
•	T9S R26E S 1/16 S 6 S 5 1969
	from which
•	A local corner, bears West, 3 lks. dist., monumented by a concrete post, 3 ins. squared, projecting 3 ins. above the ground, mkd. SW COR NW\(\frac{1}{2}\)SW\(\frac{1}{2}\)SEC 5 RE 1231 1950.
	Raise a mound of stone W. of the iron post.
	The cor. is located 10 lks. West of power line bearing N. and S.
23.10	Power line, bears E., 10 lks. dist.; line bears N. 40° E. and S.
32.50	Stockton Pass Wash, 1.40 chs. wide, 2 ft. deep, drains irregularly NE.; and Jeep trail, bears irregularly E., curving S. and W.
40.12	Point for the ½ sec. cor. of secs. 5 and 6, at proportionate dist.; there is no remaining evidence of the orig. cor.; not monumented.

Dep. Resurvey, Portion Subdivisional Lines, T. 9 S., R. 26 E.

CHAINS	
40.70	Landing Air Strip and track road, bears N. 43° E. and S. 43° W.
41.90	Fence, bears N. 43° E. and S. 43° W.
59.40	Fence, bears E. and W.
59.70	Power line, bears E. and W.
60.10	Graded road, bears E. and W.
60.80	Fence, bears E. and W.
76.30	Fence, bears E. and W.
76.45	Point for the closing cor. of secs. 5 and 6, on the N. bdy. of the Tp., at proportionate dist.; there is no remaining evidence of the original cor.; not monumented.
	from which
	The point for the cor. of secs. 31 and 32, T. 8 S., R. 26 E., bears N. 89°58' E., 4.06 chs. dist., as described in the field notes of the S. bdy., T. 8 S., R. 26 E., concurrently retraced under Group No. 470.
	Land, gently rolling to nearly level. Soil, sandy loam. No timber; undergrowth, creosote bush, mesquite, cacti and bunchgrass.
•	

GENERAL DESCRIPTION

Township 9 South, Range 26 East is located about $12\frac{1}{2}$ miles south of Safford, Arizona. U. S. Highway No. 666 traverses through the township entering in section 5 and leaving in section 33. There are a number of side roads which vary from jeep trails to partially maintained roads.

The elevation ranges from about 4,000 ft. above sea level along the south boundary of section 31 to about 3,300 ft. in the northeast corner of the township. The drainage is from the south to the north in the west portion of the township and from the southwest to the northeast in the east portion. The land varies from nearly level to rolling. The soil varies from a sandy to rocky loam. Vegetation consists mainly of creosote bush, small mesquite, cacti and bunchgrass. There are numerous stock tanks, ponds and wells, mostly in the northwest portion of the township. Grazing is the principle use of the land. There is no evidence of mining claims or of mining activity in the township. A number of houses are located in sections 5 and 6.

Form 9180-8 (March 1969)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FIELD ASSISTANTS

NAMES	CAPACITY
John H. Witmer	Supervisory Cadastral Surveyor
Ray E. Thiessen	Supervisory Surveying Technician
Jerrel L. Jones	Surveying Aid
Steven J. Hall	Surveying Aid
Michael L. Minear	Surveying Aid

7

62

CERTIFICATE OF SURVEY

(I) (XXX Louis D. Gilbert

. HEREBY

of February , 1969 , (I)XXXX) have retraced a portion of the west boundary of Township 9 South, Range 27 East and dependently resurveyed the west boundary and a portion of the subdivisional lines, along with establishment of certain \$\frac{1}{2}\$ section corners of minimum control along the east and north boundaries of Township 9 South, Range 26 East,

of the Gila and Salt River Meridian, in the State of Arizona , which are represented in the foregoing field notes as having been executed by (me), XXX) and under (my) XXXXr) direction; and that said survey has been made in strict conformity with said special instructions, the Manual of Instructions for the Survey of the Public Lands of the United States, and in specific manner described in the foregoing field notes.

December 17, 1969	Janis S. Gellent	
(Date)	(Cadastral Surveyor)	
(Date)	(Cadastral Surveyor)	

CERTIFICATE OF APPROVAL

SUBMITTED FOR APPROVAL
Date ___ APR 2 4 1972

(Date)

BUREAU OF LAND MANAGEMENT Washington, D.C.

The foregoing field notes of the retracement of a portion of the west boundary of

Township 9 South, Range 27 East, and the dependent resurvey of the west

boundary and a portion of the subdivisional lines along with the establish
ment of certain ½ section corners of minimum control along the east and north

boundaries of Township 9 South, Range 26 East, Gila and Salt River Meridian, Arizona

executed by Louis D. Gilbert,

1 1 - 01

having been critically examined and found correct, are hereby approved.

OCT 1 2 1972	Clark J Sunny
(Date)	(Chief, Division of Cadastral Survey)
GERT	FICATE OF TRANSCRIPT
I CERTIFY That the foregoing transc	cript of the field notes of the above-described surveys in
	, is a true copy of the original field notes.